PROFORMA INVOICE

Vastukala Consultants (I) Pvt Ltd
Ackruti Star, 1st Floor, 121,
Central Road, MIDC, Andheri (E),
Mumbai - 400 093
GST!N/UIN: 27AADCV4303R1ZX
State Name: Maharashtra, Code: 27
E-Mail: accounts@vastukala.org
Buyer (Bill to)

STATE BANK OF INDIA - RACPC GHATKOPAR RACPC GHATKOPAR BRANCH, OPP. DAMODAR PARK, ASHOK SILK MILLS COMPOUND, L.B.S. MARG,

GHATKOPAR (W), MUMBAI-400086 GSTIN/UIN : 27AAACS8577K2ZO State Name : Maharashtra, Code : 27

Invoice No.	Dated
PG-5638/22-23	24-Feb-23
Delivery Note	Mode/Terms of Payment
Reference No. & Date.	Other References
Buyer's Order No.	Dated
Dispatch Doc No.	Delivery Note Date
29916 / 45690	
Dispatched through	Destination
Terms of Delivery	

SI No.	Particulars	Į.	HSN/SAC	GST Rate	Amount
1	STRUCTURAL REPORT FEE (Technical Inspection and Certification Services)	CGST SGST		18 %	2,500.00 225.00 225.00
		Total	1		₹ 2,950.00

Amount Chargeable (in words)

E. & O.E

Indian Rupee Two Thousand Nine Hundred Fifty Only

HSN/SAC Taxable		Central Tax		State Tax		Total
	Value	Rate	Amount	Rate	Amount	Tax Amount
997224	2,500.00	9%	225.00	9%	225.00	450.00
Total	2,500.00		225.00		225.00	450.00

Tax Amount (in words): Indian Rupee Four Hundred Fifty Only

Remarks:

"Name of Owner: Mr. Santosh Narayan Bhogate, Name of Client / Proposed Purchaser: Mr. Frank James Fernandes & Mrs. Chona Frank Fernandes - Residential Flat No. 703, 7th Floor, Wing - B, ""Guruvilasam Co-Op. Hsg. Soc. Ltd."", Ashok Nagar, Kanjur Village, Bhandup (East), Mumbai, PIN Code – 400 042, State – Maharashtra, Country – India.

Company's PAN : AADCV4303R

Declaration

NOTE – AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137 Company's Bank Details

Bank Name : State Bank of India A/c No. : 32632562114

-VC NO. . 32632562114

Branch & IFS Code: MIDC Andheri (E) & SBIN0007074



UPI Virtual ID : vastukala@icici

for Vastukala Consultants (I) Pvt Ltd

Authorised Signatory

This is a Computer Generated Invoice





CIN: U74120MH2010PTC207869 MSME Reg. No.; UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: SBI / RACPC Ghalkopar Branch / Mr. Frank James Fernandes (29916/45690)

Page 1 of 3

Vastu/Mumbai/2023/02/29916/45690

25/04-540-NI

Date: 25.02.2023

Structural Stability Report

Structural Observation Report of Residential Flat No. 703, 7th Floor, Wing - B, "Guruvilasam Co-Op. Hsg. Soc. Ltd.", Ashok Nagar, Kanjur Village, Bhandup (East), Mumbai, PIN Code - 400 042, State - Maharashtra, Country - India.

Name of Owner: Mr. Santosh Narayan Bhogate.

Name of Client / Proposed Purchaser: Mr. Frank James Fernandes & Mrs. Chona Frank Fernandes.

This is to certify that on visual inspection, it appears that the structure of the building "Guruvilasam Co-Op. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably takes under normal working condition and with proper periodic repairs & maintenance is about 41 years.

General Information:

A.		Introduction		
1	Name of Building	Guruvilasam Co-Op. Hsg. Soc. Ltd.		
2	Property Address	Residential Flat No. 703, 7th Floor, Wing - B, "Guruvilasam Co-Op. Hsg. Soc. Ltd.", Ashok Nagar, Kanjur Village, Bhandup (East), Mumbai, PIN Code - 400 042, State - Maharashtra, Country - India		
3	Type of Building	Residential use		
4	No. of Floors	Stilt + 7 Upper Floors		
5	Whether stilt / podium / open parking provided	Stilt Car Parking		
6	Type of Construction	R.C.C. Framed Structure		
7	Type of Foundation	R.C.C. Footing		
8	Thickness of the External Walls	9" thick brick walls both side plastered		
9	Type of Compound	Brick Masonry Walls		
10	Year of Construction	2004 (As per Occupancy Certificate)		
11	Present age of building	19 years		
12	Residual age of the building	41 years Subject to proper, preventive periodic maintenance & structural repairs.		
13	No. of flats (Per Floor)	3 Flats		
14	Methodology adopted	As per visual site inspection		







Regd. Office: 121, 1st Floor, Adkruti Star, Central Road, MIDC, Andheri (E), Mumbai - 400 093, (M.S.), INDIA

TeleFax: +91 22 28371325/24 mumbai@vastukala.org

B.	External Observation of the Building			
1	Plaster	Normal Condition		
2	Chajjas	Normal Condition		
3	Plumbing	Normal Condition		
4	Cracks on the external walls	Not Found		
5	Filling cracks on the external walls	Not Found		
6	Cracks on columns & beams	Not Found		
7	Vegetation	Not Found		
8	Leakages of water in the drainage pipes or water pipes	Not Found		
9	Dampness external in the wall due to leakages	Not Found		
10	Any other observation about the condition of external side of the building	The external condition is Normal		
С	Internal Observation of the common areas of the building and captioned premises			
1	Beams (Cracks & Leakages)	Good Condition		
2	Columns (Cracks & Leakages)	Good Condition		
3	Ceiling (Cracks & Leakages)	Good Condition		
4	Leakages inside the property	Not Found		
5	Painting inside the property	Good		
6	Maintenance of staircase & cracks	Normal		

D	Common Observation		
1		As per Bye Laws No. 77 of Co-Op. Societies Bye Laws	
	- Laws No. 77 of the Model Bye Laws	under the Act the society shall conduct a Structural Audit	
	(Co-Operative Societies Act / Rules)	of the building of the society as follows	
2	Remark	No Structural Audit Report is furnished for the perusal	

Conclusion

The captioned building is having Stilt + 7 Upper Floors which is constructed in year 2004. Estimated future life under present circumstances is about 41 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 24.02.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained Normal & will stand future life subject to proper, preventive periodic maintenance & structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.



Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME / TCC / 2016-17 / 156 / Sr. No. - 193





Actual Site Photographs















