

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6416a84b96b58848585e6998"
    },
    "type": "CREDITOFFICER",
    "_id": "6416a84b96b58848585e6999a",
    "firstName": "Anupam ",
    "lastName": "Tripathi",
    "mobileNo": "",
    "workMobileNo": "7053939597",
    "email": "brmgr306@mahabank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "package": {
```

```
    "_id": "5fc0d7e47d6c8d39dc34a294",
    "title": "basic",
    "price": 5.1,
    "case": 20,
    "duration": "300"
  },
  "status": true,
  "isdelete": false,
  "_id": "5f2bdee67813470eb443deb4",
  "name": "Vastukala Consultants India Pvt. Ltd.",
  "gstNo": "18AABCT3518Q1ZZ",
  "panNo": "ABCDE1234A",
  "freeCases": "10",
  "email": "vastukalamumbai@vastukala.com",
  "phone": "9819670183",
  "address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
  "remark": "undefined",
  "theme": "DEFAULT",
  "profilePhoto": "public\\images\\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
  "shortName": "VCIPL",
  "waterMarkImage": [
    {
      "_id": "6416ab1296b58848585e6e0e",
      "path": "public\\Vastukala Letter head H 2019.jpg",
      "pageNo": "2"
    }
  ],
  "city": "Mumbai",
  "stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6416a84b96b58848585e6998",
  "name": "Borivali East Branch\t",
  "branchCode": "",
  "mobileNo": "0228709296\t",
```

```
"alternateMobileNo": "",
"email": "bom306@mahabank.co.in",
"fax": "",
"ledgerName": "",
"sendStructuralCertificate": "0",
"address": "Sun & Moon CHSL, Bldg No 12,Rajendta Nagar , Dattapada Road,
Borivali (East), Mumbai 400066\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63abe77f4e30460e90087d32",
  "zoneName": "Mumbai City Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627219d6afd7d55eddedd283",
    "role": "PICKUPPERSON",
    "firstName": "Mangesh ",
    "email": "mangeshpalande17@gmail.com",
    "lastName": "Palande",
    "mobileNo": "9833030550",
    "shortName": "MP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "627208c1afd7d55eddedc372",
    "role": "FRONTDESK",
    "firstName": "Aniket",
    "email": "Aniket@vastukala.org",
    "lastName": "Navale",
    "mobileNo": "9892222307",
    "designation": "",
    "shortName": "AN",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
```

```
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
```

```
{
  "value": "IBBI/RV/07/2018/10366",
  "label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
]
],
```

```
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": 0,
  "longitude": 0
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "20/03/2023 10:30 am",
      "remark": ""
    },
    {
      "dateTime": "2023-03-20T11:53:02.039Z",
      "remark": ""
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-03-20T11:53:02.039Z"
  }
]
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Eksar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "98\t",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vasant Apartment\t",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Daulat Naagar\t",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
```



```
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Vasant Laxmi CHSL",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
}
```

```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "202t",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```

```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "White Marble Flooring",
    "value": "White_Marble_Flooring"
  },
  "doors": {
    "label": "Teak Wood",
    "value": "TeakWood"
  },
  "windows": {
    "label": "Wooden frame openable widow with M. S. Grill",
    "value": "Wooden_frame_openable_widow_with_M._S._Grill"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
  },
}
```

```
"finishing": {
  "label": "Cement Plastering + POP Finish",
  "value": "Cement_Plastering+_POP_Finish"
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "Maa Enclave CHSL",
    "west": "Oasees CHSL",
    "south": "Tulsi Vihar CHSL",
    "east": "Road No. 1"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Medium",
    "value": "Medium"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Seller Occupied",
    "value": "Seller_Occupied"
  },
  "monthlyRent": ""
},
```

```
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MuncipalWaterSupply"
  },
  "pavementLaid": {
    "label": "No",
    "value": "No"
  },
  "carParking": {
    "label": "Open Parking",
    "value": "Open_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "1990",
    "fullDate": "1/1/1990"
  },
  "propertyTypeList": {
    "value": "Residential",
    "label": "Residential"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "label": "R.C.C. Framed Structure",
    "value": "R.C.C._Framed_Structure"
  },
  "qualityOfConstruction": {
    "label": "Normal",
    "value": "Normal"
  },
  "walls": {
    "label": "Yes",
    "value": "1"
  }
}
```

```
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"siteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "27",
"ageOfBuilding": "33",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "3",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "2"
},
"routeMap": {
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
```

```
"compositionImages": []
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
"label": "Flooring, Tilling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```



```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"createCase": "true",
"type": "CASE",
"status": true,
"caseStatus": "READYFORMAKER",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"_id": "6416ab1296b58848585e6e09",
"ownerName": "Kinjal Patel",
"ownerPhoneNo": "9920420507",
```

```
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9920420507",
"contactPersonName": "Kinjal Patel\t",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Kinjal Patel\t",
    "phone": "9920420507",
    "ownershipShare": "",
    "email": "",
    "id": "419602"
  }
],
"caseReferredBy": "627219d6afd7d55eddedd283",
"relationWithOwner": "self",
"fullAddress": " Flat No. 202\t, 2nd Floor, Vasant Apartment\t, Vasant Laxmi CHSL,
Plot No. 98\t, Daulat Naagar\t, Village - Eksar, State - Maharashtra, India",
"remark": "",
"documents": [],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "000783",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "321527",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Sun Mar 19 2023 11:56:26 GMT+0530 (India Standard Time)"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Other",
      "value": "Other"
    }
  },
  {
    "_id": "641848fe96b58848585fa49b",
    "area": "556.01",
    "providedByName": "Site Measurement",
```

```
    "providedByContactNo": "0000000000"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "978154",
    "name": "Living Room",
    "length": "14.67",
    "length1": "14",
    "length2": "8",
    "width": "9.33",
    "width1": "9",
    "width2": "4",
    "totalArea": "136.89",
    "images": [
      {
        "name": "compositionImg_1679312738057_image.jpg",
        "path": "cases/6416ab1296b58848585e6e09/
compositionImg_1679312738057_image.jpg",
        "orientation": "portrait"
      },
      {
        "name": "compositionImg_1679312737489_image.jpg",
        "path": "cases/6416ab1296b58848585e6e09/
compositionImg_1679312737489_image.jpg",
        "orientation": "portrait"
      }
    ]
  },
  "extraAreas": [],
  "finalArea": "136.89"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "11.50",
  "length1": "11",
  "length2": "6",
  "width": "7.00",
```

```
"width1": "7",
"width2": "0",
"totalArea": "80.50",
"images": [
  {
    "name": "compositionImg_1679312782232_image.jpg",
    "path": "cases/6416ab1296b58848585e6e09/
compositionImg_1679312782232_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "80.50"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "11.92",
  "length1": "11",
  "length2": "11",
  "width": "10.25",
  "width1": "10",
  "width2": "3",
  "totalArea": "122.15",
  "images": [
    {
      "name": "compositionImg_1679312857131_image.jpg",
      "path": "cases/6416ab1296b58848585e6e09/
compositionImg_1679312857131_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "122.15"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Toilet",
```

```
"length": "6.67",
"length1": "6",
"length2": "8",
"width": "4.42",
"width1": "4",
"width2": "5",
"totalArea": "29.44",
"images": [
  {
    "name": "compositionImg_1679312894829_image.jpg",
    "path": "cases/6416ab1296b58848585e6e09/
compositionImg_1679312894829_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "29.44"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "11.00",
  "length1": "11",
  "length2": "0",
  "width": "10.83",
  "width1": "10",
  "width2": "10",
  "totalArea": "119.17",
  "images": [
    {
      "name": "compositionImg_1679312930978_image.jpg",
      "path": "cases/6416ab1296b58848585e6e09/
compositionImg_1679312930978_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "119.17"
},
{
  "measurementType": {
    "label": "Square Feet",
```

```
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "9.42",
  "length1": "9",
  "length2": "5",
  "width": "3.42",
  "width1": "3",
  "width2": "5",
  "totalArea": "32.17",
  "images": [
    {
      "name": "compositionImg_1679312971451_image.jpg",
      "path": "cases/6416ab1296b58848585e6e09/
compositionImg_1679312971451_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "32.17"
}
],
"otherComposition": [
  {
    "name": {
      "label": "Passage",
      "value": "Passage"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length1": "8",
    "length2": "3",
    "length": "8.25",
    "width1": "3",
    "width2": "5",
    "width": "3.42",
    "totalArea": "28.19",
    "percentageBeforeTotal": "28.19",
    "images": [
      {
        "name": "compositionImg_1679313054226_image.jpg",
        "path": "cases/6416ab1296b58848585e6e09/
compositionImg_1679313054226_image.jpg",
```

```
    "orientation": "portrait"
  }
],
"extraAreas": [],
"percentage": "100",
"finalArea": "28.19"
},
{
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "length1": "4",
  "length2": "5",
  "length": "4.42",
  "width1": "2",
  "width2": "11",
  "width": "2.92",
  "totalArea": "12.88",
  "percentageBeforeTotal": "12.88",
  "images": [
    {
      "name": "compositionImg_1679313097108_image.jpg",
      "path": "cases/6416ab1296b58848585e6e09/
compositionImg_1679313097108_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "12.88"
}
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "status": false,
    "_id": "641849b496b58848585fa7f2",
```

```
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313299796_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa7f3",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313302046_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa7f4",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313303398_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa7f5",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313301199_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa7f6",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313308352_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa7f7",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313305272_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa7f8",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313304173_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa7f9",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313315185_image.jpg"
  },
  {
```



```
    "status": false,
    "_id": "641849b496b58848585fa7fa",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313309726_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa7fb",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313307777_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa7fc",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313312912_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa7fd",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313324874_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa7fe",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313318826_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa7ff",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313322521_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa800",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313305528_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa801",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313308410_image.jpg"
```

```
},
{
  "status": false,
  "_id": "641849b496b58848585fa802",
  "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313315996_image.jpg"
},
{
  "status": false,
  "_id": "641849b496b58848585fa803",
  "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313312793_image.jpg"
},
{
  "status": false,
  "_id": "641849b496b58848585fa804",
  "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313326434_image.jpg"
},
{
  "status": false,
  "_id": "641849b496b58848585fa805",
  "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313322780_image.jpg"
},
{
  "status": false,
  "_id": "641849b496b58848585fa806",
  "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313319213_image.jpg"
},
{
  "status": false,
  "_id": "641849b496b58848585fa807",
  "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313308711_image.jpg"
},
{
  "status": false,
  "_id": "641849b496b58848585fa808",
  "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313311217_image.jpg"
},
{
  "status": false,
  "_id": "641849b496b58848585fa809",
```

```

    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313316693_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa80a",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313314226_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa80b",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313320239_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa80c",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313326442_image.jpg"
  },
  {
    "status": false,
    "_id": "641849b496b58848585fa80d",
    "path": "cases/6416ab1296b58848585e6e09/
externallmg_r_1679313323337_image.jpg"
  }
],
"externalDocuments": [],
"createdAt": "2023-03-19T06:26:26.864Z",
"updatedAt": "2023-03-20T11:55:44.115Z",
"__v": 0,
"updatedBy": "627208c1afd7d55eddedc372",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet",
"carpetTotal": "520.3199999999999",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "41.07",
"siteVisitDate": "2023-03-20"
}

```

Name	Length	Width	Total
Composition :			
Living Room	14'8"	9'4"	136.89
Kitchen	11'6"	7'0"	80.50

Bedroom	11'11"	10'3"	122.15
Toilet	6'8"	4'5"	29.44
Bedroom	11'0"	10'10"	119.17
Toilet	9'5"	3'5"	32.17
Other Composition :			
Passage	8'3"	3'5"	28.19
Passage	4'5"	2'11"	12.88