

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6273b00bafd7d55eddee5f69"
    },
    "type": "CREDITOFFICER",
    "_id": "6363aa704d42487767aeaf99",
    "firstName": "SUNIL BHOSALE",
    "lastName": "BHOSALE",
    "mobileNo": "9004074579",
    "email": "sunil.bhosale@sbi.co.in",
    "workMobileNo": "9004074579"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "SUNIL BHOSALE",
    "expectedFees": 5000,
    "quotedAmount": "2500"
  },
  "organization": {
    "package": {
      "_id": "5fc0d7e47d6c8d39dc34a294",
      "title": "basic",
      "price": 5.1,
      "case": 20,

```

```
"duration": "300"
},
"status": true,
"isdelete": false,
"_id": "5f2bdee67813470eb443deb4",
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"freeCases": "10",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"remark": "",
"theme": "DEFAULT",
"profilePhoto": "public\\images\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"waterMarkImage": [
  {
    "_id": "6419941996b5884858606072",
    "path": "public\\Vastukala Letter head H 2019.jpg",
    "pageNo": "2"
  }
],
"city": "Mumbai",
"stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6273b00bafd7d55eddee5f69",
  "name": "SPL PBB Fort",
  "branchCode": "4205 ",
  "mobileNo": "02223662641",
  "alternateMobileNo": "",
  "email": "sbi.04205@sbi.co.in",
  "fax": "",
  "ledgerName": ""
}
```

```
"sendStructuralCertificate": "0",
"address": "Mumbai Main Branch Building, Gate no 1 Horniman Circle Mumbai
samachar marg Fort."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "627208c1afd7d55eddedc372",
    "role": "FRONTDESK",
    "firstName": "Aniket",
    "email": "Aniket@vastukala.org",
    "lastName": "Navale",
    "mobileNo": "9892222307",
    "designation": "",
    "shortName": "AN",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
```

```
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "CHECKER",
  "firstName": "VINITA",
  "email": "vinita.surve@vastukala.org",
  "lastName": "SURVE",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "VSU",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "CHECKER",
  "firstName": "VINITA",
  "email": "vinita.surve@vastukala.org",
  "lastName": "SURVE",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "VSU",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "CHECKER",
  "firstName": "VINITA",
  "email": "vinita.surve@vastukala.org",
  "lastName": "SURVE",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "VSU",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
]
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": 0,
  "longitude": 0
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-03-22T19:11:50.689Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-03-22T19:11:50.689Z"
    }
  ]
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Tue Mar 21 2023 18:51:49 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
```

```
"value": "India",
"label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "10",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": false,
"name": "Taluka",
"key": "taluka",
"value": "",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shantinath Darshan",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "L T Road Dahisar East",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
```



```
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
```

```
"name": "Block No",
"key": "blockNo",
"value": "",
"label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1001",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
}
```

```
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood",
    "value": "TeakWood"
  },
  "windows": {
    "label": "Aluminium Sliding Windows with window grills",
    "value": "Aluminium_Sliding_Windows_with_window_grills"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
  },
  "finishing": {
    "label": "Cement Plastering + POP Finish",
```

```
    "value": "Cement_Plastering+_POP_Finish"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "Jainam Tower",
    "west": "B Wing",
    "south": "New Mahavir Darshan CHSL",
    "east": "Open Ground"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Medium",
    "value": "Medium"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Seller Occupied",
    "value": "Seller_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
```

```
"label": "6\" Thk. Brick Masonery",
"value": "6\"_Thk._Brick_Masonery"
},
"waterTank": {
"label": "Municipal Water Supply",
"value": "MunicipalWaterSupply"
},
"pavementLaid": {
"label": "Yes",
"value": "Yes"
},
"carParking": {
"label": "Stilt + Open Car Parking",
"value": "Stilt+_Open_Car_Parking"
},
"constructionWorkStatus": {
"label": "Completed",
"value": "Completed"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2009",
"fullDate": "1/1/2009"
},
"propertyTypeList": {
"value": "Residential",
"label": "Residential"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"label": "R.C.C. Framed Structure",
"value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
"label": "Good",
"value": "Good"
},
"walls": {
"label": "Yes",
"value": "1"
},
"appearanceOfTheBuilding": {
```

```
"label": "Good",
"value": "Good"
},
"maintenanceOfTheBuilding": {
"label": "Good",
"value": "Good"
},
"visibleDamageInBuilding": {
"label": "No",
"value": "0"
},
"groundStilt": {
"label": "Stilt",
"value": "Stilt"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "46",
"ageOfBuilding": "14",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "12",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "4"
},
"routeMap": {
"locationMapImg": []
},
"outward": {
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
"status": false
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```



```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"createCase": "false",
"type": "CASE",
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"_id": "6419941996b5884858606071",
"ownerName": "Pritesh Pravinchandra Gogri",
"ownerPhoneNo": "9920787845",
"appAddress": "Flat no 1001 A-wing Shantinath Darshan L T Road Dahisar East",
"remark": "Cont Divya Gogri Mob no +91 9920787845",
```

```
"documents": [
  {
    "documentType": {
      "label": "Draft Agreement",
      "value": "60ae124aaa6d152c1801b2f8"
    },
    "isHardCopy": false,
    "path": "cases/6419941996b5884858606071/
document_1679397880777_90922.pdf",
    "fileName": "document_1679397880777_90922.pdf",
    "displayStatus": false,
    "id": "682754",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Tue Mar 21 2023 16:55:10 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "000841",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "736121",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Mar 21 2023 16:55:13 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Pritesh Pravinchandra Gogri",
    "phone": "9920787845",
    "ownershipShare": "",
    "email": "",
    "id": "338320"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Other",
      "value": "Other"
    }
  },
  "_id": "641b52edee0c792c533bb0f2",
```

```
"area": "809.02",
"providedByName": "Site Measurement ",
"providedByContactNo": "0000000000"
},
],
"composition": [
{
"measurementType": {
"label": "Square Feet",
"value": "Square_Feet"
},
"id": "820621",
"name": "Living Room",
"length": "18.50",
"length1": "18",
"length2": "6",
"width": "9.83",
"width1": "9",
"width2": "10",
"totalArea": "181.92",
"images": [
{
"name": "compositionImg_r_1679511682448_image.jpg",
"path": "cases/6419941996b5884858606071/
compositionImg_r_1679511682448_image.jpg",
"orientation": "portrait"
}
],
"extraAreas": [],
"finalArea": "181.92"
},
{
"measurementType": {
"label": "Square Feet",
"value": "Square_Feet"
},
"id": "1",
"name": "Kitchen",
"length": "9.83",
"length1": "9",
"length2": "10",
"width": "7.25",
"width1": "7",
"width2": "3",
"totalArea": "71.29",
"images": [
```

```
{
  "name": "compositionImg_r_1679511718720_image.jpg",
  "path": "cases/6419941996b5884858606071/
compositionImg_r_1679511718720_image.jpg",
  "orientation": "portrait"
}
],
"extraAreas": [],
"finalArea": "71.29"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "13.83",
  "length1": "13",
  "length2": "10",
  "width": "10.17",
  "width1": "10",
  "width2": "2",
  "totalArea": "140.64",
  "images": [
    {
      "name": "compositionImg_r_1679511814762_image.jpg",
      "path": "cases/6419941996b5884858606071/
compositionImg_r_1679511814762_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "140.64"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "14.42",
  "length1": "14",
  "length2": "5",
  "width": "10.25",
```

```
"width1": "10",
"width2": "3",
"totalArea": "147.77",
"images": [
  {
    "name": "compositionImg_r_1679511878220_image.jpg",
    "path": "cases/6419941996b5884858606071/
compositionImg_r_1679511878220_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "147.77"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "14.58",
  "length1": "14",
  "length2": "7",
  "width": "10.08",
  "width1": "10",
  "width2": "1",
  "totalArea": "147.05",
  "images": [
    {
      "name": "compositionImg_r_1679511932624_image.jpg",
      "path": "cases/6419941996b5884858606071/
compositionImg_r_1679511932624_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "147.05"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Dry Balcony",
```

```
"length": "6.92",
"length1": "6",
"length2": "11",
"width": "3.42",
"width1": "3",
"width2": "5",
"totalArea": "23.63",
"images": [
  {
    "name": "compositionImg_r_1679511984247_image.jpg",
    "path": "cases/6419941996b5884858606071/
compositionImg_r_1679511984247_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "23.63"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "6.75",
  "length1": "6",
  "length2": "9",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "25.31",
  "images": [
    {
      "name": "compositionImg_r_1679512148365_image.jpg",
      "path": "cases/6419941996b5884858606071/
compositionImg_r_1679512148365_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "25.31"
},
{
  "measurementType": {
    "label": "Square Feet",
```

```
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "5.83",
  "length1": "5",
  "length2": "10",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "21.87",
  "images": [
    {
      "name": "compositionImg_r_1679512183485_image.jpg",
      "path": "cases/6419941996b5884858606071/
compositionImg_r_1679512183485_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "21.87"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "5.83",
  "length1": "5",
  "length2": "10",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "21.87",
  "images": [
    {
      "name": "compositionImg_r_1679512222390_image.jpg",
      "path": "cases/6419941996b5884858606071/
compositionImg_r_1679512222390_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "21.87"
```

```
}
],
"otherComposition": [
  {
    "name": {
      "label": "Passage",
      "value": "Passage"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length1": "7",
    "length2": "6",
    "length": "7.50",
    "width1": "2",
    "width2": "10",
    "width": "2.83",
    "totalArea": "21.25",
    "percentageBeforeTotal": "21.25",
    "images": [
      {
        "name": "compositionImg_r_1679512036644_image.jpg",
        "path": "cases/6419941996b5884858606071/
compositionImg_r_1679512036644_image.jpg",
        "orientation": "portrait"
      }
    ],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "21.25"
  },
  {
    "name": {
      "label": "Passage",
      "value": "Passage"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "length1": "3",
    "length2": "9",
    "length": "3.75",
```



```
"width1": "2",
"width2": "10",
"width": "2.83",
"totalArea": "10.62",
"percentageBeforeTotal": "10.62",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "10.62"
}
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "status": false,
    "_id": "641b53b5ee0c792c533bb13d",
    "path": "cases/6419941996b5884858606071/
externallmg_r_1679512459211_image.jpg"
  },
  {
    "status": false,
    "_id": "641b53b5ee0c792c533bb13e",
    "path": "cases/6419941996b5884858606071/
externallmg_r_1679512457885_image.jpg"
  },
  {
    "status": false,
    "_id": "641b53b5ee0c792c533bb13f",
    "path": "cases/6419941996b5884858606071/
externallmg_r_1679512456595_image.jpg"
  },
  {
    "status": false,
    "_id": "641b53b5ee0c792c533bb140",
    "path": "cases/6419941996b5884858606071/
externallmg_r_1679512455753_image.jpg"
  },
  {
    "status": false,
    "_id": "641b53b5ee0c792c533bb141",
    "path": "cases/6419941996b5884858606071/
externallmg_r_1679512459873_image.jpg"
  },
  },
}
```

```

{
  "status": false,
  "_id": "641b53b5ee0c792c533bb142",
  "path": "cases/6419941996b5884858606071/
externalImg_r_1679512460949_image.jpg"
}
],
"externalDocuments": [],
"createdAt": "2023-03-21T11:25:13.610Z",
"updatedAt": "2023-03-22T19:15:01.638Z",
"__v": 0,
"fullAddress": " Flat No. 1001, 10th Floor, Wing - A, Shantinath Darshan, L T Road
Dahisar East, State - Maharashtra, India",
"updatedAt": "627208c1afd7d55eddedc372",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Pritesh Pravinchandra Gogri",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9920787845",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Dry Balcony + 3 Toilet",
"carpetTotal": "781.35",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "31.869999999999997",
"siteVisitDate": "2023-03-23"
}

```

Name	Length	Width	Total
Composition :			
Living Room	18'6"	9'10"	181.92
Kitchen	9'10"	7'3"	71.29
Bedroom	13'10"	10'2"	140.64
Bedroom	14'5"	10'3"	147.77
Bedroom	14'7"	10'1"	147.05
Dry Balcony	6'11"	3'5"	23.63
Toilet	6'9"	3'9"	25.31

Toilet	5'10"	3'9"	21.87
Toilet	5'10"	3'9"	21.87
Other Composition :			
Passage	7'6"	2'10"	21.25
Passage	3'9"	2'10"	10.62