

```
{
  "typeOfReport": {
    "label": "Residential",
    "value": "Residential"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ae9ca7191f7b344b00597b"
    },
    "type": "CREDITOFFICER",
    "_id": "6418495596b58848585fa5e9",
    "firstName": "Ulka Kulkarni",
    "lastName": "Kulkarni",
    "mobileNo": "",
    "workMobileNo": "9773756812",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10891900",
    "discussWithPerson": "Ulka Kulkarni",
    "expectedFees": 5445.95,
    "quotedAmount": ""
  },
  "organization": {
    "package": {
      "_id": "5fc0d7e47d6c8d39dc34a294",
      "title": "basic",
      "price": 5.1,
      "case": 20,

```

```
"duration": "300"
},
"status": true,
"isdelete": false,
"_id": "5f2bdee67813470eb443deb4",
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"freeCases": "10",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"remark": "",
"theme": "DEFAULT",
"profilePhoto": "public\\images\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"waterMarkImage": [
  {
    "_id": "641d8eb229e5586db05f004c",
    "path": "public\\Vastukala Letter head H 2019.jpg",
    "pageNo": "2"
  }
],
"city": "Mumbai",
"stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ae9ca7191f7b344b00597b",
  "name": " Borivali MRO A-2",
  "branchCode": "",
  "mobileNo": "2228912178",
  "alternateMobileNo": "",
  "email": "Borivali@cosmosbank.in",
  "fax": "",
  "ledgerName": ""
}
```

```
"sendStructuralCertificate": "0",
"address": "Shop No. 12 & 14, Mayfair, Ramdas Sutrale Marg, Opp. Chandawarkar
Road, Borivali (West), Mumbai - 400 092."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "627208c1afd7d55eddedc372",
    "role": "FRONTDESK",
    "firstName": "Aniket",
    "email": "Aniket@vastukala.org",
    "lastName": "Navale",
    "mobileNo": "9892222307",
    "designation": "",
    "shortName": "AN",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
```

```
"_id": "60092304a16fab0f2af9b0c2",
"role": "MAKER+CHECKER",
"firstName": "Nitesh",
"email": "nitesh.khedekar@vastukala.org",
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60092304a16fab0f2af9b0c2\
\profilePhoto_1622372532348_Nitesh Khedekar Photo (2).jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER+CHECKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60092304a16fab0f2af9b0c2\
\profilePhoto_1622372532348_Nitesh Khedekar Photo (2).jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
]
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "0",
  "longitude": "0"
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-04-03T06:20:00.198Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-04-03T06:20:00.198Z"
    }
  ]
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Sat Mar 25 2023 18:28:23 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
```

```
"value": "India",
"label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": false,
"name": "Taluka",
"key": "taluka",
"value": "",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Chimi Co-operative HSG Soc Ltd ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Haridas Nagar Shimpoli Borivali West",
```



```
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
```

```
"name": "Block No",
"key": "blockNo",
"value": "",
"label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "403",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
}
```

```
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood",
    "value": "TeakWood"
  },
  "windows": {
    "label": "Aluminium Sliding Windows with window grills",
    "value": "Aluminium_Sliding_Windows_with_window_grills"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring",
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring"
  },
  "finishing": {
```

```
    "label": "Cement Plastering + POP Finish",
    "value": "Cement_Plastering+_POP_Finish"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "Victory Aarch CHSL",
    "west": "Haridas Nagar Road",
    "south": "R.M.Bhattad Road",
    "east": "Gangotri CHSL"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"partitions": {
  "label": "6\" Thk. Brick Masonery",
  "value": "6\"_Thk._Brick_Masonery"
},
"waterTank": {
  "label": "Municipal Water Supply",
  "value": "MunicipalWaterSupply"
},
"pavementLaid": {
  "label": "Yes",
  "value": "Yes"
},
"carParking": {
  "label": "Open Parking",
  "value": "Open_Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1990",
  "fullDate": "1/1/1990"
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
}
```

```
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "27",
"ageOfBuilding": "33",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "6",
"flatFloorNo": "",
"noOfLifts": "1",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
```

```
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
```



```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"createCase": "false",
"type": "CASE",
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"_id": "641d8eb229e5586db05f004b",
```

```
"ownerName": "Rohit Koradia",
"ownerPhoneNo": "9867645013",
"appAddress": "Flat no.403 ,4 th floor, Chimi Co-operative HSG Soc Ltd Haridas
Nagar Shimpoli Borivali West",
"remark": "Saturday 25/03 /23 Evening tak Valuation report chaiye bank ko ",
"documents": [
  {
    "documentType": {
      "label": "Agreement for Sale (11 Pages from Documents)",
      "value": "60ae12b5aa6d152c1801b4e5"
    },
    "isHardCopy": false,
    "path": "cases/641d8eb229e5586db05f004b/document_1679658468520_Rohit_Kar
adiav_COSMOS_Bank_MRO_A2_Borivali_West.pdf",
    "fileName": "document_1679658468520_Rohit_Karadiav_COSMOS_Bank_MRO_A
2_Borivali_West.pdf",
    "displayStatus": false,
    "id": "683314",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Fri Mar 24 2023 17:21:11 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "000893",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "739817",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Mar 24 2023 17:21:14 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Rohit Koradia",
    "phone": "9867645013",
    "ownershipShare": "",
    "email": "",
    "id": "737073"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    }
  }
]
```

```
    },
    "providedBy": {
      "label": "Other",
      "value": "Other"
    },
    "_id": "642a6e3591d7c62df117bd18",
    "area": "539.6",
    "providedByName": "Site Measurement",
    "providedByContactNo": "0000000000"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "430744",
    "name": "Living Room",
    "length": "27.25",
    "length1": "27",
    "length2": "3",
    "width": "7.92",
    "width1": "7",
    "width2": "11",
    "totalArea": "215.73",
    "images": [
      {
        "path": "cases/641d8eb229e5586db05f004b/
compositionImg_r_1680501175762_image.jpg",
        "orientation": "portrait"
      }
    ]
  },
  {
    "extraAreas": [],
    "finalArea": "215.73"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Dining",
    "length": "10.58",
    "length1": "10",
    "length2": "7",
```

```
"width": "4.42",
"width1": "4",
"width2": "5",
"totalArea": "46.74",
"images": [
  {
    "path": "cases/641d8eb229e5586db05f004b/
compositionImg_r_1680501260791_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "46.74"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "10.33",
  "length1": "10",
  "length2": "4",
  "width": "9.75",
  "width1": "9",
  "width2": "9",
  "totalArea": "100.75",
  "images": [
    {
      "path": "cases/641d8eb229e5586db05f004b/
compositionImg_r_1680501333489_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "100.75"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "10.42",
```

```
"length1": "10",
"length2": "5",
"width": "9.67",
"width1": "9",
"width2": "8",
"totalArea": "100.69",
"images": [
  {
    "path": "cases/641d8eb229e5586db05f004b/
compositionImg_r_1680501513018_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "100.69"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "5.67",
  "length1": "5",
  "length2": "8",
  "width": "3.00",
  "width1": "3",
  "width2": "0",
  "totalArea": "17.00",
  "images": [
    {
      "path": "cases/641d8eb229e5586db05f004b/
compositionImg_r_1680501846533_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "17.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
```

```
"name": "Toilet",
"length": "5.67",
"length1": "5",
"length2": "8",
"width": "3.92",
"width1": "3",
"width2": "11",
"totalArea": "22.19",
"images": [
  {
    "path": "cases/641d8eb229e5586db05f004b/
compositionImg_r_1680501913335_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "22.19"
},
"otherComposition": [
  {
    "name": {
      "label": "Passage",
      "value": "Passage"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length1": "4",
    "length2": "7",
    "length": "4.58",
    "width1": "2",
    "width2": "7",
    "width": "2.58",
    "totalArea": "11.84",
    "percentageBeforeTotal": "11.84",
    "images": [
      {
        "path": "cases/641d8eb229e5586db05f004b/
compositionImg_r_1680501997321_image.jpg",
        "orientation": "portrait"
      }
    ]
  },
  "extraAreas": [],
```

```
"percentage": "100",
"finalArea": "11.84"
},
{
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "length1": "6",
  "length2": "11",
  "length": "6.92",
  "width1": "3",
  "width2": "10",
  "width": "3.83",
  "totalArea": "26.51",
  "percentageBeforeTotal": "26.51",
  "images": [
    {
      "path": "cases/641d8eb229e5586db05f004b/
compositionImg_r_1680502111561_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "26.51"
}
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a709591d7c62df117bea0",
    "name": "externalImg_r_1680502930119_image.jpg",
    "path": "cases/641d8eb229e5586db05f004b/
externalImg_r_1680502930119_image.jpg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "642a709591d7c62df117bea1",
      "name": "externallmg_r_1680502930529_image.jpg",
      "path": "cases/641d8eb229e5586db05f004b/
externallmg_r_1680502930529_image.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "642a709591d7c62df117bea2",
      "name": "externallmg_r_1680502930307_image.jpg",
      "path": "cases/641d8eb229e5586db05f004b/
externallmg_r_1680502930307_image.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "642a709591d7c62df117bea3",
      "name": "externallmg_r_1680502930730_image.jpg",
      "path": "cases/641d8eb229e5586db05f004b/
externallmg_r_1680502930730_image.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "642a709591d7c62df117bea4",
      "name": "externallmg_r_1680502930991_image.jpg",
      "path": "cases/641d8eb229e5586db05f004b/
externallmg_r_1680502930991_image.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "642a709591d7c62df117bea5",
      "name": "externallmg_r_1680502931208_image.jpg",
      "path": "cases/641d8eb229e5586db05f004b/
externallmg_r_1680502931208_image.jpg",
      "orientation": "portrait"
    }
  }
```



```

],
"externalDocuments": [],
"createdAt": "2023-03-24T11:51:14.310Z",
"updatedAt": "2023-04-03T06:22:24.377Z",
"__v": 0,
"fullAddress": " Flat No. 403, 4th Floor, Chimi Co-operative HSG Soc Ltd , Haridas
Nagar Shimpoli Borivali West, State - Maharashtra, India",
"updatedAt": "627208c1afd7d55eddedc372",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Rohit Koradia",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9867645013",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Dining + 2 Toilet",
"carpetTotal": "503.09999999999997",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "38.35",
"siteVisitDate": "2023-04-03"
}

```

Name	Length	Width	Total
Composition :			
Living Room	27'3"	7'11"	215.73
Dining	10'7"	4'5"	46.74
Kitchen	10'4"	9'9"	100.75
Bedroom	10'5"	9'8"	100.69
Toilet	5'8"	3'0"	17.00
Toilet	5'8"	3'11"	22.19
Other Composition :			
Passage	4'7"	2'7"	11.84
Passage	6'11"	3'10"	26.51