PROFORMA INVOICE

Vastukala Consultants (I) Pvt Ltd Ackruti Star, 1st Floor, 121, Central Road, MIDC, Andheri (E), Mumbai - 400 093 GSTIN/UIN: 27AADCV4303R1ZX

State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org

Buyer (Bill to)

STATE BANK OF INDIA - RACPC GHATKOPAR RACPC GHATKOPAR BRANCH, OPP. DAMODAR PARK,

ASHOK SILK MILLS COMPOUND, L.B.S. MARG,

GHATKOPAR (W), MUMBAI-400086 GSTIN/UIN : 27AAACS8577K2ZO State Name : Maharashtra, Code: 27

Invoice No.	Dated
PG-193/23-24	21-Apr-23
Delivery Note	Mode/Terms of Payment
	AGAINST REPORT
Reference No. & Date.	Other References
Buyer's Order No.	Dated
Dispatch Doc No.	Delivery Note Date
30629 / 2300196	
Dispatched through	Destination

SI No.	Particulars	HSN/SAC	GST Rate	Amount
1	STRUCTURAL REPORT FEE (Technical Inspection and Certification Services) CGST SGST		18 %	2,500.00 225.00 225.00
		J		
	Total	1		₹ 2,950.00

Amount Chargeable (in words)

E. & O.E

Indian Rupee Two Thousand Nine Hundred Fifty Only

HSN/SAC	Taxable	Central Tax		State Tax		Total
	Value	Rate	Amount	Rate	Amount	Tax Amount
997224	2,500.00	9%	225.00	9%	225.00	450.00
Tota	2,500.00		225.00		225.00	450.00

Tax Amount (in words): Indian Rupee Four Hundred Fifty Only

Remarks:

Mr. Abhishek Badkul, Mr. Ashok Kumar Jain & Mrs. Kalpna Jain. Name of Proposed Purchaser is Mr. Nachiket D. Humne, Mrs. Jaimala D. Humne & Mr. Dhananjay G. Humne - Residential Flat No. 505, 5th Floor, "Valentina Co-op. Hsg. Soc. Ltd.", Hiranandani Estate, Behind Municipal Commissioner Bungalow, Patlipada, Village Kolshet, Ghodbunder Road, Thane (West) - 400 607, State - Maharashtra, Country - India

Company's PAN

: AADCV4303R

Declaration

NOTE - AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137

Company's Bank Details

Bank Name : State Bank of India

32632562114 A/c No.

Branch & IFS Code: MIDC Andheri (E) & SBIN0007074



UPI Virtual ID : vastukala@icici

for Vastukala Consultants (I) Pvt Ltd

Authorised Signatory

This is a Computer Generated Invoice



Vastukala Consultants (1) Pvt. Ltd.

An ISO 9001:2015 Certified Company www.vastukala.org



CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: SBI / RACPC Ghatkopar Branch / Mr. Nachiket D. Humne (30629 / 2300196) Page 1 of 4 Vastu/Mumbai/04/2023/30629/2300196

21/05-193-SBSH Date: 21.04.2023

Structural Stability Report

Structural Observation Report of Residential Flat No. 505, 5th Floor, "Valentina Co-op. Hsg. Soc. Ltd.", Hiranandani Estate, Behind Municipal Commissioner Bungalow, Patlipada, Village Kolshet, Ghodbunder Road, Thane (West) – 400 607, State – Maharashtra, Country – India.

Name of Proposed Purchaser: Mr. Nachiket D. Humne, Mrs. Jaimala D. Humne & Mr. Dhananjay G. Humne

Name of Owners: Mr. Abhishek Badkul, Mr. Ashok Kumar Jain & Mrs. Kalpna Jain

This is to certify that on visual inspection, it appears that the structure of the at "Valentina Co-op. Hsg. Soc. Ltd." is in good condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 43 years.

General Information:

A.		Introduction			
1	Name of Building	"Valentina Co-op. Hsg. Soc. Ltd."			
2	Property Address	Residential Flat No. 505, 5th Floor, "Valentina Co-op. Hsg. Soc. Ltd.", Hiranandani Estate, Behind Municipal Commissioner Bungalow, Patlipada, Village Kolshet, Ghodbunder Road, Thane (West) – 400 607, State – Maharashtra, Country – India.			
3	Type of Building	Residential used			
4	No. of Floors	Stilt + 12 Upper Floors			
5	Whether stilt / podium / open parking provided	Along with One Open Car Parking Space No. 40			
6	Type of Construction	R.C.C. Framed Structure			
7	Type of Foundation	R.C.C. Footing			
8	Thickness of the External Walls	9* thick brick walls both sides plastered			
9	Type of Compound	Brick Masonry Walls			
10	Year of Construction	2006 (As per occupancy certificate)			
11	Present age of building	17 years			
12	Residual age of the building	43 years Subject to proper, preventive periodic maintenance & structural repairs.			
13	No. of flats (Per Floor)	6 Flats on 5 th Floor			
14	Methodology adopted	As per visual site inspection			





Our Pan India Presence at : Rajkot R Mumbai . Aurangabad Pune N'anded ₽ Thane Raipur 🖓 Indore P Delhi NCR P Nashik Ahmedabad 9 Joipur

Regd. Office: 121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai - 400 093, (M.S.), INDIA TeleFax: +91 22 28371325/24

mumbai@vastukala.org

B.	External Observation of the Building			
1	Plaster	Good Condition		
2	Chajjas	Good Condition		
3	Plumbing	Good Condition		
4	Cracks on the external walls	Not found		
5	Filling cracks on the external walls	Not found		
6	Cracks on columns & beams	Not found		
7	Vegetation	Not found		
8	Leakages of water in the drainage pipes	Not found		
	or water pipes			
9	Dampness external in the wall due to	Not found		
	leakages			
10	Any other observation about the	The external condition of the building is in good condition		
	condition of external side of the building			
С	Internal Observation of the common areas of the building and captioned premises			
1	Beams (Cracks & Leakages)	Good Condition		
2	Columns (Cracks & Leakages)	Good Condition		
3	Ceiling (Cracks & Leakages)	Good Condition		
4	Leakages Inside the property	Not found		
5	Painting inside the property	Good		
6	Maintenance of staircase & cracks	Good		
D	Common Observation			
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws		
	- Laws No. 77 of the Model Bye Laws			
	(Co-Operative Societies Act / Rules)	of the building of the society as follows		
2	Remark	No Structural Audit Report is furnished for the perusal		

Conclusion

The captioned building is having Stilt + 12 Upper Floors which are constructed in year 2006 as per occupancy certificate. Estimated future life under present circumstances is about 43 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 27.03.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in good condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar Digitally signed by Sharadkumar B. Chalikwar DN. co-Sharadkumar B. Chalikwar, o-Vastukala Consultants (I) Pvt. Ltd, ou-CMD, email=cmd@vastukala org, c=IN Date: 2023.04.21 12:47:30 +05:30'



Auth. Sign.

Director

Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME/TCC/2021-22/85/13





Actual Site Photographs

























Actual Site Photographs







Think.Innovate.Create

