PROFORMA INVOICE

Vastukala Consultants (I) Pvt Ltd
Ackruti Star, 1st Floor, 121,
Central Road, MIDC, Andheri (E),
Mumbai - 400 093
GSTIN/UIN: 27AADCV4303R1ZX
State Name: Maharashtra, Code: 27
E-Mail: accounts@vastukala.org
Buyer (Bill to)

STATE BANK OF INDIA

RACPC SION BRANCH

B-603 & 604, Kohinoor City, Commercial-1 6th Floor, Kirol Road, Off L.B.S. Marg, Kurla (West), Mumbai - 400070

State - Maharashtra, Country - India GSTIN/UIN : 27AAACS8577K2ZO State Name : Maharashtra, Code : 27

| Invoice No. | Dated |
|-------------------------------------|--------------------------------------|
| PG-387/23-24 | 2-May-23 |
| Delivery Note | Mode/Terms of Payment AGAINST REPORT |
| Reference No. & Date. | Other References |
| Buyer's Order No. | Dated |
| Dispatch Doc No. 30744 / 2300392 | Delivery Note Date |
| Dispatched through | Destination |

| - | - | D 11 | |
|-------|----|----------|---|
| Terms | OÎ | Delivery | 1 |

| SI No. | Particulars | | HSN/SAC | GST Rate | Amount |
|-----------|---|--------------|---------|-------------|------------------------------|
| 1 | STRUCTURAL REPORT FEE (Technical Inspection and Certification Services) | CGST SGST | | 18 % | 2,500.00 225.00 225.00 |
| | | | 1 | | |
| | | Total | 7 | | ₹ 2,950.00 |

Amount Chargeable (in words)

E. & O.E

Indian Rupee Two Thousand Nine Hundred Fifty Only

| HSN/SAC | Taxable Value | Central Tax | | State Tax | | Total |
|-------------------|------------------|-------------|--------|-----------|--------|------------|
| III W.S. VA. B.D. | | Rate | Amount | Rate | Amount | Tax Amount |
| 997224 | 2,500.00 | 9% | 225.00 | 9% | 225.00 | 450.00 |
| Total | 2,500.00 | | 225.00 | | 225.00 | 450.00 |

Tax Amount (in words): Indian Rupee Four Hundred Fifty Only

Company's Bank Details

Bank Name : State Bank of India

A/c No. : **32632562114**

Branch & IFS Code: MIDC Andheri (E) & SBIN0007074

Remarks:

Mrs. Arpana Singh & Mr. Vinod Kumar Singh. Residential Flat No. 07, 4th Floor, "Sai Arpan Co-op. Hsg. Soc. Ltd.", Plot No. 28, Sector - 14,

Koparkhairane, Navi Mumbai, Taluka & District - Thane, PIN Code – 400 709, State - Maharashtra, Country –

India

Company's PAN : AADCV4303R

Declaration

NOTE – AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137

UPI Virtual ID : vastukala@icici

for Vastukala Consultants (I) Pvt Ltd

Authorised Signatory

This is a Computer Generated Invoice



Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001:2015 Certified Company

www.vastukala.org



CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617

An ISO 9001:2015 Certified Company Consultants (I) Pvt. Ltd.



Structural Stability Report Prepared For: SBI / RACPC Sion / Mrs. Arpana Singh (30744/2300392) Page 1 of 3

Vastu/Mumbai/05/2023/30744/2300392 02/14-14-PA

Date: 02.05.2023

Structural Stability Report

Structural Observation Report of Residential Flat No. 07, 4th Floor, "Sai Arpan Co-op. Hsg. Soc. Ltd.", Plot No. 28, Sector - 14, Koparkhairane, Navi Mumbai, Taluka & District - Thane, PIN Code - 400 709, State -Maharashtra, Country - India.

Name of Owner: Mrs. Arpana Singh & Mr. Vinod Kumar Singh.

This is to certify that on visual inspection, it appears that the structure of "Sai Arpan Co-op. Hsg. Soc. Ltd." is in normal condition and the future life can be reasonably takes under normal condition and with proper periodic repairs & maintenance is about 40 years.

General Information:

| A. | Introduction | | | | |
|----|--|--|--|--|--|
| 1 | Name of Building | Sai Arpan Co-op. Hsg. Soc. Ltd. | | | |
| 2 | Property Address | Residential Flat No. 07, 4th Floor, "Sai Arpan Co-op. Hsg. Soc. Ltd.", Plot No. 28, Sector - 14, Koparkhairane, Navi Mumbai, Taluka & District - Thane, PIN Code - 400 709, State - Maharashtra, Country - India | | | |
| 3 | Type of Building | Residential used | | | |
| 4 | No. of Floors | Ground + 4 Upper Floors | | | |
| 5 | Whether stilt / podium / open parking provided | Open Car Parking | | | |
| 6 | Type of Construction R.C.C. Framed Structure | | | | |
| 7 | Type of Foundation | R.C.C. Footing | | | |
| 8 | Thickness of the External Walls | 9" thick brick walls both sides plastered | | | |
| 9 | Type of Compound | Brick Masonry Walls | | | |
| 10 | Year of Construction | 2003 (As per Occupancy Certificate) | | | |
| 11 | Present age of building | 20 Years | | | |
| 12 | Residual age of the building | 40 years Subject to proper, preventive periodic maintenance & structural repairs. | | | |
| 13 | No. of flats (Per Floor) | 2 Flats on 4th Floor | | | |
| 14 | Methodology adopted | As per visual site inspection | | | |





Our Pan India Presence at : **P** Rajkat Mumbai 💡 Aurangabad Pune: ↑ Thane **♀** Nanded Raipur 🖁 Indore P Delhi NCR P Nashik Ahmedabad 9 Jaipur Regd. Office: 121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai - 400 093, (M.S.), INDIA

🖀 TeleFax : +91 22 28371325/24 mumbai@vastukala.org

| B. | External Observation of the Building | | | | |
|----|--|---|--|--|--|
| 1 | Plaster | Normal Condition | | | |
| 2 | Chajjas | Normal Condition | | | |
| 3 | Plumbing | Normal Condition | | | |
| 4 | Cracks on the external walls | Not Found | | | |
| 5 | Filling cracks on the external walls | Not Found | | | |
| 6 | Cracks on columns & beams | Not Found | | | |
| 7 | Vegetation | Not Found | | | |
| 8 | Leakages of water in the drainage pipes | Not Found | | | |
| | or water pipes | | | | |
| 9 | Dampness external in the wall due to | Not Found | | | |
| | leakages | | | | |
| 10 | Any other observation about the | The external condition of the building is in normal condition | | | |
| | condition of external side of the building | | | | |
| С | Internal Observation of the comm | on areas of the building and captioned premises | | | |
| 1 | Beams (Cracks & Leakages) | Normal Condition | | | |
| 2 | Columns (Cracks & Leakages) | Normal Condition | | | |
| 3 | Ceiling (Cracks & Leakages) | Normal Condition | | | |
| 4 | Leakages inside the property | Not Found | | | |
| 5 | Painting inside the property | Normal | | | |
| 6 | Maintenance of staircase & cracks | Normal | | | |

| D | Common Observation | | |
|---|--|---|--|
| 1 | Structural Audit of the Building Under Bye | As per bye Laws No. 77 of Co-Op. Societies bye Laws | |
| | - Laws No. 77 of the Model Bye Laws under the Act the society shall conduct a Structural A | | |
| | (Co-Operative Societies Act / Rules) | of the building of the society as follows | |
| 2 | Remark | No Structural Audit Report is furnished for the perusal | |

E Conclusion

The captioned building is having Ground + 4 Upper Floors which are constructed in year 2003 (As per Occupancy Certificate). Estimated future life under present circumstances is about 40 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 05.04.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar B. Chalikwar Digitally signed by Sharadkumar B. Chalikwar DN: cn=Sharadkumar B. Chalikwar, o=Vastukala Consultants (II) Put. Ltd., ou=CMD, email=cmd@vastukala.org, c=IN Date: 2023.05.02 16:46:56+95'30'

Auth. Sign.

Sharadkumar B. Chalikwar

Director

Govt. Reg. Valuer Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME/TCC/2017-18/942/178





Actual Site Photographs











reate



