

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Education Loan",
    "value": "Education_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9b2"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230efb",
    "firstName": "Pratibha Bhatia",
    "email": "0_DEFAULT_pratibha.bhatia@cosmosbank.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-2226402884"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Pratibha Bhatia",
    "expectedFees": 2500,
    "quotedAmount": ""
  },
  "organization": {
    "package": {
      "_id": "5fc0d7e47d6c8d39dc34a294",
      "title": "basic",
      "price": 5.1,
      "case": 20,
      "duration": "300"
    }
  }
}
```

```
},
"status": true,
"isdelete": false,
"_id": "5f2bdee67813470eb443deb4",
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"freeCases": "10",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"remark": "",
"theme": "DEFAULT",
"profilePhoto": "public\\images\\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"waterMarkImage": [
  {
    "_id": "6424158d91d7c62df116ee9e",
    "path": "public\\Vastukala Letter head H 2019.jpg",
    "pageNo": "2"
  }
],
"city": "Mumbai",
"stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9b2",
  "branchCode": "000012",
  "type": "BRANCH",
  "name": "Bandra (West) Branch",
  "email": "pratibha.bhatia@cosmosbank.in",
  "mobileNo": "02226402884",
  "alternateMobileNo": "",
  "address": "16, Lubina Turner Road, Opp. Tava Restaurant Bandra (West), Mumbai -
400 050, State - Maharashtra, Country - India.",
```

```
"ledgerName": "COSMOS BANK- BANDRA WEST BRANCH",
"fax": "",
"sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "DELIVERYPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
    "lastName": "Patkar",
    "mobileNo": "7045746060",
    "shortName": "RP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "627208c1afd7d55eddedc372",
    "role": "FRONTDESK",
    "firstName": "Aniket",
    "email": "Aniket@vastukala.org",
    "lastName": "Navale",
    "mobileNo": "9892222307",
    "designation": "",
    "shortName": "AN",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
```

```
"_id": "60f915d3f3dd69653a592199",
"role": "CHECKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "CHECKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "0",
  "longitude": "0"
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-03-31T02:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-03T07:52:56.982Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-04-03T07:52:56.982Z"
    }
  ]
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Fri Mar 31 2023 09:13:01 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
}
```

```
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "mandapeshwar ",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
```

```
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": " dwarkesh dham co-op hsg soc Ltd",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
```



```
"status": false,
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
```

```
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "61",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
```

```
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Spartex",
    "value": "Spartex"
  },
  "doors": {
    "label": "Teak Wood",
    "value": "TeakWood"
  },
  "windows": {
    "label": "Alluminum sliding windows with M. S. Grills",
    "value": "Alluminum_sliding_windows_with_M._S._Grills"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring",
```

```
"value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring"
},
"finishing": {
  "label": "Good",
  "value": "Good"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "Blue Pearl CHSL",
    "west": "Under Construction Bulding",
    "south": "Raj Villa CHSL",
    "east": "Baburao Ranade Road"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Tenant Occupied",
    "value": "Tenant_Occupied"
  }
}
```

```
    },
    "monthlyRent": ""
  },
  "siteMeasurement": {
    "partitions": {
      "label": "6\" Thk. Brick Masonery",
      "value": "6\"_Thk._Brick_Masonery"
    },
    "waterTank": {
      "label": "Municipal Water Supply",
      "value": "MuncipalWaterSupply"
    },
    "pavementLaid": {
      "label": "Yes",
      "value": "Yes"
    },
    "carParking": {
      "label": "Open Parking",
      "value": "Open_Parking"
    },
    "constructionWorkStatus": {
      "label": "Completed",
      "value": "Completed"
    },
    "dateOfConstruction": {
      "date": "1",
      "month": "1",
      "year": "1992",
      "fullDate": "1/1/1992"
    },
    "propertyTypeList": {
      "value": "Residential",
      "label": "Residential"
    },
    "planningArea": {
      "value": "Residential",
      "label": "Residential"
    },
    "typeOfStructure": {
      "label": "R.C.C. Framed Structure",
      "value": "R.C.C._Framed_Structure"
    },
    "qualityOfConstruction": {
      "label": "Good",
      "value": "Good"
    }
  },
}
```

```
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "29",
"ageOfBuilding": "31",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "6",
"flatFloorNo": "",
"noOfLifts": "1",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```

```
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```



```
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"createCase": "false",
"type": "CASE",
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"_id": "6424158d91d7c62df116ee9d",
"ownerName": "Matilda F Matheson ",
"ownerPhoneNo": "9820019168",
"appAddress": "flat no - C/61, bldg name - dwarkesh dham co-op hsg soc Ltd, village -
mandapeshwar - Borivli west, L. M. road ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Re-Sale",
      "value": "60ae1294aa6d152c1801b44b"
    },
    "isHardCopy": false,
    "path": "cases/6424158d91d7c62df116ee9d/
document_1680086534724_cosmos_bandra__M.pdf",
    "fileName": "document_1680086534724_cosmos_bandra__M.pdf",
    "displayStatus": false,
    "id": "767069",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Wed Mar 29 2023 16:12:34 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "000984",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "144458",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Mar 29 2023 16:10:13 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Matilda F Matheson ",
    "phone": "9820019168",
    "ownershipShare": "",
    "email": "",
    "id": "677973"
  }
],
"siteInspection": [
  {
```

```
"areaType": {
  "label": "Carpet",
  "value": "Carpet"
},
"providedBy": {
  "label": "Other",
  "value": "Other"
},
"_id": "642a857d91d7c62df117ce49",
"area": "420.33",
"providedByName": "Site Measurement ",
"providedByContactNo": "0000000000"
}
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "531050",
    "name": "Living Room",
    "length": "11.17",
    "length1": "11",
    "length2": "2",
    "width": "9.92",
    "width1": "9",
    "width2": "11",
    "totalArea": "110.74",
    "images": [
      {
        "path": "cases/6424158d91d7c62df116ee9d/
compositionImg_r_1680507612389_image.jpg",
        "orientation": "portrait"
      }
    ]
  },
  "extraAreas": [],
  "finalArea": "110.74"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Balcony Area",
```

```
"length": "9.92",
"length1": "9",
"length2": "11",
"width": "2.50",
"width1": "2",
"width2": "6",
"totalArea": "24.79",
"images": [
  {
    "path": "cases/6424158d91d7c62df116ee9d/
compositionImg_r_1680507662667_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "24.79"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "9.92",
  "length1": "9",
  "length2": "11",
  "width": "8.08",
  "width1": "8",
  "width2": "1",
  "totalArea": "80.16",
  "images": [
    {
      "path": "cases/6424158d91d7c62df116ee9d/
compositionImg_r_1680507758482_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "80.16"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
}
```

```
"id": "3",
"name": "Bathroom",
"length": "6.00",
"length1": "6",
"length2": "0",
"width": "4.50",
"width1": "4",
"width2": "6",
"totalArea": "27.00",
"images": [
  {
    "path": "cases/6424158d91d7c62df116ee9d/
compositionImg_r_1680507849140_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "27.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "15.00",
  "images": [
    {
      "path": "cases/6424158d91d7c62df116ee9d/
compositionImg_r_1680507920298_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "15.00"
},
{
  "measurementType": {
    "label": "Square Feet",
```

```
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "10.17",
  "length1": "10",
  "length2": "2",
  "width": "9.92",
  "width1": "9",
  "width2": "11",
  "totalArea": "100.82",
  "images": [
    {
      "path": "cases/6424158d91d7c62df116ee9d/
compositionImg_r_1680508119806_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "100.82"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Balcony Area",
  "length": "10.17",
  "length1": "10",
  "length2": "2",
  "width": "2.67",
  "width1": "2",
  "width2": "8",
  "totalArea": "27.11",
  "images": [
    {
      "path": "cases/6424158d91d7c62df116ee9d/
compositionImg_r_1680508212358_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "27.11"
}
],
```

```
"otherComposition": [
  {
    "name": {
      "label": "Passage",
      "value": "Passage"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length1": "10",
    "length2": "10",
    "length": "10.83",
    "width1": "3",
    "width2": "4",
    "width": "3.33",
    "totalArea": "36.11",
    "percentageBeforeTotal": "36.11",
    "images": [
      {
        "path": "cases/6424158d91d7c62df116ee9d/
compositionImg_r_1680508003479_image.jpg",
        "orientation": "portrait"
      }
    ],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "36.11"
  }
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a864a91d7c62df117cff1",
    "name": "externalImg_r_1680508484011_image.jpg",
    "path": "cases/6424158d91d7c62df116ee9d/
externalImg_r_1680508484011_image.jpg",
    "orientation": "portrait"
  },
  {
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "642a864a91d7c62df117cff2",
"name": "externalimg_r_1680508484654_image.jpg",
"path": "cases/6424158d91d7c62df116ee9d/
externalimg_r_1680508484654_image.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "642a864a91d7c62df117cff3",
"name": "externalimg_r_1680508484301_image.jpg",
"path": "cases/6424158d91d7c62df116ee9d/
externalimg_r_1680508484301_image.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "642a864a91d7c62df117cff4",
"name": "externalimg_r_1680508484891_image.jpg",
"path": "cases/6424158d91d7c62df116ee9d/
externalimg_r_1680508484891_image.jpg",
"orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-03-29T10:40:13.959Z",
"updatedAt": "2023-04-03T07:55:25.308Z",
"__v": 0,
"updatedBy": "627208c1afd7d55eddedc372",
"fullAddress": " Flat No. 61, Basement Floor, dwarkesh dham co-op hsg soc Ltd,
Village - mandapeshwar , Mumbai, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Matilda F Matheson ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820019168",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Balcony Area +
Bathroom + WC",
```


"carpetTotal": "385.62",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "36.11",
"siteVisitDate": "2023-04-03"

}

Name	Length	Width	Total
Composition :			
Living Room	11'2"	9'11"	110.74
Balcony Area	9'11"	2'6"	24.79
Kitchen	9'11"	8'1"	80.16
Bathroom	6'0"	4'6"	27.00
WC	5'00"	3'00"	15.00
Bedroom	10'2"	9'11"	100.82
Balcony Area	10'2"	2'8"	27.11
Other Composition :			
Passage	10'10"	3'4"	36.11