

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b895"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b2f",
    "email": "asmita.doshi@cosmosbank.in",
    "firstName": "ASMITA ",
    "mobileNo": "",
    "workMobileNo": "9922662811",
    "lastName": " DOSHI"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6800000",
    "discussWithPerson": "ASMITA ",
    "expectedFees": 3400,
    "quotedAmount": ""
  },
  "organization": {
    "package": {
```

```
    "_id": "5fc0d7e47d6c8d39dc34a294",
    "title": "basic",
    "price": 5.1,
    "case": 20,
    "duration": "300"
  },
  "status": true,
  "isdelete": false,
  "_id": "5f2bdee67813470eb443deb4",
  "name": "Vastukala Consultants India Pvt. Ltd.",
  "gstNo": "18AABCT3518Q1ZZ",
  "panNo": "ABCDE1234A",
  "freeCases": "10",
  "email": "vastukalamumbai@vastukala.com",
  "phone": "9819670183",
  "address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
  "remark": "",
  "theme": "DEFAULT",
  "profilePhoto": "public\\images\\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
  "shortName": "VCIPL",
  "waterMarkImage": [
    {
      "_id": "642d201891d7c62df11cc265",
      "path": "public\\Vastukala Letter head H 2019.jpg",
      "pageNo": "2"
    }
  ],
  "city": "Mumbai",
  "stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b895",
  "branchCode": "000001",
  "type": "BRANCH",
  "name": "Bhayander (West) Branch",
```

```
"email": "bhayander@cosmosbank.in",
"mobileNo": "022-28041167",
"alternateMobileNo": "022-28041168",
"address": "Shop No. 3, 4, 5, Rishab Apartment, S. No. - 5A, Hissa No. 1Part, Patel
Nagar No.1, Station Road, Bhayander (West), Thane - 401 101, State -Maharashtra,
Country - India",
"ledgerName": "COSMOS BANK - Bhayander",
"fax": "",
"sendStructuralCertificate": "0"
},
"assetsClass": {
"value": "Land & Building /_Immovable_Property",
"label": "Land & Building / Immovable Property"
},
"propertyType": {
"value": "Residential",
"label": "Residential"
},
"zone": {
"_id": "60f919bff3dd69653a5926b8",
"zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
"pickupPerson": {
"type": "EMPLOYEE",
"_id": "627219d6afd7d55eddedd283",
"role": "PICKUPPERSON",
"firstName": "Mangesh ",
"email": "mangeshpalande17@gmail.com",
"lastName": "Palande",
"mobileNo": "9833030550",
"shortName": "MP",
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62724d51afd7d55eddedeb9f",
"role": "ADMIN",
"firstName": "Sailee",
"email": "sailee1997vastukala@gmail.com",
"lastName": "Shinde",
"mobileNo": "9607532270",
"designation": "",
"shortName": "SS",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62724d51afd7d55eddedeb9f/
profilePhoto_1653907947239_saulee1.png"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "CHECKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60eebe33f3dd69653a5837ae",
    "role": "MAKER",
    "firstName": "Shamal",
    "email": "shamal@vastukala.org",
    "lastName": "Bodke",
    "mobileNo": "9821740317",
    "designation": "",
    "shortName": "SB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "CHECKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
}
```

```
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      },
      {
        "title": {
          "value": "Registered_Valuer",
          "label": "Registered Valuer"
        },
        "_id": "60af80072ffdf65bcd658654",
```

```
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.185152295348438",
  "longitude": "72.85340206388491"
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-04-05T08:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Wed Apr 05 2023 14:29:33 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
}
```

```
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Chandrapuri CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kedarmal ROad",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Opp Zaveri Diamond H0use ",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```



```
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```

```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "201",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Malad East",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood door frame, Flush doors shutters",
    "value": "Teak_Wood_door_frame,_Flush_doors_shutters"
  },
  "windows": {
    "label": "Aluminium Sliding Windows with window grills",
    "value": "Aluminium_Sliding_Windows_with_window_grills"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
  },
  "finishing": {
```

```
    "label": "Cement Plastering",
    "value": "Cement_Plastering"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "B wing",
    "south": "Under construction building",
    "east": "slum",
    "west": "kedarnath road"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"waterTank": {
  "label": "Municipal Water Supply",
  "value": "MunicipalWaterSupply"
},
"carParking": {
  "label": "open",
  "value": "open"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1987",
  "fullDate": "1/1/1987"
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed",
  "value": "R.C.C."
},
"qualityOfConstruction": {
  "label": "Normal",
  "value": "Normal"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
```

```
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "60",
"ageOfBuilding": "36",
"estimatedAge": "24",
"noOfFloors": "4",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": ""
  }
}
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```



```
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"createCase": "false",
"type": "CASE",
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"_id": "642d201891d7c62df11cc264",
"ownerName": "sejal doshi",
"ownerPhoneNo": "9323050522",
"appAddress": "c/201 chandrapuri co op hou soc kenarnath Rd opp zaveri diamond
house Malad east",
"remark": "malad east case",
"documents": [
  {
    "documentType": {
```

```
    "value": "60ae1246aa6d152c1801b2e4",
    "label": "Index- II"
  },
  "inputs": {
    "documentDate": "30/03/2023",
    "from": {
      "value": "seller",
      "label": "seller"
    },
    "seller": "Pramodchand Babaldas SHah",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Sejal Girish DOshi",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "4842"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/642d201891d7c62df11cc264/document_undefined",
  "id": "800843",
  "uploadedBy": "6006d4ce5080a310ac1fdfc2",
  "createdAt": "Wed Apr 05 2023 14:29:28 GMT+0530 (India Standard Time)",
  "fileName": "document_undefined"
}
],
"caseNumber": "001010",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "179785",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Apr 05 2023 12:45:36 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "sejal doshi",
    "phone": "9323050522",
    "ownershipShare": "",
    "email": ""
  }
]
```

```
"id": "417912"
}
],
"siteInspection": [
{
  "areaType": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "providedBy": {
    "label": "Owner",
    "value": "Owner"
  },
  "_id": "6433a308d267175d008142cd",
  "area": "522",
  "providedByName": "sejal doshi",
  "providedByContactNo": "9323050522"
}
],
"composition": [
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "810915",
  "name": "Living Room",
  "length": "8.92",
  "length1": "8",
  "length2": "11",
  "width": "14.33",
  "width1": "14",
  "width2": "4",
  "totalArea": "127.80",
  "images": [
    {
      "path": "cases/642d201891d7c62df11cc264/
compositionImg_1681105845471_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "127.80"
},
{
  "measurementType": {
```

```
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "9.92",
  "length1": "9",
  "length2": "11",
  "width": "8.92",
  "width1": "8",
  "width2": "11",
  "totalArea": "88.42",
  "images": [
    {
      "path": "cases/642d201891d7c62df11cc264/
compositionImg_1681105875794_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "88.42"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "10.50",
  "length1": "10",
  "length2": "6",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "91.87",
  "images": [
    {
      "path": "cases/642d201891d7c62df11cc264/
compositionImg_1681105913437_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "91.87"
},
```

```
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "15.33",
  "length1": "15",
  "length2": "4",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "134.17",
  "images": [
    {
      "path": "cases/642d201891d7c62df11cc264/
compositionImg_1681105951362_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "134.17"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "6.25",
  "length1": "6",
  "length2": "3",
  "width": "4.33",
  "width1": "4",
  "width2": "4",
  "totalArea": "27.08",
  "images": [
    {
      "path": "cases/642d201891d7c62df11cc264/
compositionImg_1681105988228_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
```

```
"finalArea": "27.08"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "3.33",
  "length1": "3",
  "length2": "4",
  "width": "6.33",
  "width1": "6",
  "width2": "4",
  "totalArea": "21.11",
  "images": [
    {
      "path": "cases/642d201891d7c62df11cc264/
compositionImg_1681106014559_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "21.11"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "8.58",
  "length1": "8",
  "length2": "7",
  "width": "3.25",
  "width1": "3",
  "width2": "3",
  "totalArea": "27.90",
  "images": [
    {
      "path": "cases/642d201891d7c62df11cc264/
compositionImg_1681106048886_image.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
    ],
    "extraAreas": [],
    "finalArea": "27.90"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6433a2a3d267175d008142a2",
    "name": "externalImg_1681105568895_image.jpeg",
    "path": "cases/642d201891d7c62df11cc264/
externalImg_1681105568895_image.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-04-05T07:15:36.025Z",
"updatedAt": "2023-04-10T05:54:24.763Z",
"__v": 0,
"fullAddress": " Flat No. 201, 2nd Floor, Wing - C, Chandrapuri CHSL, Kedarmal
ROad, Opp Zaveri Diamond HOUse , Malad East, Mumbai, State - Maharashtra, India",
"updatedBy": "62724d51afd7d55eddedeb9f",
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "sejal doshi",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9323050522",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + Passage",
"carpetTotal": "518.35",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"
}
```

Name	Length	Width	Total
Composition :			
Living Room	8'11"	14'4"	127.80
Kitchen	9'11"	8'11"	88.42
Bedroom	10'6"	8'9"	91.87
Bedroom	15'4"	8'9"	134.17
Toilet	6'3"	4'4"	27.08
Toilet	3'4"	6'4"	21.11
Passage	8'7"	3'3"	27.90
Other Composition :			