

```
{
  "typeOfReport": {
    "label": "Residential",
    "value": "Residential"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "6417efae96b58848585ece9c",
    "firstName": "PRADIP PAWAR",
    "lastName": "PAWAR",
    "mobileNo": "",
    "workMobileNo": "8080004036",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2000000",
    "discussWithPerson": "PRADIP PAWAR",
    "expectedFees": 1000,
    "quotedAmount": "2500"
  },
  "organization": {
    "package": {
      "_id": "5fc0d7e47d6c8d39dc34a294",
      "title": "basic",
      "price": 5.1,
      "case": 20,

```

```
"duration": "300"
},
"status": true,
"isdelete": false,
"_id": "5f2bdee67813470eb443deb4",
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"freeCases": "10",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"remark": "",
"theme": "DEFAULT",
"profilePhoto": "public\\images\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"waterMarkImage": [
  {
    "_id": "6430fd8791d7c62df11f502a",
    "path": "public\\Vastukala Letter head H 2019.jpg",
    "pageNo": "2"
  }
],
"city": "Mumbai",
"stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli (East)",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
```

House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State - Maharashtra, Country - India.\r\n",

"ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",

"fax": "022-23707512 / 13",

"sendStructuralCertificate": "0"

},

"assetsClass": {

"value": "Land_&_Building_/_Immovable_Property",

"label": "Land & Building / Immovable Property"

},

"propertyType": {

"value": "Residential",

"label": "Residential"

},

"zone": {

"_id": "60e03dac6576061dae462469",

"zoneName": "Mumbai (Metro) & Maharashtra"

},

"staff": {

"pickupPerson": {

"type": "EMPLOYEE",

"_id": "60af3d172ffdf65bcd6585cd",

"role": "PICKUPPERSON",

"firstName": "Sachin",

"email": "sachin.joshi@vastukala.org",

"lastName": "Joshi",

"mobileNo": "9167204063",

"shortName": "SJ",

"workWithDocumentMaker": "",

"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\

profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"

},

"siteEngineer": {

"type": "EMPLOYEE",

"_id": "640c34384dda382753e651f2",

"role": "SITEENGINEER",

"firstName": "PRASHANT ",

"email": "kasarprashant121@gmail.com",

"lastName": "KASAR",

"mobileNo": "9892524464",

"designation": "",

"shortName": "PK",

"workWithDocumentMaker": "",

"profilePhoto": "users/640c34384dda382753e651f2/

profilePhoto_1678521400647_WhatsApp_Image_20230311_at_12047_PM.jpeg"

},

```
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER+CHECKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60092304a16fab0f2af9b0c2\\
\\profilePhoto_1622372532348_Nitesh Khedekar Photo (2).jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "63f313626f9c2254a9b35ba2",
  "role": "MAKER",
  "firstName": "Girish",
  "email": "agregirish@gmail.com",
  "lastName": "Agre",
  "mobileNo": "9082114817",
  "designation": "Technical Officer",
  "shortName": "GA",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f313626f9c2254a9b35ba2/
profilePhoto_1676874632701_WhatsApp_Image_20230220_at_115708_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER+CHECKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60092304a16fab0f2af9b0c2\\
\\profilePhoto_1622372532348_Nitesh Khedekar Photo (2).jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.24336235477904",
  "longitude": "73.15975527010254"
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-04-10T10:28:55.106Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-10T10:28:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-04-10T10:28:55.106Z"
    }
  ]
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Sat Apr 08 2023 11:26:50 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
```

```
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kulgaon, Badlapur (West)",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
```

```
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambernath",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Teak Wood ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
```



```
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Aarsh Avenue Wing – A Maple Wood & Wing B Teak Wood Co-Op. Hsg.
Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
```

```
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "507",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
```

```
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421 503",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood Door frame with Solid flush door",
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door"
  }
}
```

```
},
"windows": {
  "label": "Powder coated Aluminum sliding windows",
  "value": "Powder_coated_Aluminum_sliding_windows"
},
"fittings": {
  "label": "Concealed",
  "value": "Concealed"
},
"finishing": {
  "label": "Good",
  "value": "Good"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Semi Urban",
    "value": "Semi_Urban"
  },
  "townplanApprovedByList": {
    "label": "Badlapur Nagarpalika Parishad",
    "value": "Badlapur_Nagarpalika_Parishad"
  },
  "whetherCoveredUnderAnyState": {
    "value": "Yes",
    "label": "Yes"
  },
  "asPerActualAgreement": {
    "north": "Rainy Resorts ",
    "south": "internal Road",
    "west": "Maple Wood",
    "east": "Sai Shiv Complex "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  }
}
```

```
    },
    "extraDetailOfProperty": ""
  },
  "compositeRate": {
    "remark": "",
    "depreciationPercentage": "",
    "depreciationRatioOfBuilding": "",
    "salvageValue": "",
    "depreciatedCostOfConstruction": "",
    "depreciatedBuildingRate": ""
  },
  "igrRate": {
    "propertyName": "Residential Flat",
    "rate": "53130",
    "landRate": "10010",
    "igrImage": "cases/6430fd8791d7c62df11f5029/igr_1681194049337_Image.png",
    "squareMeterGuideLineRate": "55787.00",
    "squareFeetGuideLineRate": "5183.00"
  },
  "igrFinalRate": {
    "rate": "1143.00",
    "squareFeetGuideLineRate": "1143.00",
    "squareMeterGuideLineRate": "12299.00"
  },
  "outgoingDetail": {
    "areaStatusList": {
      "label": "Middle Class",
      "value": "Middle_Class"
    },
    "propertyTypeOfUseList": {
      "label": "Residential Purpose",
      "value": "Residential_Purpose"
    },
    "propertyOccupiedByList": {
      "label": "Vacant",
      "value": "Vacant"
    }
  },
  "monthlyRent": "5,000.00 Expected rental income per month",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per KBMC norms",
  "tenantName": ""
}
```

```
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "value": "covered",
    "label": "covered"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2020",
    "fullDate": "1/1/2020"
  },
  "planningArea": {
```

```
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"label": "R.C.C. Framed Structure",
"value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"label": "Good",
"value": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Designed_as_per_I.S._codes",
"label": "Designed as per I.S. codes"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"label": "Yes",
"value": "1"
},
"appearanceOfTheBuilding": {
"label": "Good",
"value": "Good"
},
"maintenanceOfTheBuilding": {
"label": "Good",
"value": "Good"
}
```

```
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Occupancy_Certificate",
  "label": "As Per Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "3",
"totalLifeBuilding": "60",
"estimatedAge": "57",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "07",
"flatFloorNo": "5",
"noOfLifts": "01",
"noOfDwellingUnitsInBuilding": "08"
},
"finalPlinthArea": {
  "area": "363.60",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "railway_station",
```



```
    "label": "railway station"
  },
  "routeMapImg": "cases/6430fd8791d7c62df11f5029/
routeMap_1681194515048_Image.png",
  "routeLat": "19.172297",
  "routeLng": "73.246151",
  "stationName": "Badlapur",
  "routeDistance": "1.3"
},
"finalLatLng": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "yhg7n",
    "name": "yhg7n",
    "image": "cases/6430fd8791d7c62df11f5029/
routeMap_1681194947240_Image.png"
  }
],
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
```

```
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "2302800.00",
"bookValue": "0",
"finalValue": "2302800.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Tue Apr 11 2023 12:02:32 GMT+0530 (India Standard Time)",
  "number": "046327",
  "dayCount": "6",
  "monthCount": "228",
  "generatedBy": "60092304a16fab0f2af9b0c2"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
```

```
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6433cc2ca99b2228209c1a55",
      "name": "externalimg_1681116202078_image.jpeg",
      "path": "cases/6430fd8791d7c62df11f5029/
externalimg_1681116202078_image.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6433cc2ca99b2228209c1a54",
      "name": "externalimg_1681116200953_image.jpeg",
      "path": "cases/6430fd8791d7c62df11f5029/
externalimg_1681116200953_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6433cc2ca99b2228209c1a56",
      "name": "externalimg_1681116202407_image.jpeg",
      "path": "cases/6430fd8791d7c62df11f5029/
externalimg_1681116202407_image.jpeg",
      "orientation": "portrait"
    }
  ],
  {
```

```
    "status": false,
    "_id": "6433cc2ca99b2228209c1a57",
    "name": "externallmg_1681116204202_image.jpeg",
    "path": "cases/6430fd8791d7c62df11f5029/
externallmg_1681116204202_image.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6433cc2ca99b2228209c1a58",
    "name": "externallmg_1681116204422_image.jpeg",
    "path": "cases/6430fd8791d7c62df11f5029/
externallmg_1681116204422_image.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "6435004fa99b2228209d3268",
    "path": "cases/6430fd8791d7c62df11f5029/
compositionlmg_1681121244046_image.jpeg",
    "orientation": "landscape",
    "name": "Flowered Area"
  },
  {
    "status": false,
    "_id": "6435004fa99b2228209d3269",
    "path": "cases/6430fd8791d7c62df11f5029/
compositionlmg_1681121377993_image.jpeg",
    "orientation": "landscape",
    "name": "Living Room"
  },
  {
    "status": false,
    "_id": "6435004fa99b2228209d326a",
    "path": "cases/6430fd8791d7c62df11f5029/
compositionlmg_1681121392532_image.jpeg",
    "orientation": "landscape",
    "name": "Living Room"
  },
  {
    "status": false,
```

```
    "_id": "6435004fa99b2228209d326b",
    "path": "cases/6430fd8791d7c62df11f5029/
compositionImg_1681121811982_image.jpeg",
    "orientation": "landscape",
    "name": "Kitchen"
  },
  {
    "status": false,
    "_id": "6435004fa99b2228209d326c",
    "path": "cases/6430fd8791d7c62df11f5029/
compositionImg_1681122115519_image.jpeg",
    "orientation": "landscape",
    "name": "Bedroom"
  }
]
},
"createCase": "false",
"type": "CASE",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "303.00",
"empanelmentNo": [],
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "6430fd8791d7c62df11f5029",
"ownerName": "Mrs. Pooja Devi Sonu Jaiswar ",
"ownerPhoneNo": "8108909980",
"appAddress": "Flat no 507 B-wing Teak Wood Kulgaon Badlapur West",
"remark": "+91 93099 77880 - Builder crm - Mr. Vaibhav Singh.",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
  },
  "inputs": {
    "documentDate": "07/07/2022",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Nagarparishad",
      "label": "Kulgaon Badlapur Nagarparishad"
    },
  },
  "from": {
    "value": "seller",
    "label": "seller"
  },
  "seller": "M/s. Swastik Developers",
  "to": {
```

```
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mrs. Pooja Devi Sonu Jaiswar & Mr. Sonu Shridularram Jaiswar.",
  "number": {
    "value": "consumer_no",
    "label": "consumer no"
  },
  "consumer_no": "2623/2023"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1681195585070_document_1680932189173_Sonu_Jaiswal__For_valuation.pdf",
"path": "cases/6430fd8791d7c62df11f5029/document_1681195585070_document_1680932189173_Sonu_Jaiswal__For_valuation.pdf",
"id": "618976",
"uploadedBy": "60092304a16fab0f2af9b0c2",
"createdAt": "Tue Apr 11 2023 12:17:19 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "02/01/2020",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "KBMC / NRV / 2019 - 2020 "
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1681195632050_document_1680932189173_Sonu_Jaiswal__For_valuation.pdf",
  "path": "cases/6430fd8791d7c62df11f5029/document_1681195632050_document_1680932189173_Sonu_Jaiswal__For_valuation.pdf",
  "id": "877282",
  "uploadedBy": "60092304a16fab0f2af9b0c2",
  "createdAt": "Tue Apr 11 2023 12:17:19 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "001048",
"createdBy": "60af3d172ffdf65bcd6585cd",
```



```
"caseHistory": [
  {
    "id": "465195",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Apr 08 2023 11:07:11 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Pooja Devi Sonu Jaiswar ",
    "phone": "8108909980",
    "ownershipShare": "",
    "email": "",
    "id": "801937"
  },
  {
    "name": "Mr. Sonu Shridularram Jaiswar",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "320555"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Built Up",
      "value": "Built Up"
    },
    "providedBy": {
      "label": "Other",
      "value": "Other"
    },
    "_id": "6433cc0da99b2228209c1a3f",
    "area": "680",
    "providedByName": "Prathamesh Dangale (Builder persol)",
    "providedByContactNo": "7887526371"
  },
  {
    "areaType": {
      "label": "Built Up",
      "value": "Built Up"
    },
    "providedBy": {
      "label": "Other",
```

```
    "value": "Other"
  },
  "_id": "6433d1b0a99b2228209c22e8",
  "area": "680",
  "providedByName": "Prathamesh Dangale ",
  "providedByContactNo": "7887526371"
}
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "101810",
    "name": "Flowered Area",
    "length": "2.25",
    "length1": "2",
    "length2": "3",
    "width": "8.83",
    "width1": "8",
    "width2": "10",
    "totalArea": "19.87",
    "images": [
      {
        "path": "cases/6430fd8791d7c62df11f5029/
compositionImg_1681121244046_image.jpeg",
        "orientation": "landscape"
      }
    ]
  },
  "extraAreas": [],
  "finalArea": "19.87"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Living Room",
  "length": "14.00",
  "length1": "14",
  "width": "9.00",
  "width1": "9",
  "totalArea": "126.00",
  "finalArea": "126.00",
```

```
"length2": "0",
"width2": "0",
"images": [
  {
    "path": "cases/6430fd8791d7c62df11f5029/
compositionImg_1681121377993_image.jpeg",
    "orientation": "landscape"
  },
  {
    "path": "cases/6430fd8791d7c62df11f5029/
compositionImg_1681121392532_image.jpeg",
    "orientation": "landscape"
  }
],
"extraAreas": [],
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "8.25",
  "length1": "8",
  "length2": "3",
  "width": "3.00",
  "width1": "3",
  "totalArea": "24.75",
  "finalArea": "24.75",
  "width2": "0",
  "images": [
    {
      "path": "cases/6430fd8791d7c62df11f5029/
compositionImg_1681121669554_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
```

```
"name": "Kitchen",
"length": "8.00",
"length1": "8",
"width": "7.42",
"width1": "7",
"width2": "5",
"totalArea": "59.33",
"finalArea": "59.33",
"length2": "0",
"images": [
  {
    "path": "cases/6430fd8791d7c62df11f5029/
compositionImg_1681121811982_image.jpeg",
    "orientation": "landscape"
  }
],
"extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Flowered Area",
  "length": "2.00",
  "length1": "2",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "14.83",
  "finalArea": "14.83",
  "length2": "0",
  "images": [
    {
      "path": "cases/6430fd8791d7c62df11f5029/
compositionImg_1681122007481_image.jpeg",
      "orientation": "landscape"
    }
  ],
  "extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
```

```
},
  "id": "5",
  "name": "Bedroom",
  "length": "11.42",
  "length1": "11",
  "length2": "5",
  "width": "9.00",
  "width1": "9",
  "totalArea": "102.75",
  "finalArea": "102.75",
  "width2": "0",
  "images": [
    {
      "path": "cases/6430fd8791d7c62df11f5029/
compositionImg_1681122115519_image.jpeg",
      "orientation": "landscape"
    }
  ],
  "extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Flowered Area",
  "length": "2.17",
  "length1": "2",
  "length2": "2",
  "width": "9.00",
  "width1": "9",
  "totalArea": "19.50",
  "finalArea": "19.50",
  "width2": "0",
  "images": [
    {
      "path": "cases/6430fd8791d7c62df11f5029/
compositionImg_1681122203998_image.jpeg",
      "orientation": "landscape"
    }
  ],
  "extraAreas": []
},
{
  "measurementType": {
```

```
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Toilets",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "7.33",
  "width1": "7",
  "width2": "4",
  "totalArea": "28.11",
  "finalArea": "28.11",
  "images": [
    {
      "path": "cases/6430fd8791d7c62df11f5029/
compositionImg_1681122330701_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "5.83",
  "width1": "5",
  "width2": "10",
  "totalArea": "22.36",
  "finalArea": "22.36",
  "images": [
    {
      "path": "cases/6430fd8791d7c62df11f5029/
compositionImg_1681122502944_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": []
}
```

```
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "198271",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "303",
    "squareMeterArea": "28.15",
    "docFinalBuiltUp": "363.6",
    "docFinalBuiltUpSquareMeter": "33.78",
    "docBUILTUPPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "_id": "6434fb1ea99b2228209d22e6",
    "id": "1",
    "property": "Located in developed area",
    "area": "458",
    "builtUpPercentage": "10",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "https://www.99acres.com/",
    "expectedPrice": "4000000",
    "expectedRate": "8733.62",
    "builtUpExpectedRate": "7939.66",
    "image": "cases/6430fd8791d7c62df11f5029/indicator_1681193758893_Image.png"
  },
  {
    "_id": "6434fb61a99b2228209d2301",
    "id": "2",
    "property": "Residential Flat ",
  }
]
```

```
"area": "412",
"builtUpPercentage": "10",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "3700000",
"expectedRate": "8980.58",
"builtUpExpectedRate": "8164.17",
"image": "cases/6430fd8791d7c62df11f5029/indicator_1681193825398_Image.png"
},
{
  "_id": "6434fb8da99b2228209d2315",
  "id": "3",
  "property": "Residential Flat ",
  "area": "925",
  "builtUpPercentage": "10",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "6500000",
  "expectedRate": "7027.03",
  "builtUpExpectedRate": "6388.21",
  "image": "cases/6430fd8791d7c62df11f5029/indicator_1681193868957_Image.png"
},
{
  "_id": "6434fbbca99b2228209d2399",
  "id": "4",
  "property": "Residation flat",
  "area": "450",
  "builtUpPercentage": "10",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "3000000",
  "expectedRate": "6666.67",
  "builtUpExpectedRate": "6060.61",
  "image": "cases/6430fd8791d7c62df11f5029/indicator_1681193916277_Image.png"
},
{
  "_id": "6434fbeaa99b2228209d23c8",
  "id": "5",
  "property": "Residential Flat ",
  "area": "450",
```



```
"builtUpPercentage": "10",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "3500000",
"expectedRate": "7777.78",
"builtUpExpectedRate": "7070.71",
"image": "cases/6430fd8791d7c62df11f5029/indicator_1681193962188_Image.png"
}
],
"externallimages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6433cc2ca99b2228209c1a54",
  "name": "externallmg_1681116200953_image.jpeg",
  "path": "cases/6430fd8791d7c62df11f5029/
externallmg_1681116200953_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6433cc2ca99b2228209c1a55",
  "name": "externallmg_1681116202078_image.jpeg",
  "path": "cases/6430fd8791d7c62df11f5029/
externallmg_1681116202078_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6433cc2ca99b2228209c1a56",
  "name": "externallmg_1681116202407_image.jpeg",
  "path": "cases/6430fd8791d7c62df11f5029/
externallmg_1681116202407_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6433cc2ca99b2228209c1a57",
  "name": "externallmg_1681116204202_image.jpeg",
  "path": "cases/6430fd8791d7c62df11f5029/
externallmg_1681116204202_image.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6433cc2ca99b2228209c1a58",
  "name": "externallmg_1681116204422_image.jpeg",
  "path": "cases/6430fd8791d7c62df11f5029/
externallmg_1681116204422_image.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-04-08T05:37:11.981Z",
"updatedAt": "2023-04-11T06:47:54.275Z",
"__v": 0,
"fullAddress": "Residential Flat No. 507, 5th Floor, Wing - B, Teak Wood , Aarsh
Avenue Wing – A Maple Wood & Wing B Teak Wood Co-Op. Hsg. Soc. Ltd., Village -
Kulgaon, Badlapur (West), Taluka - Ambernath, District - Thane, 421 503, State -
Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Sonu Jaiswal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8108909980",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 3 Flowered Area +
Passage + Toilets + Toilet",
"carpetTotal": "417.50",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0",
"siteVisitDate": "2023-04-10",
"builtupPercentage": "20",
"finalBuiltupArea": "501.00",
"finalCarpetArea": "417.50",
"finalSalableArea": "501.00",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
```

```

"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 303.00",
"buildingServicesRate": "2600",
"flatRate": "7600",
"landOtherRate": "5000",
"reason": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Flowered Area	2'3"	8'10"	19.87
Living Room	14'0"	9'0"	126.00
Passage	8'3"	3'0"	24.75
Kitchen	8'0"	7'5"	59.33
Flowered Area	2'0"	7'5"	14.83
Bedroom	11'5"	9'0"	102.75
Flowered Area	2'2"	9'0"	19.50
Toilets	3'10"	7'4"	28.11
Toilet	3'10"	5'10"	22.36
Other Composition :			