

```
{
  "typeOfReport": {
    "label": "Commercial",
    "value": "Commercial"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f9"
    },
    "type": "CREDITOFFICER",
    "_id": "640ace424dda382753e5057d",
    "firstName": "Rajeev kumar Ranjan",
    "lastName": "Ranjan",
    "mobileNo": "",
    "workMobileNo": "9967159553",
    "email": "rajeevracpc.borivali@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5472100",
    "discussWithPerson": "Rajeev kumar Ranjan",
    "expectedFees": 2736.05,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f9",
  "branchCode": "000066",
  "type": "BRANCH",
  "name": "RACPC Borivali (West) Branch",
  "email": "racpc.borivali@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "MTNL Building, Devidas Road, Borivali (West), Mumbai, State - Maharashtra, Country - India. ",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Commercial",
  "label": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6006d4ce5080a310ac1fdcf2",
  "role": "FRONTDESK",
  "firstName": "JAGDISH",
  "email": "jagdish.bhatt@vastukala.org",
  "lastName": "BHATT",
  "mobileNo": "8425864014",
  "designation": "",
  "shortName": "JB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\
\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
  "designation": "",
  "shortName": "JA",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
```

```

"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        },
        "_id": "6084131a13f01f158c6ea1f4",
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]

```

```
    }
  ]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.561094000000",
  "longitude": "73.944818000000"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.944818,
    18.561094
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-04-21T07:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-21T07:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-21T07:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-21T07:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-21T07:00:00.000Z",
      "remark": ""
    }
  ]
},
]
```

```
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Fri Apr 21 2023 13:19:00 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "A",
    "label": true
  },
}
```

```
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Pune",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Haveli",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "City Vista\\",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
```

```
"value": "",
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Kothari Public School",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
```



```
"status": true,
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "53/2A/1 (Part), 53/2A/4 (Part), 53/2A/5 (Part), 53/2A/6 (Part), 54/4/1 (Part),
54/4/2 (Part) & 54/7 (Part)",
"label": true
},
"hisNo": {
"status": false,
"name": "Hissa No.",
"key": "hisNo",
"value": "",
"label": true
},
"CTSNo": {
"status": false,
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": false
},
"selectNo": {
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "03",
"label": false
},
"municipalityWardNo": {
"status": false,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
"status": false,
"name": "Khata No",
"key": "khataNo",
```

```
"value": "",
"label": false
},
"mouza": {
  "status": true,
  "name": "Mouza",
  "key": "mouza",
  "value": "Kharadi",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 411 014",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
```

```
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "90220",
  "landRate": "29960",
  "igrImage": "cases/644234413b7e816736e8a7e2/igr_1682590618334_Image.png",
  "squareMeterGuideLineRate": "90220.00",
  "squareFeetGuideLineRate": "8382.00"
},
"igrFinalRate": {
  "rate": "90220",
  "squareMeterGuideLineRate": "90220.00",
  "squareFeetGuideLineRate": "8382.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": {
    "value": "covered",
    "label": "covered"
  },
  "constructionWorkStatus": {
```

```
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2019",
"fullDate": "1/1/2019"
},
"planningArea": {
"value": "Commercial",
"label": "Commercial"
},
"typeOfStructure": {
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
```

```
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceIssues": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "Lower_Ground_+_Upper_Ground_Floor",
"label": "Lower Ground + Upper Ground Floor"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "56",
"ageOfBuilding": "4",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
```

```
"noOfFloors": "7",
"flatFloorNo": "3",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "18"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
```



```
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"taskStatus": {
  "DOCUMENT_VERIFY": false,
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": "LEAD",
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "644234413b7e816736e8a7e2",
"ownerName": "Mr. Sameer Devidas Kapadia & Mrs. Hetal Sameer Kapadia",
"ownerPhoneNo": "9819956441",
"appAddress": "office No.A/03, 3rd floor City Vista , Village - Khardi Tal - Haveli,Dist3-
Pune",
"remark": "Customer la visit la Zaycha aadhi call kara Key Ø=ÝÝp Ureng customer & Visit
```

time ricived Engg Bldg Approved Plan copy & Bldg O.C Copy ",

```
"documents": [  
  {  
    "documentType": {  
      "value": "60ae126eaa6d152c1801b39f",  
      "label": "Agreement"  
    },  
    "inputs": {  
      "documentDate": "29/12/2014",  
      "from": {  
        "value": "Owner",  
        "label": "Owner"  
      },  
      "Owner": "Kolte-Patil Real Estate Pvt. Ltd.",  
      "to": {  
        "value": "Purchasers",  
        "label": "Purchasers"  
      },  
      "Purchasers": "Mr. Sameer Devidas Kapadia & Mrs. Hetal Sameer Kapadia"  
    },  
    "isHardCopy": false,  
    "displayStatus": true,  
    "id": "362238",  
    "path": "cases/644234413b7e816736e8a7e2/  
document_1682059886693_Sameer_kapadiya_SBI_Racpc_Borivali_West_1.pdf",  
    "fileName":  
"document_1682059886693_Sameer_kapadiya_SBI_Racpc_Borivali_West_1.pdf"  
  },  
  {  
    "documentType": {  
      "value": "60ae1247aa6d152c1801b2ea",  
      "label": "Commencement Certificate"  
    },  
    "inputs": {  
      "documentDate": "11/07/2013",  
      "nameOfApprovingAuthority": {  
        "value": "Pune_Municipal_Corporation",  
        "label": "Pune Municipal Corporation"  
      },  
      "number": {  
        "value": "Document_No",  
        "label": "Document No"  
      },  
      "Document_No": "CC/1197/13"  
    },  
    "isHardCopy": false,  
  }  
]
```

```
    "displayStatus": true,
    "fileName": "document_1682667754027_Commencement_Certificate.pdf",
    "path": "cases/644234413b7e816736e8a7e2/
document_1682667754027_Commencement_Certificate.pdf",
    "id": "497658",
    "uploadedBy": "60f91b6f344e052188ffd1fc",
    "createdAt": "Fri Apr 28 2023 13:12:37 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "001259",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "729336",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Apr 21 2023 12:29:13 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Sameer Devidas Kapadia & Mrs. Hetal Sameer Kapadia",
    "phone": "9819956441",
    "ownershipShare": "",
    "email": "",
    "id": "462540"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "644a4a014d9dc938640a0548",
    "id": "1",
    "property": "Flatr",
    "area": "568",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "1",
```

```
"source": "https://www.99acres.com/",
"expectedPrice": "8500000",
"expectedRate": "14964.79",
"builtUpExpectedRate": "13604.35",
"image": "cases/644234413b7e816736e8a7e2/
indicator_1682590209252_Image.png"
},
{
  "printlnReport": true,
  "_id": "644a4a374d9dc938640a060d",
  "id": "2",
  "property": "Flat",
  "area": "490",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "5",
  "source": "https://www.99acres.com/",
  "expectedPrice": "7200000",
  "expectedRate": "14693.88",
  "builtUpExpectedRate": "13358.07",
  "image": "cases/644234413b7e816736e8a7e2/
indicator_1682590263367_Image.png"
},
{
  "printlnReport": true,
  "_id": "644a4a7a4d9dc938640a064c",
  "id": "3",
  "property": "Flat",
  "area": "550",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "8000000",
  "expectedRate": "14545.45",
  "builtUpExpectedRate": "13223.14",
  "image": "cases/644234413b7e816736e8a7e2/
indicator_1682590330263_Image.png"
},
{
  "printlnReport": true,
  "_id": "644a4ae84d9dc938640a0794",
```

```

    "id": "4",
    "property": "Flat",
    "area": "448",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "floor": "8",
    "source": "Index_no.2",
    "expectedPrice": "5464400",
    "expectedRate": "12197.32",
    "builtUpExpectedRate": "11088.47",
    "image": "cases/644234413b7e816736e8a7e2/
indicator_1682590440385_Image.png"
  }
],
"externalImages": [],
"externalDocuments": [],
"createdAt": "2023-04-21T06:59:13.128Z",
"updatedAt": "2023-04-28T09:13:26.153Z",
"__v": 0,
"updatedBy": "60f91b6f344e052188ffd1fc",
"fullAddress": "Commercial Flat No. 03, 3rd Floor, Building No 'A', City Vista", Kothari
Public School, Mouza Kharadi, Taluka - Haveli, District - Pune, PIN - 411 014, State -
Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Harish Mohinani",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "5472100",
"relationWithOwner": "Representative of Owner",
"siteVisitContactNo": "8552947462",
"buildingServicesRate": "2500",
"flatRate": "14500",
"landOtherRate": "12000"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
