PROFORMA INVOICE

Vastukala Consultants (I) Pvt Ltd Ackruti Star, 1st Floor, 121, Central Road, MIDC, Andheri (E), Mumbai - 400 093 GSTIN/UIN: 27AADCV4303R1ZX State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org

Buyer (Bill to)

JANASEVA SAHAKARI BANK-BHAYANDER EAST

BHAYANDER EAST

Janki Avanue 1st Floor, Phatak Road.

Bhaynder East Thane-401105

GSTIN/UIN : 27AAAAJ1528R2ZA State Name : Maharashtra, Code: 27

Invoice No.	Dated
PG-700/23-24	20-May-23
Delivery Note	Mode/Terms of Payment AGAINST REPORT
Reference No. & Date.	Other References
Buyer's Order No.	Dated
Dispatch Doc No. 31111 / 2300702	Delivery Note Date
Dispatched through	Destination

Terms of Delivery

SI No.	Particulars	HSN/SAC	GST Rate	Amount
1	STRUCTURAL REPORT FEE (Technical Inspection and Certification Services) CGS SGS		18 %	1,500.00 135.00 135.00
		1		
	Tot	al		₹ 1,770.00

Amount Chargeable (in words)

E. & O.E

Indian Rupee One Thousand Seven Hundred Seventy Only

HSN/SAC	Taxable Value	Central Tax		State Tax		Total
1.4 HARDS 2000 11 HW		Rate	Amount	Rate	Amount	Tax Amount
997224	1,500.00	9%	135.00	9%	135.00	270.00
Total	1,500.00		135.00		135.00	270.00

Tax Amount (in words): Indian Rupee Two Hundred Seventy Only

Company's Bank Details

Bank Name : ICICI BANK LTD 123105000319 A/c No.

Branch & IFS Code: MIG Colony, Bandra (E.), Mumbai & ICIC0001231

Remarks:

Mr. Habib Niyaz Ahmad Manihar - Residential Flat No. 101, 1st Floor, "Anwar Apartment Co-Op. Hsg. Soc. Ltd. Opp. Reliance Infrastructure Office, Near Bhavander Phatak Road, Bhayander (East), Thane - 401 105, State - Maharashtra, Country - India

Company's PAN : AADCV4303R

Declaration

NOTE - AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137



UPI Virtual ID : vastukala@icici

for Vastukala Consultants (I) Pvt Ltd

Authorised Signatory

This is a Computer Generated Invoice



Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001:2015 Certified Company www.vastukala.org



CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Valuation Report Prepared For: JansevaSahakari / Bhayandar (East) Branch / Mr. Habib Niyaz Ahmad Manihar (31111/2300702)

Page 1 of 3

Vastu/Mumbai/05/2023/31111/2300702 20/19-313-PRSH Date: 20.05.2023

Structural Stability Report

StructuralObservation Report of Residential Flat No. 101, 1st Floor, "Anwar Apartment Co-Op. Hsg. Soc. Ltd.", Opp. Reliance Infrastructure Office, Near Bhayander Phatak Road, Bhayander (East), Thane - 401 105, State - Maharashtra, Country – India.

Name of Owners: Mr. Habib Niyaz Ahmad Manihar.

This is to certify that on visual inspection, it appears that the structure at "Anwar Apartment Co-Op. Hsg. Soc. Ltd"is in averagecondition and the future life can be reasonably takes under goodcondition and with proper periodic repairs & maintenance is about35 years.

General Information:

A.	Introduction			
1	Name of Building	"Anwar Apartment Co-Op. Hsg. Soc. Ltd."		
2	Property Address	Residential Flat No. 101, 1st Floor, "Anwar Apartment		
	//	Co-Op. Hsg. Soc. Ltd.", Opp. Reliance Infrastructure		
		Office, Near Bhayander Phatak Road, Bhayander (East),		
		Thane - 401 105, State - Maharashtra, Country - India.		
3	Type of Building	Residential		
4	No. of Floors	Ground + 4 Upper Floors		
5	Whether stilt / podium / open parking	Open Parking Space		
	provided			
6	Type of Construction	R.C.C. Framed Structure		
7	Type of Foundation	R.C.C. Footing		
8	Thickness of the External Walls	9" thick brick walls both sides plastered		
9	Type of Compound	Brick Masonry Walls		
10	Year of Construction	1998 (As per Occupancy Certificate)		
11	Present age of building	25years		
12	Residual age of the building	35years Subject to proper, preventive periodic		
		maintenance & structural repairs.		
13	No. of flats (Per Floor)	6 Flats on 10th Floor		
14	Methodology adopted	As per visual site inspection		



TeleFax: +91 22 28371325/24

Regd. Office: 121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai - 400 093, (M.S.), INDIA

🥯 mumbai@vastukala.org

B.	External Observation of the Building			
1	Plaster	Normal Condition		
2	Chajjas	Normal Condition		
3	Plumbing	Normal Condition		
4	Cracks on the external walls	Found		
5	Filling cracks on the external walls	Not found		
6	Cracks on columns & beams	Not found		
7	Vegetation	Found		
8	Leakages of water in the drainage pipes or water pipes	Not found		
9	Dampness external in the wall due to leakages	Found		
10	Any other observation about the condition of external side of the building	The external condition of the building is normal.		
С	Internal Observation of the common areas of the building and captioned premises			
1	Beams (Cracks & Leakages)	Not Found		
2	Columns (Cracks & Leakages)	Not Found		
3	Ceiling (Cracks & Leakages)	Not Found		
4	Leakages inside the property	Not Found		
5	Painting inside the property	Normal		
6	Maintenance of staircase & cracks	Normal		

D	Common Observation			
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws		
	- Laws No. 77 of the Model Bye Laws	under the Act the society shall conduct a Structural Audit		
	(Co-Operative Societies Act / Rules)	of the building of the society as follows		
2	Remark	1. The flat under valuation is averagely maintained. At		
		some places plaster is pilled out.		
		No Structural Audit Report is furnished for the perusal		

E Conclusion

The captioned building is having Ground + 4 Upper Floors whichareconstructed in year 1998as per Occupancy Certificate. Estimated future life under present circumstances is about 35 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 25.04.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

MANOJ BABURAO CHALIKWAR

Concession of Section (1997) (

Director

Auth. Sign.

Manoj B. Chalikwar

Registered Valuer Chartered Engineer (India) Reg. No. CAT-I-F-1763

SBI Empanelment No.: SME/TCC/2021-22/86/3





Actual site photographs















