#### PROFORMA INVOICE

Vastukala Consultants (I) Pvt Ltd Ackruti Star, 1st Floor, 121, Central Road, MIDC, Andheri (E), Mumbai - 400 093 GSTIN/UIN: 27AADCV4303R1ZX State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org Buyer (Bill to) Estate Department Corporate Center, 4th Floor,

STATE BANK OF INDIA- RACPC BELAPUR

CIDCO Tower No. 4, Railway Station Building, C.B.D Belapur, Navi Mumbai- 400614

: 27AAACS8577K2ZO GSTIN/UIN State Name : Maharashtra, Code: 27

Invoice No.	Dated
PG-409/23-24	3-May-23
Delivery Note	Mode/Terms of Payment AGAINST REPORT
Reference No. & Date.	Other References
Buyer's Order No.	Dated
Dispatch Doc No. 31121 / 2300414	Delivery Note Date
Dispatched through	Destination

SI No.	Particulars	HSN/SAC	GST Rate	Amount
1	STRUCTURAL REPORT FEE (Technical Inspection and Certification Services)  CGST SGST	997224	18 %	2,500.00 225.00 225.00
	Total			₹ 2,950.00

Amount Chargeable (in words)

E. & O.E

#### Indian Rupee Two Thousand Nine Hundred Fifty Only

HSN/SAC	Taxable	Central Tax		State Tax		Total
W. 2000.000	Value	Rate	Amount	Rate	Amount	Tax Amount
997224	2,500.00	9%	225.00	9%	225.00	450.00
Total	2,500.00		225.00		225.00	450.00

Tax Amount (in words): Indian Rupee Four Hundred Fifty Only

Remarks:

"Mr. Ritesh Babanrao

Dahake & Mrs. Madhuri Ritesh Dahake alias Madhuri Avdhut Wanre - Residential Flat No. 103, 1st Floor,

Wing - G, ""New Omkar Co-op. Hsg.
Soc. Ltd."", Vijay Park, Near Jangid Complex / Shanti Park, Village - Mira, Municipality Ward No. Q, Taluka -Thane,

District - Thane, Mira Road (East), PIN - 401 107, State Maharashtra, India"

Company's PAN

: AADCV4303R

Declaration

NOTE - AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137

Company's Bank Details

Bank Name : State Bank of India

A/c No. 32632562114

Branch & IFS Code: MIDC Andheri (E) & SBIN0007074



UPI Virtual ID : vastukala@icici

for Vastukala Consultants (I) Pvt Ltd

Authorised Signatory

This is a Computer Generated Invoice

CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Valuation Report Prepared For: SBI / RACPC Belapur / Mr. Ritesh Babanrao Dahake (31121/2300414)

Page 1 of 4

Vastu/Mumbai/05/2023/31121/2300414 04/03-35-JAVS Date: 04.05.2023

### Structural Stability Report

Structural Observation Report of Residential Flat No. 103, 1st Floor, Wing - G, "New Omkar Co-op. Hsg. Soc. Ltd.", Vijay Park, Near Jangid Complex / Shanti Park, Village - Mira, Municipality Ward No. Q, Taluka - Thane, District - Thane, Mira Road (East), PIN - 401 107, State - Maharashtra, India.

Name of Owners: Mr. Ritesh Babanrao Dahake &

Mrs. Madhuri Ritesh Dahake alias Madhuri Avdhut Wanre.

This is to certify that on visual inspection, it appears that the structure at "New Omkar Co-op. Hsg. Soc. Ltd." is in average condition and the future life can be reasonably takes under normal condition and with proper periodic repairs & maintenance is about 29 years.

General Information:

00110	Tal Intolliation.	
A.		Introduction
1	Name of Building	"New Omkar Co-op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 103, 1st Floor, Wing - G, "New
	//	Omkar Co-op. Hsg. Soc. Ltd.", Vijay Park, Near Jangid
	O.	Complex / Shanti Park, Village - Mira, Municipality Ward
		No. Q, Taluka - Thane, District - Thane, Mira Road (East),
		PIN - 401 107, State - Maharashtra, Country - India.
3	Type of Building	Residential
4	No. of Floors	Ground + 2 Upper Floors
5	Whether stilt / podium / open parking	Open Car Parking /
	provided	1
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1992 (As per Occupancy Certificate)
11	Present age of building	31 years
12	Residual age of the building	29 years Subject to proper, preventive periodic
		maintenance & structural repairs.
13	No. of flats (Per Floor)	1st Floor is having 4 Flats
14	Methodology adopted	As per visual site inspection
		<u> </u>



mumbai@vastukala.org





Ahmedabad V Jaipur

P Delhi NCR P Nashik

.

B.	External Observation of the Building		
1	Plaster	Normal Condition	
2	Chajjas	Normal Condition	
3	Plumbing	Normal Condition	
4	Cracks on the external walls	Minor cracks found at many places	
5	Filling cracks on the external walls	Not found	
6	Cracks on columns & beams	Minor cracks found	
7	Vegetation	Not found	
8	Leakages of water in the drainage pipes	s Not found	
	or water pipes		
9	Dampness external in the wall due to	Minor dampness found	
	leakages		
10	Any other observation about the	The external condition of the building is averagely	
_	condition of external side of the building	maintained.	
С	Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages) Minor cracks found		
2	Columns (Cracks & Leakages)	Minor cracks found	
3	Ceiling (Cracks & Leakages)	Not found	
4	Leakages inside the property	Minor leakage found	
5	Painting inside the property	Averagely maintained	
6	Maintenance of staircase & cracks	Averagely maintained	

D	Common Observation			
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws		
	- Laws No. 77 of the Model Bye Laws	under the Act the society shall conduct a Structural Audit		
	(Co-Operative Societies Act / Rules)	of the building of the society as follows		
2	Remark	No Structural Audit Report is furnished for the perusal		

#### E Conclusion

The captioned building is having Ground + 2 Upper Floors which are constructed in year 1992 as per Occupancy Certificate. Estimated future life under present circumstances is about 29 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 26.04.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in average condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

### For VASTUKALA CONSULTANTS (I) PVT. LTD.

MANOJ BABURAO CHALIKWAR

Organia, segued by MANOLI BARRILANO CHALLOWAR No. Leuto. CHALLOWAR CONSIGLATOR SI SPRANET LIMITEO, 304-307. SI STANIS CHALLOW CONSIGLATOR SI SPRANET LIMITEO, 304-307. SI STANIS CHALLOW CONSIGLATOR SI SPRANET LIMITEO, 304-307. SI STANIS CHALLOW CONSIGLATOR SI SPRANET LIMITEO, MANUAL CHALLOW CONSIGLATOR SI SPRANET LIMITEO, 304-307. SI STANIS CHALLOW CONSIGLATOR SI SPRANET CHALLOWARD CHALLOW STANIS CHALLOW CONSIGLATOR SI SPRANET CHALL

Auth. Sign.

Manoj B. Chalikwar

Director

Registered Valuer Chartered Engineer (India) Reg. No. CAT-I-F-1763

SBI Empanelment No.: SME/TCC/2021-22/86/3






# **Actual site photographs**




















## **Actual site photographs**













