

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd9434ce84bf289baab0e9",
    "firstName": "Sharmila",
    "lastName": "Mahto",
    "mobileNo": "",
    "workMobileNo": "9521405151",
    "email": "sharmila.mahto@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3000000",
    "discussWithPerson": "Sharmila",
    "expectedFees": 1500,
    "quotedAmount": "2500"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
    "lastName": "Velonde",
    "mobileNo": "8691048846",
```

```
"shortName": "SSV",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7177d2ffdf65bcd65882a\
\profilePhoto_1622701681508_WhatsApp Image 2021-06-02 at 11.09.24 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "627362b3afd7d55eddee1ee7",
  "role": "SITEENGINEER",
  "firstName": "Vicky ",
  "email": "vicky@vastukala.org",
  "lastName": "Bhor",
  "mobileNo": "9004386288",
  "designation": "",
  "shortName": "VB",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
```

```

"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "CHECKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
},
}_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}

```

```
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.069019499280788",
  "longitude": "73.09996513941037"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.09996513941037,
    19.069019499280788
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-04-25T08:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-25T08:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-25T08:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-25T08:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-25T08:30:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": [
```

```
{
  "remark": "MANUAL",
  "status": "COMPLETED",
  "dateTime": "2023-04-26T10:30:00.000Z"
}
],
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Tue Apr 25 2023 15:18:03 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Taloja",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
```

```
"status": true,
"name": "Building No",
"key": "buildingNo",
"value": "L-30",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "1",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mass Housing Scheme (LIG)",
```

```
"label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "27",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "306",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "410 208",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
```

```
"key": "suburb",
"value": "",
"label": false
},
},
"flatSpecifications": {
"roof": {
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"flooring": {
"value": "VerifiedTileFlooring",
"label": "Vitrified Tile Flooring"
},
"doors": {
"value": "Teak_Wood_Door_frame_with_Solid_flush_door",
"label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
"value": "Aluminium_Sliding_Windows_with_window_grills",
"label": "Aluminium Sliding Windows with window grills"
},
"fittings": {
"value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
"label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
},
"finishing": {
"value": "Good",
"label": "Good"
}
},
"general": {
"ownership": {
"value": "Sole_Ownership",
"label": "Sole Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "CIDCO",
```

```
"label": "City Industrial Development Corporation of Maharashtra"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Building No. L-31",
  "west": "Garden ",
  "south": "Building No. L-29",
  "east": "Internal Road "
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Taloja Sector 27",
  "rate": "54000",
  "landRate": "18100",
  "igrImage": "cases/644799ead11ef125ab256f8f/igr_1682588505008_Image.png",
  "squareMeterGuideLineRate": "54000.00",
  "squareFeetGuideLineRate": "5017.00"
},
"igrFinalRate": {
  "rate": "54000",
  "squareMeterGuideLineRate": "54000.00",
  "squareFeetGuideLineRate": "5017.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  }
},
```

```
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Vacant",
  "label": "Vacant"
},
"monthlyRent": "8000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per CIDCO norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  }
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": {
  "value": "Stilt+_Open_Car_Parking",
```

```
"label": "Stilt + Open Car Parking"
},
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2021",
  "fullDate": "1/1/2021"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "RCC_Framed_Structure",
  "label": "RCC Framed Structure"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
```

```
"label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_per_Occupancy_Certificate",
  "label": "As per Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "2",
"totalLifeBuilding": "60",
"estimatedAge": "58",
```

```
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "14",
"flatFloorNo": "3",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "353.08",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/644799ead11ef125ab256f8f/
routeMap_1682597705181_Image.png",
    "routeLat": "19.070778",
    "routeLng": "73.102778",
    "stationName": "Taloja Panchnand",
    "routeDistance": "3.1 Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "c8v2xr",
      "name": "c8v2xr",
      "image": "cases/644799ead11ef125ab256f8f/
routeMap_1682597520592_Image.png"
    }
  ]
},
```



```
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "3210000.00",
  "bookValue": "0",
  "finalValue": "3210000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Thu Apr 27 2023 17:56:55 GMT+0530 (India Standard Time)",
  "number": "046512",
  "dayCount": "6",
  "monthCount": "413",
  "generatedBy": "60eebe33f3dd69653a5837ae"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
```

```
"label": "RCC Footing/Foundation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1771402.00",
  "selectedBuildUpValue": "353.08",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "644a684c4d9dc938640a667d",
      "name": "externalimg_1682597963628_IMG_20230426_33495.jpg",
      "path": "cases/644799ead11ef125ab256f8f/
externalimg_1682597963628_IMG_20230426_33495.jpg",
      "orientation": "portrait"
    }
  ]
},
"selfieWithSiteVisitImages": [
  {
    "status": false,
```

```
    "_id": "644a68324d9dc938640a661a",
    "name": "externallmg_1682597937574_IMG_20230426_29560.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937574_IMG_20230426_29560.jpg",
    "orientation": "landscape"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "644a68324d9dc938640a6618",
    "name": "externallmg_1682597937564_IMG_20230426_3265.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937564_IMG_20230426_3265.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "644a684c4d9dc938640a6684",
    "name": "externallmg_1682597963769_IMG_20230426_235721.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597963769_IMG_20230426_235721.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "644a684c4d9dc938640a6680",
    "name": "externallmg_1682597963670_IMG_20230426_35134.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597963670_IMG_20230426_35134.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "644a68324d9dc938640a6619",
    "name": "externallmg_1682597937567_IMG_20230426_3423.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937567_IMG_20230426_3423.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [
  {
    "status": false,
    "_id": "644a68324d9dc938640a6622",
    "name": "externallmg_1682597937611_IMG_20230426_32613.jpg",
```

```
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937611_IMG_20230426_32613.jpg",
    "orientation": "portrait"
  }
],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "644a68324d9dc938640a6617",
    "name": "Living Room",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937561_IMG_20230426_3175.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "644a68324d9dc938640a661f",
    "name": "Living Room",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937593_IMG_20230426_31370.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "644a68324d9dc938640a661e",
    "name": "Kitchen",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937590_IMG_20230426_30753.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "644a68324d9dc938640a661b",
    "name": "Bedroom",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937581_IMG_20230426_29824.jpg",
    "orientation": "portrait"
  }
]
},
"taskStatus": {
  "DOCUMENT_VERIFY": false,
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": true,
}
```

```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "320.98",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "644799ead11ef125ab256f8f",
"ownerName": "Mr. Sandesh Maruti Vishwasrao",
"ownerPhoneNo": "7303171666",
"appAddress": "Flat no. 306, Building no. L 30, Plot no. 1, Sector 27, Taloja, Navi
Mumbai ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1245aa6d152c1801b2e1",
      "label": "Agreement To Sale"
    },
    "inputs": {
      "documentDate": "08/12/2021",
      "from": {
        "value": "The_Corporation",
        "label": "The Corporation"
      },
      "The_Corporation": "CIDCO",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Sandesh Maruti Vishwasrao"
    }
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "754032",
```

```
    "path": "cases/644799ead11ef125ab256f8f/
document_1682414005475_Racpc_Ghatkopar_Sandesh_Vishwasrao.pdf",
    "fileName":
"document_1682414005475_Racpc_Ghatkopar_Sandesh_Vishwasrao.pdf"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "09/09/2021",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
        "label": "Maharashtra Real Estate Regulatory Authority"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "P52000017438 "
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1682594182034_P52000017438.pdf",
    "path": "cases/644799ead11ef125ab256f8f/
document_1682594182034_P52000017438.pdf",
    "id": "921526",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Thu Apr 27 2023 16:51:05 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1246aa6d152c1801b2e6",
      "label": "Approved Plan"
    },
    "inputs": {
      "documentDate": "28/09/2017",
      "nameOfApprovingAuthority": {
        "value": "CIDCO",
        "label": "CIDCO"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      }
    }
  },
}
```



```
    "Document_No": "Proposal No. BPIHP / 2017 / 059 / 000048 "
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1682594332114_2_Building_Plan_Approval_IOD.pdf",
  "path": "cases/644799ead11ef125ab256f8f/
document_1682594332114_2_Building_Plan_Approval_IOD.pdf",
  "id": "197758",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Thu Apr 27 2023 16:51:05 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "09/05/2019",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CIDCO / Sr. Arch (Hsg. / BP-IHP) / BP-IHP-32 / 2019 / 000100
(Document No)"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "962933",
  "path": "cases/644799ead11ef125ab256f8f/document_1682594462801_3_Commen
cement_Certificates___NA_Order_for_plotted_development.pdf",
  "fileName": "document_1682594462801_3_Commencement_Certificates___NA_Or
der_for_plotted_development.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "02/11/2021",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
```

```
    "label": "CIDCO"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "CIDCO / Sr. Arch (Hsg. / BP-IHP) / BP-IHP-32 / 2021 / 000033"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1682594724408_1_Occupancy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plotted_development.pdf",
"path": "cases/644799ead11ef125ab256f8f/document_1682594724408_1_Occupancy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plotted_development.pdf",
"id": "203679",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Thu Apr 27 2023 16:55:39 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "001316",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "805354",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Apr 25 2023 14:44:18 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Sandesh Maruti Vishwasrao",
    "phone": "7303171666",
    "email": "",
    "ownershipShare": "",
    "id": "679006"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
],
```

```
"id": "758762",
"name": "Living Room",
"length": "9.75",
"length1": "9",
"length2": "9",
"width": "12.42",
"width1": "12",
"width2": "5",
"totalArea": "121.06",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "644a62d24d9dc938640a582f",
    "name": "Living Room Passage ",
    "extraAreaType": "Add",
    "length": "4.00",
    "length1": "4",
    "length2": "0",
    "width": "2.08",
    "width1": "2",
    "width2": "1",
    "totalArea": "8.33"
  }
],
"finalArea": "129.39000000000001"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "6.42",
  "length1": "6",
  "length2": "5",
  "width": "12.50",
  "width1": "12",
  "width2": "6",
  "totalArea": "80.21",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "80.21"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "9.42",
  "length1": "9",
  "length2": "5",
  "width": "9.42",
  "width1": "9",
  "width2": "5",
  "totalArea": "88.67",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "644a624e4d9dc938640a55c2",
      "name": "Bedroom passage",
      "extraAreaType": "Add",
      "length": "2.33",
      "length1": "2",
      "length2": "4",
      "width": "4.75",
      "width1": "4",
      "width2": "9",
      "totalArea": "11.08"
    }
  ],
  "finalArea": "99.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "3.92",
  "length1": "3",
```

```
"length2": "11",
"width": "3.83",
"width1": "3",
"width2": "10",
"totalArea": "15.01",
"images": [],
"extraAreas": [],
"finalArea": "15.01"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bathroom",
  "length": "4.83",
  "length1": "4",
  "length2": "10",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "18.53",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.53"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "WC",
  "length": "4.17",
  "length1": "4",
  "length2": "2",
  "width": "4.75",
  "width1": "4",
  "width2": "9",
  "totalArea": "19.79",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.79"
}
],
```

```
"otherComposition": [  
  {  
    "name": {  
      "value": "Niche",  
      "label": "Niche"  
    },  
    "measurementType": {  
      "value": "Square_Feet",  
      "label": "Square Feet"  
    },  
    "id": "0",  
    "length1": "2",  
    "length2": "1",  
    "length": "2.08",  
    "width1": "4",  
    "width2": "10",  
    "width": "4.83",  
    "totalArea": "10.07",  
    "percentageBeforeTotal": "10.07",  
    "images": [],  
    "extraAreas": [],  
    "percentage": "100",  
    "finalArea": "10.07"  
  },  
  {  
    "name": {  
      "value": "Niche",  
      "label": "Niche"  
    },  
    "measurementType": {  
      "value": "Square_Feet",  
      "label": "Square Feet"  
    },  
    "id": "1",  
    "length1": "2",  
    "length2": "2",  
    "length": "2.17",  
    "width1": "4",  
    "width2": "2",  
    "width": "4.17",  
    "totalArea": "9.03",  
    "percentageBeforeTotal": "9.03",  
    "images": [],  
    "extraAreas": [],  
    "percentage": "100",  
    "finalArea": "9.03"  
  }  
]
```

```
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1245aa6d152c1801b2e1",
      "label": "Agreement To Sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "898208",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "320.98",
    "squareMeterArea": "29.82",
    "docFinalBuiltUp": "353.07800000000003",
    "docFinalBuiltUpSquareMeter": "32.802",
    "docBultupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "_id": "644a42894d9dc9386409edf4",
    "id": "1",
    "property": "Taloja, Sector 27",
    "area": "250",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "https://www.99acres.com/",
    "expectedPrice": "2500000",
    "expectedRate": "10000.00",
    "builtUpExpectedRate": "9090.91",
    "image": "cases/644799ead11ef125ab256f8f/indicator_1682588297648_Image.png"
  },
  {
    "_id": "644a42e04d9dc9386409ee1d",
    "id": "2",
```

```
"property": "Taloja, Sector 27",
"area": "280.00",
"builtUpPercentage": "10",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "3",
"source": "https://www.99acres.com/",
"expectedPrice": "3200000",
"expectedRate": "11428.57",
"builtUpExpectedRate": "10389.61",
"image": "cases/644799ead11ef125ab256f8f/indicator_1682588384704_Image.png"
},
{
  "_id": "644a43254d9dc9386409ee6a",
  "id": "3",
  "property": "Taloja, Sector 27",
  "area": "321.00",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "14",
  "source": "https://www.99acres.com/",
  "expectedPrice": "3000000",
  "expectedRate": "9345.79",
  "builtUpExpectedRate": "8496.18",
  "image": "cases/644799ead11ef125ab256f8f/indicator_1682588453109_Image.png"
}
],
"externallimages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644a68324d9dc938640a6616",
    "name": "externallmg_1682597937558_IMG_20230426_3047.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937558_IMG_20230426_3047.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644a68324d9dc938640a6617",
    "name": "externallmg_1682597937561_IMG_20230426_3175.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937561_IMG_20230426_3175.jpg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644a68324d9dc938640a6618",
  "name": "externallmg_1682597937564_IMG_20230426_3265.jpg",
  "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937564_IMG_20230426_3265.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644a68324d9dc938640a6619",
  "name": "externallmg_1682597937567_IMG_20230426_3423.jpg",
  "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937567_IMG_20230426_3423.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644a68324d9dc938640a661a",
  "name": "externallmg_1682597937574_IMG_20230426_29560.jpg",
  "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937574_IMG_20230426_29560.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644a68324d9dc938640a661b",
  "name": "externallmg_1682597937581_IMG_20230426_29824.jpg",
  "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937581_IMG_20230426_29824.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644a68324d9dc938640a661c",
  "name": "externallmg_1682597937583_IMG_20230426_30245.jpg",
  "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937583_IMG_20230426_30245.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "644a68324d9dc938640a661d",
      "name": "externallmg_1682597937588_IMG_20230426_30453.jpg",
      "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937588_IMG_20230426_30453.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "644a68324d9dc938640a661e",
      "name": "externallmg_1682597937590_IMG_20230426_30753.jpg",
      "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937590_IMG_20230426_30753.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "644a68324d9dc938640a661f",
      "name": "externallmg_1682597937593_IMG_20230426_31370.jpg",
      "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937593_IMG_20230426_31370.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "644a68324d9dc938640a6620",
      "name": "externallmg_1682597937595_IMG_20230426_31629.jpg",
      "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937595_IMG_20230426_31629.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "644a68324d9dc938640a6621",
      "name": "externallmg_1682597937597_IMG_20230426_32303.jpg",
      "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937597_IMG_20230426_32303.jpg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644a68324d9dc938640a6622",
  "name": "externallmg_1682597937611_IMG_20230426_32613.jpg",
  "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597937611_IMG_20230426_32613.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644a68324d9dc938640a6623",
  "name": "externallmg_r_1682597937029_20230426_232731.jpg",
  "path": "cases/644799ead11ef125ab256f8f/
externallmg_r_1682597937029_20230426_232731.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644a68324d9dc938640a6624",
  "name": "externallmg_r_1682597936473_20230426_232725.jpg",
  "path": "cases/644799ead11ef125ab256f8f/
externallmg_r_1682597936473_20230426_232725.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644a684c4d9dc938640a667b",
  "name": "externallmg_1682597963600_IMG_20230426_32928.jpg",
  "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597963600_IMG_20230426_32928.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644a684c4d9dc938640a667c",
  "name": "externallmg_1682597963605_IMG_20230426_33279.jpg",
  "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597963605_IMG_20230426_33279.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644a684c4d9dc938640a667d",
    "name": "externallmg_1682597963628_IMG_20230426_33495.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597963628_IMG_20230426_33495.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644a684c4d9dc938640a667e",
    "name": "externallmg_1682597963657_IMG_20230426_33701.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597963657_IMG_20230426_33701.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644a684c4d9dc938640a667f",
    "name": "externallmg_1682597963659_IMG_20230426_34529.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597963659_IMG_20230426_34529.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644a684c4d9dc938640a6680",
    "name": "externallmg_1682597963670_IMG_20230426_35134.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597963670_IMG_20230426_35134.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644a684c4d9dc938640a6681",
    "name": "externallmg_1682597963672_IMG_20230426_35733.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externallmg_1682597963672_IMG_20230426_35733.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "644a684c4d9dc938640a6682",
    "name": "externalimg_1682597963691_IMG_20230426_36532.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externalimg_1682597963691_IMG_20230426_36532.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644a684c4d9dc938640a6683",
    "name": "externalimg_1682597963701_IMG_20230426_095116.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externalimg_1682597963701_IMG_20230426_095116.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644a684c4d9dc938640a6684",
    "name": "externalimg_1682597963769_IMG_20230426_235721.jpg",
    "path": "cases/644799ead11ef125ab256f8f/
externalimg_1682597963769_IMG_20230426_235721.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644a684c4d9dc938640a6685",
    "name": "externalimg_1682597963955_Screenshot_2023042609465283_3d9111e2
d3171bf4882369f490c087b4.jpg",
    "path": "cases/644799ead11ef125ab256f8f/externalimg_1682597963955_Screensh
ot_2023042609465283_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-04-25T09:14:18.627Z",
"updatedAt": "2023-04-27T12:33:02.616Z",
"__v": 0,
"fullAddress": "Residential Flat No. 306, 3rd Floor, Building No L-30, Mass Housing
Scheme (LIG), Plot No. 1, Sector 27, Village - Taloja, Taluka - Panvel, District - Raigad,
Navi Mumbai, 410 208, State - Maharashtra, India",
"updatedBy": "60eebe33f3dd69653a5837ae",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
```

"contactPersonName": "Mr. Sandesh Maruti Vishwasrao",
 "email": "",
 "isExternal": "false",
 "isUrgent": "false",
 "ownershipShare": "",
 "purchaseValueAsPerDocument": "",
 "relationWithOwner": "self",
 "siteVisitContactNo": "7303171666",
 "buildingServicesRate": "2700",
 "flatRate": "10000",
 "landOtherRate": "7300",
 "briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + Bathroom + WC",
 "carpetTotal": "362.68",
 "finalMeasurementType": "Sq. Ft.",
 "otherCarpetTotal": "19.10",
 "builtupPercentage": "20",
 "finalBuiltupArea": "435.22",
 "finalCarpetArea": "362.68",
 "finalSalableArea": "435.22",
 "salablePercentage": "0",
 "toBeAdded": "",
 "extendOfSiteRemark": "",
 "siteMeasurementRemark": "",
 "finalAreaType": "Carpet Area",
 "finalAsPerArea": "Agreement To Sale",
 "finalBuiltUpPercentage": "10",
 "finalCarpetConvertToBuiltUpPer": "10",
 "finalSaleablePercentage": "0",
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 320.98",
 "reason": "",
 "otherCompositionBuiltUpTotal": "0.00",
 "otherCompositionCarpetTotal": "0.00",
 "otherCompositionSaleableTotal": "0.00"

Name	Length	Width	Total
Composition :			
Living Room	9'9"	12'5"	121.06
Kitchen	6'5"	12'6"	80.21
Bedroom	9'5"	9'5"	88.67
Passage	3'11"	3'10"	15.01

Bathroom	4'10"	3'10"	18.53
WC	4'2"	4'9"	19.79
Other Composition :			
Niche	2'1"	4'10"	10.07
Niche	2'2"	4'2"	9.03