

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "KIRAN ",
    "lastName": "AWALE",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "9309969663"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
    "mobileNo": "9167204055",
```

```
"shortName": "RBK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9343b45132d6a6bdd96e8",
"role": "SITEENGINEER",
"firstName": "RAJESH",
"email": "rajeshb.ghadi@gmail.com",
"lastName": "GHADI",
"mobileNo": "8652092666",
"designation": "",
"shortName": "RHG",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "0123456789",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
```

```

"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "0123456789",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
}
},
"_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}

```

```
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.059295",
  "longitude": "73.012098"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.012098,
    19.059295
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-04-26T10:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-27T15:56:08.557Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-27T15:56:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-27T15:56:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-27T15:56:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-27T15:56:00.000Z",
      "remark": ""
    }
  ]
}
```

```
    "remark": ""
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-04-27T15:56:08.557Z"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Sanpada",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "9",
    "label": false
  },
}
```

```
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "A3",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
```

```
"value": "Millennium Towers Harmony Co-op. Hsg. Soc. Ltd.",
"label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "9",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
```



```
"status": false,
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
```

```
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400 705",
  "label": false
},
"suburb": {
  "status": false,
```

```

    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "value": "CeramicTileFlooring",
    "label": "Ceramic Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "label": "Alluminum sliding windows with M. S. Grills",
    "value": "Alluminum_sliding_windows_with_M._S._Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "label": "Cement Plastering + POP Finish",
    "value": "Cement_Plastering+_POP_Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  }
},

```

```
"townplanApprovedByList": {
  "label": "Navi Mumbai Municipal Corporation",
  "value": "NMMC"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Building No. A2",
  "south": "Building No. A4",
  "east": "Internal Road ",
  "west": "Internal Road "
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "30",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "19020",
  "depreciatedBuildingRate": "1820"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "143800",
  "landRate": "60800",
  "igrImage": "cases/6449046f4d9dc9386408f8e1/igr_1683111872330_Image.png",
  "squareMeterGuideLineRate": "150990.00",
  "squareFeetGuideLineRate": "14027.00"
},
"igrFinalRate": {
  "rate": "12352.00",
  "squareFeetGuideLineRate": "12352.00",
  "squareMeterGuideLineRate": "132952.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
```

```
"label": "Medium"
},
"propertyTypeOfUseList": {
  "label": "Residential Purpose",
  "value": "Residential_Purpose"
},
"propertyOccupiedByList": {
  "label": "Tenant Occupied",
  "value": "Tenant_Occupied"
},
"monthlyRent": "33,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Consumer No. 000296145581",
"meterCardHolderName": "Mr. Tushar M. Nimbalkar & T. T. Nimbalkar",
"undividedAreaOfLandAsPerSaleDeed": "Not applicable",
"floorSpaceIndex": "As per CIDCO norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  }
},
```

```
"carParking": {
  "value": "Stilt+_Open_Car_Parking",
  "label": "Stilt + Open Car Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2003",
  "fullDate": "1/1/2003"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
  "value": "RCC_Framed_Structure",
  "label": "RCC Framed Structure"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
}
```

```
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_per_Possession_Letter",
  "label": "As per Possession Letter"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "20",
```

```
"totalLifeBuilding": "60",
"estimatedAge": "40",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "14",
"flatFloorNo": "9",
"noOfLifts": "02",
"noOfDwellingUnitsInBuilding": "06"
},
"finalPlinthArea": {
  "area": "836.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6449046f4d9dc9386408f8e1/
routeMap_1683019009041_Image.png",
    "routeLat": "19.059306",
    "routeLng": "73.012111",
    "stationName": "Sanpada ",
    "routeDistance": "1.1 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "b7xc8",
      "name": "b7xc8",
      "image": "cases/6449046f4d9dc9386408f8e1/
routeMap_1683018844241_Image.png"
    }
  ]
}
```



```
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "15900720.00",
  "bookValue": "0",
  "finalValue": "15900720.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Wed May 03 2023 16:36:34 GMT+0530 (India Standard Time)",
  "number": "046570",
  "dayCount": "11",
  "monthCount": "30",
  "generatedBy": "60eebe33f3dd69653a5837ae"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "10326272.00",
  "selectedBuildUpValue": "836.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6450d54f6cf92978c09bb8c3",
      "name": "externallmg_r_1683019085476_20230427Thu_123242PM__xrrdrrxz2
223murism_____hnbm_lmjn__org.jpg",
      "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019085476_20230
427Thu_123242PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
      "orientation": "portrait"
    }
  ],
}
```

```
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "6450d55b6cf92978c09bb929",
    "name": "externallmg_1683019098511_20230427Thu_124834PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externallmg_1683019098511_20230427Thu_124834PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "6450d54f6cf92978c09bb8ca",
    "name": "externallmg_r_1683019085700_20230427Thu_123541PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019085700_20230427Thu_123541PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6450d54f6cf92978c09bb8c8",
    "name": "externallmg_r_1683019085685_20230427Thu_123436PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019085685_20230427Thu_123436PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6450d54f6cf92978c09bb8c6",
    "name": "externallmg_r_1683019085560_20230427Thu_123258PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019085560_20230427Thu_123258PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6450d54f6cf92978c09bb8c2",
    "name": "externallmg_r_1683019085071_20230427Thu_123240PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019085071_20230427Thu_123240PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  }
]
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6450d54f6cf92978c09bb8c1",
    "name": "externallmg_r_1683019085548_20230427Thu_123244PM__xrrdrrxz2
223murism_____hnbm_lmjn__org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019085548_20230
427Thu_123244PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6450d54f6cf92978c09bb8c7",
    "name": "externallmg_r_1683019085671_20230427Thu_123406PM__xrrdrrxz2
223murism_____hnbm_lmjn__org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019085671_20230
427Thu_123406PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "6450d54f6cf92978c09bb8c9",
    "name": "Bedroom",
    "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019085723_20230
427Thu_124210PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6450d55b6cf92978c09bb930",
    "name": "Bedroom",
    "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019098389_20230
427Thu_124215PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6450d55b6cf92978c09bb932",
    "name": "Kitchen",
    "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019098496_20230
```

```
427Thu_124234PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6450d55b6cf92978c09bb933",
  "name": "Living Room",
  "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019098466_20230
427Thu_124228PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6450d55b6cf92978c09bb92d",
  "name": "Passage",
  "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019098424_20230
427Thu_124219PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
}
]
},
"taskStatus": {
  "DOCUMENT_VERIFY": false,
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": true,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": "LEAD",
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "836.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"status": true,
"caseStatus": "READYFORCHECKER",
```

```
"_id": "6449046f4d9dc9386408f8e1",
"ownerName": "Mr. Bijaykumar Sahu, Mrs. Trupti Bijaykumar Sahu, Mr. Jaganath
Gopinath Sahu & Mrs. Jhunurani Jaganath Sahu",
"ownerPhoneNo": "9768475539",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9768475539",
"contactPersonName": "Mr. Bijaykumar Sahu",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Mr. Bijaykumar Sahu, Mrs. Trupti Bijaykumar Sahu, Mr. Jaganath Gopinath
Sahu & Mrs. Jhunurani Jaganath Sahu",
    "phone": "9768475539",
    "email": "",
    "ownershipShare": "",
    "id": "862616"
  }
],
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 1, 9th Floor, Building No A3, Millennium Towers
Harmony Co-op. Hsg. Soc. Ltd., Sector 9, Village - Sanpada, Taluka - Thane, District -
Thane, Navi Mumbai, 400 705, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1254aa6d152c1801b326",
      "label": "Agreement For Sale"
    },
    "inputs": {
      "documentDate": "24/04/2023",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Mr. Tushar Mohanrao Nimbalkar & Mrs. Tanvi Tushar Nimbalkar",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Bijaykumar Sahu, Mrs. Trupti Bijaykumar Sahu, Mr. Jaganath
Gopinath Sahu & Mrs. Jhunurani Jaganath Sahu"
    },
    "isHardCopy": false,
```



```
"displayStatus": true,
"fileName": "document_1683014108738_Agreement.pdf",
"path": "cases/6449046f4d9dc9386408f8e1/
document_1683014108738_Agreement.pdf",
"id": "417400",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue May 02 2023 13:25:11 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f3",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "21/01/2023",
    "to": {
      "value": "Seller",
      "label": "Seller"
    },
    "Seller": "Mr. Tushar Mohanrao Nimbalkar & Mrs. Tanvi Tushar Nimbalkar",
    "number": {
      "value": "Consumer_No",
      "label": "Consumer No"
    },
    "Consumer_No": "000296145581"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/6449046f4d9dc9386408f8e1/
document_1683014176663_1618026.pdf",
  "id": "371703",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Tue May 02 2023 13:27:17 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1258aa6d152c1801b339",
    "label": "Possession Letter"
  },
  "inputs": {
    "documentDate": "23/12/2003",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    }
  }
},
}
```

```
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6449046f4d9dc9386408f8e1/
document_1683014235050_1177849.pdf",
    "id": "498870",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Tue May 02 2023 13:27:17 GMT+0530 (India Standard Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "001336",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "797727",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Wed Apr 26 2023 16:31:03 GMT+0530 (India Standard Time)"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Built Up",
      "value": "Built Up"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "644a9b864d9dc938640a7f2e",
    "area": "00",
    "providedByName": "Vijaykumar Sahu\u201c",
    "providedByContactNo": "9768475539"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "10",
    "name": "Living Room",
```

```
"length": "10.08",
"length1": "10",
"length2": "1",
"width": "16.17",
"width1": "16",
"width2": "2",
"totalArea": "163.01",
"images": [],
"finalArea": "163.01",
"extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "10",
  "name": "Passage",
  "length": "14.58",
  "length1": "14",
  "length2": "7",
  "width": "3.33",
  "width1": "3",
  "width2": "4",
  "totalArea": "48.61",
  "images": [],
  "finalArea": "66.61",
  "extraAreas": [
    {
      "measurementType": {
        "label": "Square Feet",
        "value": "Square_Feet"
      },
      "_id": "6450d2136cf92978c09bab2d",
      "name": "Passage 1",
      "extraAreaType": "Add",
      "length": "5.00",
      "length1": "5",
      "length2": "00",
      "width": "2.00",
      "width1": "2",
      "width2": "00",
      "totalArea": "10.00"
    }
  ],
  {
    "measurementType": {
```

```
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "_id": "6450d25a6cf92978c09bac55",
  "name": "Passage 2",
  "extraAreaType": "Add",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "8.00"
}
]
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "10",
  "name": "Kitchen",
  "length": "9.25",
  "length1": "9",
  "length2": "3",
  "width": "6.08",
  "width1": "6",
  "width2": "1",
  "totalArea": "56.27",
  "images": [],
  "finalArea": "56.27",
  "extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
```

```
"width2": "00",
"totalArea": "12.00",
"images": [],
"extraAreas": [],
"finalArea": "12.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "20.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "10",
  "name": "Bedroom",
  "length": "9.17",
  "length1": "9",
  "length2": "2",
  "width": "10.08",
  "width1": "10",
  "width2": "1",
  "totalArea": "92.43",
  "images": [],
  "finalArea": "92.43",
  "extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  }
}
```

```
},
  "id": "10",
  "name": "Bedroom",
  "length": "9.33",
  "length1": "9",
  "length2": "4",
  "width": "12.42",
  "width1": "12",
  "width2": "5",
  "totalArea": "115.89",
  "images": [],
  "finalArea": "115.89",
  "extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "9",
  "name": "Toilet",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "35.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "35.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Flower Bed Area",
      "value": "Flower_Bed_Area"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    }
  }
]
```

```
    },
    "id": "0",
    "length1": "2",
    "length2": "00",
    "length": "2.00",
    "width1": "8",
    "width": "8.00",
    "totalArea": "16.00",
    "percentageBeforeTotal": "16.00",
    "percentage": "100",
    "width2": "0",
    "images": [],
    "extraAreas": [],
    "finalArea": "16.00"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1254aa6d152c1801b326",
      "label": "Agreement For Sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "954545",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "836",
    "squareMeterArea": "77.67",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBUILTUPPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64523ddb53151277305ebb0",
    "id": "1",
    "property": "Flat",
```

```
"area": "700",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "14",
"source": "https://www.99acres.com/",
"expectedPrice": "16500000",
"expectedRate": "23571.43",
"builtUpExpectedRate": "19642.86",
"image": "cases/6449046f4d9dc9386408f8e1/
indicator_1683111387458_Image.png"
},
{
  "printlnReport": true,
  "_id": "64523e37b53151277305edcf",
  "id": "2",
  "property": "Flat",
  "area": "750",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "17500000",
  "expectedRate": "23333.33",
  "builtUpExpectedRate": "19444.44",
  "image": "cases/6449046f4d9dc9386408f8e1/
indicator_1683111479112_Image.png"
},
{
  "printlnReport": true,
  "_id": "64523e73b53151277305eddf",
  "id": "3",
  "property": "Flat",
  "area": "700",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "17000000",
  "expectedRate": "24285.71",
  "builtUpExpectedRate": "20238.10",
```



```
    "image": "cases/6449046f4d9dc9386408f8e1/
indicator_1683111539462_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "64523ee0b53151277305edf0",
    "id": "4",
    "property": "Flat",
    "area": "847",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "floor": "12",
    "source": "Index_no.2",
    "expectedPrice": "15300000",
    "expectedRate": "18063.75",
    "builtUpExpectedRate": "15300000",
    "image": "cases/6449046f4d9dc9386408f8e1/
indicator_1683111648753_Image.jpeg"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6450d54f6cf92978c09bb8c0",
    "name": "externalImg_r_1683019085555_20230427Thu_123256PM__xrrddrrxz22
23murism_____hnbm_lmjn__org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externalImg_r_1683019085555_202304
27Thu_123256PM__xrrddrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6450d54f6cf92978c09bb8c1",
    "name": "externalImg_r_1683019085548_20230427Thu_123244PM__xrrddrrxz22
23murism_____hnbm_lmjn__org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externalImg_r_1683019085548_202304
27Thu_123244PM__xrrddrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6450d54f6cf92978c09bb8c2",
    "name": "externalimg_r_1683019085071_20230427Thu_123240PM__xrrddrrxz22
23murism_____hnbm_lmjn__org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externalimg_r_1683019085071_202304
27Thu_123240PM__xrrddrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6450d54f6cf92978c09bb8c3",
    "name": "externalimg_r_1683019085476_20230427Thu_123242PM__xrrddrrxz22
23murism_____hnbm_lmjn__org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externalimg_r_1683019085476_202304
27Thu_123242PM__xrrddrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6450d54f6cf92978c09bb8c4",
    "name": "externalimg_r_1683019085581_20230427Thu_123316PM__xrrddrrxz22
23murism_____hnbm_lmjn__org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externalimg_r_1683019085581_202304
27Thu_123316PM__xrrddrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6450d54f6cf92978c09bb8c5",
    "name": "externalimg_r_1683019085633_20230427Thu_123400PM__xrrddrrxz22
23murism_____hnbm_lmjn__org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externalimg_r_1683019085633_202304
27Thu_123400PM__xrrddrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6450d54f6cf92978c09bb8c6",
    "name": "externalimg_r_1683019085560_20230427Thu_123258PM__xrrddrrxz22
23murism_____hnbm_lmjn__org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externalimg_r_1683019085560_202304
27Thu_123258PM__xrrddrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  }
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6450d54f6cf92978c09bb8c7",
  "name": "externallmg_r_1683019085671_20230427Thu_123406PM__xrrddrrxz223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019085671_20230427Thu_123406PM__xrrddrrxz223murism_____hnbm_lmjn__org.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6450d54f6cf92978c09bb8c8",
  "name": "externallmg_r_1683019085685_20230427Thu_123436PM__xrrddrrxz223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019085685_20230427Thu_123436PM__xrrddrrxz223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6450d54f6cf92978c09bb8c9",
  "name": "externallmg_r_1683019085723_20230427Thu_124210PM__xrrddrrxz223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019085723_20230427Thu_124210PM__xrrddrrxz223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6450d54f6cf92978c09bb8ca",
  "name": "externallmg_r_1683019085700_20230427Thu_123541PM__xrrddrrxz223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019085700_20230427Thu_123541PM__xrrddrrxz223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6450d54f6cf92978c09bb8cb",
  "name": "externallmg_r_1683019085737_20230427Thu_124212PM__xrrddrrxz223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019085737_20230427Thu_124212PM__xrrddrrxz223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
}
```

```
23murism_____hnbm_lmjn___org.jpg",
  "path": "cases/6449046f4d9dc9386408f8e1/externallmg_r_1683019085737_202304
27Thu_124212PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6450d55b6cf92978c09bb929",
  "name": "externallmg_1683019098511_20230427Thu_124834PM___xrrddrrxz2223
murism_____hnbm_lmjn___org.jpg",
  "path": "cases/6449046f4d9dc9386408f8e1/externallmg_1683019098511_2023042
7Thu_124834PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6450d55b6cf92978c09bb92a",
  "name": "externallmg_1683019098538_IMG_20230427_210534.jpg",
  "path": "cases/6449046f4d9dc9386408f8e1/
externallmg_1683019098538_IMG_20230427_210534.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6450d55b6cf92978c09bb92b",
  "name": "externallmg_1683019098555_IMG_20230427_210537.jpg",
  "path": "cases/6449046f4d9dc9386408f8e1/
externallmg_1683019098555_IMG_20230427_210537.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6450d55b6cf92978c09bb92c",
  "name": "externallmg_1683019098578_Screenshot_20230427_210809.jpg",
  "path": "cases/6449046f4d9dc9386408f8e1/
externallmg_1683019098578_Screenshot_20230427_210809.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6450d55b6cf92978c09bb92d",
```

```
    "name": "externalimg_r_1683019098424_20230427Thu_124219PM___xrddrrxz22
23murism_____hnbm_lmjn___org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externalimg_r_1683019098424_202304
27Thu_124219PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6450d55b6cf92978c09bb92e",
    "name": "externalimg_r_1683019098440_20230427Thu_124227PM___xrddrrxz22
23murism_____hnbm_lmjn___org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externalimg_r_1683019098440_202304
27Thu_124227PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6450d55b6cf92978c09bb92f",
    "name": "externalimg_r_1683019098408_20230427Thu_124217PM___xrddrrxz22
23murism_____hnbm_lmjn___org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externalimg_r_1683019098408_202304
27Thu_124217PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6450d55b6cf92978c09bb930",
    "name": "externalimg_r_1683019098389_20230427Thu_124215PM___xrddrrxz22
23murism_____hnbm_lmjn___org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externalimg_r_1683019098389_202304
27Thu_124215PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6450d55b6cf92978c09bb931",
    "name": "externalimg_r_1683019098483_20230427Thu_124231PM___xrddrrxz22
23murism_____hnbm_lmjn___org.jpg",
    "path": "cases/6449046f4d9dc9386408f8e1/externalimg_r_1683019098483_202304
27Thu_124231PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6450d55b6cf92978c09bb932",
  "name": "externalImg_r_1683019098496_20230427Thu_124234PM__xrrdrrxz22
23murism_____hnbm_lmjn__org.jpg",
  "path": "cases/6449046f4d9dc9386408f8e1/externalImg_r_1683019098496_202304
27Thu_124234PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6450d55b6cf92978c09bb933",
  "name": "externalImg_r_1683019098466_20230427Thu_124228PM__xrrdrrxz22
23murism_____hnbm_lmjn__org.jpg",
  "path": "cases/6449046f4d9dc9386408f8e1/externalImg_r_1683019098466_202304
27Thu_124228PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-04-26T11:01:03.743Z",
"updatedAt": "2023-05-04T05:38:45.226Z",
"__v": 0,
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + WC +
Bathroom + Toilet",
"carpetTotal": "561.21",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"siteVisitDate": "2023-04-27",
"addressForMap": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "16.00",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "692.65",
"finalCarpetArea": "577.21",
"finalSalableArea": "692.65",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
```

"finalBuiltUpPercentage": "20",  
 "finalCarpetConvertToBuiltUpPer": "20",  
 "finalSaleablePercentage": "0",  
 "finalValuationAreaString": "Built Up Area in Sq. Ft. = 836.00",  
 "reason": "",  
 "buildingServicesRate": "2600",  
 "flatRate": "19800",  
 "landOtherRate": "17200"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	10'1"	16'2"	163.01
Passage	14'7"	3'4"	48.61
Kitchen	9'3"	6'1"	56.27
WC	3'00"	4'00"	12.00
Bathroom	5'00"	4'00"	20.00
Bedroom	9'2"	10'1"	92.43
Bedroom	9'4"	12'5"	115.89
Toilet	5'00"	7'00"	35.00
Other Composition :			
Flower Bed Area	2'00"	8'0"	16.00