

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb63"
    },
    "type": "CREDITOFFICER",
    "_id": "64378b6be4256a03ecdf4219",
    "firstName": "Sandeep",
    "lastName": "Lohakare",
    "mobileNo": "",
    "workMobileNo": "9594965498",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",
    "name": "Thane",
    "email": "thane@vastukala.com",
    "phone": "1234567890",
    "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
```

```
400 601",
  "city": "Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb63",
  "branchCode": "000355",
  "type": "BRANCH",
  "name": "RACPC Kalyan",
  "email": "rasecc.thane@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Main Branch, 1st Floor, Near LIC Office\nMurbad Road, Kalyan West.
421301.\n\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land & Building / _Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62720e52afd7d55eddedc887",
    "role": "SITEENGINEER",
    "firstName": "Harshad",
    "email": "harshad@vastukala.org",
    "lastName": "Panchal",
```

```
"mobileNo": "9029575553",
"shortName": "HP",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "640c34384dda382753e651f2",
  "role": "SITEENGINEER",
  "firstName": "PRASHANT ",
  "email": "kasarprashant121@gmail.com",
  "lastName": "KASAR",
  "mobileNo": "9892524464",
  "designation": "",
  "shortName": "PK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/640c34384dda382753e651f2/
profilePhoto_1678521400647_WhatsApp_Image_20230311_at_12047_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PSH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
```

```
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    }
  ],
}
```

```
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.154104865213796 ",
  "longitude": "73.22714827116467"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-05-04T08:00:00.000Z",
```



```
{
  "dateTime": "2023-05-04T08:00:00.000Z",
  "remark": ""
},
{
  "dateTime": "2023-05-04T08:00:00.000Z",
  "remark": ""
},
{
  "dateTime": "2023-05-04T08:00:00.000Z",
  "remark": ""
}
],
"visitedDate": [
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-05-03T18:30:00.000Z"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Shirgaon, Badlapur (East)",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambarnath",
  "label": true
},
}
```



```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Om Savai Niketan",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Opp. Proposed Panvel Highway",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
```

```
"value": "B",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "142, Ward No. 11/27, F 2/1",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "5 & 6",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "102",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421503",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Kulgaon_Badlapur_Municipal_Council",
"label": "Kulgaon Badlapur Municipal Council"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Building No. 10, Jeevan lifestyle Building",
"west": "Opp. Proposed Panvel Highway",
"south": "Konark Gardens Building",
"east": "Parking Area"
},
"asPerDocumentAgreement": {
"north": "by 30 meter wide existing D. P. Road",
"west": "Land bearing Survey No. 143, Hissa No. 6",
"south": "for some part by 30 Meter Road and for remaining",
"east": "Land bearing Survey No. 143, Hissa No. 3"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "0",
"depreciationRatioOfBuilding": "",
"salvageValue": "",
"depreciatedCostOfConstruction": "5700",
"depreciatedBuildingRate": "2600"
},
"igrRate": {
"propertyName": "Shirgaon Village, Badlapur",
"rate": "52400",
"landRate": "8290",
"igrImage": "cases/64537947a159bc3d87afc345/igr_1683202788687_Image.png",
```

```
"squareMeterGuideLineRate": "52400.00",
"squareFeetGuideLineRate": "4868.00"
},
"igrFinalRate": {
  "rate": "4663.00",
  "squareFeetGuideLineRate": "4663.00",
  "squareMeterGuideLineRate": "50195.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "6000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "KBNC",
  "tenantName": "",
  "maintenanceOfFlat": "Good (Flat internal painting work in progress)"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
```

```
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": {
"value": "Stilt+_Open_Car_Parking",
"label": "Stilt + Open Car Parking"
},
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2018",
"fullDate": "1/1/2018"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
```

```
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceIssues": {
"value": "Information_not_available",
"label": "Information not available"
},
"visibleDamageInBuilding": {
"value": "Information_not_available",
"label": "Information not available"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
}
```



```
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "5",
"totalLifeBuilding": "60",
"estimatedAge": "55",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "1",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "551.10",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64537947a159bc3d87afc345/
routeMap_1683273423053_Image.png",
    "routeLat": "19.154002",
    "routeLng": "73227322",
    "stationName": "Badlapur",
    "routeDistance": "2.6Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
}
```

```
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "on4s8",
    "name": "on4s8",
    "image": "cases/64537947a159bc3d87afc345/
routeMap_1683273571079_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "2855700.00",
  "bookValue": "0",
  "finalValue": "2855700.00"
},
"outward": {
```

```
"status": true,
"remark": "SYSTEM_GENERATED",
"date": "Fri May 05 2023 13:36:50 GMT+0530 (India Standard Time)",
"number": "046587",
"dayCount": "8",
"monthCount": "47",
"generatedBy": "627222afafd7d55eddeddd82"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2569779.00",
  "selectedBuildUpValue": "551.10",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
```

```
"frontPageImages": [
  {
    "status": false,
    "_id": "6454b7d614bbf555ec468535",
    "name": "externallmg_1683273684910_IMG20230504WA0008.jpg",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273684910_IMG20230504WA0008.jpg",
    "orientation": "landscape"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "6454b7d614bbf555ec468534",
    "name": "externallmg_1683273684844_IMG20230504WA0005.jpg",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273684844_IMG20230504WA0005.jpg",
    "orientation": "landscape"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "6454b7d614bbf555ec468536",
    "name": "externallmg_1683273684984_IMG20230504WA0009.jpg",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273684984_IMG20230504WA0009.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6454b7d614bbf555ec468535",
    "name": "externallmg_1683273684910_IMG20230504WA0008.jpg",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273684910_IMG20230504WA0008.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6454b7d614bbf555ec468538",
    "name": "externallmg_1683273685110_IMG20230504WA0011.jpg",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685110_IMG20230504WA0011.jpg",
    "orientation": "portrait"
  },
  {

```

```
    "status": false,
    "_id": "6454b7d614bbf555ec468544",
    "name": "externallmg_1683273685617_IMG20230504WA0027.jpg",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685617_IMG20230504WA0027.jpg",
    "orientation": "landscape"
  }
],
"parkingImages": [
  {
    "status": false,
    "_id": "6454b7d614bbf555ec468537",
    "name": "externallmg_1683273685045_IMG20230504WA0010.jpg",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685045_IMG20230504WA0010.jpg",
    "orientation": "portrait"
  }
],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "6454b7d614bbf555ec46853e",
    "name": "Living Room",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685454_IMG20230504WA0019.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6454b7d614bbf555ec468541",
    "name": "Kitchen",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685545_IMG20230504WA0024.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6454b7d614bbf555ec468540",
    "name": "Bedroom",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685517_IMG20230504WA0022.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
```

```
    "_id": "6454b7d614bbf555ec468542",
    "name": "Bedroom",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685578_IMG20230504WA0025.jpg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": true,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false,
  "DOCUMENT_VERIFY": false
},
"createCase": "true",
"type": "CASE",
"leadType": "LEAD",
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "501.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"status": true,
"caseStatus": "REPORTGENERATED",
"_id": "64537947a159bc3d87afc345",
"ownerName": "Mr. Rajendra Kumar Rakesh Kumar Dubey & Mrs. Ashadevi Rakesh Dubey\t",
"ownerPhoneNo": "8108856767",
"ownershipShare": "",
```

```
"email": "",
"siteVisitContactNo": "7880976263",
"contactPersonName": "Mr. Rajendra Kumar Dubey - (Owner) Contact No.
8108856767",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Mr. Rajendra Kumar Rakesh Kumar Dubey & Mrs. Ashadevi Rakesh Dubey
\t",
    "phone": "8108856767",
    "ownershipShare": "",
    "email": "",
    "id": "197615"
  }
],
"caseReferredBy": "6410199a140f140ffc59b58c",
"relationWithOwner": "Person Met on Site - Mr. Shashikant - Painter ",
"fullAddress": "Residential Flat No. 102, 1st Floor, Wing - B, Om Savai Niketan, Opp.
Proposed Panvel Highway, Village - Shirgaon, Badlapur (East), Taluka - Ambarnath,
District - Thane, PIN Code - 421503, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Sagar Super Structures Pvt. Ltd.",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mr. Rajendra Kumar Rakesh Kumar Dubey & Mrs. Ashadevi Rakesh
Dubey"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1683266400866_AGREEMENT_6.pdf",
    "path": "cases/64537947a159bc3d87afc345/
document_1683266400866_AGREEMENT_6.pdf",
    "id": "657814",
```

```
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri May 05 2023 12:00:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "07/03/2014",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "KBNP / BP / 2013 – 2014 / 420 / UNIK No. 29"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "path": "cases/64537947a159bc3d87afc345/
document_1683266569485_265167.pdf",
  "id": "755601",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Fri May 05 2023 12:00:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "26/10/2018",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "KBNP / NRV / 8074 / 2018 – 2019"
  },
  "isHardCopy": false,
```

```
"displayStatus": true,
"path": "cases/64537947a159bc3d87afc345/
document_1683266827877_205902.pdf",
"id": "542359",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri May 05 2023 12:00:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1298aa6d152c1801b460",
    "label": "Demand Letter"
  },
  "inputs": {
    "documentDate": "12/04/2023",
    "remark": "issued by Sagar Super Structures Pvt. Ltd",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "NA"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "path": "cases/64537947a159bc3d87afc345/
document_1683267036861_63416.pdf",
"id": "309205",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri May 05 2023 12:00:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1246aa6d152c1801b2e5",
    "label": "Allotment Letter"
  },
  "inputs": {
    "documentDate": "06/04/2023",
    "from": {
      "value": "Promoter",
      "label": "Promoter"
    },
    "Promoter": "Sagar Super Structures Pvt. Ltd",
    "to": {
      "value": "Allottee",
      "label": "Allottee"
    },
    "Allottee": "Mr. Rajendra Kumar Rakesh Kumar Dubey & Mrs. Ashadevi Rakesh
Dubey"
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "path": "cases/64537947a159bc3d87afc345/
document_1683267220267_161673.pdf",
    "id": "202480",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Fri May 05 2023 12:00:26 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "22/08/2017",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
        "label": "Maharashtra Real Estate Regulatory Authority"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "P51700009373"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "path": "cases/64537947a159bc3d87afc345/
document_1683267370502_144514.pdf",
    "id": "655110",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Fri May 05 2023 12:00:26 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1249aa6d152c1801b2f2",
      "label": "7/12 Extract"
    },
    "inputs": {
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "NA"
    },
  },
}
```

```
    "isHardCopy": false,
    "displayStatus": true,
    "path": "cases/64537947a159bc3d87afc345/
document_1683267630970_143025.pdf",
    "id": "610902",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Fri May 05 2023 12:00:26 GMT+0530 (India Standard Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "001422",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "537400",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Thu May 04 2023 14:52:15 GMT+0530 (India Standard Time)"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "827348",
    "name": "Bedroom",
    "length": "8.00",
    "length1": "8",
    "length2": "00",
    "width": "10.00",
    "width1": "10",
    "width2": "00",
    "totalArea": "80.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "80.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
]
```

```
},
  "id": "13",
  "name": "Bedroom",
  "length": "8.00",
  "length1": "8",
  "length2": "0",
  "width": "11.00",
  "width1": "11",
  "width2": "0",
  "totalArea": "88.00",
  "images": [],
  "finalArea": "88.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Living Room",
  "length": "8.00",
  "length1": "8",
  "length2": "00",
  "width": "14.00",
  "width1": "14",
  "width2": "00",
  "totalArea": "112.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "112.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "",
  "length1": "9",
  "length2": "0",
  "width": "",
  "width1": "7",
  "width2": "0",
  "totalArea": "63.00",
```



```
"images": [],
"finalArea": "63.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Flowered Area",
  "length": "8.00",
  "length1": "8",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "24.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Flowered Area",
  "length": "8.00",
  "length1": "8",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "24.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
```

```
"name": "Flowered Area",
"length": "",
"length1": "8",
"length2": "0",
"width": "",
"width1": "3",
"width2": "0",
"totalArea": "24.00",
"images": [],
"finalArea": "24.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "13",
  "name": "Flowered Area",
  "length": "9.00",
  "length1": "9",
  "length2": "0",
  "width": "3.00",
  "width1": "3",
  "width2": "0",
  "totalArea": "27.00",
  "images": [],
  "finalArea": "27.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "WC",
  "length": "2.00",
  "length1": "2",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "6.00",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "6.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Bathroom",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "21.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Passage",
  "length": "2.00",
```

```
"length1": "2",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "2.00",
"images": [],
"extraAreas": [],
"finalArea": "2.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "13",
  "name": "Toilet",
  "length": "",
  "length1": "4",
  "length2": "0",
  "width": "",
  "width1": "8",
  "width2": "0",
  "totalArea": "32.00",
  "images": [],
  "finalArea": "32.00",
  "extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "411526",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "501",
    "squareMeterArea": "46.54",
    "docFinalBuiltUp": "551.1",
```

```
"docFinalBuiltUpSquareMeter": "51.194",
"docBuiltupPercentage": "10",
"docSaleablePercentage": "10",
"docFinalSaleable": "606.21",
"docFinalSaleableSquareMeter": "56.3134"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "6453a0fea159bc3d87b06a14",
  "id": "1",
  "property": "Badlapur East, Shirgaon Village",
  "area": "665",
  "builtUpPercentage": "10",
  "saleablePercentage": "40",
  "rateType": "price_Indicator",
  "areaType": "Saleable",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "2850000",
  "expectedRate": "4285.71",
  "builtUpExpectedRate": "6000.00",
  "image": "cases/64537947a159bc3d87afc345/
indicator_1683202302164_Image.png"
},
{
  "printlnReport": true,
  "_id": "6453a14ca159bc3d87b06a23",
  "id": "2",
  "property": "Badlapur East, Shirgaon Village",
  "area": "410",
  "builtUpPercentage": "10",
  "saleablePercentage": "40",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "https://www.99acres.com/",
  "expectedPrice": "2400000",
  "expectedRate": "5853.66",
  "builtUpExpectedRate": "5321.51",
  "image": "cases/64537947a159bc3d87afc345/
indicator_1683202380682_Image.png"
},
{
```

```
"printlnReport": true,
  "_id": "6453a194a159bc3d87b06a33",
  "id": "3",
  "property": "adlapur East, Shirgaon Village",
  "area": "475",
  "builtUpPercentage": "10",
  "saleablePercentage": "40",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "2nd Floor",
  "source": "magic_bricks",
  "expectedPrice": "2750000",
  "expectedRate": "5789.47",
  "builtUpExpectedRate": "5263.16",
  "image": "cases/64537947a159bc3d87afc345/
indicator_1683202452763_Image.png"
},
{
  "printlnReport": true,
  "_id": "6453a286a159bc3d87b06a44",
  "id": "4",
  "property": "Om Savai Niketan, Badlapur East",
  "area": "361",
  "builtUpPercentage": "10",
  "saleablePercentage": "40",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "4th Floor",
  "source": "Index_no.2",
  "expectedPrice": "2000000",
  "expectedRate": "5540.17",
  "builtUpExpectedRate": "5036.51",
  "image": "cases/64537947a159bc3d87afc345/
indicator_1683202693945_Image.png"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6454b7d614bbf555ec468534",
    "name": "externallmg_1683273684844_IMG20230504WA0005.jpg",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273684844_IMG20230504WA0005.jpg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6454b7d614bbf555ec468535",
  "name": "externallmg_1683273684910_IMG20230504WA0008.jpg",
  "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273684910_IMG20230504WA0008.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6454b7d614bbf555ec468536",
  "name": "externallmg_1683273684984_IMG20230504WA0009.jpg",
  "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273684984_IMG20230504WA0009.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6454b7d614bbf555ec468537",
  "name": "externallmg_1683273685045_IMG20230504WA0010.jpg",
  "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685045_IMG20230504WA0010.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6454b7d614bbf555ec468538",
  "name": "externallmg_1683273685110_IMG20230504WA0011.jpg",
  "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685110_IMG20230504WA0011.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6454b7d614bbf555ec468539",
  "name": "externallmg_1683273685169_IMG20230504WA0012.jpg",
  "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685169_IMG20230504WA0012.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6454b7d614bbf555ec46853a",
    "name": "externallmg_1683273685207_IMG20230504WA0013.jpg",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685207_IMG20230504WA0013.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6454b7d614bbf555ec46853b",
    "name": "externallmg_1683273685264_IMG20230504WA0015.jpg",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685264_IMG20230504WA0015.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6454b7d614bbf555ec46853c",
    "name": "externallmg_1683273685328_IMG20230504WA0017.jpg",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685328_IMG20230504WA0017.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6454b7d614bbf555ec46853d",
    "name": "externallmg_1683273685388_IMG20230504WA0018.jpg",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685388_IMG20230504WA0018.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6454b7d614bbf555ec46853e",
    "name": "externallmg_1683273685454_IMG20230504WA0019.jpg",
    "path": "cases/64537947a159bc3d87afc345/
externallmg_1683273685454_IMG20230504WA0019.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "6454b7d614bbf555ec46853f",
  "name": "externalimg_1683273685477_IMG20230504WA0020.jpg",
  "path": "cases/64537947a159bc3d87afc345/
externalimg_1683273685477_IMG20230504WA0020.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6454b7d614bbf555ec468540",
  "name": "externalimg_1683273685517_IMG20230504WA0022.jpg",
  "path": "cases/64537947a159bc3d87afc345/
externalimg_1683273685517_IMG20230504WA0022.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6454b7d614bbf555ec468541",
  "name": "externalimg_1683273685545_IMG20230504WA0024.jpg",
  "path": "cases/64537947a159bc3d87afc345/
externalimg_1683273685545_IMG20230504WA0024.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6454b7d614bbf555ec468542",
  "name": "externalimg_1683273685578_IMG20230504WA0025.jpg",
  "path": "cases/64537947a159bc3d87afc345/
externalimg_1683273685578_IMG20230504WA0025.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6454b7d614bbf555ec468543",
  "name": "externalimg_1683273685597_IMG20230504WA0026.jpg",
  "path": "cases/64537947a159bc3d87afc345/
externalimg_1683273685597_IMG20230504WA0026.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```

    "_id": "6454b7d614bbf555ec468544",
    "name": "externalimg_1683273685617_IMG20230504WA0027.jpg",
    "path": "cases/64537947a159bc3d87afc345/
externalimg_1683273685617_IMG20230504WA0027.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"createdAt": "2023-05-04T09:22:15.434Z",
"updatedAt": "2023-05-06T10:35:58.501Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"buildingServicesRate": "2600",
"flatRate": "5700",
"landOtherRate": "3100",
"reason": "",
"addressForMap": "",
"siteVisitDate": "2023-05-04",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 4 Flowered Area + WC
+ Bathroom + 2 Passage + Toilet",
"carpetTotal": "515",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "566.50",
"finalCarpetArea": "515.00",
"finalSalableArea": "623.15",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalSaleablePercentage": "10",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 501.00",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			

Bedroom	8'00"	10'00"	80.00
Bedroom	8'0"	11'0"	88.00
Living Room	8'00"	14'00"	112.00
Kitchen	9'0"	7'0"	63.00
Flowered Area	8'00"	3'00"	24.00
Flowered Area	8'00"	3'00"	24.00
Flowered Area	8'0"	3'0"	24.00
Flowered Area	9'0"	3'0"	27.00
WC	2'00"	3'00"	6.00
Bathroom	3'00"	4'00"	12.00
Passage	3'00"	7'00"	21.00
Passage	2'00"	1'00"	2.00
Toilet	4'0"	8'0"	32.00
Other Composition :			