

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd93aace84bf289baab038",
    "firstName": "Pranjli ",
    "lastName": "Prabhu",
    "mobileNo": "",
    "workMobileNo": "9969957108",
    "email": "pranjli.prabhu@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3000000",
    "discussWithPerson": "Pranjli ",
    "expectedFees": 1500,
    "quotedAmount": "2500"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1 6th Floor, Kiro Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
    "lastName": "Velonde",
    "mobileNo": "8691048846",
```

```
"shortName": "SSV",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7177d2ffdf65bcd65882a\
\profilePhoto_1622701681508_WhatsApp Image 2021-06-02 at 11.09.24 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "627362b3afd7d55eddee1ee7",
"role": "SITEENGINEER",
"firstName": "Vicky ",
"email": "vicky@vastukala.org",
"lastName": "Bhor",
"mobileNo": "9004386288",
"designation": "",
"shortName": "VB",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "CHECKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627208c1afd7d55eddedc372",
"role": "SITEENGINEER",
"firstName": "Aniket",
"email": "aniket@vastukala.org",
"lastName": "Navale",
"mobileNo": "9892222307",
"designation": "",
"shortName": "AN",
"workWithDocumentMaker": "",
"profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
},
"checker": {
```

```
"type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ]
  }
]
```

```
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.067627320020826",
  "longitude": "73.09809832213168"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.09809832213168,
    19.067627320020826
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-05-06T12:00:00.000Z",
      "remark": ""
    }
  ]
}
```

```
    },
    {
      "dateTime": "2023-05-06T12:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-05-06T12:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "remark": "MANUAL",
      "status": "COMPLETED",
      "dateTime": "2023-05-06T09:30:00.000Z"
    },
    {
      "remark": "MANUAL",
      "status": "COMPLETED",
      "dateTime": "2023-05-07T06:00:00.000Z"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Sat May 06 2023 17:31:56 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Taloja",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "L09",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mass Housing Scheme (General)",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "27",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```



```
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```

```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "105",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "410208",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/ _Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "CIDCO",
    "label": "City Industrial Development Corporation of Maharashtra"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Road",
    "west": "Building No. L-08",
    "south": "Meter station",
    "east": "Building No. L-10"
  },
  "asPerDocumentAgreement": {
    "north": "Details Not Available",
    "west": "Details Not Available",
    "south": "Details Not Available",
    "east": "Details Not Available"
  },
  "extraDetailOfProperty": "The property is at 3.1 Km. travelling distance from nearest railway station Taloja. "
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": ""
}
```

```
"depreciatedCostOfConstruction": "",
"depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Taloja Sector 27",
  "rate": "54000",
  "landRate": "18100",
  "igrImage": "cases/645637317f94762ec7849484/igr_1683525396018_Image.png",
  "squareMeterGuideLineRate": "54000.00",
  "squareFeetGuideLineRate": "5017.00"
},
"igrFinalRate": {
  "rate": "54000",
  "squareMeterGuideLineRate": "54000.00",
  "squareFeetGuideLineRate": "5017.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "8000",
  "assessmentNo": "Details Not Available",
  "taxPaidHolderName": "Details Not Available",
  "taxAmount": "Details Not Available",
  "electricityServiceConnectionNo": "028611213427",
  "meterCardHolderName": "Mr. Rajkiran Shivprasad Tandekar",
  "undividedAreaOfLandAsPerSaleDeed": "Details Not Available",
  "floorSpaceIndex": "Details Not Available",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
```

```
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": {
    "value": "Open_Car_Parking",
    "label": "Open Car Parking"
  },
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2021",
    "fullDate": "1/1/2021"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  },
  "typeOfFoundation": {
```

```
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenancelssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
}
```

```
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "2",
"totalLifeBuilding": "60",
"estimatedAge": "58",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "14",
"flatFloorNo": "1",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "353.08",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "routeMapImg": "cases/645637317f94762ec7849484/
routeMap_1683527517588_Image.png",
  "routeLat": "19.072242",
  "routeLng": "73.103452",
  "stationName": "Taloja",
  "routeDistance": "3.2 Km"
```



```
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "4fa53w",
    "name": "4fa53w",
    "image": "cases/645637317f94762ec7849484/
routeMap_1683527558727_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
}
```

```
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3210000.00",
"bookValue": "0",
"finalValue": "3210000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Mon May 08 2023 12:15:27 GMT+0530 (India Standard Time)",
  "number": "046610",
  "dayCount": "8",
  "monthCount": "70",
  "generatedBy": "627208c1afd7d55eddedc372"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1771402.00",
  "selectedBuildUpValue": "353.08",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "645898437f94762ec7853882",
      "name": "externallmg_1683527746298_IMG_20230507_1917.jpg",
      "path": "cases/645637317f94762ec7849484/externallmg_1683527746298_IMG_20230507_1917.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "645898437f94762ec7853880",
      "name": "externallmg_1683527746032_IMG_20230507_2113.jpg",
      "path": "cases/645637317f94762ec7849484/externallmg_1683527746032_IMG_20230507_2113.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "645898437f94762ec7853881",
      "name": "externallmg_1683527746035_IMG_20230507_20739.jpg",
      "path": "cases/645637317f94762ec7849484/externallmg_1683527746035_IMG_20230507_20739.jpg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [
    {
      "status": false,
      "_id": "645898437f94762ec7853883",
      "name": "externallmg_r_1683527746039_IMG20230507103539.jpg",
      "path": "cases/645637317f94762ec7849484/externallmg_r_1683527746039_IMG20230507103539.jpg",
      "orientation": "landscape"
    }
  ]
}
```

```
}
],
"compositionImages": [
  {
    "status": false,
    "_id": "64589a687f94762ec7853f30",
    "path": "cases/645637317f94762ec7849484/
compositionImg_1683527992411_IMG_20230507_2338.jpg",
    "orientation": "landscape",
    "name": "Bedroom"
  },
  {
    "status": false,
    "_id": "64589a687f94762ec7853f31",
    "path": "cases/645637317f94762ec7849484/
compositionImg_1683528014145_IMG_20230507_24491.jpg",
    "orientation": "portrait",
    "name": "Kitchen"
  },
  {
    "status": false,
    "_id": "64589a687f94762ec7853f32",
    "path": "cases/645637317f94762ec7849484/
compositionImg_1683528054489_IMG_20230507_252.jpg",
    "orientation": "portrait",
    "name": "Living Room"
  },
  {
    "status": false,
    "_id": "64589a687f94762ec7853f33",
    "path": "cases/645637317f94762ec7849484/
compositionImg_1683528101424_IMG_20230507_23914.jpg",
    "orientation": "portrait",
    "name": "Passage"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
```



```
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": true,
"CHECKER": true,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "320.98",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"status": true,
"caseStatus": "REPORTGENERATED",
"_id": "645637317f94762ec7849484",
"ownerName": "Rajkiran Shivprasad Tandekar ",
"ownerPhoneNo": "9082267949",
"appAddress": "Flat no. 105, 1st Floor, Building no. L 09, Sector 27, Taloja Navi
Mumbai ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "CIDCO Allotment Letter",
      "value": "60ae1258aa6d152c1801b33b"
    },
    "inputs": {
      "documentDate": "09/09/2019",
      "nameOfApprovingAuthority": {
        "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
        "label": "City and Industrial Development Corp Of Maharashtra Ltd."
      }
    }
  },
  {
    "isHardCopy": false,
```

```
"displayStatus": true,
"id": "345903",
"path": "cases/645637317f94762ec7849484/
document_1683371792803_Racpc_Sion_Rajkiran_Tandekar.pdf",
"fileName": "document_1683371792803_Racpc_Sion_Rajkiran_Tandekar.pdf"
},
{
  "documentType": {
    "value": "60ae1246aa6d152c1801b2e4",
    "label": "Index- II"
  },
  "inputs": {
    "documentDate": "02/12/2021",
    "from": {
      "value": "The_Corporation",
      "label": "The Corporation"
    },
    "The_Corporation": "CIDCO",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mr. Rajkiran Shivprasad Tandekar",
    "number": {
      "value": "Registration_No",
      "label": "Registration No"
    },
    "Registration_No": "16642/2021"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1683528954919_Agreement.pdf",
  "path": "cases/645637317f94762ec7849484/
document_1683528954919_Agreement.pdf",
  "id": "271634",
  "uploadedBy": "627208c1afd7d55eddedc372",
  "createdAt": "Mon May 08 2023 12:32:06 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "02/12/2021",
    "nameOfApprovingAuthority": {
```

```
    "value": "CIDCO",
    "label": "CIDCO"
  },
  "from": {
    "value": "The_Corporation",
    "label": "The Corporation"
  },
  "The_Corporation": "CIDCO",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mr. Rajkiran Shivprasad Tandekar",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "16642/2021"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1683529038895_Agreement.pdf",
"path": "cases/645637317f94762ec7849484/
document_1683529038895_Agreement.pdf",
"id": "925519",
"uploadedBy": "627208c1afd7d55eddedc372",
"createdAt": "Mon May 08 2023 12:32:06 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "02/11/2021",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CIDCO/Sr.Arch(BP-IHP)/BP-IHP-32/2021/000033"
  },
  "isHardCopy": false,
```

```
    "displayStatus": true,
    "fileName": "document_1683529150585_Agreement.pdf",
    "path": "cases/645637317f94762ec7849484/
document_1683529150585_Agreement.pdf",
    "id": "432202",
    "uploadedBy": "627208c1afd7d55eddedc372",
    "createdAt": "Mon May 08 2023 12:32:06 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "6077c791395bc80714864a30",
      "label": "Electricity Bill"
    },
    "inputs": {
      "documentDate": "27/12/2021",
      "to": {
        "value": "Flatholder",
        "label": "Flatholder"
      },
      "Flatholder": "Mr. Rajkiran Shivprasad Tandekar ",
      "number": {
        "value": "Consumer_No",
        "label": "Consumer No"
      },
      "Consumer_No": "028611213427"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "path": "cases/645637317f94762ec7849484/
document_1683529313842_2974611.pdf",
    "id": "349211",
    "uploadedBy": "627208c1afd7d55eddedc372",
    "createdAt": "Mon May 08 2023 12:32:06 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "001456",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "669125",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat May 06 2023 16:47:05 GMT+0530 (India Standard Time)"
  }
],
"owners": [
```

```
{
  "name": "Rajkiran Shivprasad Tandekar ",
  "phone": "9082267949",
  "email": "",
  "ownershipShare": "",
  "id": "769040"
}
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "6",
    "name": "Bedroom",
    "length": "",
    "length1": "9",
    "length2": "9",
    "width": "",
    "width1": "9",
    "width2": "5",
    "totalArea": "91.81",
    "images": [
      {
        "path": "cases/645637317f94762ec7849484/
compositionImg_1683527992411_IMG_20230507_2338.jpg",
        "orientation": "landscape"
      }
    ],
    "finalArea": "102.7",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "6",
    "name": "Kitchen",
    "length": "",
    "length1": "12",
    "length2": "3",
    "width": "",
    "width1": "6",
```

```
"width2": "8",
"totalArea": "81.67",
"images": [
  {
    "path": "cases/645637317f94762ec7849484/
compositionImg_1683528014145_IMG_20230507_24491.jpg",
    "orientation": "portrait"
  }
],
"finalArea": "81.67",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Living Room",
  "length": "",
  "length1": "10",
  "length2": "3",
  "width": "",
  "width1": "12",
  "width2": "3",
  "totalArea": "125.56",
  "images": [
    {
      "path": "cases/645637317f94762ec7849484/
compositionImg_1683528054489_IMG_20230507_252.jpg",
      "orientation": "portrait"
    }
  ],
  "finalArea": "135.13",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "",
  "length1": "3",
  "length2": "11",
```

```
"width": "",
"width1": "3",
"width2": "11",
"totalArea": "15.34",
"images": [
  {
    "path": "cases/645637317f94762ec7849484/
compositionImg_1683528101424_IMG_20230507_23914.jpg",
    "orientation": "portrait"
  }
],
"finalArea": "15.34",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "WC",
  "length": "",
  "length1": "4",
  "length2": "10",
  "width": "",
  "width1": "3",
  "width2": "10",
  "totalArea": "18.53",
  "images": [
    {
      "path": "cases/645637317f94762ec7849484/
compositionImg_1683528122053_IMG_20230507_23555.jpg",
      "orientation": "portrait"
    }
  ],
  "finalArea": "18.53",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bathroom",
  "length": "",
```

```
"length1": "4",
"length2": "9",
"width": "",
"width1": "3",
"width2": "9",
"totalArea": "17.81",
"images": [
  {
    "path": "cases/645637317f94762ec7849484/
compositionImg_1683528150281_IMG_20230507_23314.jpg",
    "orientation": "portrait"
  }
],
"finalArea": "17.81",
"extraAreas": []
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "value": "Niche",
      "label": "Niche"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "length1": "5",
    "length2": "5",
    "length": "5.42",
    "width1": "2",
    "width2": "2",
    "width": "2.17",
    "totalArea": "11.74",
    "percentageBeforeTotal": "11.74",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "11.74"
  },
  {
```



```
"toBeAdded": {
  "label": "Carpet",
  "value": "Carpet"
},
"name": {
  "value": "Niche",
  "label": "Niche"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "1",
"length1": "4",
"length2": "9",
"length": "4.75",
"width1": "2",
"width2": "4",
"width": "2.33",
"totalArea": "11.08",
"percentageBeforeTotal": "11.08",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "11.08"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "CIDCO Allotment Letter",
    "value": "60ae1258aa6d152c1801b33b"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "774753",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "321",
  "squareMeterArea": "29.82",
  "docFinalBuiltUp": "353.1",
  "docFinalBuiltUpSquareMeter": "32.802",
  "docBuiltupPercentage": "10",
  "docSaleablePercentage": "0",
```

```
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "64588eb87f94762ec7851c1f",
  "id": "1",
  "property": "Taloja Sector 27",
  "area": "250",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "8",
  "source": "https://www.99acres.com/",
  "expectedPrice": "2500000",
  "expectedRate": "10000.00",
  "builtUpExpectedRate": "9090.91",
  "image": "cases/645637317f94762ec7849484/
indicator_1683525304644_Image.png"
},
{
  "printlnReport": true,
  "_id": "64588ee17f94762ec7851ce4",
  "id": "2",
  "property": "Taloja Sector 27",
  "area": "280",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "3",
  "source": "https://www.99acres.com/",
  "expectedPrice": "3200000",
  "expectedRate": "11428.57",
  "builtUpExpectedRate": "10389.61",
  "image": "cases/645637317f94762ec7849484/
indicator_1683525345073_Image.png"
},
{
  "printlnReport": true,
  "_id": "64588ee17f94762ec7851ce5",
  "id": "3",
```

```
"property": "Taloja Sector 27",
"area": "280",
"builtUpPercentage": "10",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "3",
"source": "https://www.99acres.com/",
"expectedPrice": "3200000",
"expectedRate": "11428.57",
"builtUpExpectedRate": "10389.61",
"image": "cases/645637317f94762ec7849484/
indicator_1683525345577_Image.png"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "645898437f94762ec7853880",
"name": "externallmg_1683527746032_IMG_20230507_2113.jpg",
"path": "cases/645637317f94762ec7849484/
externallmg_1683527746032_IMG_20230507_2113.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "645898437f94762ec7853881",
"name": "externallmg_1683527746035_IMG_20230507_20739.jpg",
"path": "cases/645637317f94762ec7849484/
externallmg_1683527746035_IMG_20230507_20739.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "645898437f94762ec7853882",
"name": "externallmg_1683527746298_IMG_20230507_1917.jpg",
"path": "cases/645637317f94762ec7849484/
externallmg_1683527746298_IMG_20230507_1917.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
```

```
    "_id": "645898437f94762ec7853883",
    "name": "externalimg_r_1683527746039_IMG20230507103539.jpg",
    "path": "cases/645637317f94762ec7849484/
externalimg_r_1683527746039_IMG20230507103539.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64589a687f94762ec7853f2f",
    "name": "externalimg_1683528296321_IMG_20230507_22216.jpg",
    "path": "cases/645637317f94762ec7849484/
externalimg_1683528296321_IMG_20230507_22216.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"createdAt": "2023-05-06T11:17:05.048Z",
"updatedAt": "2023-05-08T10:50:02.338Z",
"__v": 0,
"fullAddress": "Residential Flat No. 105, 1st Floor, Building No L09, Mass Housing
Scheme (General), Sector 27, Village - Taloja, Taluka - Panvel, District - Raigad, Navi
Mumbai, 410208, State - Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Rajkiran Tandekar ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9082267949",
"reason": "",
"siteVisitDate": "2023-05-07",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + WC +
Bathroom",
"carpetTotal": "371.18",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "11.08",
"buildingServicesRate": "2700",
"flatRate": "10000",
"landOtherRate": "7300",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "22.82",
```

"otherCompositionSaleableTotal": "0.00",
 "builtupPercentage": "10",
 "finalBuiltupArea": "433.40",
 "finalCarpetArea": "394.00",
 "finalSalableArea": "476.74",
 "salablePercentage": "10",
 "toBeAdded": "",
 "extendOfSiteRemark": "",
 "siteMeasurementRemark": "",
 "finalAreaType": "Carpet Area",
 "finalAsPerArea": "CIDCO Allotment Letter",
 "finalBuiltUpPercentage": "10",
 "finalCarpetConvertToBuiltUpPer": "10",
 "finalSaleablePercentage": "0",
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 320.98"

Name	Length	Width	Total
Composition :			
Bedroom	9'9"	9'5"	91.81
Kitchen	12'3"	6'8"	81.67
Living Room	10'3"	12'3"	125.56
Passage	3'11"	3'11"	15.34
WC	4'10"	3'10"	18.53
Bathroom	4'9"	3'9"	17.81
Other Composition :			
Niche	5'5"	2'2"	11.74
Niche	4'9"	2'4"	11.08