

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd93aace84bf289baab038",
    "firstName": "Pranjli ",
    "lastName": "Prabhu",
    "mobileNo": "",
    "workMobileNo": "9969957108",
    "email": "pranjli.prabhu@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Pranjli ",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1 6th Floor, Kiro Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
    "lastName": "Velonde",
    "mobileNo": "8691048846",
```

```
    "shortName": "SSV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60b7177d2ffdf65bcd65882a\
\profilePhoto_1622701681508_WhatsApp Image 2021-06-02 at 11.09.24 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f9343b45132d6a6bdd96e8",
    "role": "SITEENGINEER",
    "firstName": "RAJESH",
    "email": "rajeshb.ghadi@gmail.com",
    "lastName": "GHADI",
    "mobileNo": "8652092666",
    "designation": "",
    "shortName": "RHG",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER+CHECKER",
    "firstName": "Nitesh",
    "email": "nitesh.khedekar@vastukala.org",
    "lastName": "Khedekar",
    "mobileNo": "8369040652",
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER+CHECKER",
    "firstName": "Nitesh",
    "email": "nitesh.khedekar@vastukala.org",
    "lastName": "Khedekar",
    "mobileNo": "8369040652",
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "checker": {
```

```
"type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    }
  }
]
```

```
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "18.975170461062675",
  "longitude": "73.11489873442395"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.11489873442395,
    18.975170461062675
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-05-11"
    }
  ]
}
```

```
    }
  ],
  "schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Wed May 10 2023 10:53:59 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Karanjade",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "10",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
  }
}
```

```
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "30",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": true,
```

```
"name": "Sector",
"key": "selectArea",
"value": "5A",
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "Divya Heights",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
}
```



```
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1001",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
```

```
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
}
```

```
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood / Glass Door",
    "value": "Teak_Wood_/ _Glass_Door"
  },
  "windows": {
    "label": "Alluminum sliding windows with M. S. Grills",
    "value": "Alluminum_sliding_windows_with_M._S._Grills"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring",
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring"
  },
  "finishing": {
    "label": "Cement Plastering + POP Finish",
    "value": "Cement_Plastering+_POP_Finish"
  }
},
"general": {
  "populationClassList": {
    "label": "Upper Class",
    "value": "UpperClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "As per CIDCO norms",
    "value": "As_per_CIDCO_norms"
  },
  "asPerActualAgreement": {
    "north": "ROAD",
    "south": "Canra Bank",
    "east": "Skyline Height",
    "west": "Keshavkunj"
```

```
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "I Class",
    "value": "I_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Vacant",
    "value": "Vacant"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Open Parking",
    "value": "Open_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
```

```
"month": "1",
"year": "2019",
"fullDate": "1/1/2019"
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
},
"qualityOfConstruction": {
  "label": "Excellent",
  "value": "Excellent"
},
},
"walls": {
  "label": "Yes",
  "value": "1"
},
},
"appearanceOfTheBuilding": {
  "label": "Excellent",
  "value": "Excellent"
},
},
"maintenanceOfTheBuilding": {
  "label": "Excellent",
  "value": "Excellent"
},
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
},
"isSiteVisitAllowed": true,
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
```

```
"totalLifeBuilding": "60",
"ageOfBuilding": "4",
"estimatedAge": "56",
"noOfFloors": "013",
"noOfDwellingUnitsInBuilding": "04",
"noOfLifts": "02"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```



```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
},
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```

```
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "645b209a7f94762ec786da33",
"ownerName": "Kanchan Sandeep Patil",
"ownerPhoneNo": "8999250807",
"appAddress": "Flat no. 1001, 10th Floor, Divya Heights, Plot no. 30, Sector 5A,
Karnjade, Panvel",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "02/05/2023",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Usha Ajay Patel",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Kanchan Sandeep Patil"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "id": "800631",
    "path": "cases/645b209a7f94762ec786da33/
document_1683693691510_sandip_patil_agreemnt_new.pdf",
    "fileName": "document_1683693691510_sandip_patil_agreemnt_new.pdf"
  }
],
"caseNumber": "001494",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "110354",
    "title": "Create Lead",
    "description": "Create Lead",
```

```
"datetime": "Wed May 10 2023 10:12:02 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
  "name": "Kanchan Sandeep Patil",
  "phone": "8999250807",
  "ownershipShare": "",
  "email": "",
  "id": "844306"
}
],
"siteInspection": [
{
  "areaType": {
    "label": "Saleable",
    "value": "Saleable"
  },
  "providedBy": {
    "label": "Other",
    "value": "Other"
  },
  "_id": "645c557d7f94762ec787c740",
  "area": "698",
  "providedByName": "MR BHUSHAN DOKE",
  "providedByContactNo": "091465 531"
}
],
"composition": [
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "620547",
  "name": "Bedroom",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "11.00",
  "width1": "11",
  "width2": "00",
  "totalArea": "99.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "99.00"
}
]
```

```
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "6.92",
  "length1": "6",
  "length2": "11",
  "width": "2.83",
  "width1": "2",
  "width2": "10",
  "totalArea": "19.60",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.60"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "WC",
  "length": "2.83",
  "length1": "2",
  "length2": "10",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "10.86",
  "images": [],
  "extraAreas": [],
  "finalArea": "10.86"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Bathroom",
  "length": "4.83",
  "length1": "4",
```

```
"length2": "10",
"width": "3.83",
"width1": "3",
"width2": "10",
"totalArea": "18.53",
"images": [],
"extraAreas": [],
"finalArea": "18.53"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "6.83",
  "width1": "6",
  "width2": "10",
  "totalArea": "52.96",
  "images": [],
  "extraAreas": [],
  "finalArea": "52.96"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Living Room",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "16.25",
  "width1": "16",
  "width2": "3",
  "totalArea": "146.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "146.25"
},
{
```

```
"measurementType": {
  "label": "Square Feet",
  "value": "Square_Feet"
},
"id": "6",
"name": "Passage",
"length": "1.67",
"length1": "1",
"length2": "8",
"width": "4.00",
"width1": "4",
"width2": "00",
"totalArea": "6.67",
"images": [],
"extraAreas": [],
"finalArea": "6.67"
}
],
"otherComposition": [
{
  "name": {
    "label": "Terrace",
    "value": "Terrace"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "0",
  "length1": "5",
  "length2": "00",
  "length": "5.00",
  "width1": "9",
  "width2": "00",
  "width": "9.00",
  "totalArea": "45.00",
  "percentageBeforeTotal": "45.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "45"
},
{
  "name": {
    "label": "Flower Bed Area",
    "value": "Flower_Bed_Area"
```



```
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "length1": "2",
    "length2": "00",
    "length": "2.00",
    "width1": "9",
    "width2": "00",
    "width": "9.00",
    "totalArea": "18.00",
    "percentageBeforeTotal": "18.00",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "18"
  },
  {
    "name": {
      "label": "Flower Bed Area",
      "value": "Flower_Bed_Area"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "2",
    "length1": "1",
    "length2": "8",
    "length": "1.67",
    "width1": "6",
    "width2": "10",
    "width": "6.83",
    "totalArea": "11.39",
    "percentageBeforeTotal": "11.39",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "11.39"
  }
],
"externalReport": [],
"documentPerArea": [],
"images": [],
```

```
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "645c53ad7f94762ec787c684",
    "name": "externallmg_1683772326091_1683772221494_image_0.jpeg",
    "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772326091_1683772221494_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "645c53ad7f94762ec787c685",
    "name": "externallmg_1683772326115_1683772221494_image_1.jpeg",
    "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772326115_1683772221494_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "645c53ad7f94762ec787c686",
    "name": "externallmg_1683772326185_1683772221494_image_2.jpeg",
    "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772326185_1683772221494_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "645c53ad7f94762ec787c687",
    "name": "externallmg_1683772326205_1683772221494_image_3.jpeg",
    "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772326205_1683772221494_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "645c53ad7f94762ec787c688",
    "name": "externallmg_1683772326240_1683772221494_image_4.jpeg",
    "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772326240_1683772221494_image_4.jpeg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "645c53ad7f94762ec787c689",
      "name": "externallmg_1683772326275_1683772221494_image_5.jpeg",
      "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772326275_1683772221494_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "645c53ad7f94762ec787c68a",
      "name": "externallmg_1683772328852_1683772221494_image_6.jpeg",
      "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772328852_1683772221494_image_6.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "645c53ad7f94762ec787c68b",
      "name": "externallmg_1683772328852_1683772221494_image_7.jpeg",
      "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772328852_1683772221494_image_7.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "645c53ad7f94762ec787c68c",
      "name": "externallmg_1683772328853_1683772221494_image_8.jpeg",
      "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772328853_1683772221494_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "645c53ad7f94762ec787c68d",
      "name": "externallmg_1683772328854_1683772221494_image_9.jpeg",
      "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772328854_1683772221494_image_9.jpeg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "645c53ad7f94762ec787c68e",
  "name": "externallmg_1683772328855_1683772221494_image_10.jpeg",
  "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772328855_1683772221494_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "645c53ad7f94762ec787c68f",
  "name": "externallmg_1683772328855_1683772221494_image_11.jpeg",
  "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772328855_1683772221494_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "645c53ad7f94762ec787c690",
  "name": "externallmg_1683772330165_1683772221494_image_12.jpeg",
  "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772330165_1683772221494_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "645c53ad7f94762ec787c691",
  "name": "externallmg_1683772330205_1683772221494_image_13.jpeg",
  "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772330205_1683772221494_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "645c53ad7f94762ec787c692",
  "name": "externallmg_1683772330225_1683772221494_image_14.jpeg",
  "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772330225_1683772221494_image_14.jpeg",
  "orientation": "portrait"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "645c53ad7f94762ec787c693",
"name": "externallmg_1683772330495_1683772221494_image_15.jpeg",
"path": "cases/645b209a7f94762ec786da33/
externallmg_1683772330495_1683772221494_image_15.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "645c53ad7f94762ec787c694",
"name": "externallmg_1683772293396_1683772189134_image_0.jpeg",
"path": "cases/645b209a7f94762ec786da33/
externallmg_1683772293396_1683772189134_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "645c53ad7f94762ec787c695",
"name": "externallmg_1683772293466_1683772189134_image_1.jpeg",
"path": "cases/645b209a7f94762ec786da33/
externallmg_1683772293466_1683772189134_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "645c53ad7f94762ec787c696",
"name": "externallmg_1683772293550_1683772189134_image_2.jpeg",
"path": "cases/645b209a7f94762ec786da33/
externallmg_1683772293550_1683772189134_image_2.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "645c53ad7f94762ec787c697",
"name": "externallmg_1683772293580_1683772189134_image_3.jpeg",
"path": "cases/645b209a7f94762ec786da33/
externallmg_1683772293580_1683772189134_image_3.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "645c53ad7f94762ec787c698",
  "name": "externallmg_1683772293640_1683772189134_image_4.jpeg",
  "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772293640_1683772189134_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "645c53ad7f94762ec787c699",
  "name": "externallmg_1683772293680_1683772189134_image_5.jpeg",
  "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772293680_1683772189134_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "645c53ad7f94762ec787c69a",
  "name": "externallmg_1683772296708_1683772189134_image_6.jpeg",
  "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772296708_1683772189134_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "645c53ad7f94762ec787c69b",
  "name": "externallmg_1683772296709_1683772189134_image_7.jpeg",
  "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772296709_1683772189134_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "645c53ad7f94762ec787c69c",
  "name": "externallmg_1683772296709_1683772189134_image_8.jpeg",
  "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772296709_1683772189134_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "645c53ad7f94762ec787c69d",
    "name": "externallmg_1683772296710_1683772189134_image_9.jpeg",
    "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772296710_1683772189134_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "645c53ad7f94762ec787c69e",
    "name": "externallmg_1683772296711_1683772189134_image_10.jpeg",
    "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772296711_1683772189134_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "645c53ad7f94762ec787c69f",
    "name": "externallmg_1683772296712_1683772189134_image_11.jpeg",
    "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772296712_1683772189134_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "645c53ad7f94762ec787c6a0",
    "name": "externallmg_1683772298390_1683772189134_image_12.jpeg",
    "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772298390_1683772189134_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "645c53ad7f94762ec787c6a1",
    "name": "externallmg_1683772298430_1683772189134_image_13.jpeg",
    "path": "cases/645b209a7f94762ec786da33/
externallmg_1683772298430_1683772189134_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "645c53ad7f94762ec787c6a2",
```

```

    "name": "externalImg_1683772298456_1683772189134_image_14.jpeg",
    "path": "cases/645b209a7f94762ec786da33/
externalImg_1683772298456_1683772189134_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "645c53ad7f94762ec787c6a3",
    "name": "externalImg_1683772298720_1683772189134_image_15.jpeg",
    "path": "cases/645b209a7f94762ec786da33/
externalImg_1683772298720_1683772189134_image_15.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-05-10T04:42:02.217Z",
"updatedAt": "2023-05-11T02:40:49.050Z",
"__v": 0,
"fullAddress": "Residential Flat No. 1001, 10th Floor, Wing - Divya Heights, Plot No.
30, Sector 5A, Village - Karanjade, Navi Mumbai, State - Maharashtra, India",
"updatedBy": "60f9343b45132d6a6bdd96e8",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Kanchan Sandeep Patil",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8999250807",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Passage + WC +
Bathroom",
"carpetTotal": "353.87",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "74.39"
}

```

Name	Length	Width	Total
Composition :			
Bedroom	9'00"	11'00"	99.00
Passage	6'11"	2'10"	19.60

WC	2'10"	3'10"	10.86
Bathroom	4'10"	3'10"	18.53
Kitchen	7'9"	6'10"	52.96
Living Room	9'00"	16'3"	146.25
Passage	1'8"	4'00"	6.67
Other Composition :			
Terrace	5'00"	9'00"	45.00
Flower Bed Area	2'00"	9'00"	18.00
Flower Bed Area	1'8"	6'10"	11.39