

```
{
  "typeOfReport": {
    "label": "Land",
    "value": "Land"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Market Value",
    "value": "Market_Value"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b263d9191f7b344b008894"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b75",
    "email": "abk@sbi.co.in",
    "firstName": "ABHISHEK",
    "mobileNo": "",
    "workMobileNo": "9920665690",
    "lastName": " KUMAR"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "ABHISHEK KUMAR",
    "expectedFees": 5000,
    "quotedAmount": "15000"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b263d9191f7b344b008894",
  "name": "COMMERCIAL BRANCH PM ROAD FORT",
  "branchCode": "",
  "mobileNo": "022-22624308",
  "alternateMobileNo": "",
  "email": "sbi.60113@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Gresham House, Sir P. M. Road Branch, Fort, \nMumbai - 400 001, State
- Maharashtra, Country - India."
},
"assetsClass": {
  "value": "Land_ & Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Commercial",
  "label": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": ""
  }
}
```

```
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "RAJESH",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "GHADI",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
```

```
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "0123456789",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
  "valuersRegistrationNumber": [
    {
      "value": "IBBI/RV/07/2018/10366",
      "label": "Registered Valuer"
    }
  ],
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
```

```
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.030760558296276",
  "longitude": "73.10035879602222"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.10035879602222,
    19.030760558296276
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-05-18"
    }
  ]
},
],
```

```
"schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Wed May 17 2023 14:07:00 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kalamboli",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
}
```

```
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "1533",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
```

```
"value": "KWC",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Road No 17",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
```



```
"status": false,
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
```

```
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
```

```

"roof": {
  "label": "Proposed RCC SLab",
  "value": "Proposed_RCC_SLab"
},
"flooring": {
  "label": "Ceramic Tile Flooring",
  "value": "CeramicTileFlooring"
},
"doors": {
  "label": "Proposed Teak wood door frame with flush doors",
  "value": "Proposed_Teak_wood_door_frame_with_flush_doors"
},
"windows": {
  "label": "Proposed Powder coated aluminium sliding windows",
  "value": "Proposed_Powder_coated_aluminium_sliding_windows"
},
"fittings": {
  "label": "Open-Conduit plumbing with Casing Capping Electrical wiring ",
  "value": "Open-Conduit_plumbing_with_Casing_Capping_Electrical_wiring_"
},
"finishing": {
  "label": "Proposed Cement Plastering",
  "value": "Proposed_Cement_Plastering"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "asPerActualAgreement": {
    "north": "PLOT NO 1535",
    "south": "P No 1532",
    "east": "P NO 1560",
    "west": "Road"
  },
  "asPerDocumentAgreement": {
    "north": "",

```

```
"west": "",
"south": "",
"east": ""
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Commercial use",
    "value": "Commercial_use"
  },
  "propertyOccupiedByList": {
    "label": "Tenant Occupied",
    "value": "Tenant_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "pavementLaid": {
    "label": "Proposed, Yes",
    "value": "Proposed,_Yes"
  },
  "carParking": {
    "label": "Open Parking",
    "value": "Open_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2010",
    "fullDate": "1/1/2010"
  }
}
```

```
},
"propertyTypeList": {
  "value": "Commercial",
  "label": "Commercial"
},
"planningArea": {
  "value": "Commercial",
  "label": "Commercial"
},
"typeOfStructure": {
  "label": "Proposed RCC Slab",
  "value": "Proposed_RCC_Slab"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "PROPOSED, Yes",
  "value": "PROPOSED,_Yes"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "0",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "0",
```

```
"totalLifeBuilding": "60",
"ageOfBuilding": "13",
"estimatedAge": "47"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```



```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
```

```
"title": "Potential value, if any",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "PARTIAL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
```

```
"empanelmentNo": [],
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "64648d63ee6a9735bf794f07",
"ownerName": "Jevil Vinodkumar Shah",
"ownerPhoneNo": "9930192923",
"appAddress": "Plot no 1533&1534 .Road No 17,Sector KWC.Kalamboli Navi Mumbai
",
"remark": "Site cont Person No 082914 38430\n099301 92923\nDocuments check
vaishali madam ",
"documents": [
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "isHardCopy": false,
  "path": "cases/64648d63ee6a9735bf794f07/
document_1684311076572_Plot_No1533_Purchase_Agreement.pdf",
  "fileName": "document_1684311076572_Plot_No1533_Purchase_Agreement.pdf",
  "displayStatus": false,
  "id": "638813",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Wed May 17 2023 13:46:25 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "isHardCopy": false,
  "path": "cases/64648d63ee6a9735bf794f07/
document_1684311133131_kalamboli_plot15341535.pdf",
  "fileName": "document_1684311133131_kalamboli_plot15341535.pdf",
  "displayStatus": false,
  "id": "528264",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Wed May 17 2023 13:46:25 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "mortgage NOC",
    "value": "60ae12aeaa6d152c1801b4c7"
  },
  "isHardCopy": false,
  "path": "cases/64648d63ee6a9735bf794f07/
document_1684311311184_1533_MORGAGE_NOC.PDF",
```

```
"fileName": "document_1684311311184_1533_MORGAGE_NOC.PDF",
"displayStatus": false,
"id": "126394",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Wed May 17 2023 13:46:25 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "mortgage NOC",
    "value": "60ae12aeaa6d152c1801b4c7"
  },
  "isHardCopy": false,
  "path": "cases/64648d63ee6a9735bf794f07/
document_1684311327636_1534_MORGAGE_NOC.PDF",
  "fileName": "document_1684311327636_1534_MORGAGE_NOC.PDF",
  "displayStatus": false,
  "id": "872329",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Wed May 17 2023 13:46:25 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "001607",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "713744",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed May 17 2023 13:46:35 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Jevil Vinodkumar Shah",
    "phone": "9930192923",
    "ownershipShare": "",
    "email": "",
    "id": "445425"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Saleable",
      "value": "Saleable"
    }
  },
]
```

```
"providedBy": {
  "label": "Owner",
  "value": "Owner"
},
"_id": "6465bb9eee6a9735bf79bd87",
"area": "900",
"providedByName": "Jevil Vinodkumar Shah",
"providedByContactNo": "9930192923"
}
],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991a3",
    "name": "externalImg_1684378021607_1684377923847_image_0.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externalImg_1684378021607_1684377923847_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991a4",
    "name": "externalImg_1684378021672_1684377923847_image_1.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externalImg_1684378021672_1684377923847_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991a5",
    "name": "externalImg_1684378021727_1684377923847_image_2.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externalImg_1684378021727_1684377923847_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "646591a8ee6a9735bf7991a6",
    "name": "externallmg_1684378021776_1684377923847_image_3.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378021776_1684377923847_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991a7",
    "name": "externallmg_1684378021826_1684377923847_image_4.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378021826_1684377923847_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991a8",
    "name": "externallmg_1684378021876_1684377923847_image_5.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378021876_1684377923847_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991a9",
    "name": "externallmg_1684378021937_1684377923847_image_6.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378021937_1684377923847_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991aa",
    "name": "externallmg_1684378021981_1684377923847_image_7.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378021981_1684377923847_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "646591a8ee6a9735bf7991ab",
    "name": "externallmg_1684378022016_1684377923847_image_8.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378022016_1684377923847_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991ac",
    "name": "externallmg_1684378022061_1684377923847_image_9.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378022061_1684377923847_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991ad",
    "name": "externallmg_1684378022328_1684377923847_image_10.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378022328_1684377923847_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991ae",
    "name": "externallmg_1684378022376_1684377923847_image_11.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378022376_1684377923847_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991af",
    "name": "externallmg_1684378022460_1684377923847_image_12.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378022460_1684377923847_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991b0",
```



```
    "name": "externallmg_1684378022491_1684377923847_image_13.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378022491_1684377923847_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991b1",
    "name": "externallmg_1684378022546_1684377923847_image_14.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378022546_1684377923847_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991b2",
    "name": "externallmg_1684378022621_1684377923847_image_15.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378022621_1684377923847_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646591a8ee6a9735bf7991b3",
    "name": "externallmg_1684378022686_1684377923847_image_16.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378022686_1684377923847_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646591a8ee6a9735bf7991b4",
    "name": "externallmg_1684378002880_1684377904379_image_0.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378002880_1684377904379_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646591a8ee6a9735bf7991b5",
    "name": "externallmg_1684378002927_1684377904380_image_1.jpeg",
```

```
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378002927_1684377904380_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646591a8ee6a9735bf7991b6",
    "name": "externallmg_1684378002976_1684377904380_image_2.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378002976_1684377904380_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646591a8ee6a9735bf7991b7",
    "name": "externallmg_1684378003036_1684377904380_image_3.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378003036_1684377904380_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646591a8ee6a9735bf7991b8",
    "name": "externallmg_1684378003086_1684377904380_image_4.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378003086_1684377904380_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646591a8ee6a9735bf7991b9",
    "name": "externallmg_1684378003133_1684377904380_image_5.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378003133_1684377904380_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646591a8ee6a9735bf7991ba",
    "name": "externallmg_1684378003181_1684377904380_image_6.jpeg",
    "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378003181_1684377904380_image_6.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646591a8ee6a9735bf7991bb",
  "name": "externallmg_1684378003216_1684377904381_image_7.jpeg",
  "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378003216_1684377904381_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646591a8ee6a9735bf7991bc",
  "name": "externallmg_1684378003251_1684377904381_image_8.jpeg",
  "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378003251_1684377904381_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646591a8ee6a9735bf7991bd",
  "name": "externallmg_1684378003301_1684377904381_image_9.jpeg",
  "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378003301_1684377904381_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646591a8ee6a9735bf7991be",
  "name": "externallmg_1684378003556_1684377904381_image_10.jpeg",
  "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378003556_1684377904381_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646591a8ee6a9735bf7991bf",
  "name": "externallmg_1684378003612_1684377904381_image_11.jpeg",
  "path": "cases/64648d63ee6a9735bf794f07/
externallmg_1684378003612_1684377904381_image_11.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "646591a8ee6a9735bf7991c0",
      "name": "externallmg_1684378003666_1684377904381_image_12.jpeg",
      "path": "cases/64648d63ee6a9735bf794f07/externallmg_1684378003666_1684377904381_image_12.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "646591a8ee6a9735bf7991c1",
      "name": "externallmg_1684378003701_1684377904381_image_13.jpeg",
      "path": "cases/64648d63ee6a9735bf794f07/externallmg_1684378003701_1684377904381_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "646591a8ee6a9735bf7991c2",
      "name": "externallmg_1684378003751_1684377904381_image_14.jpeg",
      "path": "cases/64648d63ee6a9735bf794f07/externallmg_1684378003751_1684377904381_image_14.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "646591a8ee6a9735bf7991c3",
      "name": "externallmg_1684378003821_1684377904381_image_15.jpeg",
      "path": "cases/64648d63ee6a9735bf794f07/externallmg_1684378003821_1684377904381_image_15.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "646591a8ee6a9735bf7991c4",
      "name": "externallmg_1684378003886_1684377904381_image_16.jpeg",
      "path": "cases/64648d63ee6a9735bf794f07/externallmg_1684378003886_1684377904381_image_16.jpeg",
      "orientation": "landscape"
    }
  ]
}
```

```
],
"externalDocuments": [],
"createdAt": "2023-05-17T08:16:35.561Z",
"updatedAt": "2023-05-18T05:46:06.632Z",
"__v": 0,
"fullAddress": " Land No. Basement Floor, Plot No. 1533, Sector KWC, Road No 17,
Village - Kalamboli, Navi Mumbai, State - Maharashtra, India",
"updatedAtBy": "60f9343b45132d6a6bdd96e8",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Jevil Vinodkumar Shah",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9930192923"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			