

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6410bda0319ffa48baa5636c"
    },
    "type": "CREDITOFFICER",
    "_id": "6410bda0319ffa48baa5636e",
    "firstName": "Borlar",
    "lastName": "Borlar",
    "mobileNo": "",
    "workMobileNo": "0000000000",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "3000"
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",

```

```
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d185c",
  "type": "BANK",
  "name": "SVC CO-OPERATIVE BANK LTD",
  "displayName": "SVC BANK",
  "initial": "SVC",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6410bda0319ffa48baa5636c",
  "name": "Koperkhairane Branch\t",
  "branchCode": "",
  "mobileNo": "02532455407",
  "alternateMobileNo": "",
  "email": "kopar@svc.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "FAM CHSL Shop no 5A to 9A Ground Floor , Plot no 19 & 19 A Sector
kperkhairane Navi Mumbai\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60fbaf81d8cfc56a13fa8863",
  "zoneName": "PAN INDIA"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62720e52afd7d55eddedc887",
    "role": "SITEENGINEER",
```

```
"firstName": "Harshad",
"email": "harshad@vastukala.org",
"lastName": "Panchal",
"mobileNo": "9029575553",
"shortName": "HP",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "RAJESH",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "GHADI",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PSH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
```

```
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.060953560453072",
  "longitude": "73.00231996441791"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
```

```
    "status": "COMPLETED",
    "dateTime": "2023-05-23"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-05-23"
  }
],
"schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Sat May 20 2023 13:37:11 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Sanpada",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  }
}
```

```
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "1",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
```

```
"key": "buildingName",
"value": "Nivasti Imperium",
"label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "19",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Palm Beach Road",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
}
```



```
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Shop No.15",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
```

```
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400 705",
  "label": false
},
"suburb": {
```

```
"status": false,
"name": "Suburb",
"key": "suburb",
"value": "",
"label": false
}
},
"flatSpecifications": {
"roof": {
"label": "R. C. C. Slab",
"value": "rcc_Slab"
},
"flooring": {
"label": "Vitrified Tile Flooring",
"value": "VerifiedTileFlooring"
},
"doors": {
"label": "Teal wood door frame with flush shutters",
"value": "Teal_wood_door_frame_with_flush_shutters"
},
"windows": {
"label": "Powder coated Aluminum sliding windows with M. S. Grills",
"value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills"
},
"fittings": {
"label": "Open Conduit Plumbing With Concealed Electrification",
"value": "Open_Conduit_Plumbing_With_Concealed_Electrification"
},
"finishing": {
"label": "Cement Plastering + POP Finish",
"value": "Cement_Plastering+_POP_Finish"
}
},
"general": {
"populationClassList": {
"label": "Higher Middle Class",
"value": "HigherMiddleClass"
},
"populationGroupList": {
"label": "Urban",
"value": "Urban"
},
"townplanApprovedByList": {
"label": "Navi Mumbai Municipal Corporation",
"value": "NMMC"
},
}
```

```
"asPerActualAgreement": {
  "north": "ROAD",
  "east": "BHOOMO CALESTA",
  "west": "ROAD",
  "south": "MAHAVIR AMRUT"
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "I Class",
    "value": "I_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Commercial use",
    "value": "Commercial_use"
  },
  "propertyOccupiedByList": {
    "label": "Vacant",
    "value": "Vacant"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Basement Parking",
    "value": "Basement_Parking"
  },
  "constructionWorkStatus": {
```

```
"label": "Completed",
"value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2010",
  "fullDate": "1/1/2010"
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Excellent",
  "value": "Excellent"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Excellent",
  "value": "Excellent"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
```

```
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "60",
"ageOfBuilding": "13",
"estimatedAge": "47",
"noOfBasement": "01",
"noOfFloors": "03",
"noOfDwellingUnitsInBuilding": "023",
"noOfLifts": "02"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```



```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
```

```
"title": "Extra collapsible gates / grill works etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
```

```
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "64687f8b46e69b7878ea06d5",
"ownerName": "Mrs. Bismillah Nasir Khan",
"ownerPhoneNo": "9920242439",
"fullAddress": " Flat No. Shop No.15, Ground Floor, Nivasti Imperium, Palm Beach
Road, Plot No. 1, Sector 19, Village - Sanpada, District - Thane, Navi Mumbai, 400 705,
State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "18/05/2023",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Mr. Abuzar Kabir",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mrs. Bismillah Nasir Khan"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "path": "cases/64687f8b46e69b7878ea06d5/document_undefined",
    "id": "877831",
    "uploadedBy": "6430f74691d7c62df11f3f15",
    "createdAt": "Sat May 20 2023 13:36:26 GMT+0530 (India Standard Time)",
    "fileName": "document_undefined"
  }
],
```

```
"caseNumber": "001660",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "776679",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat May 20 2023 13:36:35 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Bismillah Nasir Khan",
    "phone": "9920242439",
    "ownershipShare": "",
    "email": "",
    "id": "774036"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Saleable",
      "value": "Saleable"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "646c2c25b05e530fb6c36831",
    "area": "0",
    "providedByName": "Mrs. Bismillah Nasir Khan",
    "providedByContactNo": "9920242439"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "347224",
    "name": "Living Room",
    "length": "10.50",
    "length1": "10",
    "length2": "6",
```

```
"width": "24.08",
"width1": "24",
"width2": "1",
"totalArea": "252.87",
"images": [],
"extraAreas": [],
"finalArea": "252.87"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "646c2af6b05e530fb6c3674b",
"name": "externalImg_1684810482134_1684810263575_image_0.jpeg",
"path": "cases/64687f8b46e69b7878ea06d5/
externalImg_1684810482134_1684810263575_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "646c2af6b05e530fb6c3674c",
"name": "externalImg_1684810482136_1684810263575_image_1.jpeg",
"path": "cases/64687f8b46e69b7878ea06d5/
externalImg_1684810482136_1684810263575_image_1.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "646c2af6b05e530fb6c3674d",
"name": "externalImg_1684810482309_1684810263575_image_2.jpeg",
"path": "cases/64687f8b46e69b7878ea06d5/
externalImg_1684810482309_1684810263575_image_2.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "646c2af6b05e530fb6c3674e",
```

```
    "name": "externallmg_1684810482489_1684810263575_image_3.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810482489_1684810263575_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646c2af6b05e530fb6c3674f",
    "name": "externallmg_1684810482524_1684810263575_image_4.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810482524_1684810263575_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646c2af6b05e530fb6c36750",
    "name": "externallmg_1684810482569_1684810263575_image_5.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810482569_1684810263575_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646c2af6b05e530fb6c36751",
    "name": "externallmg_1684810482929_1684810263575_image_6.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810482929_1684810263575_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646c2af6b05e530fb6c36752",
    "name": "externallmg_1684810482954_1684810263575_image_7.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810482954_1684810263575_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646c2af6b05e530fb6c36753",
    "name": "externallmg_1684810482969_1684810263576_image_8.jpeg",
```

```
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810482969_1684810263576_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646c2af6b05e530fb6c36754",
    "name": "externallmg_1684810482989_1684810263576_image_9.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810482989_1684810263576_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646c2af6b05e530fb6c36755",
    "name": "externallmg_1684810483034_1684810263576_image_10.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810483034_1684810263576_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646c2af6b05e530fb6c36756",
    "name": "externallmg_1684810483054_1684810263576_image_11.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810483054_1684810263576_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646c2af6b05e530fb6c36757",
    "name": "externallmg_1684810483079_1684810263576_image_12.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810483079_1684810263576_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646c2af6b05e530fb6c36758",
    "name": "externallmg_1684810483114_1684810263576_image_13.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810483114_1684810263576_image_13.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646c2af6b05e530fb6c36759",
  "name": "externallmg_1684810483129_1684810263576_image_14.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810483129_1684810263576_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646c2af6b05e530fb6c3675a",
  "name": "externallmg_1684810483184_1684810263576_image_15.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810483184_1684810263576_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646c2af6b05e530fb6c3675b",
  "name": "externallmg_1684810483814_1684810263576_image_16.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810483814_1684810263576_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646c2af6b05e530fb6c3675c",
  "name": "externallmg_1684810483864_1684810263576_image_17.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810483864_1684810263576_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646c2af6b05e530fb6c3675d",
  "name": "externallmg_1684810484194_1684810263576_image_18.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810484194_1684810263576_image_18.jpeg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646c2af6b05e530fb6c3675e",
  "name": "externallmg_1684810484209_1684810263576_image_19.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810484209_1684810263576_image_19.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646c2af6b05e530fb6c3675f",
  "name": "externallmg_1684810458161_1684810235748_image_0.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810458161_1684810235748_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646c2af6b05e530fb6c36760",
  "name": "externallmg_1684810458161_1684810235748_image_1.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810458161_1684810235748_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646c2af6b05e530fb6c36761",
  "name": "externallmg_1684810458221_1684810235748_image_2.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810458221_1684810235748_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646c2af6b05e530fb6c36762",
  "name": "externallmg_1684810458280_1684810235748_image_3.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810458280_1684810235748_image_3.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646c2af6b05e530fb6c36763",
  "name": "externallmg_1684810458450_1684810235748_image_4.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810458450_1684810235748_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646c2af6b05e530fb6c36764",
  "name": "externallmg_1684810458655_1684810235748_image_5.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810458655_1684810235748_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646c2af6b05e530fb6c36765",
  "name": "externallmg_1684810459060_1684810235748_image_6.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810459060_1684810235748_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646c2af6b05e530fb6c36766",
  "name": "externallmg_1684810459090_1684810235748_image_7.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810459090_1684810235748_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646c2af6b05e530fb6c36767",
  "name": "externallmg_1684810459110_1684810235748_image_8.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810459110_1684810235748_image_8.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646c2af6b05e530fb6c36768",
    "name": "externallmg_1684810459140_1684810235748_image_9.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810459140_1684810235748_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646c2af6b05e530fb6c36769",
    "name": "externallmg_1684810459184_1684810235748_image_10.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810459184_1684810235748_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646c2af6b05e530fb6c3676a",
    "name": "externallmg_1684810459200_1684810235748_image_11.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810459200_1684810235748_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646c2af6b05e530fb6c3676b",
    "name": "externallmg_1684810459240_1684810235748_image_12.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810459240_1684810235748_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646c2af6b05e530fb6c3676c",
    "name": "externallmg_1684810459274_1684810235748_image_13.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810459274_1684810235748_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "646c2af6b05e530fb6c3676d",
  "name": "externallmg_1684810459290_1684810235748_image_14.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810459290_1684810235748_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646c2af6b05e530fb6c3676e",
  "name": "externallmg_1684810459364_1684810235748_image_15.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810459364_1684810235748_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646c2af6b05e530fb6c3676f",
  "name": "externallmg_1684810460450_1684810235748_image_16.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810460450_1684810235748_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646c2af6b05e530fb6c36770",
  "name": "externallmg_1684810460485_1684810235748_image_17.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810460485_1684810235748_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646c2af6b05e530fb6c36771",
  "name": "externallmg_1684810460595_1684810235748_image_18.jpeg",
  "path": "cases/64687f8b46e69b7878ea06d5/
externallmg_1684810460595_1684810235748_image_18.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```

    "_id": "646c2af6b05e530fb6c36772",
    "name": "externalimg_1684810460630_1684810235748_image_19.jpeg",
    "path": "cases/64687f8b46e69b7878ea06d5/
externalimg_1684810460630_1684810235748_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-05-20T08:06:35.480Z",
"updatedAt": "2023-05-23T03:00:54.079Z",
"__v": 0,
"addressForMap": "",
"caseReferredBy": "62720e52afd7d55eddedc887",
"contactPersonName": "Mrs. Bismillah Nasir Khan",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9920242439",
"updatedBy": "60f9343b45132d6a6bdd96e8",
"briefDescOfProperty": "Living Room",
"carpetTotal": "252.87",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"
}

```

Name	Length	Width	Total
Composition :			
Living Room	10'6"	24'1"	252.87
Other Composition :			