

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "type": "CREDITOFFICER",
    "_id": "635f7d78e363ef22db2f2888",
    "firstName": "Amita ",
    "lastName": "Patel",
    "mobileNo": "",
    "email": "me2@me.com",
    "workMobileNo": "8691048841"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3400000",
    "discussWithPerson": "Amita ",
    "expectedFees": 1700,
    "quotedAmount": "3000"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
    "mobileNo": "9167204055",
    "shortName": "RBK",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "RAJESH",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "GHADI",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER+CHECKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627208c1afd7d55eddedc372",
  "role": "SITEENGINEER+MAKAR",
  "firstName": "Aniket",
  "email": "aniket@vastukala.org",
  "lastName": "Navale",
  "mobileNo": "9892222307",
  "designation": "",
  "shortName": "AN",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
```

```
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER+CHECKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
```

```
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.97007798949242",
  "longitude": "73.02662617999515"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.02662617999515,
    18.97007798949242
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-06-07"
    }
  ]
}
```

```
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Mon Jun 05 2023 14:14:59 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Ulwe",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": false,
```

```
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shreeji Darshan",
  "label": false
}
```

```
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "19",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
```



```
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "307",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
}
```

```
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
```

```
"value": "",
"label": false
}
},
"flatSpecifications": {
"roof": {
"label": "R. C. C. Slab",
"value": "rcc_Slab"
},
"flooring": {
"label": "Vitrified Tile Flooring",
"value": "VerifiedTileFlooring"
},
"doors": {
"label": "Proposed Teak wood",
"value": "Proposed_Teak_wood"
},
"windows": {
"label": "Proposed Powder coated aluminium sliding windows",
"value": "Proposed_Powder_coated_aluminium_sliding_windows"
},
"fittings": {
"label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring",
"value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring"
},
"finishing": {
"label": "Proposed Cement Plastering",
"value": "Proposed_Cement_Plastering"
}
},
"general": {
"populationClassList": {
"label": "Middle Class",
"value": "MiddleClass"
},
"populationGroupList": {
"label": "Urban",
"value": "Urban"
},
"townplanApprovedByList": {
"label": "As per CIDCO norms",
"value": "As_per_CIDCO_norms"
},
"asPerActualAgreement": {
"north": "OPEN ",
"south": "open ",
```

```
"east": "OPEN ",
"west": "OPEN"
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "waterTank": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "pavementLaid": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "carParking": {
    "label": "Open Parking",
    "value": "Open_Parking"
  },
}
```

```
"constructionWorkStatus": {
  "label": "Under Construction",
  "value": "InProgress"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2024",
  "fullDate": "1/1/2024"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
```

```
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"appearanceOfTheBuilding": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"maintenanceOfTheBuilding": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "0",
"noOfPodium": "0",
```

```
"noOfAmenityFloors": "0",
"noOfFloors": "07",
"flatFloorNo": "3",
"noOfLifts": "01",
"noOfDwellingUnitsInBuilding": "07"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "InProgress",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```



```
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
```

```
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "647d8e280ab64c23c9fc15a3",
"ownerName": "Rashmi mhatre ",
"ownerPhoneNo": "9967302534",
"appAddress": "flat no 307 shreeji Darshan plot no 336 sector no 19 ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1685954686249_sbi_Rasmecc_panvel_Rashmi_mhatre_1.pdf",
    "path": "cases/647d8e280ab64c23c9fc15a3/
document_1685954686249_sbi_Rasmecc_panvel_Rashmi_mhatre_1.pdf",
    "id": "442917",
    "uploadedBy": "62691c48afd7d55eddecfda3",
    "createdAt": "Mon Jun 05 2023 14:14:51 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "001834",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "688673",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jun 05 2023 12:56:32 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Rashmi mhatre ",
    "phone": "9967302534",
    "ownershipShare": "",
    "email": "",
    "id": "777676"
  }
]
```

```
],
"siteInspection": [
  {
    "areaType": {
      "label": "Saleable",
      "value": "Saleable"
    },
    "providedBy": {
      "label": "Other",
      "value": "Other"
    },
    "_id": "648004d19bf7f73019a40200",
    "area": "630",
    "providedByName": "MR JADHAV",
    "providedByContactNo": "9004650021"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "460737",
    "name": "Kitchen",
    "length": "6.58",
    "length1": "6",
    "length2": "7",
    "width": "6.42",
    "width1": "6",
    "width2": "5",
    "totalArea": "42.24",
    "images": [],
    "extraAreas": [],
    "finalArea": "42.24"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Living Room",
    "length": "8.92",
    "length1": "8",
    "length2": "11",
```

```
"width": "13.08",
"width1": "13",
"width2": "1",
"totalArea": "116.66",
"images": [],
"extraAreas": [],
"finalArea": "116.66"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "4.50",
  "length1": "4",
  "length2": "6",
  "width": "2.92",
  "width1": "2",
  "width2": "11",
  "totalArea": "13.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.12"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "5.67",
  "length1": "5",
  "length2": "8",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "21.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.25"
},
{
  "measurementType": {
```

```
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "8.83",
  "length1": "8",
  "length2": "10",
  "width": "9.75",
  "width1": "9",
  "width2": "9",
  "totalArea": "86.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "86.12"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "4.83",
  "length1": "4",
  "length2": "10",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "18.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.12"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Flower Bed Area",
      "value": "Flower_Bed_Area"
    }
  },
  "measurementType": {
```



```
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "0",
  "length1": "6",
  "length2": "7",
  "length": "6.58",
  "width1": "2",
  "width2": "00",
  "width": "2.00",
  "totalArea": "13.17",
  "percentageBeforeTotal": "13.17",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "13.17"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flower Bed Area",
    "value": "Flower_Bed_Area"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "length1": "2",
  "length2": "00",
  "length": "2.00",
  "width1": "9",
  "width2": "00",
  "width": "9.00",
  "totalArea": "18.00",
  "percentageBeforeTotal": "18.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "18"
},
{
  "toBeAdded": {
```

```
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flower Bed Area",
    "value": "Flower_Bed_Area"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "length1": "2",
  "length2": "00",
  "length": "2.00",
  "width1": "8",
  "width2": "00",
  "width": "8.00",
  "totalArea": "16.00",
  "percentageBeforeTotal": "16.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "16"
}
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648002e69bf7f73019a4006f",
    "name": "externalImg_1686110943641_1686110736885_image_0.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externalImg_1686110943641_1686110736885_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648002e69bf7f73019a40070",
    "name": "externalImg_1686110943678_1686110736885_image_1.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externalImg_1686110943678_1686110736885_image_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648002e69bf7f73019a40071",
  "name": "externallmg_1686110943707_1686110736885_image_2.jpeg",
  "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110943707_1686110736885_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648002e69bf7f73019a40072",
  "name": "externallmg_1686110943742_1686110736885_image_3.jpeg",
  "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110943742_1686110736885_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648002e69bf7f73019a40073",
  "name": "externallmg_1686110943772_1686110736885_image_4.jpeg",
  "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110943772_1686110736885_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648002e69bf7f73019a40074",
  "name": "externallmg_1686110943836_1686110736885_image_5.jpeg",
  "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110943836_1686110736885_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648002e69bf7f73019a40075",
  "name": "externallmg_1686110943902_1686110736885_image_6.jpeg",
  "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110943902_1686110736885_image_6.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "648002e69bf7f73019a40076",
      "name": "externallmg_1686110943903_1686110736885_image_7.jpeg",
      "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110943903_1686110736885_image_7.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "648002e69bf7f73019a40077",
      "name": "externallmg_1686110943947_1686110736885_image_8.jpeg",
      "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110943947_1686110736885_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "648002e69bf7f73019a40078",
      "name": "externallmg_1686110946745_1686110736885_image_9.jpeg",
      "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110946745_1686110736885_image_9.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "648002e69bf7f73019a40079",
      "name": "externallmg_1686110946746_1686110736885_image_10.jpeg",
      "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110946746_1686110736885_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "648002e69bf7f73019a4007a",
      "name": "externallmg_1686110946866_1686110736885_image_11.jpeg",
      "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110946866_1686110736885_image_11.jpeg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648002e69bf7f73019a4007b",
  "name": "externallmg_1686110947092_1686110736885_image_12.jpeg",
  "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110947092_1686110736885_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648002e69bf7f73019a4007c",
  "name": "externallmg_1686110947176_1686110736885_image_13.jpeg",
  "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110947176_1686110736885_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648002e69bf7f73019a4007d",
  "name": "externallmg_1686110947177_1686110736885_image_14.jpeg",
  "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110947177_1686110736885_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648002e69bf7f73019a4007e",
  "name": "externallmg_1686110947207_1686110736885_image_15.jpeg",
  "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110947207_1686110736885_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648002e69bf7f73019a4007f",
  "name": "externallmg_1686110947216_1686110736885_image_16.jpeg",
  "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110947216_1686110736885_image_16.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648002e69bf7f73019a40080",
    "name": "externallmg_1686110947251_1686110736885_image_17.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110947251_1686110736885_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648002e69bf7f73019a40081",
    "name": "externallmg_1686110947512_1686110736885_image_18.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110947512_1686110736885_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648002e69bf7f73019a40082",
    "name": "externallmg_1686110947592_1686110736885_image_19.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110947592_1686110736885_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a40083",
    "name": "externallmg_1686110914531_1686110697236_image_0.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110914531_1686110697236_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a40084",
    "name": "externallmg_1686110914563_1686110697236_image_1.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110914563_1686110697236_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "648002e69bf7f73019a40085",
    "name": "externallmg_1686110914601_1686110697236_image_2.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110914601_1686110697236_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a40086",
    "name": "externallmg_1686110914642_1686110697236_image_3.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110914642_1686110697236_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a40087",
    "name": "externallmg_1686110914692_1686110697236_image_4.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110914692_1686110697236_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a40088",
    "name": "externallmg_1686110914791_1686110697236_image_5.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110914791_1686110697236_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a40089",
    "name": "externallmg_1686110914928_1686110697236_image_6.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110914928_1686110697236_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "648002e69bf7f73019a4008a",
    "name": "externallmg_1686110914928_1686110697236_image_7.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110914928_1686110697236_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a4008b",
    "name": "externallmg_1686110915032_1686110697236_image_8.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110915032_1686110697236_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a4008c",
    "name": "externallmg_1686110918168_1686110697236_image_9.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110918168_1686110697236_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a4008d",
    "name": "externallmg_1686110918186_1686110697236_image_10.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110918186_1686110697236_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a4008e",
    "name": "externallmg_1686110919212_1686110697236_image_11.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110919212_1686110697236_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a4008f",
```



```
    "name": "externallmg_1686110921519_1686110697236_image_12.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110921519_1686110697236_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a40090",
    "name": "externallmg_1686110921521_1686110697236_image_13.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110921521_1686110697236_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a40091",
    "name": "externallmg_1686110921522_1686110697236_image_14.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110921522_1686110697236_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a40092",
    "name": "externallmg_1686110921523_1686110697236_image_15.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110921523_1686110697236_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a40093",
    "name": "externallmg_1686110921524_1686110697236_image_16.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externallmg_1686110921524_1686110697236_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a40094",
    "name": "externallmg_1686110921525_1686110697236_image_17.jpeg",
```

```
    "path": "cases/647d8e280ab64c23c9fc15a3/
externalImg_1686110921525_1686110697236_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a40095",
    "name": "externalImg_1686110921821_1686110697236_image_18.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externalImg_1686110921821_1686110697236_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648002e69bf7f73019a40096",
    "name": "externalImg_1686110921822_1686110697236_image_19.jpeg",
    "path": "cases/647d8e280ab64c23c9fc15a3/
externalImg_1686110921822_1686110697236_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-06-05T07:26:32.987Z",
"updatedAt": "2023-06-08T09:35:49.643Z",
"__v": 0,
"fullAddress": "Residential Flat No. 307, 3rd Floor, Shreeji Darshan, Sector 19, Village
- Ulwe, State - Maharashtra, India",
"updatedBy": "627208c1afd7d55eddedc372",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Rashmi mhatre ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9967302534",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"carpetTotal": "297.51",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "47.17",
"siteVisitDate": "2023-06-07",
"otherCompositionBuiltUpTotal": "0.00",
```

"otherCompositionCarpetTotal": "47.17",
 "otherCompositionSaleableTotal": "0.00",
 "builtupPercentage": "10",
 "finalBuiltupArea": "379.15",
 "finalCarpetArea": "344.68",
 "finalSalableArea": "417.06",
 "salablePercentage": "10",
 "toBeAdded": ""

}

Name	Length	Width	Total
Composition :			
Kitchen	6'7"	6'5"	42.24
Living Room	8'11"	13'1"	116.66
Passage	4'6"	2'11"	13.12
Toilet	5'8"	3'9"	21.25
Bedroom	8'10"	9'9"	86.12
Toilet	4'10"	3'9"	18.12
Other Composition :			
Flower Bed Area	6'7"	2'00"	13.17
Flower Bed Area	2'00"	9'00"	18.00
Flower Bed Area	2'00"	8'00"	16.00