

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "type": "CREDITOFFICER",
    "_id": "635f7d78e363ef22db2f2888",
    "firstName": "Amita ",
    "lastName": "Patel",
    "mobileNo": "",
    "email": "me2@me.com",
    "workMobileNo": "8691048841"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
    "mobileNo": "9167204055",
    "shortName": "RBK",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "RAJESH",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "GHADI",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": "",
  "shortName": "PR",
  "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
  "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
```

```
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "0123456789",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
  "valuersRegistrationNumber": [
    {
      "value": "IBBI/RV/07/2018/10366",
      "label": "Registered Valuer"
    }
  ],
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
```

```
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.079840938354923",
  "longitude": " 73.07683451327694"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-06-09"
    }
  ]
}
```

```
],
"schedule": [],
},
"marketAnalysisAndRemark": {
"audioNotes": []
},
"address": {
"state": {
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
"status": true,
"name": "Village",
"key": "village",
"value": "Kharghar",
"label": true
},
"floorNo": {
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "5",
"label": false
},
"buildingNo": {
"status": true,
"name": "Building No",
"key": "buildingNo",
"value": "EWS /E22/t",
"label": true
},
"district": {
"status": false,
"name": "District",
"key": "district",
```

```
"value": "",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Swapnpoorti Housing Scheme\t",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "36\t",
  "label": true
},
"street1": {
```

```
"status": false,
"name": "Street 1",
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
```



```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "501\t",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  }
},
```

```
"flooring": {
  "label": "Vitrified Tile Flooring",
  "value": "VerifiedTileFlooring"
},
"doors": {
  "label": "Teak Wood Door frame with Solid flush door",
  "value": "Teak_Wood_Door_frame_with_Solid_flush_door"
},
"windows": {
  "label": "Aluminium Sliding Window ",
  "value": "Aluminium_Sliding_Window_"
},
"fixtures": {
  "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring",
  "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring"
},
"finishing": {
  "label": "Cement Plastering with POP false Ceiling",
  "value": "Cement_Plastering_with_POP_false_Ceiling"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "As per CIDCO norms",
    "value": "As_per_CIDCO_norms"
  },
  "asPerActualAgreement": {
    "north": "ADIRAJ",
    "south": "ROAD",
    "east": "ROAD",
    "west": "BUILDING"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
}
```

```
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Tenant Occupied",
    "value": "Tenant_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Open Parking",
    "value": "Open_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "",
    "year": "",
    "fullDate": ""
  },
  "propertyTypeList": {
    "value": "Residential",
```

```
"label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"isSiteVisitAllowed": true,
"noOfBasement": "0",
"noOfPodium": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "",
"ageOfBuilding": "",
"estimatedAge": "",
"noOfDwellingUnitsInBuilding": "06",
"noOfAmenityFloors": "",
"noOfFloors": "07",
"noOfLifts": "01"
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
```



```
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "true",
type": "CASE",
leadType": "LEAD",
siteVisitType": "PARTIAL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
isAdvanceInvoice": false,
status": true,
caseStatus": "SITEVISITCOMPLETED",
_id": "64801ee49bf7f73019a4138f",
ownerName": "Asimita Zine\t",
```

```
"ownerPhoneNo": "8879622434",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "8879622434",
"contactPersonName": "Asimita Zine\t",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Asimita Zine\t",
    "phone": "8879622434",
    "ownershipShare": "",
    "email": "",
    "id": "165880"
  }
],
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 501\t, 5th Floor, Building No EWS /E22\t,
Swapnpoorti Housing Scheme\t, Sector 36\t, Village - Kharghar, State - Maharashtra,
India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1246aa6d152c1801b2e4",
      "label": "Index- II"
    },
    "inputs": {
      "documentDate": "31/05/2023",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Ashish Jadhav",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Asimita Zine\t",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "9749"
    }
  },
  "isHardCopy": false,
```

```
"displayStatus": false,
"path": "cases/64801ee49bf7f73019a4138f/document_undefined",
"id": "854548",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Wed Jun 07 2023 11:38:24 GMT+0530 (India Standard Time)",
"fileName": "document_undefined"
}
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "001881",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
{
  "id": "236099",
  "title": "Create Case",
  "description": "Create Case",
  "datetime": "Wed Jun 07 2023 11:38:36 GMT+0530 (India Standard Time)"
}
],
"siteInspection": [
{
  "areaType": {
    "label": "Saleable",
    "value": "Saleable"
  },
  "providedBy": {
    "label": "Owner",
    "value": "Owner"
  },
  "_id": "64828bb89c1ac80fee48fba2",
  "area": "0",
  "providedByName": "Asimita Zine\t",
  "providedByContactNo": "8879622434"
}
],
"composition": [
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "165342",
  "name": "Living Room",
  "length": "12.83",
```

```
"length1": "12",
"length2": "10",
"width": "9.83",
"width1": "9",
"width2": "10",
"totalArea": "126.19",
"images": [],
"extraAreas": [],
"finalArea": "126.19"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "9.25",
  "length1": "9",
  "length2": "3",
  "width": "9.67",
  "width1": "9",
  "width2": "8",
  "totalArea": "89.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "89.42"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "6.75",
  "length1": "6",
  "length2": "9",
  "width": "6.92",
  "width1": "6",
  "width2": "11",
  "totalArea": "46.69",
  "images": [],
  "extraAreas": [],
  "finalArea": "46.69"
},
}
```

```
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "3.92",
  "length1": "3",
  "length2": "11",
  "width": "3.33",
  "width1": "3",
  "width2": "4",
  "totalArea": "13.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.06"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "W.C",
  "length": "2.83",
  "length1": "2",
  "length2": "10",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "10.86",
  "images": [],
  "extraAreas": [],
  "finalArea": "10.86"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "3.75",
  "length1": "3",
  "length2": "9",
```

```
"width": "3.83",
"width1": "3",
"width2": "10",
"totalArea": "14.37",
"images": [],
"extraAreas": [],
"finalArea": "14.37"
}
],
"otherComposition": [
{
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "0",
  "length1": "2",
  "length2": "6",
  "length": "2.50",
  "width1": "3",
  "width2": "7",
  "width": "3.58",
  "totalArea": "8.96",
  "percentageBeforeTotal": "8.96",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "8.96"
},
{
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "length1": "2",
  "length2": "9",
  "length": "2.75",
```



```
"width1": "4",
"width2": "00",
"width": "4.00",
"totalArea": "11.00",
"percentageBeforeTotal": "11.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "11"
}
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "648294109c1ac80fee49083b",
"name": "externallmg_1686279178829_1686278974959_image_0.jpeg",
"path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279178829_1686278974959_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "648294109c1ac80fee49083c",
"name": "externallmg_1686279178875_1686278974960_image_1.jpeg",
"path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279178875_1686278974960_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "648294109c1ac80fee49083d",
"name": "externallmg_1686279179721_1686278974960_image_2.jpeg",
"path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279179721_1686278974960_image_2.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
```

```
    "_id": "648294109c1ac80fee49083e",
    "name": "externallmg_1686279179737_1686278974960_image_3.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279179737_1686278974960_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648294109c1ac80fee49083f",
    "name": "externallmg_1686279179746_1686278974960_image_4.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279179746_1686278974960_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648294109c1ac80fee490840",
    "name": "externallmg_1686279181828_1686278974960_image_5.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279181828_1686278974960_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648294109c1ac80fee490841",
    "name": "externallmg_1686279181828_1686278974960_image_6.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279181828_1686278974960_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648294109c1ac80fee490842",
    "name": "externallmg_1686279181954_1686278974960_image_7.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279181954_1686278974960_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648294109c1ac80fee490843",
```

```
    "name": "externallmg_1686279182260_1686278974960_image_8.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279182260_1686278974960_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648294109c1ac80fee490844",
    "name": "externallmg_1686279182414_1686278974960_image_9.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279182414_1686278974960_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648294109c1ac80fee490845",
    "name": "externallmg_1686279182424_1686278974960_image_10.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279182424_1686278974960_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648294109c1ac80fee490846",
    "name": "externallmg_1686279182449_1686278974960_image_11.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279182449_1686278974960_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648294109c1ac80fee490847",
    "name": "externallmg_1686279182469_1686278974960_image_12.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279182469_1686278974960_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648294109c1ac80fee490848",
    "name": "externallmg_1686279182479_1686278974960_image_13.jpeg",
```

```
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279182479_1686278974960_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648294109c1ac80fee490849",
    "name": "externallmg_1686279182504_1686278974960_image_14.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279182504_1686278974960_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648294109c1ac80fee49084a",
    "name": "externallmg_1686279182514_1686278974960_image_15.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279182514_1686278974960_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648294109c1ac80fee49084b",
    "name": "externallmg_1686279182539_1686278974960_image_16.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279182539_1686278974960_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648294109c1ac80fee49084c",
    "name": "externallmg_1686279150240_1686278946382_image_0.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279150240_1686278946382_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648294109c1ac80fee49084d",
    "name": "externallmg_1686279150270_1686278946382_image_1.jpeg",
    "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279150270_1686278946382_image_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648294109c1ac80fee49084e",
  "name": "externallmg_1686279151380_1686278946382_image_2.jpeg",
  "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279151380_1686278946382_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648294109c1ac80fee49084f",
  "name": "externallmg_1686279151394_1686278946382_image_3.jpeg",
  "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279151394_1686278946382_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648294109c1ac80fee490850",
  "name": "externallmg_1686279151410_1686278946382_image_4.jpeg",
  "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279151410_1686278946382_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648294109c1ac80fee490851",
  "name": "externallmg_1686279153290_1686278946382_image_5.jpeg",
  "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279153290_1686278946382_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648294109c1ac80fee490852",
  "name": "externallmg_1686279153295_1686278946382_image_6.jpeg",
  "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279153295_1686278946382_image_6.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "648294109c1ac80fee490853",
      "name": "externallmg_1686279153516_1686278946382_image_7.jpeg",
      "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279153516_1686278946382_image_7.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "648294109c1ac80fee490854",
      "name": "externallmg_1686279154055_1686278946382_image_8.jpeg",
      "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279154055_1686278946382_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "648294109c1ac80fee490855",
      "name": "externallmg_1686279154255_1686278946382_image_9.jpeg",
      "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279154255_1686278946382_image_9.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "648294109c1ac80fee490856",
      "name": "externallmg_1686279154270_1686278946382_image_10.jpeg",
      "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279154270_1686278946382_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "648294109c1ac80fee490857",
      "name": "externallmg_1686279154295_1686278946382_image_11.jpeg",
      "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279154295_1686278946382_image_11.jpeg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648294109c1ac80fee490858",
  "name": "externallmg_1686279154320_1686278946382_image_12.jpeg",
  "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279154320_1686278946382_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648294109c1ac80fee490859",
  "name": "externallmg_1686279154375_1686278946382_image_13.jpeg",
  "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279154375_1686278946382_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648294109c1ac80fee49085a",
  "name": "externallmg_1686279154535_1686278946382_image_14.jpeg",
  "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279154535_1686278946382_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648294109c1ac80fee49085b",
  "name": "externallmg_1686279154540_1686278946382_image_15.jpeg",
  "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279154540_1686278946382_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648294109c1ac80fee49085c",
  "name": "externallmg_1686279154555_1686278946382_image_16.jpeg",
  "path": "cases/64801ee49bf7f73019a4138f/
externallmg_1686279154555_1686278946382_image_16.jpeg",
  "orientation": "portrait"
}
],
```

```

"externalDocuments": [],
"createdAt": "2023-06-07T06:08:36.478Z",
"updatedAt": "2023-06-09T02:57:51.077Z",
"__v": 0,
"updatedBy": "60f9343b45132d6a6bdd96e8",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + W.C +
Bathroom",
"carpetTotal": "300.59000000000003",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "19.96"
}

```

Name	Length	Width	Total
Composition :			
Living Room	12'10"	9'10"	126.19
Bedroom	9'3"	9'8"	89.42
Kitchen	6'9"	6'11"	46.69
Passage	3'11"	3'4"	13.06
W.C	2'10"	3'10"	10.86
Bathroom	3'9"	3'10"	14.37
Other Composition :			
Cupboard	2'6"	3'7"	8.96
Cupboard	2'9"	4'00"	11.00