

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb1d"
    },
    "type": "CREDITOFFICER",
    "_id": "636b7ad64d42487767af7c8d",
    "firstName": "Birendra",
    "lastName": "Thakur",
    "mobileNo": "",
    "workMobileNo": "9969782542",
    "email": "birendra.thakur@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "3000"
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",
    "name": "Thane",
    "email": "thane@vastukala.com",
    "phone": "1234567890",
    "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
```

```
400 601",
  "city": "Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb1d",
  "branchCode": "5354",
  "type": "BRANCH",
  "name": "Naupada Branch Thane",
  "email": "sbi.05354@sbi.co.in",
  "mobileNo": "5413552365",
  "alternateMobileNo": "",
  "address": "425, Gokhale Road, Naupada, Thane, Maharashtra",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62720e52afd7d55eddedc887",
    "role": "SITEENGINEER",
    "firstName": "Harshad",
    "email": "harshad@vastukala.org",
    "lastName": "Panchal",
    "mobileNo": "9029575553",
```

```
"shortName": "HP",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "RAJESH",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "GHADI",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PSH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
```

```
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "0123456789",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
  "valuersRegistrationNumber": [
    {
      "value": "IBBI/RV/07/2018/10366",
      "label": "Registered Valuer"
    }
  ],
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
```

```
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.02140197481806",
  "longitude": "73.15566073558196"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-06-16"
    }
  ]
},
],
```

```
"schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Thu Jun 15 2023 10:48:52 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kevale",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
}
```

```
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Panvel Pride",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
```

```
"value": "",
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "E",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
```



```
"status": false,
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "004",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
```

```
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": true,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "75/1A",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "410 206",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
```

```
"roof": {
  "label": "R. C. C. Slab",
  "value": "rcc_Slab"
},
"flooring": {
  "label": "Proposed Vitrified tiles flooring",
  "value": "Proposed_Vitrified_tiles_flooring"
},
"doors": {
  "label": "Proposed Teak wood",
  "value": "Proposed_Teak_wood"
},
"windows": {
  "label": "Proposed Powder coated aluminium sliding windows",
  "value": "Proposed_Powder_coated_aluminium_sliding_windows"
},
"fittings": {
  "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring",
  "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring"
},
"finishing": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Semi Urban",
    "value": "Semi_Urban"
  },
  "townplanApprovedByList": {
    "label": "Other",
    "value": "Other"
  },
  "asPerActualAgreement": {
    "north": "OPEN",
    "south": "ROAD",
    "east": "D WING",
    "west": "Open "
  },
  "asPerDocumentAgreement": {
    "north": "",
```

```
"west": "",
"south": "",
"east": ""
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Grampanchayat",
    "value": "Grampanchayat"
  },
  "pavementLaid": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "carParking": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "constructionWorkStatus": {
    "label": "Under Construction",
    "value": "InProgress"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2024",
    "fullDate": "1/1/2024"
  }
}
```

```
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"walls": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"appearanceOfTheBuilding": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"maintenanceOfTheBuilding": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"visibleDamageInBuilding": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "",
"ageOfBuilding": "",
"estimatedAge": "",
```

```
"noOfLifts": "02",
"noOfDwellingUnitsInBuilding": "8",
"noOfFloors": "04"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "1",
    "percentage": "6.67",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "1",
    "percentage": "7.00",
```

```
"isHideFloor": false,
"status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "1",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "1",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "2",
"percentage": "2.00",
"isHideFloor": false,
"status": true
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "36.17",
"isHideFloor": true,
```



```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
```

```
"title": "Potential value, if any",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "PARTIAL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
```

```
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "648a9dcdda662768e994e4f0",
"ownerName": "Mr. Sandip Ashok Sutar & Sanjana Sandip Sutar",
"ownerPhoneNo": "9768554789",
"fullAddress": " Flat No. 004, Basement Floor, Wing - E, Panvel Pride, Village - Kevale,
Gut No. 75/1A, Taluka - Panvel, District - Raigad , 410 206, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "01/06/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Ashiana Lifestyle",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mr. Sandip Ashok Sutar & Sanjana Sandip Sutar"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1686806322152_SBI_Naupada_sandeep_sutar.pdf",
    "path": "cases/648a9dcdda662768e994e4f0/
document_1686806322152_SBI_Naupada_sandeep_sutar.pdf",
    "id": "310364",
    "uploadedBy": "6430f74691d7c62df11f3f15",
    "createdAt": "Thu Jun 15 2023 10:48:47 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "001951",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "131893",
    "title": "Create Lead",
    "description": "Create Lead",
```

```
"datetime": "Thu Jun 15 2023 10:42:45 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mr. Sandip Ashok Sutar & Sanjana Sandip Sutar",
"phone": "9768554789",
"ownershipShare": "",
"email": "",
"id": "326566"
}
],
"siteInspection": [
{
"areaType": {
"label": "Saleable",
"value": "Saleable"
},
"providedBy": {
"label": "Owner",
"value": "Owner"
},
"_id": "648bd352719c32253ddd4508",
"area": "485",
"providedByName": "Mr. Sandip Ashok Sutar & Sanjana Sandip Sutar",
"providedByContactNo": "9768554789"
}
],
"composition": [
{
"measurementType": {
"label": "Square Feet",
"value": "Square_Feet"
},
"id": "968451",
"name": "Living Room",
"length": "8.83",
"length1": "8",
"length2": "10",
"width": "13.42",
"width1": "13",
"width2": "5",
"totalArea": "118.51",
"images": [],
"extraAreas": [],
"finalArea": "118.51"
}
]
```

```
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "4.33",
  "length1": "4",
  "length2": "4",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "17.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.33"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Bathroom",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "20.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "3.00",
  "length1": "3",
```

```
"length2": "00",
"width": "4.00",
"width1": "4",
"width2": "00",
"totalArea": "12.00",
"images": [],
"extraAreas": [],
"finalArea": "12.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "7.83",
  "length1": "7",
  "length2": "10",
  "width": "8.83",
  "width1": "8",
  "width2": "10",
  "totalArea": "69.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "69.19"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Kitchen",
  "length": "7.83",
  "length1": "7",
  "length2": "10",
  "width": "6.92",
  "width1": "6",
  "width2": "11",
  "totalArea": "54.18",
  "images": [],
  "extraAreas": [],
  "finalArea": "54.18"
}
],
```

```
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd4426",
    "name": "externallmg_1686884748508_1686884520448_image_0.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884748508_1686884520448_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd4427",
    "name": "externallmg_1686884748793_1686884520448_image_1.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884748793_1686884520448_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd4428",
    "name": "externallmg_1686884748848_1686884520448_image_2.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884748848_1686884520448_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd4429",
    "name": "externallmg_1686884749643_1686884520448_image_3.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884749643_1686884520448_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd442a",
```



```
    "name": "externallmg_1686884752265_1686884520448_image_4.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884752265_1686884520448_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd442b",
    "name": "externallmg_1686884753204_1686884520448_image_5.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884753204_1686884520448_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd442c",
    "name": "externallmg_1686884756008_1686884520448_image_6.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884756008_1686884520448_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd442d",
    "name": "externallmg_1686884756348_1686884520448_image_7.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884756348_1686884520448_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd442e",
    "name": "externallmg_1686884756773_1686884520448_image_8.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884756773_1686884520448_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd442f",
    "name": "externallmg_1686884758393_1686884520448_image_9.jpeg",
```

```
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884758393_1686884520448_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd4430",
    "name": "externallmg_1686884759258_1686884520448_image_10.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884759258_1686884520448_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd4431",
    "name": "externallmg_1686884759313_1686884520448_image_11.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884759313_1686884520448_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd4432",
    "name": "externallmg_1686884759368_1686884520448_image_12.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884759368_1686884520448_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd4433",
    "name": "externallmg_1686884759403_1686884520448_image_13.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884759403_1686884520448_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648bd19b719c32253ddd4434",
    "name": "externallmg_1686884759718_1686884520448_image_14.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884759718_1686884520448_image_14.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648bd19b719c32253ddd4435",
  "name": "externallmg_1686884698674_1686884477300_image_0.jpeg",
  "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884698674_1686884477300_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648bd19b719c32253ddd4436",
  "name": "externallmg_1686884698939_1686884477300_image_1.jpeg",
  "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884698939_1686884477300_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648bd19b719c32253ddd4437",
  "name": "externallmg_1686884698984_1686884477301_image_2.jpeg",
  "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884698984_1686884477301_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648bd19b719c32253ddd4438",
  "name": "externallmg_1686884699734_1686884477301_image_3.jpeg",
  "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884699734_1686884477301_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648bd19b719c32253ddd4439",
  "name": "externallmg_1686884701777_1686884477301_image_4.jpeg",
  "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884701777_1686884477301_image_4.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648bd19b719c32253ddd443a",
    "name": "externallmg_1686884702558_1686884477301_image_5.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884702558_1686884477301_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648bd19b719c32253ddd443b",
    "name": "externallmg_1686884704368_1686884477301_image_6.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884704368_1686884477301_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648bd19b719c32253ddd443c",
    "name": "externallmg_1686884704784_1686884477301_image_7.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884704784_1686884477301_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648bd19b719c32253ddd443d",
    "name": "externallmg_1686884705468_1686884477301_image_8.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884705468_1686884477301_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "648bd19b719c32253ddd443e",
    "name": "externallmg_1686884708095_1686884477301_image_9.jpeg",
    "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884708095_1686884477301_image_9.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648bd19b719c32253ddd443f",
  "name": "externallmg_1686884708403_1686884477301_image_10.jpeg",
  "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884708403_1686884477301_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648bd19b719c32253ddd4440",
  "name": "externallmg_1686884708453_1686884477301_image_11.jpeg",
  "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884708453_1686884477301_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648bd19b719c32253ddd4441",
  "name": "externallmg_1686884708499_1686884477301_image_12.jpeg",
  "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884708499_1686884477301_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648bd19b719c32253ddd4442",
  "name": "externallmg_1686884708530_1686884477301_image_13.jpeg",
  "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884708530_1686884477301_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "648bd19b719c32253ddd4443",
  "name": "externallmg_1686884708828_1686884477301_image_14.jpeg",
  "path": "cases/648a9dcdda662768e994e4f0/
externallmg_1686884708828_1686884477301_image_14.jpeg",
  "orientation": "portrait"
}
],
```

```

"externalDocuments": [],
"createdAt": "2023-06-15T05:12:45.948Z",
"updatedAt": "2023-06-16T03:14:45.197Z",
"__v": 0,
"updatedBy": "60f9343b45132d6a6bdd96e8",
"addressForMap": "",
"caseReferredBy": "62720e52afd7d55eddedc887",
"contactPersonName": "Mr. Sandip Ashok Sutar & Sanjana Sandip Sutar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9768554789",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + Bathroom +
WC",
"carpetTotal": "291.21",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"

```

Name	Length	Width	Total
Composition :			
Living Room	8'10"	13'5"	118.51
Passage	4'4"	4'00"	17.33
Bathroom	5'00"	4'00"	20.00
WC	3'00"	4'00"	12.00
Bedroom	7'10"	8'10"	69.19
Kitchen	7'10"	6'11"	54.18
Other Composition :			