

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "648aa63dda662768e994f772",
    "firstName": "Saumita Chakraborty",
    "lastName": "Chakraborty",
    "mobileNo": "",
    "workMobileNo": "9167177426",
    "email": "Saumita.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Saumita Chakraborty",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
```

```
"name": "Vastukala Consultants India Pvt. Ltd.",
"email": "info@vastukala.org",
"address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1 6th Floor, Kiro Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
```

```
"firstName": "Saurabh",
"email": "saurabhvelonde143@gmail.com",
"lastName": "Velonde",
"mobileNo": "8691048846",
"shortName": "SSV",
"workWithDocumentMaker": "",
"profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "627208c1afd7d55eddedc372",
"role": "SITEENGINEER+MAKAR",
"firstName": "Aniket",
"email": "aniket@vastukala.org",
"lastName": "Navale",
"mobileNo": "9892222307",
"designation": "",
"shortName": "AN",
"workWithDocumentMaker": "",
"profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER+CHECKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60092304a16fab0f2af9b0c2",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Nitesh",
"email": "nitesh.khedekar@vastukala.org",
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
```

```
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "627221f4afd7d55eddeddcb4",
    "role": "MAKER+CHECKER",
    "firstName": "Prajakta",
    "email": "prajakta@vastukala.org",
    "lastName": "Patil",
    "mobileNo": "9769797568",
    "designation": "",
    "shortName": "P",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "6084131a13f01f158c6ea1f3",
      "PANNo": "AEAPC7114Q",
      "role": "VALUER",
      "firstName": "Sharadkumar",
      "fatherName": "Baburao",
      "email": "cmd@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9422171100",
      "designation": "CMD",
      "registrationNo": [
        {
          "title": {
            "value": "Wealth_Tax",
            "label": "Wealth Tax"
          },
          "_id": "6084131a13f01f158c6ea1f4",
          "number": "[N]C.C.I.T/I -14/52/2008-09"
        }
      ]
    }
  ]
}
```

```
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.203006322444523",
  "longitude": "72.82496765722946"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82496765722946,
    19.203006322444523
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-06-17T07:51:04.382Z",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "0",
  "lumpsumValue": "0",
  "rateMax": "0",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
}
```

```
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Thu Jun 15 2023 15:51:18 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
```

```
"value": "",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Malvani Regal CHS",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": false,
"name": "Street 1",
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Malvani Regal CHS, Building no. 41, Malvani, Malad West",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
```



```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "001 & 002",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  }
},
```

```
"flooring": {
  "label": "Ceramic tiles Flooring & Marble Flooring",
  "value": "Ceramic_tiles_Flooring_&_Marble_Flooring"
},
"doors": {
  "label": "Teak Wood Door frame with Solid flush door",
  "value": "Teak_Wood_Door_frame_with_Solid_flush_door"
},
"windows": {
  "label": "Aluminium Sliding Window ",
  "value": "Aluminium_Sliding_Window_"
},
"fixtures": {
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed ",
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_"
},
"finishing": {
  "label": "Cement Plastering",
  "value": "Cement_Plastering"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "Building No. 43",
    "west": "Building No. 47",
    "south": "BMC ground",
    "east": "Road / Building No. 38"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
}
```

```
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Open Car Parking",
    "value": "Open_Car_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2002",
    "fullDate": "1/1/2002"
  },
  "propertyTypeList": {
    "value": "Residential",
```

```
"label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed",
  "value": "R.C.C."
},
"qualityOfConstruction": {
  "label": "Normal",
  "value": "Normal"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "39",
"ageOfBuilding": "21",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "7",
"flatFloorNo": "",
"noOfLifts": "1",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "8"
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
```



```
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
isAdvanceInvoice": false,
status": true,
```

```
"caseStatus": "SITEVISITCOMPLETED",
"_id": "648aa912da662768e994fd03",
"ownerName": "Kombayya Nadar",
"ownerPhoneNo": "8655267949",
"appAddress": "Flat no. 001 & 002, Ground Floor, Malvani Regal CHS, Building no. 41,
Malvani, Malad West ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/648aa912da662768e994fd03/
document_1686808785769_Racpc_Sion_Kaslinga_Nadar_0102_NPA.pdf",
    "fileName":
"document_1686808785769_Racpc_Sion_Kaslinga_Nadar_0102_NPA.pdf",
    "displayStatus": false,
    "id": "722769",
    "uploadedBy": "60b7177d2ffdf65bcd65882a",
    "createdAt": "Thu Jun 15 2023 11:30:37 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "001955",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "833056",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jun 15 2023 11:30:50 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Kombayya Nadar",
    "phone": "8655267949",
    "ownershipShare": "",
    "email": "",
    "id": "240241"
  }
],
"siteInspection": [
  {
    "areaType": {
```

```
    "label": "Carpet",
    "value": "Carpet"
  },
  "providedBy": {
    "label": "Other",
    "value": "Other"
  },
  "_id": "648d663c07df79469f40a8d4",
  "area": "476.41",
  "providedByName": "Site Visit Measurements",
  "providedByContactNo": "0000000000"
}
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "244731",
    "name": "Living Room",
    "length": "16.42",
    "length1": "16",
    "length2": "5",
    "width": "9.58",
    "width1": "9",
    "width2": "7",
    "totalArea": "157.33",
    "images": [
      {
        "path": "cases/648aa912da662768e994fd03/
compositionImg_r_1686987925925_image.jpg",
        "orientation": "portrait"
      }
    ]
  },
  "extraAreas": [],
  "finalArea": "157.33"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "9.83",
```

```
"length1": "9",
"length2": "10",
"width": "6.42",
"width1": "6",
"width2": "5",
"totalArea": "63.10",
"images": [
  {
    "path": "cases/648aa912da662768e994fd03/
compositionImg_r_1686987971409_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "_id": "648d65c007df79469f40a88f",
    "name": "Kitchen ",
    "extraAreaType": "Add",
    "length": "5.50",
    "length1": "5",
    "length2": "6",
    "width": "4.67",
    "width1": "4",
    "width2": "8",
    "totalArea": "25.67"
  }
],
"finalArea": "88.77000000000001"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "4.67",
  "width1": "4",
  "width2": "8",
```

```
"totalArea": "36.17",
"images": [
  {
    "path": "cases/648aa912da662768e994fd03/
compositionImg_r_1686988068882_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "36.17"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "13.25",
  "length1": "13",
  "length2": "3",
  "width": "8.42",
  "width1": "8",
  "width2": "5",
  "totalArea": "111.52",
  "images": [
    {
      "path": "cases/648aa912da662768e994fd03/
compositionImg_r_1686988112541_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "111.52"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "5.33",
  "length1": "5",
  "length2": "4",
  "width": "4.67",
```

```
"width1": "4",
"width2": "8",
"totalArea": "24.89",
"images": [
  {
    "path": "cases/648aa912da662768e994fd03/
compositionImg_r_1686988149492_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "24.89"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "9.50",
  "length1": "9",
  "length2": "6",
  "width": "7.75",
  "width1": "7",
  "width2": "9",
  "totalArea": "73.62",
  "images": [
    {
      "path": "cases/648aa912da662768e994fd03/
compositionImg_r_1686988200489_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "73.62"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "648d66a807df79469f40ac5c",
  "name": "externalimg_r_1686988440477_image.jpg",
  "path": "cases/648aa912da662768e994fd03/
externalimg_r_1686988440477_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648d66a807df79469f40ac5d",
  "name": "externalimg_r_1686988439529_image.jpg",
  "path": "cases/648aa912da662768e994fd03/
externalimg_r_1686988439529_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648d66a807df79469f40ac5e",
  "name": "externalimg_r_1686988442385_image.jpg",
  "path": "cases/648aa912da662768e994fd03/
externalimg_r_1686988442385_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648d66a807df79469f40ac5f",
  "name": "externalimg_r_1686988441109_image.jpg",
  "path": "cases/648aa912da662768e994fd03/
externalimg_r_1686988441109_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648d66a807df79469f40ac60",
  "name": "externalimg_r_1686988446937_image.jpg",
  "path": "cases/648aa912da662768e994fd03/
externalimg_r_1686988446937_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```

    "_id": "648d66a807df79469f40ac61",
    "name": "externalimg_r_1686988443380_image.jpg",
    "path": "cases/648aa912da662768e994fd03/
externalimg_r_1686988443380_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648d66a807df79469f40ac62",
    "name": "externalimg_r_1686988445221_image.jpg",
    "path": "cases/648aa912da662768e994fd03/
externalimg_r_1686988445221_image.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-06-15T06:00:50.060Z",
"updatedAt": "2023-06-17T07:54:40.561Z",
"__v": 0,
"fullAddress": " Flat No. 001 & 002, Ground Floor, Malvani Regal CHS, Malvani Regal
CHS, Building no. 41, Malvani, Malad West, State - Maharashtra, India",
"updatedBy": "627208c1afd7d55eddedc372",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Kombayya Nadar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8655267949",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet",
"carpetTotal": "466.63",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0",
"siteVisitDate": "2023-06-17"
}

```

Name	Length	Width	Total
Composition :			
Living Room	16'5"	9'7"	157.33
Kitchen	9'10"	6'5"	63.10

Toilet	7'9"	4'8"	36.17
Bedroom	13'3"	8'5"	111.52
Toilet	5'4"	4'8"	24.89
Bedroom	9'6"	7'9"	73.62
Other Composition :			