

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2000000",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": 1000,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
    "mobileNo": "9167204055",
```

```
"shortName": "RBK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9343b45132d6a6bdd96e8",
"role": "SITEENGINEER",
"firstName": "Rajesh",
"email": "rajeshb.ghadi@gmail.com",
"lastName": "Ghadi",
"mobileNo": "8652092666",
"designation": "",
"shortName": "RHG",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60092304a16fab0f2af9b0c2",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Nitesh",
"email": "nitesh.khedekar@vastukala.org",
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60092304a16fab0f2af9b0c2",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Nitesh",
"email": "nitesh.khedekar@vastukala.org",
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"checker": {
```

```
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER+CHECKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ]
  }
]
```

```
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.118938847509142",
  "longitude": "72.99878119125454"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.99878119125454,
    19.118938847509142
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-06-26"
    }
  ]
}
```

```
    }
  ],
  "schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Wed Jun 21 2023 17:23:13 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Ghansoli",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
```

```
"status": true,
"name": "Building No",
"key": "buildingNo",
"value": "C3\t",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Siddheshwar CHSL\t",
```

```
"label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "9",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "101\t",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
```

```

    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "label": "Proposed RCC SLab",
    "value": "Proposed_RCC_SLab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood Door frame with Solid door with safety door",
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door"
  },
  "windows": {
    "label": "Aluminium Open Windows",
    "value": "Aluminium_Open_Windows"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring",
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring"
  },
  "finishing": {
    "label": "Cement Plastering + POP Finish",
    "value": "Cement_Plastering_+_POP_Finish"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Navi Mumbai Municipal Corporation",
    "value": "NMMC"
  },
  "asPerActualAgreement": {

```

```
"north": "road ",
"south": "B NO C9",
"east": "N NO C4",
"west": "B NO C2"
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Tenant Occupied",
    "value": "Tenant_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Open Car Parking Space",
    "value": "Open_Car_Parking_Space"
  },
  "constructionWorkStatus": {
    "label": "Completed",
```

```
"value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2005",
  "fullDate": "1/1/2005"
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Excellent",
  "value": "Excellent"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Excellent",
  "value": "Excellent"
},
"maintenanceOfTheBuilding": {
  "label": "Excellent",
  "value": "Excellent"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"noOfBasement": "0",
```

```
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "60",
"ageOfBuilding": "18",
"estimatedAge": "42",
"noOfFloors": "03",
"noOfDwellingUnitsInBuilding": "04"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
```

```
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```



```
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
```

```
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "6492d350ff2e4a17ce894eed",
"ownerName": "Shivaji Dhondge\t",
"ownerPhoneNo": "9867797640",
"appAddress": "flat no. 101 c 3 Wing Shree siddheswar ghansoli ",
"remark": "9867799690",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/6492d350ff2e4a17ce894eed/
document_1687343896566_Valuation_Report_Swapnil_Balasaheb_Kshirsagar_1.pdf",
    "fileName":
"document_1687343896566_Valuation_Report_Swapnil_Balasaheb_Kshirsagar_1.pdf",
    "displayStatus": false,
    "id": "138521",
    "uploadedBy": "60b7189d2ffdf65bcd65882b",
    "createdAt": "Wed Jun 21 2023 16:08:57 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "002070",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "436647",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jun 21 2023 16:09:12 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shivaji Dhondge\t",
```

```
    "phone": "9867797640",
    "ownershipShare": "",
    "email": "",
    "id": "748392"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Saleable",
      "value": "Saleable"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "6499b01fcab24d3d1a2cdc13",
    "area": "0",
    "providedByName": "Shivaji Dhondge\t",
    "providedByContactNo": "9867797640"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "219378",
    "name": "Living Room",
    "length": "15.67",
    "length1": "15",
    "length2": "8",
    "width": "9.42",
    "width1": "9",
    "width2": "5",
    "totalArea": "147.53",
    "images": [],
    "extraAreas": [],
    "finalArea": "147.53"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
  },
]
```

```
"id": "1",
"name": "W.C",
"length": "3.00",
"length1": "3",
"length2": "00",
"width": "4.00",
"width1": "4",
"width2": "00",
"totalArea": "12.00",
"images": [],
"extraAreas": [],
"finalArea": "12.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Bathroom",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "20.00",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "20.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "7.42",
  "length1": "7",
  "length2": "5",
  "width": "6.83",
  "width1": "6",
  "width2": "10",
  "totalArea": "50.68",
  "images": [],
  "extraAreas": [],
  "finalArea": "50.68"
}
],
"otherComposition": [
  {
    "name": {
      "label": "Cupboard",
      "value": "Cupboard"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length1": "1",
    "length2": "2",
    "length": "1.17",
    "width1": "3",
    "width2": "00",
    "width": "3.00",
    "totalArea": "3.50",
    "percentageBeforeTotal": "3.50",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "3.5"
  }
]
```

```
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdae2",
    "name": "externallmg_1687793269356_1687793059765_image_0.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793269356_1687793059765_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdae3",
    "name": "externallmg_1687793270668_1687793059765_image_1.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793270668_1687793059765_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdae4",
    "name": "externallmg_1687793270692_1687793059765_image_2.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793270692_1687793059765_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdae5",
    "name": "externallmg_1687793271142_1687793059765_image_3.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793271142_1687793059765_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdae6",
```



```
    "name": "externallmg_1687793273932_1687793059765_image_4.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793273932_1687793059765_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdae7",
    "name": "externallmg_1687793273938_1687793059765_image_5.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793273938_1687793059765_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdae8",
    "name": "externallmg_1687793273939_1687793059765_image_6.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793273939_1687793059765_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdae9",
    "name": "externallmg_1687793273939_1687793059765_image_7.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793273939_1687793059765_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdaea",
    "name": "externallmg_1687793273940_1687793059765_image_8.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793273940_1687793059765_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdaeb",
    "name": "externallmg_1687793273941_1687793059765_image_9.jpeg",
```

```
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793273941_1687793059765_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdaec",
    "name": "externallmg_1687793273942_1687793059765_image_10.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793273942_1687793059765_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdaed",
    "name": "externallmg_1687793273943_1687793059765_image_11.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793273943_1687793059765_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdaee",
    "name": "externallmg_1687793274047_1687793059765_image_12.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793274047_1687793059765_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdaef",
    "name": "externallmg_1687793274048_1687793059765_image_13.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793274048_1687793059765_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdaf0",
    "name": "externallmg_1687793274049_1687793059765_image_14.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793274049_1687793059765_image_14.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6499ae87cab24d3d1a2cdaf1",
  "name": "externallmg_1687793274050_1687793059765_image_15.jpeg",
  "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793274050_1687793059765_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6499ae87cab24d3d1a2cdaf2",
  "name": "externallmg_1687793274051_1687793059766_image_16.jpeg",
  "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793274051_1687793059766_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6499ae87cab24d3d1a2cdaf3",
  "name": "externallmg_1687793274051_1687793059766_image_17.jpeg",
  "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793274051_1687793059766_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6499ae87cab24d3d1a2cdaf4",
  "name": "externallmg_1687793275532_1687793036358_image_0.jpeg",
  "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793275532_1687793036358_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6499ae87cab24d3d1a2cdaf5",
  "name": "externallmg_1687793277602_1687793036359_image_1.jpeg",
  "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793277602_1687793036359_image_1.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6499ae87cab24d3d1a2cdaf6",
      "name": "externallmg_1687793277772_1687793036359_image_2.jpeg",
      "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793277772_1687793036359_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6499ae87cab24d3d1a2cdaf7",
      "name": "externallmg_1687793279924_1687793036359_image_3.jpeg",
      "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793279924_1687793036359_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6499ae87cab24d3d1a2cdaf8",
      "name": "externallmg_1687793280724_1687793036359_image_4.jpeg",
      "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793280724_1687793036359_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6499ae87cab24d3d1a2cdaf9",
      "name": "externallmg_1687793280725_1687793036359_image_5.jpeg",
      "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793280725_1687793036359_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6499ae87cab24d3d1a2cdafa",
      "name": "externallmg_1687793280726_1687793036359_image_6.jpeg",
      "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793280726_1687793036359_image_6.jpeg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6499ae87cab24d3d1a2cdafb",
  "name": "externallmg_1687793280726_1687793036359_image_7.jpeg",
  "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793280726_1687793036359_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6499ae87cab24d3d1a2cdafc",
  "name": "externallmg_1687793280727_1687793036359_image_8.jpeg",
  "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793280727_1687793036359_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6499ae87cab24d3d1a2cdafd",
  "name": "externallmg_1687793280752_1687793036359_image_9.jpeg",
  "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793280752_1687793036359_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6499ae87cab24d3d1a2cdafe",
  "name": "externallmg_1687793280822_1687793036359_image_10.jpeg",
  "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793280822_1687793036359_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6499ae87cab24d3d1a2cdaff",
  "name": "externallmg_1687793281992_1687793036359_image_11.jpeg",
  "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793281992_1687793036359_image_11.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdb00",
    "name": "externallmg_1687793282067_1687793036359_image_12.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793282067_1687793036359_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdb01",
    "name": "externallmg_1687793282077_1687793036359_image_13.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793282077_1687793036359_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdb02",
    "name": "externallmg_1687793282262_1687793036359_image_14.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793282262_1687793036359_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdb03",
    "name": "externallmg_1687793282263_1687793036359_image_15.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793282263_1687793036359_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6499ae87cab24d3d1a2cdb04",
    "name": "externallmg_1687793282492_1687793036359_image_16.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externallmg_1687793282492_1687793036359_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```

    "status": false,
    "_id": "6499ae87cab24d3d1a2cdb05",
    "name": "externalImg_1687793282658_1687793036359_image_17.jpeg",
    "path": "cases/6492d350ff2e4a17ce894eed/
externalImg_1687793282658_1687793036359_image_17.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-06-21T10:39:12.445Z",
"updatedAt": "2023-06-26T15:35:49.387Z",
"__v": 0,
"fullAddress": " Flat No. 101\t, 1st Floor, Building No C3\t, Siddheshwar CHSL\t, Sector
9, Village - Ghansoli, State - Maharashtra, India",
"updatedBy": "60f9343b45132d6a6bdd96e8",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Shivaji Dhondge\t",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9867797640",
"scheduleSiteVisitDate": "2023-06-26",
"briefDescOfProperty": "Living Room + Kitchen + W.C + Passage + Bathroom",
"carpetTotal": "242.21",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "3.5"
}

```

Name	Length	Width	Total
Composition :			
Living Room	15'8"	9'5"	147.53
W.C	3'00"	4'00"	12.00
Passage	3'00"	4'00"	12.00
Bathroom	5'00"	4'00"	20.00
Kitchen	7'5"	6'10"	50.68

Other
Composition :

Cupboard	1'2"	3'00"	3.50
----------	------	-------	------
