

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b942312d0",
    "firstName": "Tarun kumar",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9699679202"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  },
}
```

```
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
    "mobileNo": "9167204055",
    "shortName": "RBK",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
```

```

    "_id": "627221f4afd7d55eddeddcb4",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Prajakta",
    "email": "prajakta@vastukala.org",
    "lastName": "Patil",
    "mobileNo": "9769797568",
    "designation": "",
    "shortName": "P",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "CAT-I-A-1930",
          "label": "Chartered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "60af7d4d2ffdf65bcd658643",
      "PANNo": "AESPC7493M",
      "role": "VALUER",
      "firstName": "Vidhi",
      "fatherName": "Manoj",
      "email": "vids_singh@yahoo.com",
      "lastName": "Chalikwar",
      "mobileNo": "9820549087",
      "designation": "Valuer",
      "registrationNo": [
        {
          "title": {
            "value": "Chartered_Valuer",
            "label": "Chartered Valuer"
          },
          "_id": "60eeb39af3dd69653a58168d",
          "number": "CAT-I-A-1930"
        }
      ],
      "shortName": "VC",
      "workWithDocumentMaker": "",
      "profilePhoto": "users\\60af7d4d2ffdf65bcd658643\\
profilePhoto_1622113613002_Vidhi C.jpeg"
    }
  ]

```



```
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-06-26T04:00:00.000Z"
  },
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-06-26T09:00:00.000Z"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kalamboli",
    "label": true
  },
  "floorNo": {
    "status": true,
```

```
"name": "Floor No",
"key": "floorNo",
"value": "9",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "17",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "4",
  "label": true
}
```

```
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Amarante Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "9E",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
```



```
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "901",
  "label": false
},
}
```

```
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
```

```
"value": "410 218",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  }
}
```

```
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "CIDCO",
  "label": "City Industrial Development Corporation of Maharashtra"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road & D-Mart ",
  "west": "D-Mart Road",
  "south": "Road & Patel Plaza CHSL",
  "east": "Internal Road & Bianca Building"
},
"asPerDocumentAgreement": {
  "north": "Plot No. 3",
  "west": "Road",
  "south": "Road",
  "east": "Road"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "10.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "12316.5",
  "depreciatedBuildingRate": "2416.5"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "83500",
  "landRate": "27100",
  "igrImage": "cases/64966237c3eaaa5554d39ae4/igr_1687860488036_Image.jpeg",
  "squareMeterGuideLineRate": "87675.00",
  "squareFeetGuideLineRate": "8145.00"
},
"igrFinalRate": {
  "rate": "7751.00",
  "squareFeetGuideLineRate": "7751.00",
```

```
"squareMeterGuideLineRate": "83435.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "18,500",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per CIDCO norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\\_Thk._Brick_Masonry",
    "label": "6\\ Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  }
}
```

```
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": {
  "value": "Along_with_One_Car_Parking",
  "label": "Along with One Car Parking"
},
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2016",
  "fullDate": "1/1/2016"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
}
```

```
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
```

```
    "value": "as_per_occupancy_certificate",
    "label": "As per occupancy certificate"
  },
  "isSiteVisitAllowed": true,
  "ageOfBuilding": "7",
  "totalLifeBuilding": "60",
  "estimatedAge": "53",
  "noOfBasement": "",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "17",
  "flatFloorNo": "9",
  "noOfLifts": "2",
  "noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "812.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64966237c3eaaa5554d39ae4/
routeMap_1687860717225_Image.png",
    "routeLat": "19.037923",
    "routeLng": "73.102731",
    "stationName": "Kalamboli",
    "routeDistance": "3 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
```



```
    "id": "eyyw4h",
    "name": "eyyw4h",
    "image": "cases/64966237c3eaaa5554d39ae4/
routeMap_1687860643990_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "8917508.00",
  "bookValue": "0",
  "finalValue": "8917508.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "6293812.00",
  "selectedBuildUpValue": "812.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "649ab6a2612f77109a9d4989",
      "name": "externalImg_1687860897862_exteranal.jpg",
      "path": "cases/64966237c3eaaa5554d39ae4/
externalImg_1687860897862_exteranal.jpg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],

```

```
"externalPhotos": [
  {
    "status": false,
    "_id": "649ab606612f77109a9d45b6",
    "name": "externallmg_r_1687860741733_20230626Mon_043944PM__xrrdrrxz2
223murism_____hnbm_lmjn__org.jpg",
    "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860741733_2023
0626Mon_043944PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "649ab606612f77109a9d45b9",
    "name": "externallmg_r_1687860741745_20230626Mon_044027PM__xrrdrrxz2
223murism_____hnbm_lmjn__org.jpg",
    "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860741745_2023
0626Mon_044027PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "649ab6a2612f77109a9d4989",
    "name": "externallmg_1687860897862_exteranal.jpg",
    "path": "cases/64966237c3eaaa5554d39ae4/
externallmg_1687860897862_exteranal.jpg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "649ab606612f77109a9d45b7",
    "name": "externallmg_r_1687860741712_20230626Mon_043853PM__xrrdrrxz2
223murism_____hnbm_lmjn__org.jpg",
    "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860741712_2023
0626Mon_043853PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "649ab611612f77109a9d4629",
    "name": "Living Room",
    "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860751861_2023
```

```
0626Mon_044252PM__xrrdrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "649ab611612f77109a9d4628",
  "name": "Living Room",
  "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860751871_2023
0626Mon_044254PM__xrrdrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "649ab606612f77109a9d45be",
  "name": "Living Room",
  "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860741779_2023
0626Mon_044243PM__xrrdrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "649ab606612f77109a9d45ba",
  "name": "Living Room",
  "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860741755_2023
0626Mon_044212PM__xrrdrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "649ab606612f77109a9d45bd",
  "name": "Living Room",
  "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860741771_2023
0626Mon_044238PM__xrrdrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "649ab606612f77109a9d45bb",
  "name": "Terrace Area",
  "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860741759_2023
0626Mon_044214PM__xrrdrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
```

```
"carpetRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
```



```
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": true,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "724.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64966237c3eaaa5554d39ae4",
"ownerName": "Ms. Shwetali Gangadhare",
"ownerPhoneNo": "9967772141",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9930039077",
"contactPersonName": "Ms. Shwetali Gangadhare",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Ms. Shwetali Gangadhare",
```

```
"phone": "9967772141",
"ownershipShare": "",
"email": "",
"id": "632811"
}
],
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"relationWithOwner": "Owner",
"fullAddress": "Residential Flat No. 901, 9th Floor, Building No 17, Amarante Co-op.
Hsg. Soc. Ltd., Plot No. 4, Sector 9E, Village - Kalamboli, Taluka - Panvel, District -
Raigad, Navi Mumbai, 410 218, State - Maharashtra, India",
"remark": "",
"documents": [
{
"documentType": {
"value": "60af48bf2ffdf65bcd6585fa",
"label": "Agreement for sale"
},
"inputs": {
"documentDate": "21/06/2023",
"from": {
"value": "Transferor",
"label": "Transferor"
},
"Transferor": "Mr. Harish Kumar Madaan & Mrs. Sonia Harish Madaan",
"to": {
"value": "Transferee",
"label": "Transferee"
},
"Transferee": "Ms. Shwetali Gangadhare"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1687851515940_Part_Agreement_scan.pdf",
"path": "cases/64966237c3eaaa5554d39ae4/
document_1687851515940_Part_Agreement_scan.pdf",
"id": "529616",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Jun 27 2023 13:31:37 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"value": "60ae1247aa6d152c1801b2ea",
"label": "Commencement Certificate"
},
"inputs": {
```

```
"documentDate": "30/03/2012",
"nameOfApprovingAuthority": {
  "value": "CIDCO",
  "label": "CIDCO"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "CIDCO / ATPO / 2474"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/64966237c3eaaa5554d39ae4/
document_1687852148194_153930.pdf",
"id": "943680",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Jun 27 2023 13:31:37 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "07/01/2016",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CIDCO / BP-2861 / TPO (NM & K) / 2016 / 1479"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/64966237c3eaaa5554d39ae4/
document_1687852618714_161426.pdf",
"id": "320744",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Jun 27 2023 13:31:37 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
```

```
    "value": "60ae1285aa6d152c1801b40d",
    "label": "Car Parking Allotment Letter"
  },
  "inputs": {
    "documentDate": "11/11/2017"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/64966237c3eaaa5554d39ae4/
document_1687852712206_155867.pdf",
  "id": "498518",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Tue Jun 27 2023 13:31:37 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f1",
    "label": "Society Maintenance Bill"
  },
  "inputs": {
    "documentDate": "15/10/2022",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "22-23 / 10-12 / 0764"
},
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/64966237c3eaaa5554d39ae4/
document_1687852772541_149469.pdf",
  "id": "620621",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Tue Jun 27 2023 13:31:37 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "002130",
"createdBy": "6006d4ce5080a310ac1fd2",
"caseHistory": [
  {
    "id": "218225",
    "title": "Create Case",
    "description": "Create Case",
```

```
"datetime": "Sat Jun 24 2023 08:55:43 GMT+0530 (India Standard Time)"
}
],
"siteInspection": [],
"composition": [
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "326614",
  "name": "Bedroom",
  "length": "9.75",
  "length1": "9",
  "length2": "9",
  "width": "12.17",
  "width1": "12",
  "width2": "2",
  "totalArea": "118.62",
  "images": [],
  "extraAreas": [],
  "finalArea": "118.62"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Toilet",
  "length": "3.17",
  "length1": "3",
  "length2": "2",
  "width": "6.67",
  "width1": "6",
  "width2": "8",
  "totalArea": "21.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "2",
"name": "Toilet",
"length": "3.17",
"length1": "3",
"length2": "2",
"width": "6.67",
"width1": "6",
"width2": "8",
"totalArea": "21.11",
"images": [],
"extraAreas": [],
"finalArea": "21.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "10.17",
  "length1": "10",
  "length2": "2",
  "width": "2.75",
  "width1": "2",
  "width2": "9",
  "totalArea": "27.96",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.96"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "11.00",
  "length1": "11",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "99.00",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "99.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Living Room",
  "length": "19.00",
  "length1": "19",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "190.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "190.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Kitchen",
  "length": "8.08",
  "length1": "8",
  "length2": "1",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "70.73",
  "images": [],
  "extraAreas": [],
  "finalArea": "70.73"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Terrace Area",
```

```
"length": "4.58",
"length1": "4",
"length2": "7",
"width": "10.33",
"width1": "10",
"width2": "4",
"totalArea": "47.36",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "649aabb1612f77109a9d11bf",
    "name": "2nd Terrace",
    "extraAreaType": "Add",
    "length": "5.00",
    "length1": "5",
    "length2": "00",
    "width": "6.00",
    "width1": "6",
    "width2": "00",
    "totalArea": "30.00"
  }
],
"finalArea": "77.36"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Dry Balcony",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
```



```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Flowered Area",
  "length": "2.00",
  "length1": "2",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "18.00",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "649aabfe612f77109a9d1373",
      "name": "2nd Flowerbed ",
      "extraAreaType": "Add",
      "length": "2.00",
      "length1": "2",
      "length2": "00",
      "width": "8.00",
      "width1": "8",
      "width2": "00",
      "totalArea": "16.00"
    }
  ],
  "finalArea": "34"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "551847",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "724",
  "squareMeterArea": "67.26",
  "docFinalBuiltUp": "868.8",
  "docFinalBuiltUpSquareMeter": "80.712",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
},
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "231783",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "812",
  "squareMeterArea": "75.44",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBuiltupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "649ab32a612f77109a9d36f5",
    "id": "1",
    "property": "Flat",
    "area": "701",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
```

```
"floor": "9",
"source": "https://www.99acres.com/",
"expectedPrice": "8500000",
"expectedRate": "12125.53",
"builtUpExpectedRate": "11023.21",
"image": "cases/64966237c3eaaa5554d39ae4/
indicator_1687860010611_Image.png"
},
{
  "printlnReport": true,
  "_id": "649ab368612f77109a9d3706",
  "id": "2",
  "property": "Flat",
  "area": "657",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "3",
  "source": "magic_bricks",
  "expectedPrice": "8100000",
  "expectedRate": "12328.77",
  "builtUpExpectedRate": "11207.97",
  "image": "cases/64966237c3eaaa5554d39ae4/
indicator_1687860072608_Image.png"
},
{
  "printlnReport": true,
  "_id": "649ab3b6612f77109a9d380f",
  "id": "3",
  "property": "Flat",
  "area": "750",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "12",
  "source": "magic_bricks",
  "expectedPrice": "9000000",
  "expectedRate": "12000.00",
  "builtUpExpectedRate": "10909.09",
  "image": "cases/64966237c3eaaa5554d39ae4/
indicator_1687860150845_Image.png"
},
{
  "printlnReport": true,
```

```
  "_id": "649ab423612f77109a9d3c47",
  "id": "4",
  "property": "Flat",
  "area": "850",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "16",
  "source": "Nobroker.com",
  "expectedPrice": "11000000",
  "expectedRate": "12941.18",
  "builtUpExpectedRate": "10784.31",
  "image": "cases/64966237c3eaaa5554d39ae4/
indicator_1687860259179_Image.png"
}
],
"externallImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649ab606612f77109a9d45b4",
  "name": "externallmg_r_1687860741702_20230626Mon_043843PM__xrrdrrxz22
23murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860741702_20230
626Mon_043843PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649ab606612f77109a9d45b5",
  "name": "externallmg_r_1687860741706_20230626Mon_043846PM__xrrdrrxz22
23murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860741706_20230
626Mon_043846PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649ab606612f77109a9d45b6",
  "name": "externallmg_r_1687860741733_20230626Mon_043944PM__xrrdrrxz22
23murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860741733_20230
626Mon_043944PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649ab606612f77109a9d45b7",
  "name": "externallmg_r_1687860741712_20230626Mon_043853PM__xrrdrrxz223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860741712_20230626Mon_043853PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649ab606612f77109a9d45b8",
  "name": "externallmg_r_1687860741750_20230626Mon_044030PM__xrrdrrxz223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860741750_20230626Mon_044030PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649ab606612f77109a9d45b9",
  "name": "externallmg_r_1687860741745_20230626Mon_044027PM__xrrdrrxz223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860741745_20230626Mon_044027PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649ab606612f77109a9d45ba",
  "name": "externallmg_r_1687860741755_20230626Mon_044212PM__xrrdrrxz223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860741755_20230626Mon_044212PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649ab606612f77109a9d45bb",
```

```
    "name": "externalimg_r_1687860741759_20230626Mon_044214PM___xrddrrxz22
23murism_____hnbm_lmjn___org.jpg",
    "path": "cases/64966237c3eaaa5554d39ae4/externalimg_r_1687860741759_20230
626Mon_044214PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649ab606612f77109a9d45bc",
    "name": "externalimg_r_1687860741763_20230626Mon_044233PM___xrddrrxz22
23murism_____hnbm_lmjn___org.jpg",
    "path": "cases/64966237c3eaaa5554d39ae4/externalimg_r_1687860741763_20230
626Mon_044233PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649ab606612f77109a9d45bd",
    "name": "externalimg_r_1687860741771_20230626Mon_044238PM___xrddrrxz22
23murism_____hnbm_lmjn___org.jpg",
    "path": "cases/64966237c3eaaa5554d39ae4/externalimg_r_1687860741771_20230
626Mon_044238PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649ab606612f77109a9d45be",
    "name": "externalimg_r_1687860741779_20230626Mon_044243PM___xrddrrxz22
23murism_____hnbm_lmjn___org.jpg",
    "path": "cases/64966237c3eaaa5554d39ae4/externalimg_r_1687860741779_20230
626Mon_044243PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649ab606612f77109a9d45bf",
    "name": "externalimg_r_1687860741775_20230626Mon_044241PM___xrddrrxz22
23murism_____hnbm_lmjn___org.jpg",
    "path": "cases/64966237c3eaaa5554d39ae4/externalimg_r_1687860741775_20230
626Mon_044241PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
    "orientation": "portrait"
  },
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649ab611612f77109a9d4622",
  "name": "externallmg_1687860751882_IMG_20230627_080158.jpg",
  "path": "cases/64966237c3eaaa5554d39ae4/
externallmg_1687860751882_IMG_20230627_080158.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649ab611612f77109a9d4623",
  "name": "externallmg_1687860751916_IMG_20230627_080201.jpg",
  "path": "cases/64966237c3eaaa5554d39ae4/
externallmg_1687860751916_IMG_20230627_080201.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649ab611612f77109a9d4624",
  "name": "externallmg_1687860751924_IMG_20230627_080206.jpg",
  "path": "cases/64966237c3eaaa5554d39ae4/
externallmg_1687860751924_IMG_20230627_080206.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649ab611612f77109a9d4625",
  "name": "externallmg_1687860751936_Screenshot_20230627_080252.jpg",
  "path": "cases/64966237c3eaaa5554d39ae4/
externallmg_1687860751936_Screenshot_20230627_080252.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649ab611612f77109a9d4626",
  "name": "externallmg_1687860751941_Screenshot_20230627_080256.jpg",
  "path": "cases/64966237c3eaaa5554d39ae4/
externallmg_1687860751941_Screenshot_20230627_080256.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649ab611612f77109a9d4627",
    "name": "externallmg_r_1687860751877_20230626Mon_044952PM__xrrdrrxz223murism_____hnbm_lmjn__org.jpg",
    "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860751877_20230626Mon_044952PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649ab611612f77109a9d4628",
    "name": "externallmg_r_1687860751871_20230626Mon_044254PM__xrrdrrxz223murism_____hnbm_lmjn__org.jpg",
    "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860751871_20230626Mon_044254PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649ab611612f77109a9d4629",
    "name": "externallmg_r_1687860751861_20230626Mon_044252PM__xrrdrrxz223murism_____hnbm_lmjn__org.jpg",
    "path": "cases/64966237c3eaaa5554d39ae4/externallmg_r_1687860751861_20230626Mon_044252PM__xrrdrrxz2223murism_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649ab6a2612f77109a9d4989",
    "name": "externallmg_1687860897862_exteranal.jpg",
    "path": "cases/64966237c3eaaa5554d39ae4/externallmg_1687860897862_exteranal.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"createdAt": "2023-06-24T03:25:43.611Z",
"updatedAt": "2023-06-27T11:27:12.152Z",
"__v": 0,
"reason": "",
"addressForMap": "",
"siteVisitDate": "2023-06-26",
```



"updatedBy": "627221f4afd7d55eddeddcb4",  
 "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + Passage +  
 Terrace Area + Dry Balcony + Flowered Area",  
 "carpetTotal": "463.89",  
 "finalMeasurementType": "Sq. Ft.",  
 "otherCarpetTotal": "0.00",  
 "builtupPercentage": "20",  
 "finalBuiltupArea": "806.27",  
 "finalCarpetArea": "671.89",  
 "finalSalableArea": "886.89",  
 "salablePercentage": "10",  
 "toBeAdded": "",  
 "extendOfSiteRemark": "\nCarpet Area in Sq. Ft. = 441.00\nOther Adjoining Area in  
 Sq. Ft. = 283.00\nTotal Carpet Area in Sq. Ft. = 724.00\n(Area as per Agreement for  
 sale)",  
 "siteMeasurementRemark": "\nCarpet Area in Sq. Ft. = 549.00\nTerrace Area in Sq. Ft.  
 = 77.00\nFlowerbed area in Sq. Ft. = 34.00\nDry Balcony area in Sq. Ft. = 12.00\nTotal  
 Carpet Area in Sq. Ft. = 672.00\n(Area as per actual site measurement)",  
 "finalAreaType": "Carpet Area",  
 "finalAsPerArea": "Agreement for sale",  
 "finalBuiltUpPercentage": "20",  
 "finalCarpetConvertToBuiltUpPer": "20",  
 "finalSaleablePercentage": "0",  
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 724.00",  
 "buildingServicesRate": "2700",  
 "flatRate": "12600",  
 "landOtherRate": "9900",  
 "otherCompositionBuiltUpTotal": "0.00",  
 "otherCompositionCarpetTotal": "0.00",  
 "otherCompositionSaleableTotal": "0.00"

Name	Length	Width	Total
Composition :			
Bedroom	9'9"	12'2"	118.62
Toilet	3'2"	6'8"	21.11
Toilet	3'2"	6'8"	21.11
Passage	10'2"	2'9"	27.96
Bedroom	11'00"	9'00"	99.00
Living Room	19'00"	10'00"	190.00

Kitchen	8'1"	8'9"	70.73
Terrace Area	4'7"	10'4"	47.36
Dry Balcony	4'00"	3'00"	12.00
Flowered Area	2'00"	9'00"	18.00
Other Composition :			