
Eliman oroda ella isulo di






Actual site photographs













B.	External Observation of the Building							
1	Plaster	Normal Condition						
2	Chajjas	Normal Condition						
3	Plumbing	Normal Condition						
4	Cracks on the external walls	Not found						
5	Filling cracks on the external walls	Not found						
6	Cracks on columns & beams	Not found						
7	Vegetation	Not found						
8	Leakages of water in the drainage pipes or water pipes	Not found						
9	Dampness external in the wall due to leakages	Not found						
10	Any other observation about the condition of external side of the building	As per site inspection, building external repairing work was in progress.						
С		on areas of the building and captioned premises						
1	Beams (Cracks & Leakages)	Normal Condition						
2	Columns (Cracks & Leakages)	Normal Condition						
3	Ceiling (Cracks & Leakages)	Normal Condition						
4	Leakages inside the property	Not found						
5	Painting inside the property	Normal						
6	Maintenance of staircase & cracks	Normal						

D	Common Observation							
1	Structural Audit of the Building Under Bye - Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules) As per bye Laws No. 77 of Co-Op. Societies under the Act the society shall conduct a Structural Audit of the Building of the society as follows							
2	Remark	No Structural Audit Report is furnished for the perusal						

Conclusion

The captioned building is having Ground + 7 Upper Floors which are constructed in year 2006 as per Full Occupancy Certificate. Estimated future life under present circumstances is about 43 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 26.06.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Normal structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar Digitally signed by Sharadkumar B. Chalikwar, o=Vastukala Consultants (I) PVr. Ltd., ou=CMD, enall=cmd@vastukala.org, c=IN Date: 2023.07.01 1141:43 +05330

Auth. Sign.

Director

Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India) Reg. No. IBBI/RV/07/2019/11744 Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME/TCC/2021-22/85/13





CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company

Vastukalo



Structural Stability Report Prepared For: SBI/RACPC - Chinchpokli (East) /Vishal Arvind Mane (002260/ 2301376) Page 1 of 3

Vastu/Mumbai/06/2023/002260/2301376 01/01-01-SKVS Date: 30.06.2023

Structural Stability Report

Structural Observation Report of Residential Flat No. 308, 3rd Floor, B Wing, Building No. R1, "Sai Srushti Coop. Hsg. Soc. Ltd.", Subhash Nagar, MMRDA Project, Village Road, Nahur, Bhandup (West), Mumbai -400078, State - Maharashtra, Country - India.

Name of Owners: Mr. Vishal Arvind Mane

This is to certify that on visual inspection, it appears that the structure of the Wing - B at " Sai Srushti Co-op. Hsq. Soc. Ltd." is in normal condition and the future life can be reasonably takes under normal condition and with proper periodic repairs & maintenance is about 43 years.

General Information:

A.		Introduction					
1	Name of Building	"Sai Srushti Co-op. Hsg. Soc. Ltd."					
Property Address Residential Flat No. 308, 3rd Floor, B Wing, Bu R1, "Sai Srushti Co-op. Hsg. Soc. Ltd.", Nagar, MMRDA Project, Village Road, Nahur (West), Mumbai – 400078, State – Maharashtra, India							
3	Type of Building	Residential used					
4	No. of Floors	Ground + 7 Upper Floors					
5	Whether stilt / podium / open parking provided	Open Car Parking					
6	Type of Construction	R.C.C. Framed Structure					
7	Type of Foundation	R.C.C. Footing					
8	Thickness of the External Walls	9" thick brick walls both sides plastered					
9	Type of Compound	Brick Masonry Walls					
10	Year of Construction Think In	2006 (As per Full Occupancy Certificate)					
11	Present age of building	17 years					
12	Residual age of the building	43 years Subject to proper, preventive periodic maintenance & structural repairs.					
13	No. of flats (Per Floor)	8 Flats on 3 rd Floor					
14	Methodology adopted	As per visual site inspection					





Our Pan India Presence at:

Mumbai 💡 ▼ Thane

💡 Delhi NCR 💡 Nashik

P Nanded

Aurangabad Pune 🗣 Ahmedabad 💡 Jaipur

Rajkot Rajkot Raipur



TeleFax: +91 22 28371325/24 mumbai@vastukala.org



PROFORMA INVOICE

Vastukala Consultants (I) Pvt Ltd

B1-001, U/B FLOOR,

BOOMERANG, CHANDIVALI FARM ROAD,

ANDHERI-EAST 400072

GSTIN/UIN: 27AADCV4303R1ZX State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org

Buyer (Bill to)

STATE BANK OF INDIA - RACPC CHINCHPOKALI

RACPC, Voltas House, 1st Floor,

Dr. Ambedkar Marg, Chinchpokali (East),

Mumbai - 400 033

GSTIN/UIN

: 27AAACS8577K2ZO

State Name : Maharashtra, Code : 27

Invoice No.	Dated
PG-1375/23-24	30-Jun-23
Delivery Note	Mode/Terms of Payment AGAINST REPORT
Reference No. & Date.	Other References
Buyer's Order No.	Dated
Dispatch Doc No. 002260 / 2301376	Delivery Note Date
Dispatched through	Destination

Terms of Delivery

SI No.	Particulars	/	HSN/SAC	GST Rate	Amount
1	STRUCTURAL REPORT FEE (Technical Inspection and Certification Services)	CGST SGST	997224	18 %	2,500.00 225.00 225.00
	A	Total			₹ 2,950.00

Amount Chargeable (in words)

Indian Rupee Two Thousand Nine Hundred Fifty Only

HSN/SAC	Taxable Value 2.500.00	Central Tax		State Tax		Total
		Rate 9%	Amount 225.00	Rate	Amount 225.00	Tax Amount 450.00
997224				9%		
Total	2,500.00		225.00		225.00	450.00

Tax Amount (in words): Indian Rupee Four Hundred Fifty Only

Company's Bank Details

Bank Name

: State Bank of India

A/c No.

32632562114

Branch & IFS Code: MIDC Andheri (E) & SBIN0007074

Remarks:

Mr. Vishal Arvind Mane - Residential Flat No. 308, 3rd Floor, B Wing, Building No. R1, "Sai Srushti Co-op. Hsg. Soc. Ltd.", Subhash Nagar, MMRDA Project, Village Road, Nahur, Bhandup (West), Mumbai – 400078, State – Maharashtra, Country – India

Company's PAN

: AADCV4303R

Declaration

NOTE – AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137

UPI Virtual ID : vastukala@icici

for Vastukala Consultants (I) Pvt Ltd

Authorised Signatory

E. & O.E

This is a Computer Generated Invoice



Vastukala Consultants (I) Pvt. Ltd.

Think.Innovate.Create An ISO 9001:2015 Certified Company

www.vastukala.org

