

```
{
  "typeOfReport": {
    "label": "Residential Row House ",
    "value": "Residential_Row_House_"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6410712a319ffa48baa54078"
    },
    "type": "CREDITOFFICER",
    "_id": "6410712a319ffa48baa5407a",
    "firstName": "Shreekant ",
    "lastName": "patil",
    "mobileNo": "",
    "workMobileNo": "9712282388",
    "email": "ambadnasik@unionbankofindia.bank"
  },
  "fees": {
    "quotedAmount": "",
    "discussWithPerson": "Shreekant ",
    "type": "fixed",
    "expectedFees": 125,
    "propertyValue": "250000"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
    Andheri(East), Mumbai - 400 072.",
  }
}
```

```
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6410712a319ffa48baa54078",
  "name": "Ambad Branch, Nashik",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "ambadnasik@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Ramashray Apartment Sector C Plot No 283 Near Sambhaji Stadium
Bhadrapada Nasik\n"
},
"zone": {
  "_id": "63fda9ecce84bf289baadd43",
  "zoneName": "Nashik Zone"
},
"staff": {
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "636a29b64d42487767af43ea",
    "role": "NASHIK (LEAD + VISIT + RATE)",
    "firstName": "Sachin",
    "email": "sachinraundal9021@gmail.com",
    "lastName": "Raundal",
    "mobileNo": "9021337843",
    "designation": "Site Engg",
    "shortName": "Sachin",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f9147bf3dd69653a591e8c",
```

```
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Vinita",
    "email": "vinita.surve@vastukala.org",
    "lastName": "Surve",
    "mobileNo": "9820652818",
    "designation": "",
    "shortName": "V",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
  },
  "valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "0",
  "longitude": "0"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-07-12",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
}
```

```
"address": {
  "state": {
    "status": false
  },
  "country": {
    "status": false
  },
  "village": {
    "status": false
  },
  "floorNo": {
    "status": false
  },
  "buildingNo": {
    "status": false
  },
  "district": {
    "status": false
  },
  "city": {
    "status": false
  },
  "tahasilNo": {
    "status": false
  },
  "taluka": {
    "status": false
  },
  "plotNo": {
    "status": false
  },
  "buildingName": {
    "status": false
  },
  "selectArea": {
    "status": false
  },
  "street1": {
    "status": false
  },
  "street2": {
    "status": false
  },
  "landmark": {
    "status": false
  },
}
```

```
"wing": {
  "status": false
},
"projectName": {
  "status": false
},
"oldSurveyNumber": {
  "status": false
},
"newSurveyNumber": {
  "status": false
},
"hissaNo": {
  "status": false
},
"CTSNo": {
  "status": false
},
"blockNo": {
  "status": false
},
"selectNo": {
  "status": false
},
"municipalityWardNo": {
  "status": false
},
"khataNo": {
  "status": false
},
"mouza": {
  "status": false
},
"SRO": {
  "status": false
},
"policeStation": {
  "status": false
},
"GUTNo": {
  "status": false
},
"postalCode": {
  "status": false
},
"suburb": {
```

```
    "status": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```



```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "value": "LEAD"
```

```
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "64ad1f41d9a15943959f7e59",
"ownerName": "sunil ramu nigal",
"ownerPhoneNo": "8830182676",
"appAddress": "Row house C-7 & C-8 sai sanket row house ambad near lordas bakery
Ambad kamatwade road",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/64ad1f41d9a15943959f7e59/
document_1689066399267_CamScanner_07112023_1329.pdf",
    "fileName": "document_1689066399267_CamScanner_07112023_1329.pdf",
    "displayStatus": false,
    "id": "182737",
    "uploadedBy": "636a29b64d42487767af43ea",
    "createdAt": "Tue Jul 11 2023 14:51:49 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Commencement Certificate",
      "value": "60ae1247aa6d152c1801b2ea"
    },
    "isHardCopy": false,
    "path": "cases/64ad1f41d9a15943959f7e59/
document_1689066966414_CamScanner_07112023_1328.pdf",
    "fileName": "document_1689066966414_CamScanner_07112023_1328.pdf",
    "displayStatus": false,
    "id": "470634",
    "uploadedBy": "636a29b64d42487767af43ea",
    "createdAt": "Tue Jul 11 2023 14:51:49 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Approved Building Plan",
```

```
    "value": "60ae1277aa6d152c1801b3cc"
  },
  "isHardCopy": false,
  "path": "cases/64ad1f41d9a15943959f7e59/
document_1689067075773_CamScanner_07112023_1327.pdf",
  "fileName": "document_1689067075773_CamScanner_07112023_1327.pdf",
  "displayStatus": false,
  "id": "631564",
  "uploadedBy": "636a29b64d42487767af43ea",
  "createdAt": "Tue Jul 11 2023 14:51:49 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Building Plan",
    "value": "60ae124eaa6d152c1801b308"
  },
  "isHardCopy": false,
  "path": "cases/64ad1f41d9a15943959f7e59/
document_1689067233211_CamScanner_07112023_1337.pdf",
  "fileName": "document_1689067233211_CamScanner_07112023_1337.pdf",
  "displayStatus": false,
  "id": "150156",
  "uploadedBy": "636a29b64d42487767af43ea",
  "createdAt": "Tue Jul 11 2023 14:51:49 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "16/01/2002",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "2"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1689311440023_OC.pdf",
  "path": "cases/64ad1f41d9a15943959f7e59/document_1689311440023_OC.pdf",
```

```
    "id": "471817",
    "uploadedBy": "60f9147bf3dd69653a591e8c",
    "createdAt": "Fri Jul 14 2023 10:40:40 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "002451",
"createdBy": "636a29b64d42487767af43ea",
"caseHistory": [
  {
    "id": "930263",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 11 2023 14:52:09 GMT+0530 (India Standard Time)"
  }
],
"owners": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ae877a2fdc2966a2ec9505",
    "name": "externalImg_1689159507334_1689159310502_image_0.jpeg",
    "path": "cases/64ad1f41d9a15943959f7e59/externalImg_1689159507334_1689159310502_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ae877a2fdc2966a2ec9506",
    "name": "externalImg_1689159507859_1689159310502_image_1.jpeg",
    "path": "cases/64ad1f41d9a15943959f7e59/externalImg_1689159507859_1689159310502_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ae877a2fdc2966a2ec9507",
```

```
    "name": "externallmg_1689159508387_1689159310502_image_2.jpeg",
    "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159508387_1689159310502_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ae877a2fdc2966a2ec9508",
    "name": "externallmg_1689159508760_1689159310502_image_3.jpeg",
    "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159508760_1689159310502_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ae877a2fdc2966a2ec9509",
    "name": "externallmg_1689159508961_1689159310502_image_4.jpeg",
    "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159508961_1689159310502_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ae877a2fdc2966a2ec950a",
    "name": "externallmg_1689159509151_1689159310502_image_5.jpeg",
    "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159509151_1689159310502_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ae877a2fdc2966a2ec950b",
    "name": "externallmg_1689159509843_1689159310502_image_6.jpeg",
    "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159509843_1689159310502_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ae877a2fdc2966a2ec950c",
    "name": "externallmg_1689159509917_1689159310502_image_7.jpeg",
```

```
    "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159509917_1689159310502_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ae877a2fdc2966a2ec950d",
    "name": "externallmg_1689159509977_1689159310502_image_8.jpeg",
    "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159509977_1689159310502_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ae877a2fdc2966a2ec950e",
    "name": "externallmg_1689159510111_1689159310502_image_9.jpeg",
    "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159510111_1689159310502_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ae877a2fdc2966a2ec950f",
    "name": "externallmg_1689159510357_1689159310502_image_10.jpeg",
    "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159510357_1689159310502_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ae877a2fdc2966a2ec9510",
    "name": "externallmg_1689159510645_1689159310503_image_11.jpeg",
    "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159510645_1689159310503_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ae877a2fdc2966a2ec9511",
    "name": "externallmg_1689159511327_1689159310503_image_12.jpeg",
    "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159511327_1689159310503_image_12.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ae877a2fdc2966a2ec9512",
  "name": "externallmg_1689159511483_1689159310503_image_13.jpeg",
  "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159511483_1689159310503_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ae877a2fdc2966a2ec9513",
  "name": "externallmg_1689159511575_1689159310503_image_14.jpeg",
  "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159511575_1689159310503_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ae877a2fdc2966a2ec9514",
  "name": "externallmg_1689159511746_1689159310503_image_15.jpeg",
  "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159511746_1689159310503_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ae877a2fdc2966a2ec9515",
  "name": "externallmg_1689159512038_1689159310503_image_16.jpeg",
  "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159512038_1689159310503_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ae877a2fdc2966a2ec9516",
  "name": "externallmg_1689159512249_1689159310503_image_17.jpeg",
  "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159512249_1689159310503_image_17.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ae877a2fdc2966a2ec9517",
      "name": "externallmg_1689159512350_1689159310503_image_18.jpeg",
      "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159512350_1689159310503_image_18.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64ae877a2fdc2966a2ec9518",
      "name": "externallmg_1689159512408_1689159310503_image_19.jpeg",
      "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159512408_1689159310503_image_19.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "64ae877a2fdc2966a2ec9519",
      "name": "externallmg_1689159543547_1689159245161_image_0.jpeg",
      "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159543547_1689159245161_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "64ae877a2fdc2966a2ec951a",
      "name": "externallmg_1689159543890_1689159245161_image_1.jpeg",
      "path": "cases/64ad1f41d9a15943959f7e59/
externallmg_1689159543890_1689159245161_image_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "createdAt": "2023-07-11T09:22:09.772Z",
  "updatedAt": "2023-07-14T05:10:40.180Z",
  "__v": 0,
  "invoiceId": "64ad1f41d9a15943959f7e6c",
  "updatedBy": "60f9147bf3dd69653a591e8c"
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			