

## Structural Stability Report

Structural Observation Report of Residential Flat No. 3981, 2<sup>nd</sup> Floor, Building No. 116, Wing – B, "Geet Govind Co-op. Hsg. Soc. Ltd.", Tilak Nagar, Village – Chembur, Municipality Ward No. M, Tuluka – Kurla, District – Mumbai, 400 089, State – Maharashtra, India.

Name of Owner: Mrs. Veena Vinayak Madkaikar & Mr. Vinayak Suresh Madkaikar.

This is to certify that on visual inspection, it appears that the structure of the Building No. 116, Wing – B at "Geet Govind Co-op. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 8 years.

### General Information:

A.	Introduction	
1	Name of Building	"Geet Govind Co-op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 3981, 2 <sup>nd</sup> Floor, Building No. 116, Wing – B, "Geet Govind Co-op. Hsg. Soc. Ltd.", Tilak Nagar, Village – Chembur, Municipality Ward No. M, Tuluka – Kurla, District – Mumbai, 400 089, State – Maharashtra, India.
3	Type of Building	Residential used
4	No. of Floors	Ground + 4 Upper Floors
5	Whether stilt / podium / open parking provided	Open Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1971 (As per agreement)
11	Present age of building	52 years
12	Residual age of the building	8 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	2 Flats on 2 <sup>nd</sup> Floor
14	Methodology adopted	As per visual site inspection



### Our Pan India Presence at :

- Mumbai
- Thane
- Delhi NCR
- Aurangabad
- Nanded
- Nashik
- Pune
- Indore
- Ahmedabad
- Rajkot
- Raipur
- Jaipur



**Regd. Office :** B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA  
TeleFax : +91 22 28371325/24  
mumbai@vastukala.org

<b>B. External Observation of the Building</b>		
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Found
5	Filling cracks on the external walls	Found
6	Cracks on columns & beams	Found
7	Vegetation	Found
8	Leakages of water in the drainage pipes or water pipes	Found
9	Dampness external in the wall due to leakages	Found
10	Any other observation about the condition of external side of the building	The external condition of the building is in normal condition
<b>C Internal Observation of the common areas of the building and captioned premises</b>		
1	Beams (Cracks & Leakages)	Good Condition
2	Columns (Cracks & Leakages)	Good Condition
3	Ceiling (Cracks & Leakages)	Good Condition
4	Leakages inside the property	Not found
5	Painting inside the property	Good
6	Maintenance of staircase & cracks	Good

<b>D Common Observation</b>		
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal

<b>E Conclusion</b>	
<p>The captioned building is having Ground + 4 Upper Floors which are constructed in year 1971 as per agreement. Estimated future life under present circumstances is about 8 years subject to proper, preventive periodic maintenance &amp; structural repairs.</p> <p>The inspection dated 05.07.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition &amp; will stand future life subject to proper, preventive periodic maintenance &amp; Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Director

Auth. Sign.

Sharadkumar B. Chalikwar

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME/TCC/2021-22/85/13



Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001:2015 Certified Company

www.vastukala.org



## Actual Site Photographs

