CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: State Bank of India / Jakegram Branch / Mr. Pradeep Kumar Hawaldar Singh (2620/2301639)

Page 1 of 4

Vastu/Thane/07/2023/2620/2301639 17/54-264-PSSH

Date: 17.07.2023

Structural Stability Report

Structural Observation Report of Residential Flat No. 404, 4th Floor, Wing - A, "Harmony", Harmony Tower Co-Op. Hsg. Soc. Ltd.", Siddheshwar Gardens, Kolshet Road, Village - Dhokali, Taluka - Thane, District - Thane, Thane (West), PIN Code - 400 607, State - Maharashtra, India.

Name of Owners: Mr. Pradeep Kumar Hawaldar Singh.

This is to certify that on visual inspection, it appears that the structure of the "Harmony" is in normal condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 45 years.

General Information:

A.		Introduction
1	Name of Building	" Harmony"
2	Property Address	Residential Flat No. 404, 4th Floor, Wing - A, "Harmony",
		Harmony Tower Co-Op. Hsg. Soc. Ltd.", Siddheshwar
		Gardens, Kolshet Road, Village - Dhokali, Taluka - Thane,
		District - Thane, Thane (West), PIN Code - 400 607, State
		- Maharashtra, India.
3	Type of Building	Residential used
4	No. of Floors	Stilt + 15 Upper Floors
5	Whether stilt / podium / open parking	Stilt + Open Car Parking
	provided	
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls COTO
10	Year of Construction	2008 (As per occupancy certificate)
11	Present age of building	15 Years
12	Residual age of the building	45 years Subject to proper, preventive periodic
		maintenance & structural repairs.
13	No. of flats (Per Floor)	4 Flats on 4 th Floor
14	Methodology adopted	As per visual site inspection



Thane: 101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) - 400 601, (M.S.), INDIA


E-mail: thane@vastukala.org, Tel.: 80978 82976 / 90216 25621

Our Pan India Presence at:

Mumbai Aurangabad Thane 💡 Nanded Nashik Delhi NCR

Pune Indore 🕈 Ahmedabad 💡 Jaipur

🦞 Rajkot **♀** Raipur



B.	External O	bservation of the Building
1	Plaster	Good Condition
2	Chajjas	Good Condition
3	Plumbing	Good Condition
4	Cracks on the external walls	Not found
5	Filling cracks on the external walls	Not found
6	Cracks on columns & beams	Not found
7	Vegetation	Not found
8	Leakages of water in the drainage pipes	Not found
	or water pipes	
9	Dampness external in the wall due to	Found
	leakages	
10	Any other observation about the condition	The external condition of the building is in normal condition
	of external side of the building	
С	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Not found
2	Columns (Cracks & Leakages)	Not found
3	Ceiling (Cracks & Leakages)	Not found
4	Leakages inside the property	Not found
5	Painting inside the property	Good
6	Maintenance of staircase & cracks	Good

D	Con	nmon Observation
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws
	- Laws No. 77 of the Model Bye Laws (Co-	under the Act the society shall conduct a Structural Audit of
	Operative Societies Act / Rules)	the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal

E Conclusion

The captioned building is having Stilt + 15 Upper Floors which are constructed in year 2008 as per Occupancy Certificate. Estimated future life under present circumstances is about 45 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 31.05.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in good condition & will stand future life subject to proper, preventive periodic maintenance & normal structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Director

Auth. Sign.

Manoj B. Chalikwar

Registered Valuer Chartered Engineer (India) Reg. No. CAT-I-F-1763

SBI Empanelment No.: SME/TCC/2021-22/86/3





Actual Site Photographs


















Actual Site Photographs

















