#### PROFORMA INVOICE

Invoice No. Dated Vastukala Consultants (I) Pvt Ltd B1-001, U/B FLOOR, PG-1703/23-24 24-Jul-23 BOOMERANG, CHANDIVALI FARM ROAD, **Delivery Note** Mode/Terms of Payment ANDHERI-EAST 400072 AGAINST REPORT GSTIN/UIN: 27AADCV4303R1ZX Reference No. & Date. Other References State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org Buyer's Order No. Dated Buyer (Bill to) STATE BANK OF INDIA- RASMECCC Panvel Dispatch Doc No. Delivery Note Date RASMECCC Panvel 002765 / 2301757 Sharda Terrace, Shop No 5, Ground Floor, Dispatched through Destination Plot No 65, Sector-11, CBD Belapur : 27AAACS8577K2ZO GSTIN/UIN State Name : Maharashtra, Code: 27 Terms of Delivery

SI No.	Particulars	HSN/SAC	GST Rate	Amount
1	STRUCTURAL REPORT FEE (Technical Inspection and Certification Services)  CGS SGS		18 %	2,500.00 225.00 225.00
	To	tal		₹ 2.950.00

Amount Chargeable (in words)

E. & O.E

### Indian Rupee Two Thousand Nine Hundred Fifty Only

Taxable	Central Tax		State Tax		Total
Value	Rate	Amount	Rate	Amount	Tax Amount
2,500.00	9%	2.25.00	9%	225.00	450.00
2,500.00		225.00	4	225.00	450.00
	Value 2,500.00	Value Rate 2,500.00 9%	Taxable         Central Tax           Value         Rate         Amount           2,500.00         9%         2.25.00	Taxable         Central Tax         State           Value         Rate         Amount         Rate           2,500.00         9%         225.00         9%	Taxable         Central Tax         State Tax           Value         Rate         Amount         Rate         Amount           2,500.00         9%         2:25.00         9%         225.00

Tax Amount (in words): Indian Rupee Four Hundred Fifty Only

Company's Bank Details

Bank Name State Bank of India

A/c No. 32632562114

Branch & IFS Code: MIDC Andheri (E) & SBIN0007074

Remarks:

Mr. Hemant Ranjit Chitnawis - Structural Observation Report of Residential Flat No. 401, 4th Floor, Wing - C "New Kanak Sarovar Co-op. Hsg. Soc. Ltd.", Plot No. 17 / 1, 2, 3 & 6, Old Thane Naka Road, Village - Panvel, Taluka - Panvel, District - Raigad, Navi Mumbai, PIN -410 206, State - Maharashtra, India

Company's PAN

: AADCV4303R

Declaration

NOTE - AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE MSME Registration No. - 27222201137

UPI Virtual ID : vastukala@icici

for Vastukala Consultants (I) Pvt Ltd

Authorised Signatory

This is a Computer Generated Invoice



Vastukala Consultants (1) Pvt. Ltd.

wate-Create An ISO 9001:2015 Certified Company www.vastukala.org



CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: SBI / RASMECCC Panvel / Mr. Hemant Ranjit Chitnawis (2765/2301757) Page 1 of 3

Vastu/Mumbai/07/2023/2765/2301757 25/02-382-SBSK Date: 25.07.2023

## Structural Stability Report

Structural Observation Report of Residential Flat No. 401, 4th Floor, Wing – C, "New Kanak Sarovar Co-op. Hsg. Soc. Ltd.", Plot No. 17 / 1, 2, 3 & 6, Old Thane Naka Road, Village – Panvel, Taluka – Panvel, District – Raigad, Navi Mumbai, PIN – 410 206, State – Maharashtra, India.

Name of Owner: Mr. Hemant Ranjit Chitnawis.

This is to certify that on visual inspection, it appears that the structure of the Wing – C at "New Kanak Sarovar Co-op. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 41 years.

#### General Information:

A.		Introduction			
1	Name of Building	"New Kanak Sarovar Co-op. Hsg. Soc. Ltd."			
2	Property Address	Residential Flat No. 401, 4th Floor, Wing – C, "New Kanak Sarovar Co-op. Hsg. Soc. Ltd.", Plot No. 17 / 1, 2, 3 & 6, Old Thane Naka Road, Village – Panvel, Taluka – Panvel, District – Raigad, Navi Mumbai, PIN – 410 206, State – Maharashtra, India.			
3	Type of Building	Residential used			
4	No. of Floors	Stilt + 4 Upper Floors			
5	Whether stilt / podium / open parking provided	Open / Covered Car Parking			
6	Type of Construction	R.C.C. Framed Structure			
7	Type of Foundation	R.C.C. Footing			
8	Thickness of the External Walls	9" thick brick walls both sides plastered			
9	Type of Compound	Brick Masonry Walls			
10	Year of Construction 2004 (As per part occupancy certificate)				
11	Present age of building 19 years				
12	Residual age of the building	41 years Subject to proper, preventive periodic maintenance & structural repairs.			
13	No. of flats (Per Floor)	5 Flats on 4 <sup>th</sup> Floor			
14	Methodology adopted	As per visual site inspection			







B.	External Observation of the Building		
1	Plaster	Normal Condition	
2	Chajjas	Normal Condition	
3	Plumbing Normal Condition		
4	Cracks on the external walls	Not found	
5	Filling cracks on the external walls	Not found	
6	Cracks on columns & beams Not found		
7	Vegetation	Not found	
8	Leakages of water in the drainage pipes	Not found	
	or water pipes		
9	Dampness external in the wall due to	Not found	
	leakages		
10	Any other observation about the	The external condition of the building is in normal condition	
	condition of external side of the building		
С	Internal Observation of the comm	on areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Normal Condition	
2	Columns (Cracks & Leakages)	Normal Condition	
3	Ceiling (Cracks & Leakages)	Normal Condition	
4	Leakages inside the property	Not found	
5	Painting inside the property	Normal	
6	Maintenance of staircase & cracks	Normal	

D	Common Observation		
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws	
	- Laws No. 77 of the Model Bye Laws	under the Act the society shall conduct a Structural Audit	
	(Co-Operative Societies Act / Rules)	of the building of the society as follows	
2	Remark	No Structural Audit Report is furnished for the perusal	

#### Ε Conclusion

The captioned building is having Stilt + 4 Upper Floors which are constructed in year 2004 as per part occupancy certificate. Estimated future life under present circumstances is about 41 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 20.07.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs. Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

# For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar B. Chalikwar

Director

Chalikwar DN: cn=Sharadkumar B. Chalikwar, σ=Vastukala Consultants (l) Pvt. Ltd., σι.⇒CMD, email=cmd@vastukala.org, c: Date::2023.07.25 11:35:31 +05'30'

Auth. Sign

Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME/TCC/2021-22/85/13





# **Actual Site Photographs**





















