

```
{
  "typeOfReport": {
    "value": "Proposed_Buyer",
    "label": "Proposed Buyer"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64b67240f76ce54e5d42fc9a"
    },
    "type": "CREDITOFFICER",
    "_id": "64b67240f76ce54e5d42fc9c",
    "firstName": "Test",
    "lastName": "Apmc",
    "mobileNo": "",
    "workMobileNo": "0000000000",
    "email": "cb0439@corpbank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",
    "name": "Thane",
    "email": "thane@vastukala.com",
    "phone": "1234567890",
    "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
```

```
400 601",
  "city": "Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64b67240f76ce54e5d42fc9a",
  "name": "Turbhe Branch\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "cb0439@corpbank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Corporation Bank Building, 1st Floor, Unit 6Banking Complex Plot no
179, APMC Market, Sector 19 Turbhe Vashi Navi MUmbai\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62720e52afd7d55eddedc887",
    "role": "PICKUPPERSON",
    "firstName": "Harshad",
    "email": "harshad@vastukala.org",
    "lastName": "Panchal",
    "mobileNo": "9029575553",
```

```
"shortName": "HP",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "627362b3afd7d55eddee1ee7",
  "role": "SITEENGINEER",
  "firstName": "Vicky ",
  "email": "vicky@vastukala.org",
  "lastName": "Bhor",
  "mobileNo": "9004386288",
  "designation": "",
  "shortName": "VB",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
```

```
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": []
},
"clientType": {
"value": "BANK",
"label": "BANK"
},
"location": {
"latitude": "19.01340365935369",
"longitude": " 73.09093600859508"
},
"geo": {
"type": "Point",
"coordinates": [
0,
0
]
},
"siteVisit": {
"siteVisitStatus": false,
"schedule": [
{
"dateTime": "2023-07-26T05:00:00.000Z",
"remark": ""
},
{
"dateTime": "2023-07-26T05:00:00.000Z",
"remark": ""
},
{
"dateTime": "2023-07-26T05:00:00.000Z",
"remark": ""
},
{
"dateTime": "2023-07-26T05:00:00.000Z",
"remark": ""
}
```

```
    }
  ],
  "visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Panvel",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  }
}
```

```
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "448 & 449",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Gangotri",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
```

```
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
```

```
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "301",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
```



```
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "410 206",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
```

```
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
```

```
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"_id": "64c0af4e9d3a3e4ed9b9bb67",
"ownerName": "Mr. Sudhakar Dattaram Shelar & Mrs. Sanjana Sudhakar Shelar",
"ownerPhoneNo": "9307590398",
"fullAddress": "Residential Proposed Buyer No. 301, 3rd Floor, Gangotri, Plot No. 448
& 449, Village - Panvel, Taluka - Panvel, District - Raigad , Navi Mumbai, 410 206, State
- Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae125daa6d152c1801b352",
      "label": "Search Report"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "852401",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
document_1690349358051_Adobe_Scan_Jul_25_2023_1.pdf",
    "fileName": "document_1690349358051_Adobe_Scan_Jul_25_2023_1.pdf"
  },
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "18/03/2010",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Yogesh Haribhau Mhatre & Mrs. Shraddha Yogesh Mhatre",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Amrut Hanmant Shintre & Mr. Hanmant Mahadev Shintre"
    },
    "isHardCopy": false,
    "displayStatus": true,
  }
]
```



```
    "fileName": "document_1690807492323_Adobe_Scan_Jul_25_2023.pdf",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
document_1690807492323_Adobe_Scan_Jul_25_2023.pdf",
    "id": "751591",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Mon Jul 31 2023 18:14:52 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "002785",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "401963",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jul 26 2023 10:59:50 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Sudhakar Dattaram Shelar & Mrs. Sanjana Sudhakar Shelar",
    "phone": "9307590398",
    "ownershipShare": "",
    "email": "",
    "id": "144172"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5570950be569ff8d379",
    "name": "externalImg_1690629462959_Screenshot_2023072909525886_3d9111e2
d3171bf4882369f490c087b4.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/externalImg_1690629462959_Screens
hot_2023072909525886_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  }
],
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5570950be569ff8d37a",
    "name": "externalImg_1690629462979_IMG_20230729_4966.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalImg_1690629462979_IMG_20230729_4966.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5570950be569ff8d37b",
    "name": "externalImg_1690629462987_IMG_20230729_5696.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalImg_1690629462987_IMG_20230729_5696.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5570950be569ff8d37c",
    "name": "externalImg_1690629462991_IMG_20230729_43821.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalImg_1690629462991_IMG_20230729_43821.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5570950be569ff8d37d",
    "name": "externalImg_1690629462993_IMG_20230729_44549.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalImg_1690629462993_IMG_20230729_44549.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5570950be569ff8d37e",
    "name": "externalImg_r_1690629462742_IMG20230729093410.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalImg_r_1690629462742_IMG20230729093410.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64c4f5570950be569ff8d37f",
  "name": "externalimg_r_1690629462875_IMG20230729154406.jpg",
  "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalimg_r_1690629462875_IMG20230729154406.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c4f5570950be569ff8d380",
  "name": "externalimg_r_1690629462780_IMG20230729093414.jpg",
  "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalimg_r_1690629462780_IMG20230729093414.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c4f5570950be569ff8d381",
  "name": "externalimg_r_1690629462833_IMG20230729095716.jpg",
  "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalimg_r_1690629462833_IMG20230729095716.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c4f5570950be569ff8d382",
  "name": "externalimg_r_1690629462926_IMG20230729154410.jpg",
  "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalimg_r_1690629462926_IMG20230729154410.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c4f5690950be569ff8d401",
  "name": "externalimg_1690629481592_IMG_20230729_45544.jpg",
  "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalimg_1690629481592_IMG_20230729_45544.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "64c4f5690950be569ff8d402",
    "name": "externalimg_1690629481596_IMG_20230729_46459.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalimg_1690629481596_IMG_20230729_46459.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d403",
    "name": "externalimg_1690629481600_IMG_20230729_47427.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalimg_1690629481600_IMG_20230729_47427.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d404",
    "name": "externalimg_1690629481606_IMG_20230729_48225.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalimg_1690629481606_IMG_20230729_48225.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d405",
    "name": "externalimg_1690629481611_IMG_20230729_49655.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalimg_1690629481611_IMG_20230729_49655.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d406",
    "name": "externalimg_1690629481613_IMG_20230729_50162.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalimg_1690629481613_IMG_20230729_50162.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d407",
```

```
    "name": "externalImg_1690629481615_IMG_20230729_50580.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalImg_1690629481615_IMG_20230729_50580.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d408",
    "name": "externalImg_1690629481618_IMG_20230729_51115.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalImg_1690629481618_IMG_20230729_51115.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d409",
    "name": "externalImg_1690629481619_IMG_20230729_51672.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalImg_1690629481619_IMG_20230729_51672.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d40a",
    "name": "externalImg_1690629481621_IMG_20230729_52502.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalImg_1690629481621_IMG_20230729_52502.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d40b",
    "name": "externalImg_1690629481623_IMG_20230729_52927.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalImg_1690629481623_IMG_20230729_52927.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d40c",
    "name": "externalImg_1690629481625_IMG_20230729_53415.jpg",
```

```
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externallmg_1690629481625_IMG_20230729_53415.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d40d",
    "name": "externallmg_1690629481627_IMG_20230729_53982.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externallmg_1690629481627_IMG_20230729_53982.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d40e",
    "name": "externallmg_1690629481628_IMG_20230729_54308.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externallmg_1690629481628_IMG_20230729_54308.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d40f",
    "name": "externallmg_1690629481629_IMG_20230729_54681.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externallmg_1690629481629_IMG_20230729_54681.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d410",
    "name": "externallmg_1690629481631_IMG_20230729_54986.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externallmg_1690629481631_IMG_20230729_54986.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d411",
    "name": "externallmg_1690629481631_IMG_20230729_55341.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externallmg_1690629481631_IMG_20230729_55341.jpg",
```

```

    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d412",
    "name": "externalImg_1690629481634_IMG_20230729_55698.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalImg_1690629481634_IMG_20230729_55698.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c4f5690950be569ff8d413",
    "name": "externalImg_1690629481637_IMG_20230729_56477.jpg",
    "path": "cases/64c0af4e9d3a3e4ed9b9bb67/
externalImg_1690629481637_IMG_20230729_56477.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-07-26T05:29:50.563Z",
"updatedAt": "2023-07-31T12:44:52.671Z",
"__v": 0,
"invoiceId": "64c0af4f9d3a3e4ed9b9bbe",
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "62720e52afd7d55eddedc887",
"contactPersonName": "Mr. Sudhakar Dattaram Shelar & Mrs. Sanjana Sudhakar
Shelar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9307590398"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
