

```
{
  "typeOfReport": {
    "label": "Residential Row House ",
    "value": "Residential_Row_House_"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8cd"
    },
    "type": "CREDITOFFICER",
    "_id": "64991fbbc3eaaa5554d5b9d6",
    "firstName": "Swapnil",
    "lastName": "Bhuwad",
    "mobileNo": "",
    "workMobileNo": "9702538015",
    "email": "Swapnil@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "Swapnil",
    "expectedFees": 5000,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
```

```
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8cd",
  "branchCode": "000127",
  "type": "BRANCH",
  "name": "SME Hindu Colony Dadar Branch ",
  "email": "sbi.04114@sbi.co.in",
  "mobileNo": "02224101894",
  "alternateMobileNo": "",
  "address": "Bullet Building, Lakhmshi Nappu Road, Opposite Raje Chhatrapati
Shivaji Vidyalaya, Hindu Colony, Dadar (East), Mumbai - 400 014, State - Maharashtra,
Country - India. ",
  "ledgerName": "STATE BANK OF INDIA - Commercial Br. Dadar",
  "fax": "02224101892",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "PICKUPPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
```

```
"lastName": "Patkar",
"mobileNo": "7045746060",
"shortName": "RP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc575ece84bf289ba9e82d",
  "role": "SITEENGINEER",
  "firstName": "Deepak ",
  "email": "daksh7831@gmail.com",
  "lastName": "Jain ",
  "mobileNo": "9022815908",
  "designation": "",
  "shortName": "DJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": "",
"maker": "",
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.21941433145307",
  "longitude": "72.86321207170452"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86321207170452,
```

```
19.21941433145307
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mahathane",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
```

```
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbao",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Magathane Udhyan Darshan ",
  "label": false
}
```

```
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
```

```
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "44/176",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
}
```



```
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
```

```
    "value": "",
    "label": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
```

```
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64c1fee19d3a3e4ed9d2efc8",
"ownerName": "Ranjan Nagwekar ",
"ownerPhoneNo": "9082756133",
"appAddress": "44/746, Udyar Darshan - sahkari gruhnirman sanstha, chawl no - 43 to
47, Guomohar vasahat, Magathane, Borivali east ",
"remark": "contact person - Archana ",
"documents": [],
"caseNumber": "002803",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "941102",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jul 27 2023 10:51:37 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Ranjan Nagwekar ",
    "phone": "9082756133",
    "ownershipShare": "",
    "email": "",
    "id": "133812"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "64c33e8a0950be569fecf01a",
    "name":
"externallmg_1690517130300_IMG_20230727_142800_copy_1200x900.jpg",
    "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517130300_IMG_20230727_142800_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c33e8a0950be569fecf01b",
    "name":
"externallmg_1690517130316_IMG_20230727_142821_copy_1200x900.jpg",
    "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517130316_IMG_20230727_142821_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c33e8a0950be569fecf01c",
    "name":
"externallmg_1690517130330_IMG_20230727_143236_copy_1200x900.jpg",
    "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517130330_IMG_20230727_143236_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c33e8a0950be569fecf01d",
    "name":
"externallmg_1690517130346_IMG_20230727_143237_copy_1200x900.jpg",
    "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517130346_IMG_20230727_143237_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c33e980950be569fecf051",
    "name":
"externallmg_1690517143943_IMG_20230727_143238_copy_1200x900.jpg",
    "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517143943_IMG_20230727_143238_copy_1200x900.jpg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c33e980950be569fecf052",
    "name":
"externallmg_1690517143961_IMG_20230727_143240_copy_1200x900.jpg",
    "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517143961_IMG_20230727_143240_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c33e980950be569fecf053",
    "name":
"externallmg_1690517143977_IMG_20230727_143242_copy_1200x900.jpg",
    "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517143977_IMG_20230727_143242_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c33e980950be569fecf054",
    "name":
"externallmg_1690517143992_IMG_20230727_143254_copy_1200x1597.jpg",
    "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517143992_IMG_20230727_143254_copy_1200x1597.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c33e980950be569fecf055",
    "name":
"externallmg_1690517144014_IMG_20230727_143303_copy_1200x1600.jpg",
    "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144014_IMG_20230727_143303_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c33e980950be569fecf056",
```

```
    "name":
"externallmg_1690517144027_IMG_20230727_142740_copy_1200x900.jpg",
  "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144027_IMG_20230727_142740_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c33e980950be569fecf057",
  "name":
"externallmg_1690517144038_IMG_20230727_142744_copy_1200x900.jpg",
  "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144038_IMG_20230727_142744_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c33e980950be569fecf058",
  "name":
"externallmg_1690517144053_IMG_20230727_142750_copy_1200x900.jpg",
  "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144053_IMG_20230727_142750_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c33e980950be569fecf059",
  "name":
"externallmg_1690517144063_IMG_20230727_142752_copy_1200x900.jpg",
  "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144063_IMG_20230727_142752_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c33e980950be569fecf05a",
  "name":
"externallmg_1690517144076_IMG_20230727_142755_copy_1200x1600.jpg",
  "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144076_IMG_20230727_142755_copy_1200x1600.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c33e980950be569fecf05b",
  "name":
"externallmg_1690517144082_IMG_20230727_142811_copy_1200x1600.jpg",
  "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144082_IMG_20230727_142811_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c33e980950be569fecf05c",
  "name":
"externallmg_1690517144088_IMG_20230727_142812_copy_1200x1600.jpg",
  "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144088_IMG_20230727_142812_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c33e980950be569fecf05d",
  "name":
"externallmg_1690517144093_IMG_20230727_142815_copy_1200x900.jpg",
  "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144093_IMG_20230727_142815_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c33e980950be569fecf05e",
  "name":
"externallmg_1690517144103_IMG_20230727_142824_copy_1200x900.jpg",
  "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144103_IMG_20230727_142824_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c33e980950be569fecf05f",
  "name":
"externallmg_1690517144113_IMG_20230727_143230_copy_1200x1600.jpg",
```

```
    "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144113_IMG_20230727_143230_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c33e980950be569fecf060",
    "name":
"externallmg_1690517144122_IMG_20230727_143232_copy_1200x1600.jpg",
    "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144122_IMG_20230727_143232_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c33e980950be569fecf061",
    "name":
"externallmg_1690517144133_IMG_20230727_143300_copy_1200x1600.jpg",
    "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144133_IMG_20230727_143300_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c33e980950be569fecf062",
    "name":
"externallmg_1690517144140_IMG_20230727_143301_copy_1200x1600.jpg",
    "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144140_IMG_20230727_143301_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c33e980950be569fecf063",
    "name":
"externallmg_1690517144146_IMG_20230727_203824_copy_1200x1600.jpg",
    "path": "cases/64c1fee19d3a3e4ed9d2efc8/
externallmg_1690517144146_IMG_20230727_203824_copy_1200x1600.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```

"createdAt": "2023-07-27T05:21:37.571Z",  
"updatedAt": "2023-07-28T04:05:44.240Z",  
"\_\_v": 0,  
"updatedBy": "6006d4ce5080a310ac1fdfc2",  
"fullAddress": " Residential Row House No. 44/176, Ground Floor, Magathane Udhyan  
Darshan , Village - Mahathane, Mumbao, State - Maharashtra, India",  
"addressForMap": "",  
"caseReferredBy": "62723addafd7d55eddeddfe4",  
"contactPersonName": "Ranjan Nagwekar ",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "9082756133"

}

| <b>Name</b>   | <b>Length</b> | <b>Width</b> | <b>Total</b> |
|---------------|---------------|--------------|--------------|
| <hr/>         |               |              |              |
| Composition : |               |              |              |
| <hr/>         |               |              |              |
| Other         |               |              |              |
| Composition : |               |              |              |
| <hr/>         |               |              |              |