

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb32"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b942312e3",
    "firstName": "Rupesh M Kamdar",
    "email": "0_default_rupesh.kandar@sbi.co.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9892978940"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",
    "name": "Thane",
    "email": "thane@vastukala.com",
    "phone": "1234567890",
    "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) - 400 601",
```

```
"city": "Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb32",
  "branchCode": "000337",
  "type": "BRANCH",
  "name": "Thane Main Branch",
  "email": "sbi.00489@sbi.co.in",
  "mobileNo": "02225388402",
  "alternateMobileNo": "",
  "address": "Parsi Agyani Cross Lane,Jabhali Naka,Thane West-400601",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "64abdb2806d6ec174986d16b",
    "role": "PICKUPPERSON",
    "firstName": "Sahadu",
    "email": "thoratsahadu8679@gmail.com",
    "lastName": "Thorat",
    "mobileNo": "9422389642",
    "shortName": "ST",
```

```
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64c777a8a5c3051014f4dd1f",
  "role": "SITEENGINEER",
  "firstName": "Pratik",
  "email": "pratikjain2277@gmail.com",
  "lastName": "Jain",
  "mobileNo": "9619286285",
  "designation": "",
  "shortName": "Pratik",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
```

```
{
  "value": "IBBI/RV/07/2018/10366",
  "label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
]
],
```

```
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.23394082944806",
  "longitude": "72.83063693558229"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-07-31T06:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-07-31T06:00:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
```

```
"state": {
  "status": true,
  "name": "State",
  "key": "state",
  "value": "Maharashtra",
  "label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Borivali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Subrban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
```

```
"value": "Mumbai",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "9",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Casa Billisimo",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
```

```
"status": false,
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Gorai",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "189",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
```



```
"label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "46",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1504",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
```

```
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400 092",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  }
}
```

```
    },
    "locationMapImg": [],
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
  "rateVerify": {
    "status": false
  },
  "underConstruction": {
    "rccFootingFoundation": {
      "label": "RCC Footing/Foundation",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": true
    },
    "rccPlinth": {
      "label": "RCC Plinth",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "fullBuildingRcc": {
      "label": "Full Building Rcc",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "internalBrickWork": {
      "label": "Internal Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "externalBrickWork": {
      "label": "External Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    }
  },
}
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
```

```
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64c76590a5c3051014f4b281",
"ownerName": "Mr. Nirav Parmar",
"ownerPhoneNo": "8080605585",
"fullAddress": "Residential Flat No. 1504, Basement Floor, Wing - B, Casa Billisimo,
Gorai, Plot No. 9, Village - Borivali, Taluka - Borivali, District - Mumbai Subrban,
Mumbai, 400 092, State - Maharashtra, India",
```



```
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae128eaa6d152c1801b430",
      "label": "Aadhaar Card"
    },
    "inputs": {
      "documentDate": "12/07/1992"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName":
"document_1690789234784_eAadhaar_Unmasked_Nirav_Parmar_without_PW.pdf",
    "path": "cases/64c76590a5c3051014f4b281/
document_1690789234784_eAadhaar_Unmasked_Nirav_Parmar_without_PW.pdf",
    "id": "862903",
    "uploadedBy": "6430f74691d7c62df11f3f15",
    "createdAt": "Mon Jul 31 2023 13:10:40 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "002861",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "973261",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jul 31 2023 13:11:04 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Nirav Parmar",
    "phone": "8080605585",
    "ownershipShare": "",
    "email": "",
    "id": "825385"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
```

```
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7af8da5c3051014f59bb4",
    "name":
"externalImg_1690808205730_IMG_20230731_143843_copy_1200x900.jpg",
    "path": "cases/64c76590a5c3051014f4b281/
externalImg_1690808205730_IMG_20230731_143843_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7af8da5c3051014f59bb5",
    "name":
"externalImg_1690808205748_IMG_20230731_145226_copy_1200x900.jpg",
    "path": "cases/64c76590a5c3051014f4b281/
externalImg_1690808205748_IMG_20230731_145226_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7af8da5c3051014f59bb6",
    "name":
"externalImg_1690808205760_IMG_20230731_145922_copy_1200x1597.jpg",
    "path": "cases/64c76590a5c3051014f4b281/
externalImg_1690808205760_IMG_20230731_145922_copy_1200x1597.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7af8da5c3051014f59bb7",
    "name":
"externalImg_1690808205806_IMG_20230731_145924_copy_1200x1597.jpg",
    "path": "cases/64c76590a5c3051014f4b281/
externalImg_1690808205806_IMG_20230731_145924_copy_1200x1597.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7af8da5c3051014f59bb8",
```

```
    "name":  
    "externallmg_1690808205829_IMG_20230731_181042_copy_1200x900.jpg",  
    "path": "cases/64c76590a5c3051014f4b281/  
externallmg_1690808205829_IMG_20230731_181042_copy_1200x900.jpg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "64c7af8da5c3051014f59bb9",  
    "name":  
    "externallmg_1690808205845_IMG_20230731_143840_copy_1200x1600.jpg",  
    "path": "cases/64c76590a5c3051014f4b281/  
externallmg_1690808205845_IMG_20230731_143840_copy_1200x1600.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "64c7af8da5c3051014f59bba",  
    "name":  
    "externallmg_1690808205852_IMG_20230731_143914_copy_1200x1600.jpg",  
    "path": "cases/64c76590a5c3051014f4b281/  
externallmg_1690808205852_IMG_20230731_143914_copy_1200x1600.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "64c7af8da5c3051014f59bbb",  
    "name":  
    "externallmg_1690808205855_IMG_20230731_143916_copy_1200x1600.jpg",  
    "path": "cases/64c76590a5c3051014f4b281/  
externallmg_1690808205855_IMG_20230731_143916_copy_1200x1600.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "64c7af8da5c3051014f59bbc",  
    "name":  
    "externallmg_1690808205858_IMG_20230731_145228_copy_1200x900.jpg",  
    "path": "cases/64c76590a5c3051014f4b281/  
externallmg_1690808205858_IMG_20230731_145228_copy_1200x900.jpg",  
    "orientation": "landscape"  
  },  
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7af8da5c3051014f59bbd",
  "name":
"externallmg_1690808205870_IMG_20230731_145236_copy_1200x900.jpg",
  "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808205870_IMG_20230731_145236_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7af8da5c3051014f59bbe",
  "name":
"externallmg_1690808205877_IMG_20230731_145239_copy_1200x900.jpg",
  "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808205877_IMG_20230731_145239_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7af9fa5c3051014f59bf9",
  "name":
"externallmg_1690808223643_IMG_20230731_145242_copy_1200x900.jpg",
  "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223643_IMG_20230731_145242_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7af9fa5c3051014f59bfa",
  "name":
"externallmg_1690808223659_IMG_20230731_145244_copy_1200x900.jpg",
  "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223659_IMG_20230731_145244_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7af9fa5c3051014f59bfb",
  "name":
"externallmg_1690808223670_IMG_20230731_145248_copy_1200x900.jpg",
```

```
    "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223670_IMG_20230731_145248_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7af9fa5c3051014f59bfc",
    "name":
"externallmg_1690808223681_IMG_20230731_145249_copy_1200x900.jpg",
    "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223681_IMG_20230731_145249_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7af9fa5c3051014f59bfd",
    "name":
"externallmg_1690808223690_IMG_20230731_145251_copy_1200x1600.jpg",
    "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223690_IMG_20230731_145251_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7af9fa5c3051014f59bfe",
    "name":
"externallmg_1690808223694_IMG_20230731_145256_copy_1200x1600.jpg",
    "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223694_IMG_20230731_145256_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7af9fa5c3051014f59bff",
    "name":
"externallmg_1690808223697_IMG_20230731_145300_copy_1200x900.jpg",
    "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223697_IMG_20230731_145300_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64c7af9fa5c3051014f59c00",
  "name":
"externallmg_1690808223705_IMG_20230731_145304_copy_1200x900.jpg",
  "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223705_IMG_20230731_145304_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7af9fa5c3051014f59c01",
  "name":
"externallmg_1690808223716_IMG_20230731_145305_copy_1200x900.jpg",
  "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223716_IMG_20230731_145305_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7af9fa5c3051014f59c02",
  "name":
"externallmg_1690808223727_IMG_20230731_145311_copy_1200x900.jpg",
  "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223727_IMG_20230731_145311_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7af9fa5c3051014f59c03",
  "name":
"externallmg_1690808223734_IMG_20230731_145312_copy_1200x900.jpg",
  "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223734_IMG_20230731_145312_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7af9fa5c3051014f59c04",
  "name":
"externallmg_1690808223743_IMG_20230731_145637_copy_1200x1600.jpg",
  "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223743_IMG_20230731_145637_copy_1200x1600.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7af9fa5c3051014f59c05",
    "name":
"externallmg_1690808223748_IMG_20230731_145638_copy_1200x1600.jpg",
    "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223748_IMG_20230731_145638_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7af9fa5c3051014f59c06",
    "name":
"externallmg_1690808223753_IMG_20230731_150013_copy_1200x1600.jpg",
    "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223753_IMG_20230731_150013_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7af9fa5c3051014f59c07",
    "name":
"externallmg_1690808223763_IMG_20230731_150014_copy_1200x1600.jpg",
    "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223763_IMG_20230731_150014_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7af9fa5c3051014f59c08",
    "name":
"externallmg_1690808223772_IMG_20230731_150017_copy_1200x1600.jpg",
    "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223772_IMG_20230731_150017_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c7af9fa5c3051014f59c09",
```

```
    "name":
"externallmg_1690808223778_IMG_20230731_150019_copy_1200x1600.jpg",
  "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223778_IMG_20230731_150019_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7af9fa5c3051014f59c0a",
  "name":
"externallmg_1690808223785_IMG_20230731_181044_copy_1200x1600.jpg",
  "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223785_IMG_20230731_181044_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c7af9fa5c3051014f59c0b",
  "name":
"externallmg_1690808223791_IMG_20230731_181155_copy_1200x1600.jpg",
  "path": "cases/64c76590a5c3051014f4b281/
externallmg_1690808223791_IMG_20230731_181155_copy_1200x1600.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-07-31T07:41:04.656Z",
"updatedAt": "2023-07-31T12:57:03.887Z",
"__v": 0,
"invoiceId": "64c76590a5c3051014f4b28d",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Nirav Parmar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8080605585"
}
```


Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			