

```
{
  "typeOfReport": {
    "label": "Residential",
    "value": "Residential"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230faa",
    "firstName": "Dineshkumar Mishra",
    "email": "0_default_dineshkumar.nishra@sbi.co.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9022373500"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Dineshkumar Mishra",
    "expectedFees": 2500,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  }
}
```

```
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land & Building / _Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62727444afd7d55eddee092c",
    "role": "PICKUPPERSON",
    "firstName": "Shantilal",
    "email": "shantilal@vastukala.org",
    "lastName": "Patel",
```

```
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "627362b3afd7d55eddee1ee7",
  "role": "SITEENGINEER",
  "firstName": "Vicky ",
  "email": "vicky@vastukala.org",
  "lastName": "Bhor",
  "mobileNo": "9004386288",
  "designation": "",
  "shortName": "VB",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "designation": "",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"maker": "",
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
```

```
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
```

```
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.972219199567224",
  "longitude": "72.95513077139208"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.95513077139208,
    18.972219199567224
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-08-04T10:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "3E",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mandar",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "21",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Trans Railway Area",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
}
```

```
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Mazgaon Dock Madar CHSL",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```



```
"value": "",
"label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "511",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "New Panvel",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
```

```
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64ccba34f474da339ad4d3c8",
"ownerName": "Shailendra Mohan Parulekar ",
"ownerPhoneNo": "9870426379",
"appAddress": "Mazagon Dock Mandar co operative society Ltd\n511 5th floor Panvel
\nNew Mumbai ",
"remark": "Tomorrow soft copy required ",
"documents": [
  {
    "documentType": {
      "label": "Allotment Letter",
      "value": "60ae1246aa6d152c1801b2e5"
    },
    "isHardCopy": false,
    "path": "cases/64ccba34f474da339ad4d3c8/
document_1691138473606_343443.pdf",
    "fileName": "document_1691138473606_343443.pdf",
    "displayStatus": false,
    "id": "722461",
    "uploadedBy": "62727444afd7d55eddee092c",
```



```
"createdAt": "Fri Aug 04 2023 14:13:08 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Allotment Letter",
    "value": "60ae1246aa6d152c1801b2e5"
  },
  "isHardCopy": false,
  "path": "cases/64ccba34f474da339ad4d3c8/document_1691138529802_Mr_shailendra_Mohan_pulker_Racpc_chinchpokli_Dinesh_sir.pdf",
  "fileName": "document_1691138529802_Mr_shailendra_Mohan_pulker_Racpc_chinchpokli_Dinesh_sir.pdf",
  "displayStatus": false,
  "id": "907453",
  "uploadedBy": "62727444afd7d55eddee092c",
  "createdAt": "Fri Aug 04 2023 14:13:08 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "002941",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "321109",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Aug 04 2023 14:13:32 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shailendra Mohan Parulekar ",
    "phone": "9870426379",
    "ownershipShare": "",
    "email": "",
    "id": "289904"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013b93",
    "name": "externallmg_1691409185622_IMG_20230807_0170.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185622_IMG_20230807_0170.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013b94",
    "name": "externallmg_1691409185627_IMG_20230807_0498.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185627_IMG_20230807_0498.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013b95",
    "name": "externallmg_1691409185633_IMG_20230807_0937.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185633_IMG_20230807_0937.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013b96",
    "name": "externallmg_1691409185635_IMG_20230807_1483.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185635_IMG_20230807_1483.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013b97",
    "name": "externallmg_1691409185639_IMG_20230807_5349.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185639_IMG_20230807_5349.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64d0db21dc9f3034f3013b98",
    "name": "externallmg_1691409185646_IMG_20230807_5617.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185646_IMG_20230807_5617.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013b99",
    "name": "externallmg_1691409185650_IMG_20230807_51981.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185650_IMG_20230807_51981.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013b9a",
    "name": "externallmg_1691409185656_IMG_20230807_52564.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185656_IMG_20230807_52564.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013b9b",
    "name": "externallmg_1691409185659_IMG_20230807_53769.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185659_IMG_20230807_53769.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013b9c",
    "name": "externallmg_1691409185664_IMG_20230807_54406.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185664_IMG_20230807_54406.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "64d0db21dc9f3034f3013b9d",
    "name": "externallmg_1691409185667_IMG_20230807_55210.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185667_IMG_20230807_55210.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013b9e",
    "name": "externallmg_1691409185671_IMG_20230807_55671.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185671_IMG_20230807_55671.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013b9f",
    "name": "externallmg_1691409185674_IMG_20230807_56273.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185674_IMG_20230807_56273.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013ba0",
    "name": "externallmg_1691409185677_IMG_20230807_56657.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185677_IMG_20230807_56657.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013ba1",
    "name": "externallmg_1691409185680_IMG_20230807_56872.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185680_IMG_20230807_56872.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013ba2",
```

```
    "name": "externallmg_1691409185681_IMG_20230807_57106.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185681_IMG_20230807_57106.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013ba3",
    "name": "externallmg_1691409185682_IMG_20230807_57354.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185682_IMG_20230807_57354.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db21dc9f3034f3013ba4",
    "name": "externallmg_1691409185684_IMG_20230807_57588.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409185684_IMG_20230807_57588.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db3adc9f3034f3013c09",
    "name": "externallmg_1691409210478_IMG_20230807_57902.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409210478_IMG_20230807_57902.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db3adc9f3034f3013c0a",
    "name": "externallmg_1691409210479_IMG_20230807_58244.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409210479_IMG_20230807_58244.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db3adc9f3034f3013c0b",
    "name": "externallmg_1691409210482_IMG_20230807_58559.jpg",
```

```
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409210482_IMG_20230807_58559.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db3adc9f3034f3013c0c",
    "name": "externallmg_1691409210487_IMG_20230807_58903.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409210487_IMG_20230807_58903.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db3adc9f3034f3013c0d",
    "name": "externallmg_1691409210490_IMG_20230807_59266.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409210490_IMG_20230807_59266.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db3adc9f3034f3013c0e",
    "name": "externallmg_1691409210495_IMG_20230807_59596.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409210495_IMG_20230807_59596.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db3adc9f3034f3013c0f",
    "name": "externallmg_1691409210498_IMG_20230807_59910.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externallmg_1691409210498_IMG_20230807_59910.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db3adc9f3034f3013c10",
    "name": "externallmg_1691409210567_Screenshot_2023080713255825_3d9111e2
d3171bf4882369f490c087b4.jpg",
```

```
    "path": "cases/64ccba34f474da339ad4d3c8/externalImg_1691409210567_Screens
hot_2023080713255825_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db3adc9f3034f3013c11",
    "name": "externalImg_r_1691409210535_IMG20230807155216.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externalImg_r_1691409210535_IMG20230807155216.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d0db3adc9f3034f3013c12",
    "name": "externalImg_r_1691409210501_IMG20230807155212.jpg",
    "path": "cases/64ccba34f474da339ad4d3c8/
externalImg_r_1691409210501_IMG20230807155212.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-08-04T08:43:32.283Z",
"updatedAt": "2023-08-07T11:53:30.852Z",
"__v": 0,
"invoiceId": "64ccba34f474da339ad4d3d5",
"fullAddress": " Flat No. 511, 5th Floor, Wing - B, Mandar, Mazgaon Dock Madar
CHSL, Plot No. 3E, Sector 21, Trans Railway Area, New Panvel, State - Maharashtra,
India",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Shailendra Mohan Parulekar ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9870426379"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			