PROFORMA INVOICE

Invoice No. Dated Vastukala Consultants (I) Pvt Ltd B1-001.U/B FLOOR. PG-1936/23-24 9-Aug-23 BOOMERANG, CHANDIVALI FARM ROAD. Delivery Note Mode/Terms of Payment ANDHERI-EAST 400072 AGAINST REPORT GSTIN/UIN: 27AADCV4303R1ZX Reference No. & Date. Other References State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org Buyer's Order No. Dated Buyer (Bill to) STATE BANK OF INDIA Dispatch Doc No. Delivery Note Date RACPC SION BRANCH 003040 / 2301996 B-603 & 604, Kohinoor City, Commercial-1 6th Floor, Kirol Dispatched through Destination Road, Off L.B.S. Marg, Kurla (West), Mumbai - 400070 State - Maharashtra, Country - India GSTIN/UIN : 27AAACS8577K2ZO Terms of Delivery

State Name : Maharashtra, Code: 27

| SI No. | Particulars | / | HSN/SAC | GST Rate | Amount |
|-----------|---|--------------|---------|-------------|------------------------------|
| 1 | STRUCTURAL REPORT FEE (Technical Inspection and Certification Services) | CGST SGST | 997224 | 18 % | 2,500.00 225.00 225.00 |
| | | | | | |
| | | Total | 1 | | 2 950 00 |

Amount Chargeable (in words)

E. & O.E

Indian Rupee Two Thousand Nine Hundred Fifty Only

| HSN/SAC | Taxable Value | Central Tax | | State Tax | | Total |
|---------|------------------|-------------|--------|-----------|--------|------------|
| | | Rate | Amount | Rate | Amount | Tax Amount |
| 997224 | 2,500.00 | 9% | 225.00 | 9% | 225.00 | 450.00 |
| Total | 2,500.00 | | 225.00 | | 225.00 | 450.00 |

Tax Amount (in words): Indian Rupee Four Hundred Fifty Only

Company's Bank Details

Bank Name : State Bank of India

32632562114 A/c No.

Branch & IFS Code: MIDC Andheri (E) & SBIN0007074

Remarks:

Mr Chetan Pratap Rane & Mrs Veena Chetan Rane -Residential Flat No. 504, 5th Floor, Building No 50, Code No. 159, "Malwani Prathamesh Co-Op. Hsg. Soc. Ltd.", Shree Chhatrapati Shivaji Raje Complex, Opp. Ekta Nagar, Village - Malwani, Kandivali (West), Mumbai, Taluka - Borivali, District - Mumbai Suburban, 400 067, State - Maharashtra, India

Company's PAN

: AADCV4303R

Declaration

NOTE - AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137



UPI Virtual ID : vastukala@icici

for Vastukala Consultants (I) Pvt Ltd

Authorised Signatory

This is a Computer Generated Invoice





CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: SBI / RACPC Sion / Mr Chetan Pratap Rane (3040/2301996)

Page 1 of 3

Vastu/Mumbai/08/2023/3040/2301996 09/25-142-NIPA

Date: 09.08.2023

Structural Stability Report

Structural Observation Report of Residential Flat No. 504, 5th Floor, Building No 50, Code No. 159, "Malwani Prathamesh Co-Op. Hsg. Soc. Ltd.", Shree Chhatrapati Shivaji Raje Complex, Opp. Ekta Nagar, Village - Malwani, Kandivali (West), Mumbai, Taluka - Borivali, District - Mumbai Suburban, 400 067, State - Maharashtra, Country - India.

Name of Owner: Mr Chetan Pratap Rane & Mrs Veena Chetan Rane.

This is to certify that on visual inspection, it appears that the structure of "Malwani Prathamesh Co-Op. Hsg. Soc. Ltd." is in normal condition and the future life can be reasonably takes under normal condition and with proper periodic repairs & maintenance is about 38 years.

General Information:

| A. | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | Introduction |
|----|--|---|
| 1 | Name of Building | Malwani Prathamesh Co-Op. Hsg. Soc. Ltd. |
| 2 | Property Address | Residential Flat No. 504, 5th Floor, Building No 50, Code No. 159, "Malwani Prathamesh Co-Op. Hsg. Soc. Ltd.", Shree Chhatrapati Shivaji Raje Complex, Opp. Ekta Nagar, Village - Malwani, Kandivali (West), Mumbai, Taluka - Borivali, District - Mumbai Suburban, 400 067, State - Maharashtra, Country - India |
| 3 | Type of Building Residential | |
| 4 | No. of Floors | Ground + 7 Upper Floors |
| 5 | Whether stilt / podium / open parking provided | Open Car Parking |
| 6 | Type of Construction | R.C.C. Framed Structure |
| 7 | Type of Foundation | R.C.C. Footing |
| 8 | Thickness of the External Walls | 9" thick brick walls both sides plastered |
| 9 | Type of Compound | Brick Masonry Walls |
| 10 | Year of Construction | 2001 (As per occupancy certificate) |
| 11 | Present age of building | 22 years |
| 12 | Residual age of the building | 38 years Subject to proper, preventive periodic maintenance & structural repairs. |
| 13 | No. of flats (Per Floor) | 5th Floor is having 8 Flats |
| 14 | Methodology adopted | As per visual site inspection |





Regd. Office: B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 40/0072, (M.S..), INDIA
 TeleFax: +91 22 2837132/5/24

🧧 mumbai@vastukala.org

| B. | External Observation of the Building | | |
|----|---|---|--|
| 1 | Plaster | Normal Condition | |
| 2 | Chajjas | Normal Condition | |
| 3 | Plumbing | Normal Condition | |
| 4 | Cracks on the external walls | Found | |
| 5 | Filling cracks on the external walls | Found | |
| 6 | Cracks on columns & beams | Not Found | |
| 7 | Vegetation | Not Found | |
| 8 | Leakages of water in the drainage pipes or water pipes | Not Found | |
| 9 | Dampness external in the wall due to leakages | e wall due to Not Found | |
| 10 | Any other observation about the condition of external side of the building | The external condition of the building is in normal condition | |
| С | Internal Observation of the common areas of the building and captioned premises | | |
| 1 | Beams (Cracks & Leakages) | Normal Condition | |
| 2 | Columns (Cracks & Leakages) | Normal Condition | |
| 3 | Ceiling (Cracks & Leakages) | Normal Condition | |
| 4 | Leakages inside the property | Not Found | |
| 5 | Painting inside the property | Normal | |
| 6 | Maintenance of staircase & cracks | Normal | |

| D | Common Observation | |
|---|--|--|
| 1 | Structural Audit of the Building Under Bye | As per bye Laws No. 77 of Co-Op. Societies bye Laws |
| | - Laws No. 77 of the Model Bye Laws | under the Act the society shall conduct a Structural Audit |
| | (Co-Operative Societies Act / Rules) | of the building of the society as follows |
| 2 | Remark | No Structural Audit Report is furnished for the perusal |

E Conclusion

The captioned building is having Ground + 7 Upper Floors which are constructed in year 2001 (As per occupancy certificate). Estimated future life under present circumstances is about 38 years' subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 08.08.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.



Manoj Chalikwar

Govt. Reg. Valuer Chartered Engineer (India) Reg. No. IBBI/RV/07/2018/10366

SBI Empanelment No.: SME/TCC/2021-22/86/3





Actual Site Photographs

















