PROFORMA INVOICE

Vastukala Consultants (I) Pvt Ltd B1-001,U/B FLOOR, BOOMERANG, CHANDIVALI FARM ROAD, ANDHERI-EAST 400072 GSTIN/UIN: 27AADCV4303R1ZX

State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org

Buyer (Bill to)

JANASEVA SAHAKARI BANK-BHAYANDER EAST

BHAYANDER EAST

Janki Avanue 1st Floor Phatak Road. Bhaynder East Thane-401105

GSTIN/UIN

: 27AAAAJ1528R2ZA

State Name

: Maharashtra, Code: 27

| Invoice No. | Dated |
|-----------------------|-----------------------|
| PG-1950/23-24 | 10-Aug-23 |
| Delivery Note | Mode/Terms of Payment |
| Reference No. & Date. | Other References |
| Buyer's Order No. | Dated |
| Dispatch Doc No. | Delivery Note Date |
| 3081 / 2302011 | |
| Dispatched through | Destination |

Terms of Delivery

| SI No. | Particulars | | HSN/SAC | GST Rate | Amount |
|-----------|---|--------------|---------|-------------|------------------------------|
| 1 | STRUCTURAL REPORT FEE (Technical Inspection and Certification Services) | CGST SGST | 997224 | 18 % | 1,500.00 135.00 135.00 |
| | | Total | 1 | | 1,770.00 |
| Ām | ount Chargeable (in words) | | / | | E. & O.E |

Amount Chargeable (in words)

Indian Rupee One Thousand Seven Hundred Seventy Only

| HSN/SAC | Taxable Value | Central Tax | | State Tax | | Total |
|---------|------------------|-------------|--------|-----------|--------|------------|
| | | Rate | Amount | Rate | Amount | Tax Amount |
| 997224 | 1,500.00 | 9% | 135.00 | 9% | 135.00 | 270.00 |
| Total | 1,500.00 | | 135.00 | | 135.00 | 270.00 |

Tax Amount (in words) . Indian Rupee Two Hundred Seventy Only

Company's Bank Details

Bank Name

: ICICI BANK LTD

A/c No.

: 123105000319

Branch & IFS Code: MIG Colony, Bandra (E.), Mumbai & ICIC0001231

Remarks:

Shri. Ajay Kharpatiram Chaurasia - Commercial Shop No. 13, Ground Floor, "Ostwal Shopping Centre Co-op. Hsg. Soc. Ltd.", Jesal Park, Opp. Railway Station, Village Khari, Bhayandar (East), Thane - 401 105, State - Maharashtra, Country - India.

Company's PAN

: AADCV4303R

Declaration

NOTE - AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137

UPI Virtual ID : vastukala@icici

for Vastukala Consultants (I) Pvt Ltd

Authorised Signatory

This is a Computer Generated Invoice



Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001:2015 Certified Company

www.vastukala.org



CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: Janseva Sahakari Bank / Bhaynder (East) Branch / Shri. Ajay Kharpatiram Chaurasia (3081/2302011) Page 1 of 3

Vastu/Mumbai/08/2023/3081/2302011 10/14-157-SBSK Date: 10.08.2023

Structural Stability Report

Structural Observation Report of Commercial Shop No. 13, Ground Floor, "Ostwal Shopping Centre Co-op. Hsg. Soc. Ltd.", Jesal Park, Opp. Railway Station, Village Khari, Bhayandar (East), Thane – 401 105, State – Maharashtra, Country – India.

Name of Owner: Shri. Ajay Kharpatiram Chaurasia.

This is to certify that on visual inspection, it appears that the structure of the at "Ostwal Shopping Centre Coop. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 29 years.

General Information:

| A. | | Introduction | | |
|----|---|---|--|--|
| 1 | Name of Building | "Ostwal Shopping Centre Co-op. Hsg. Soc. Ltd." | | |
| 2 | Property Address | Commercial Shop No. 13, Ground Floor, "Ostwal Shopping Centre Co-op. Hsg. Soc. Ltd.", Jesal Park, Opp. Railway Station, Village Khari, Bhayandar (East), Thane – 401 105, State – Maharashtra, Country – India. | | |
| 3 | Type of Building | Residential used | | |
| 4 | No. of Floors | Ground + 7 Upper Floors | | |
| 5 | Whether stilt / podium / open parking provided | Open Car Parking | | |
| 6 | Type of Construction | R.C.C. Framed Structure | | |
| 7 | Type of Foundation | R.C.C. Footing | | |
| 8 | Thickness of the External Walls | 9" thick brick walls both sides plastered | | |
| 9 | Type of Compound | Brick Masonry Walls | | |
| 10 | Year of Construction 1992 (As per site information) | | | |
| 11 | Present age of building | 31 years at e. Create | | |
| 12 | Residual age of the building | 29 years Subject to proper, preventive periodic maintenance & structural repairs. | | |
| 13 | No. of flats (Per Floor) | 36 Shops on Ground Floor | | |
| 14 | Methodology adopted | As per visual site inspection | | |





| В. | External Observation of the Building | | |
|----|---|---|--|
| 1 | Plaster | Normal Condition | |
| 2 | Chajjas | Normal Condition | |
| 3 | Plumbing | Normal Condition | |
| 4 | Cracks on the external walls | Not found | |
| 5 | Filling cracks on the external walls | Not found | |
| 6 | Cracks on columns & beams | Not found | |
| 7 | Vegetation | Not found | |
| 8 | Leakages of water in the drainage pipes or water pipes | Not found | |
| 9 | Dampness external in the wall due to leakages | Not found | |
| 10 | Any other observation about the condition of external side of the building | The external condition of the building is in normal condition | |
| С | Internal Observation of the common areas of the building and captioned premises | | |
| 1 | Beams (Cracks & Leakages) | Normal Condition | |
| 2 | Columns (Cracks & Leakages) | Normal Condition | |
| 3 | Ceiling (Cracks & Leakages) | Normal Condition | |
| 4 | Leakages inside the property | Not found | |
| 5 | Painting inside the property | Normal | |
| 6 | Maintenance of staircase & cracks | Normal | |

| D | Common Observation | | | |
|-----|--|--|--|--|
| 1 | Structural Audit of the Building Under Bye | As per bye Laws No. 77 of Co-Op. Societies bye Laws | | |
| | - Laws No. 77 of the Model Bye Laws | s under the Act the society shall conduct a Structural Audit | | |
| _ 1 | (Co-Operative Societies Act / Rules) | of the building of the society as follows | | |
| 2 | Remark | No Structural Audit Report is furnished for the perusal | | |

E Conclusion

The captioned building is having Ground + 7 Upper Floors which are constructed in year 1992 (As per site information). Estimated future life under present circumstances is about 29 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 04.08.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar B. Chalikwar

Director

Oigitally signed by Sharadkumar B. Chalikwar
Dh. cn-Sharadkumar B. Chalikwar,
cs-Vastukala Consultants II) PM. Ltd.
ou-CMD, amale-condievastokala.org. CN
24t: 2021.08.11 10:02:27+05:30

Auth. Sign.

Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09

JSB Emp. No. 36/LOAN H.O./2016-17/232





Actual Site Photographs













