

## PROFORMA INVOICE

<b>Vastukala Consultants (I) Pvt Ltd</b> B1-001,U/B FLOOR, BOOMERANG,CHANDIVALI FARM ROAD, ANDHERI-EAST 400072 GSTIN/UIN: 27AADCV4303R1ZX State Name : Maharashtra, Code : 27 E-Mail : accounts@vastukala.org Buyer (Bill to) <b>STATE BANK INDIA-PBB CHINCHPOKLI</b> Voltas House A, Dr. Ambedkar Road, Chinchpokli (East), Mumbai-400033 State Name : Maharashtra, Code : 27	Invoice No. <b>PG-1960/23-24</b> Delivery Note Reference No. & Date. Buyer's Order No. Dispatch Doc No. <b>003090 / 2302020</b> Dispatched through Terms of Delivery	Dated <b>11-Aug-23</b> Mode/Terms of Payment <b>AGAINST REPORT</b> Other References Dated Delivery Note Date Destination
---	--	---

SI No.	Particulars	HSN/SAC	GST Rate	Amount
1	<b>STRUCTURAL REPORT FEE</b> <i>(Technical Inspection and Certification Services)</i>	997224	18 %	<b>2,500.00</b>
	<b>CGST</b>			<b>225.00</b>
	<b>SGST</b>			<b>225.00</b>
	<b>Total</b>			<b>2,950.00</b>

Amount Chargeable (in words) E. & O.E

**Indian Rupee Two Thousand Nine Hundred Fifty Only**

HSN/SAC	Taxable Value	Central Tax		State Tax		Total Tax Amount
		Rate	Amount	Rate	Amount	
997224	2,500.00	9%	225.00	9%	225.00	450.00
<b>Total</b>	<b>2,500.00</b>		<b>225.00</b>		<b>225.00</b>	<b>450.00</b>

Tax Amount (in words) : **Indian Rupee Four Hundred Fifty Only**

**Remarks:**

"Triveni Sudhir Walkar & Shri. Sudhir Madan Walkar - Residential Flat No. 102, 1st Floor, Building No 5, Wing - J, ""Shree Sai Complex Co-op. Hsg. Soc. Ltd."" , Plot No. 587 & 588, Sayani Road, Village - Lower Parel Division, Municipality Ward No. G/North, District - Mumbai, Prabhadevi, PIN - 400 025, State - Maharashtra, India"

Company's PAN : **AADCV4303R**

**Declaration**

NOTE - AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE.  
 MSME Registration No. - 27222201137

**Company's Bank Details**

Bank Name : **State Bank of India**  
 A/c No. : **32632562114**  
 Branch & IFS Code : **MIDC Andheri (E) & SBIN0007074**



UPI Virtual ID : vastukala@icici

for Vastukala Consultants (I) Pvt Ltd

*Ratod*  
 Authorised Signatory

This is a Computer Generated Invoice



**Vastukala Consultants (I) Pvt. Ltd.**

An ISO 9001:2015 Certified Company

www.vastukala.org



## Structural Stability Report

Structural Observation Report of Residential Flat No. 102, 1<sup>st</sup> Floor, Building No. 5, Wing – J, "Shree Sai Complex Co-op. Hsg. Soc. Ltd.", Plot No. 587 & 588, Sayani Road, Village – Lower Parel Division, Municipality Ward No. G/North, District – Mumbai, Prabhadevi, PIN – 400 025, State – Maharashtra, India.

Name of Owner: Triveni Sudhir Walkar & Shri. Sudhir Madan Walkar.

This is to certify that on visual inspection, it appears that the structure of the Building No. 5, Wing – J at "Shree Sai Complex Co-op. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 39 years.

### General Information:

A.	Introduction	
1	Name of Building	"Shree Sai Complex Co-op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 102, 1 <sup>st</sup> Floor, Building No. 5, Wing – J, "Shree Sai Complex Co-op. Hsg. Soc. Ltd.", Plot No. 587 & 588, Sayani Road, Village – Lower Parel Division, Municipality Ward No. G/North, District – Mumbai, Prabhadevi, PIN – 400 025, State – Maharashtra, India.
3	Type of Building	Residential used
4	No. of Floors	Stilt + 7 Upper Floors
5	Whether stilt / podium / open parking provided	Open / Covered Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2002 (As per site information)
11	Present age of building	21 years
12	Residual age of the building	39 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	2 Flats on 1 <sup>st</sup> Floor
14	Methodology adopted	As per visual site inspection



### Our Pan India Presence at :

Mumbai Aurangabad Pune Rajkot  
Thane Nanded Indore Raipur  
Delhi NCR Nashik Ahmedabad Jaipur

Regd. Office : B1-001, U/B Floor, Boomerang,  
Chandivali Farm Road, Andheri (East),  
Mumbai - 400 072, (M.S.), INDIA  
TeleFax : +91 22 28371325/24  
mumbai@vastukala.org

B.	External Observation of the Building	
1	Plaster	Good Condition
2	Chajjas	Good Condition
3	Plumbing	Good Condition
4	Cracks on the external walls	Not found
5	Filling cracks on the external walls	Not found
6	Cracks on columns & beams	Not found
7	Vegetation	Not found
8	Leakages of water in the drainage pipes or water pipes	Not found
9	Dampness external in the wall due to leakages	Found
10	Any other observation about the condition of external side of the building	The external condition of the building is in normal condition
C	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Good Condition
2	Columns (Cracks & Leakages)	Good Condition
3	Ceiling (Cracks & Leakages)	Good Condition
4	Leakages inside the property	Not found
5	Painting inside the property	Good
6	Maintenance of staircase & cracks	Good

D	Common Observation	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal

E	Conclusion
	<p>The captioned building is having Stilt + 7 Upper Floors which are constructed in year 2002 as per site information. Estimated future life under present circumstances is about 39 years subject to proper, preventive periodic maintenance &amp; structural repairs.</p> <p>The inspection dated 03.08.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition &amp; will stand future life subject to proper, preventive periodic maintenance &amp; good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only.</p>

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar  
B. Chalikwar

Digitally signed by Sharadkumar B. Chalikwar  
DN: cn=Sharadkumar B. Chalikwar,  
o=Vastukala Consultants (I) Pvt. Ltd.,  
ou=CMD, email=cmd@vastukala.org, c=IN  
Date: 2023.08.11 13:11:39 +05'30'



C.M.D.

Auth. Sign

Sharadkumar B. Chalikwar

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

SBI Panelment No.: SME/TCC/2021-22/85/13



Think.innovate.Create®

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001:2015 Certified Company

www.vastukala.org



## Actual Site Photographs

