

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9b2"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230efb",
    "firstName": "Pratibha Bhatia",
    "email": "0_default_pratibha.bhatia@cosmosbank.in",
    "mobileNo": "-",
    "workMobileNo": "9820701094",
    "lastName": "Bhatia"
  },
  "fees": {
    "type": "fixed"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
  }
}
```

```
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9b2",
  "branchCode": "000012",
  "type": "BRANCH",
  "name": "Bandra (West) Branch",
  "email": "pratibha.bhatia@cosmosbank.in",
  "mobileNo": "02226402884",
  "alternateMobileNo": "",
  "address": "16, Lubina Turner Road, Opp. Tava Restaurant Bandra (West), Mumbai -
400 050, State - Maharashtra, Country - India.",
  "ledgerName": "COSMOS BANK- BANDRA WEST BRANCH",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "PICKUPPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
```

```
"lastName": "Patkar",
"mobileNo": "7045746060",
"shortName": "RP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f949ce45132d6a6bddbcc3",
  "role": "SITEENGINEER",
  "firstName": "Tushar ",
  "email": "tusharbhuwad90@gmail.com",
  "lastName": "Bhuwad",
  "mobileNo": "9082053889",
  "designation": "",
  "shortName": "TSB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": "",
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
],
"type": "EMPLOYEE",
```

```
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
```

```
    }
  ]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.088379738846935",
  "longitude": "72.85651086107492"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85651086107492,
    19.088379738846935
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-08-28T03:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kole Kalyan",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sambhav Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Vakola",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
```

```
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
}
```



```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "501",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```

```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Santacruz East",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```

```
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "64ddf258ccaf1e7b7f658906",
"ownerName": "Maheshchandra D mehta",
"ownerPhoneNo": "9869143718",
"appAddress": "flat no 501,B wing, sambhav apartment, chatrapati Shivaji Maharaj
road, vakola bridge, Santacruz East ",
"remark": "tomorrow visit ",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "path": "cases/64ddf258ccaf1e7b7f658906/
document_1692268051377_CB_Bandra_Maheshchandra.pdf",
```



```
"fileName": "document_1692268051377_CB_Bandra_Maheshchandra.pdf",
"displayStatus": false,
"id": "825063",
"uploadedBy": "62723addafd7d55eddeddfe4",
"createdAt": "Thu Aug 17 2023 15:58:21 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003161",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
{
  "id": "490929",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Thu Aug 17 2023 15:41:36 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
  "name": "Maheshchandra D mehta",
  "phone": "9869143718",
  "ownershipShare": "",
  "email": "",
  "id": "130805"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1c27eb1f822256d73184",
  "name": "externalImg_1693195303601_IMG20230827WA0027.jpg",
  "path": "cases/64ddf258ccaf1e7b7f658906/
externalImg_1693195303601_IMG20230827WA0027.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64ec1c27eb1f822256d73185",
    "name": "externalimg_1693195303613_IMG20230827WA0028.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externalimg_1693195303613_IMG20230827WA0028.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c27eb1f822256d73186",
    "name": "externalimg_1693195303633_IMG20230827WA0020.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externalimg_1693195303633_IMG20230827WA0020.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c27eb1f822256d73187",
    "name": "externalimg_1693195303640_IMG20230827WA0021.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externalimg_1693195303640_IMG20230827WA0021.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c27eb1f822256d73188",
    "name": "externalimg_1693195303648_IMG20230827WA0022.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externalimg_1693195303648_IMG20230827WA0022.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c27eb1f822256d73189",
    "name": "externalimg_1693195303653_IMG20230827WA0023.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externalimg_1693195303653_IMG20230827WA0023.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "64ec1c27eb1f822256d7318a",
    "name": "externallmg_1693195303658_IMG20230827WA0024.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195303658_IMG20230827WA0024.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c27eb1f822256d7318b",
    "name": "externallmg_1693195303662_IMG20230827WA0025.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195303662_IMG20230827WA0025.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c27eb1f822256d7318c",
    "name": "externallmg_1693195303679_IMG20230827WA0026.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195303679_IMG20230827WA0026.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c27eb1f822256d7318d",
    "name": "externallmg_1693195303691_IMG20230827WA0029.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195303691_IMG20230827WA0029.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c27eb1f822256d7318e",
    "name": "externallmg_1693195303710_IMG20230827WA0030.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195303710_IMG20230827WA0030.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c3aeb1f822256d731cb",
```

```
    "name": "externalImg_1693195322199_IMG20230827WA0031.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externalImg_1693195322199_IMG20230827WA0031.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c3aeb1f822256d731cc",
    "name": "externalImg_1693195322204_IMG20230827WA0032.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externalImg_1693195322204_IMG20230827WA0032.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c3aeb1f822256d731cd",
    "name": "externalImg_1693195322218_IMG20230827WA0033.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externalImg_1693195322218_IMG20230827WA0033.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c3aeb1f822256d731ce",
    "name": "externalImg_1693195322223_IMG20230827WA0034.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externalImg_1693195322223_IMG20230827WA0034.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c3aeb1f822256d731cf",
    "name": "externalImg_1693195322228_IMG20230827WA0035.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externalImg_1693195322228_IMG20230827WA0035.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c3aeb1f822256d731d0",
    "name": "externalImg_1693195322232_IMG20230827WA0036.jpg",
```

```
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195322232_IMG20230827WA0036.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c3aeb1f822256d731d1",
    "name": "externallmg_1693195322236_IMG20230827WA0037.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195322236_IMG20230827WA0037.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c3aeb1f822256d731d2",
    "name": "externallmg_1693195322244_IMG20230827WA0038.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195322244_IMG20230827WA0038.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c3aeb1f822256d731d3",
    "name": "externallmg_1693195322248_IMG20230827WA0039.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195322248_IMG20230827WA0039.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c3aeb1f822256d731d4",
    "name": "externallmg_1693195322252_IMG20230827WA0040.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195322252_IMG20230827WA0040.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c3aeb1f822256d731d5",
    "name": "externallmg_1693195322256_IMG20230827WA0041.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195322256_IMG20230827WA0041.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1c3aeb1f822256d731d6",
  "name": "externallmg_1693195322260_IMG20230827WA0042.jpg",
  "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195322260_IMG20230827WA0042.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1c3aeb1f822256d731d7",
  "name": "externallmg_1693195322262_IMG20230827WA0043.jpg",
  "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195322262_IMG20230827WA0043.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1c3aeb1f822256d731d8",
  "name": "externallmg_1693195322270_IMG20230827WA0044.jpg",
  "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195322270_IMG20230827WA0044.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1c3aeb1f822256d731d9",
  "name": "externallmg_1693195322275_IMG20230827WA0045.jpg",
  "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195322275_IMG20230827WA0045.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1c3aeb1f822256d731da",
  "name": "externallmg_1693195322282_IMG20230827WA0046.jpg",
  "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195322282_IMG20230827WA0046.jpg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c3aeb1f822256d731db",
    "name": "externallmg_1693195322288_IMG20230827WA0047.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195322288_IMG20230827WA0047.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c3aeb1f822256d731dc",
    "name": "externallmg_1693195322292_IMG20230827WA0048.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195322292_IMG20230827WA0048.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c3aeb1f822256d731dd",
    "name": "externallmg_1693195322296_IMG20230827WA0049.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_1693195322296_IMG20230827WA0049.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c66eb1f822256d73271",
    "name":
"externallmg_r_1693195365837_IMG20230827011934_BURST000_COVER.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_r_1693195365837_IMG20230827011934_BURST000_COVER.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1c66eb1f822256d73272",
    "name": "externallmg_r_1693195365870_IMG20230827012031.jpg",
    "path": "cases/64ddf258ccaf1e7b7f658906/
externallmg_r_1693195365870_IMG20230827012031.jpg",
    "orientation": "landscape"
  }
}
```

```

    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "createdAt": "2023-08-17T10:11:36.040Z",
  "updatedAt": "2023-08-28T04:02:46.426Z",
  "__v": 0,
  "updatedBy": "6006d4ce5080a310ac1fdcf2",
  "fullAddress": " Flat No. 501, 5th Floor, Wing - B, Sambhav Apartment, Vakola, Village
- Kole Kalyan, Santacruz East, Mumbai",
  "addressForMap": "",
  "caseReferredBy": "5ffe92d27737ca4d986b6453",
  "contactPersonName": "Maheshchandra D mehta",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "9869143718",
  "remarks": []
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			