

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6273b00bafd7d55eddee5f69"
    },
    "type": "CREDITOFFICER",
    "_id": "6417f07e96b58848585ed4db",
    "firstName": "Jeetendra Vaity",
    "lastName": "Vaity",
    "mobileNo": "",
    "workMobileNo": "9987835248",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2500000",
    "discussWithPerson": "Jeetendra Vaity",
    "expectedFees": 1250,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6273b00bafd7d55eddee5f69",
  "name": "SPL PBB Fort",
  "branchCode": "4205 ",
  "mobileNo": "02223662641",
  "alternateMobileNo": "",
  "email": "sbi.04205@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate no 1 Horniman Circle Mumbai
samachar marg Fort."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
```

```
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "648fcad91b499c2d52dc86f3",
"role": "SITEENGINEER",
"firstName": "Barkat",
"email": "barkathodekar68@gmail.com",
"lastName": "Hodekar",
"mobileNo": "8879011615",
"designation": "Site Engg",
"shortName": "Barkat",
"workWithDocumentMaker": "",
"profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
```

```
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.119186809154822",
  "longitude": "72.93751661968545"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.93751661968545,
    19.119186809154822
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-23",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Hariyali ",
    "label": true
  }
},
```

```
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "192",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
```

```
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Chintan Anandmay Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kannamwar Nagar No. 2",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
```



```
"status": false,
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "356-A",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "7374",
```

```
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
```

```

    "name": "Postal Code",
    "key": "postalCode",
    "value": "PIN Code - 400 083",
    "label": false
  },
  "suburb": {
    "status": true,
    "name": "Suburb",
    "key": "suburb",
    "value": "Vikroli (East)",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Open_Windows",
    "label": "Aluminium Open Windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {

```

```
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "MCGM",
"label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Under Construction Building",
"west": "Service Road & Mumbai Agra National Highway",
"south": "Building No. 193",
"east": "Aatmaram Surve Marg & Vikhroli Police Station"
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "64.5",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "18194",
"depreciatedBuildingRate": "994"
},
"igrRate": {
"propertyName": "Kannamwar Nagar",
"rate": "139830",
"landRate": "58970",
"igrImage": "cases/64e48b4ddaee6a1c980e9d9c/igr_1692859144277_Image.png",
"squareMeterGuideLineRate": "125847.00",
"squareFeetGuideLineRate": "11692.00"
},
"igrFinalRate": {
```

```
"rate": "9020.00",
"squareFeetGuideLineRate": "9020.00",
"squareMeterGuideLineRate": "97090.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Seller_Occupied",
    "label": "Seller Occupied"
  },
  "monthlyRent": "10000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "N.A.",
  "floorSpaceIndex": "Details not available",
  "tenantName": "",
  "maintenanceOfFlat": "Details not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
```

```
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "1980",
"fullDate": "1/1/1980"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "RCC_Framed_Structure",
"label": "RCC Framed Structure"
},
"qualityOfConstruction": {
"value": "Normal",
"label": "Normal"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Average",
"label": "Average"
},
}
```

```
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "0",
  "label": "No"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "0",
  "label": "No"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
```

```
"label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "17",
"ageOfBuilding": "43",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "270.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64e48b4ddaae6a1c980e9d9c/
routeMap_1692861130994_Image.png",
    "routeLat": "19.118946",
    "routeLng": "72.937075",
    "stationName": "Vikhroli",
    "routeDistance": "1.8 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "5kvi93",
```



```
    "name": "5kvi93",
    "image": "cases/64e48b4ddaae6a1c980e9d9c/
routeMap_1692861196528_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "4912380.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "4912380.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2435400.00",
  "selectedBuildUpValue": "270.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64e5b211daae6a1c981051a9",
      "name": "externalimg_1692774832741_1692774694310_image_5.jpeg",
      "path": "cases/64e48b4ddaee6a1c980e9d9c/
externalimg_1692774832741_1692774694310_image_5.jpeg",
      "orientation": "landscape"
    }
  ]
},
],
```

```
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "64e5b211daae6a1c981051a8",
    "name": "externallmg_1692774832314_1692774694310_image_4.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774832314_1692774694310_image_4.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "64e5b211daae6a1c981051a9",
    "name": "externallmg_1692774832741_1692774694310_image_5.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774832741_1692774694310_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64e5b211daae6a1c981051ac",
    "name": "externallmg_1692774857005_1692774694310_image_8.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774857005_1692774694310_image_8.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "64e5b211daae6a1c981051b3",
    "name": "externallmg_1692774913420_1692774764877_image_5.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774913420_1692774764877_image_5.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "64e5b211daae6a1c981051a5",
    "name": "Living Room",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774826560_1692774694310_image_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64e5b211daae6a1c981051a6",
    "name": "Living Room",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774829116_1692774694310_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64e5b211daae6a1c981051ae",
    "name": "Living Room",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774891485_1692774764876_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64e5b211daae6a1c981051af",
    "name": "Living Room",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774892930_1692774764876_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64e5b211daae6a1c981051b0",
    "name": "Living Room",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774905150_1692774764876_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64e5b211daae6a1c981051b2",
    "name": "Living Room",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774912675_1692774764877_image_4.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": null,
"max": null
},
"builtUpRateRange": {
  "min": null,
  "max": null
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```



```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "270.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64e48b4ddaae6a1c980e9d9c",
"ownerName": "Mr. Prasad Balwant Mhase",
"ownerPhoneNo": "9967366517",
"appAddress": "Flat no 7374,2floor,Building No 192,Chintan Anandmay
CHS,Kannamwar Nagar 2,Vikhroli East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    }
  },

```

```
"inputs": {
  "documentDate": "31/07/2023",
  "from": {
    "value": "The_Transferor",
    "label": "The Transferor"
  },
  "The_Transferor": "Smt. Sunita Shivram Parab",
  "to": {
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Mr. Prasad Balwant Mhase, Mr. Balwant B. Mhase & Mrs. Nanda
Balwant Mhase"
},
"isHardCopy": false,
"displayStatus": true,
"id": "120925",
"path": "cases/64e48b4ddaae6a1c980e9d9c/
document_1692699107916_PRASAD_MHASE_1.pdf",
"fileName": "document_1692699107916_PRASAD_MHASE_1.pdf"
},
{
  "documentType": {
    "value": "60ae1257aa6d152c1801b335",
    "label": "Society Registration Certificate"
  },
  "inputs": {
    "documentDate": "19/01/1983",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "7968"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "849246",
  "path": "cases/64e48b4ddaae6a1c980e9d9c/
document_1692699177005_PRASAD_MHASE_3.pdf",
  "fileName": "document_1692699177005_PRASAD_MHASE_3.pdf"
},
{
  "documentType": {
    "value": "60ae1246aa6d152c1801b2e5",
    "label": "Allotment Letter"
  },
}
```

```
"inputs": {
  "documentDate": "27/05/1980",
  "from": {
    "value": "Developers",
    "label": "Developers"
  },
  "Developers": "Bombay Housing & Area Development Board",
  "to": {
    "value": "Allottee",
    "label": "Allottee"
  },
  "Allottee": "Shri. S. V. Redkar (Previous Owner)"
},
"isHardCopy": false,
"displayStatus": false,
"id": "779493",
"path": "cases/64e48b4ddaae6a1c980e9d9c/
document_1692699226964_PRASAD_MHASE_2.pdf",
"fileName": "document_1692699226964_PRASAD_MHASE_2.pdf"
},
{
  "documentType": {
    "label": "Title Search Report",
    "value": "60ae12a8aa6d152c1801b4a7"
  },
  "inputs": {
    "documentDate": "19/08/2023",
    "remark": "issued by S S P Legal"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "543646",
  "path": "cases/64e48b4ddaae6a1c980e9d9c/
document_1692699344883_PRASAD_MHASE_REPORT.pdf",
  "fileName": "document_1692699344883_PRASAD_MHASE_REPORT.pdf"
}
],
"caseNumber": "003296",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "380205",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Aug 22 2023 15:47:49 GMT+0530 (India Standard Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Mr. Prasad Balwant Mhase",
    "phone": "9967366517",
    "ownershipShare": "",
    "email": "",
    "id": "715221"
  },
  {
    "name": "Mr. Balwant B. Mhase",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "173847"
  },
  {
    "name": "Mrs. Nanda Balwant Mhase",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "547084"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "945835",
    "name": "Living Room",
    "length": "12.00",
    "length1": "12",
    "length2": "00",
    "width": "9.00",
    "width1": "9",
    "width2": "00",
    "totalArea": "108.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "108.00"
  },
  {
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "2",
"name": "Passage",
"length": "",
"length1": "2",
"length2": "9",
"width": "",
"width1": "4",
"width2": "0",
"totalArea": "11.00",
"images": [],
"finalArea": "11.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "6.58",
  "width1": "6",
  "width2": "7",
  "totalArea": "79.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "79.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilets",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "4.00",
```

```
"width1": "4",
"width2": "00",
"totalArea": "28.00",
"images": [],
"extraAreas": [],
"finalArea": "28.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "20.90",
  "totalAreaDocument": "225",
  "docBuiltpPercentage": "20",
  "docFinalBuiltp": "270.00",
  "docFinalBuiltpSquareMeter": "25.08",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "223156"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": false,
  "_id": "64e6fb441452884516b5a16f",
  "property": "Kanammwar Nagar, II, Vikhroli East, Mumbai",
  "area": "415",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Housing.Com",
  "expectedPrice": "8600000",
  "expectedRate": "20722.89",
```

```
"builtUpExpectedRate": "0.00",
"image": "cases/64e48b4ddaae6a1c980e9d9c/
indicator_1692858873214_Image.png",
"squareMeter": "38.55",
"id": "472192"
},
{
"printlnReport": false,
"_id": "64e6fb441452884516b5a170",
"property": "Kanammwar Nagar, II, Vikhroli East, Mumbai",
"area": "850",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"source": "https://www.99acres.com/",
"expectedPrice": "17500000",
"expectedRate": "20588.24",
"builtUpExpectedRate": "0.00",
"image": "cases/64e48b4ddaae6a1c980e9d9c/
indicator_1692858906119_Image.png",
"squareMeter": "78.97",
"id": "698061"
},
{
"printlnReport": false,
"_id": "64e6fb441452884516b5a171",
"property": "Kannamwar Nagar II, Vikhroli East",
"area": "220",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "https://www.99acres.com/",
"expectedPrice": "4800000",
"expectedRate": "21818.18",
"builtUpExpectedRate": "18181.82",
"image": "cases/64e48b4ddaae6a1c980e9d9c/
indicator_1692858970433_Image.png",
"squareMeter": "20.44",
"id": "231228"
},
{
"printlnReport": false,
"_id": "64e6fb441452884516b5a172",
"property": "Kannamwar Nagar II",
```

```
"area": "320",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"source": "magic_bricks",
"expectedPrice": "6500000",
"expectedRate": "20312.50",
"builtUpExpectedRate": "0.00",
"image": "cases/64e48b4ddaae6a1c980e9d9c/
indicator_1692859003872_Image.png",
"squareMeter": "29.73",
"id": "754776"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64e5b211daae6a1c981051a4",
"name": "externallmg_1692774823095_1692774694310_image_0.jpeg",
"path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774823095_1692774694310_image_0.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64e5b211daae6a1c981051a5",
"name": "externallmg_1692774826560_1692774694310_image_1.jpeg",
"path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774826560_1692774694310_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64e5b211daae6a1c981051a6",
"name": "externallmg_1692774829116_1692774694310_image_2.jpeg",
"path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774829116_1692774694310_image_2.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
```



```
    "_id": "64e5b211daae6a1c981051a7",
    "name": "externallmg_1692774829826_1692774694310_image_3.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774829826_1692774694310_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051a8",
    "name": "externallmg_1692774832314_1692774694310_image_4.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774832314_1692774694310_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051a9",
    "name": "externallmg_1692774832741_1692774694310_image_5.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774832741_1692774694310_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051aa",
    "name": "externallmg_1692774839195_1692774694310_image_6.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774839195_1692774694310_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051ab",
    "name": "externallmg_1692774849241_1692774694310_image_7.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774849241_1692774694310_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051ac",
```

```
    "name": "externallmg_1692774857005_1692774694310_image_8.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774857005_1692774694310_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051ad",
    "name": "externallmg_1692774860460_1692774694310_image_9.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774860460_1692774694310_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051ae",
    "name": "externallmg_1692774891485_1692774764876_image_0.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774891485_1692774764876_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051af",
    "name": "externallmg_1692774892930_1692774764876_image_1.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774892930_1692774764876_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051b0",
    "name": "externallmg_1692774905150_1692774764876_image_2.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774905150_1692774764876_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051b1",
    "name": "externallmg_1692774910201_1692774764877_image_3.jpeg",
```

```
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774910201_1692774764877_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051b2",
    "name": "externallmg_1692774912675_1692774764877_image_4.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774912675_1692774764877_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051b3",
    "name": "externallmg_1692774913420_1692774764877_image_5.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774913420_1692774764877_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051b4",
    "name": "externallmg_1692774914694_1692774764877_image_6.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774914694_1692774764877_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051b5",
    "name": "externallmg_1692774916399_1692774764877_image_7.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774916399_1692774764877_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e5b211daae6a1c981051b6",
    "name": "externallmg_1692774918679_1692774764877_image_8.jpeg",
    "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774918679_1692774764877_image_8.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e5b211daae6a1c981051b7",
  "name": "externallmg_1692774919815_1692774764877_image_9.jpeg",
  "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774919815_1692774764877_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64e5b211daae6a1c981051b8",
  "name": "externallmg_1692774783504_1692774658316_image_0.jpeg",
  "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774783504_1692774658316_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64e5b211daae6a1c981051b9",
  "name": "externallmg_1692774783907_1692774658316_image_1.jpeg",
  "path": "cases/64e48b4ddaae6a1c980e9d9c/
externallmg_1692774783907_1692774658316_image_1.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-22T10:17:49.609Z",
"updatedAt": "2023-08-24T09:18:23.365Z",
"__v": 0,
"invoiceId": "64e48b4ddaae6a1c980e9db0",
"fullAddress": "Residential Flat No. 7374, 2nd Floor, Building No 192, Wing - B,
Chintan Anandmay Co-op. Hsg. Soc. Ltd., Kannamwar Nagar No. 2, Village - Hariyali ,
Vikroli (East), Taluka - Kurla, District - Mumbai, PIN Code - 400 083, State -
Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Prasad Balwant Mhase",
"email": "",
"isExternal": "false",
```

```

"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9967366517",
"buildingServicesRate": "2800.00",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 270.00",
"flatRate": "20000",
"landOtherRate": "17200",
"briefDescOfProperty": "Living Room + Kitchen + Passage + Toilets",
"carpetTotal": "226.00",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "248.60",
"finalCarpetArea": "226.00",
"finalSalableArea": "273.46",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"siteVisitDate": "2023-08-23"

```

Name	Length	Width	Total
Composition :			
Living Room	12'00"	9'00"	108.00
Passage	2'9"	4'0"	11.00
Kitchen	12'00"	6'7"	79.00
Toilets	7'00"	4'00"	28.00

Other
Composition :
