



Structural Stability Report Prepared For: BOM / Kasarwadavli Branch / Mr. Prakash Mulchand Patel (3425/2302275)

Page 1 of 4

Vastu/Thane/08/3425/23002275 28/11-421-PSSH Date: 28.08.2023

Structural Stability Report

Structural Observation Report of Residential Flat No. 3, Ground Floor, Wing - B, **"Neelkanth Sadan"**, "Makar - Dhwaj Co-Op. Hsg. Soc. Ltd.", Gokhale Road, Vishnu Nagar, Village – Navagaon, Dombivli (West) Taluka – Kalyan, District - Thane, PIN Code - 421 202, State – Maharashtra, Country – India.

Name of Owners: Mr. Prakash Mulchand Patel & Mr. Mulchand Dahyabhai Patel.

This is to certify that on visual inspection, it appears that the structure of the "Neelkanth Sadan", "Makar - Dhwaj Co-Op. Hsg. Soc. Ltd." is in normal condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 29 years.

General Information:

Α.		Introduction				
1	Name of Building	"Neelkanth Sadan"				
2	Property Address	Residential Flat No. 3, Ground Floor, Wing - B, "Neelkanth				
		Sadan", "Makar - Dhwaj Co-Op. Hsg. Soc. Ltd.", Gokhale				
		Road, Vishnu Nagar, Village – Navagaon, Dombivli (West)				
	U	Taluka – Kalyan, District - Thane, PIN Code - 421 202,				
		State – Maharashtra, Country – India				
3	Type of Building	Residential used				
4	No. of Floors	Ground + 4 Upper Floors				
5	Whether stilt / podium / open parking	Open Parking				
	provided					
6	Type of Construction	R.C.C. Framed Structure				
7	Type of Foundation	R.C.C. Footing				
8	Thickness of the External Walls	9" thick brick walls both sides plastered				
9	Type of Compound	Brick Masonry Walls C C C C				
10	Year of Construction	1992 (As per Site Information)				
11	Present age of building	31 Years				
12	Residual age of the building	29 years Subject to proper, preventive periodic				
		maintenance & structural repairs.				
13	No. of flats (Per Floor)	Ground Floor is having 4 Flats				
14	Methodology adopted	As per visual site inspection				





Thane : 101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) - 400 601, (M.S.), INDIA E-mail : thane@vastukala.org, Tel. : 80978 82976 / 90216 25621

(Our Pan India Presence at :							
9	Mumbai Thane Delhi NCR	9	Aurangabad Nanded Nashik	9	Pune Indore Ahmedabad	9	Rajkot Raipur Jaipur	

Regd. Office : B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

- 🖀 TeleFax : +91 22 28371325/24
- 🖂 mumbai@vastukala.org

В.	External Observation of the Building					
1	Plaster	Good Condition				
2	Chajjas	Good Condition				
3	Plumbing	Good Condition				
4	Cracks on the external walls	Found				
5	Filling cracks on the external walls	Not found				
6	Cracks on columns & beams	Not found				
7	Vegetation	Not found				
8	Leakages of water in the drainage pipes	Not found				
	or water pipes					
9	Dampness external in the wall due to	Found				
	leakages					
10	Any other observation about the condition	The external condition of the building is in normal condition				
	of external side of the building					
С	Internal Observation of the comm	on areas of the building and captioned premises				
1	Beams (Cracks & Leakages)	Not found				
2	Columns (Cracks & Leakages)	Not found				
3	Ceiling (Cracks & Leakages)	Not found				
4	Leakages inside the property	Not found				
5	Painting inside the property	Good				
6	Maintenance of staircase & cracks	Good				

D	Common Observation					
1		As per bye Laws No. 77 of Co-Op. Societies bye Laws				
	– Laws No. 77 of the Model Bye Laws (Co-	under the Act the society shall conduct a Structural Audit of				
	Operative Societies Act / Rules)	the building of the society as follows				
2	Remark	No Structural Audit Report is furnished for the perusal				

E Conclusion

The captioned building is having Ground + 4 Upper Floors which are constructed in year 1992 as per site information. Estimated future life under present circumstances is about 29 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 05.08.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & normal structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only. ate. Create

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Director


Auth. Sign.

Manoj B. Chalikwar Registered Valuer Chartered Engineer (India) Reg. No. CAT-I-F-1763 BOM Emp. No. AX33/CREMON/Valuer / Empanelment/2021-22





Actual Site Photographs





3





Actual Site Photographs8



Think.Innovate.Create



