

Structural Stability Report

Structural Observation Report of Residential Flat No. 1003, 10th Floor, Wing – A, "Sai Anand Plaza", "Ekata – Safalya Co-Op. Hsg. Soc. Ltd.", Azad Nagar No. 2, Near Vikas Complex, Meenatai Thakare Chowk, L. B. S. Marg, Village - Panchpakhadi, Thane (West), Taluka & District - Thane, PIN Code – 400 601, State - Maharashtra, Country – India.

Name of Owners: **Mr. Rajendra Naik.**

This is to certify that on visual inspection, it appears that the structure of the "Sai Anand Plaza", "Ekata – Safalya Co-Op. Hsg. Soc. Ltd." is in normal condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 44 years.

General Information:

A.	Introduction	
1	Name of Building	" Sai Anand Plaza "
2	Property Address	Residential Flat No. 1003, 10 th Floor, Wing – A, "Sai Anand Plaza", "Ekata – Safalya Co-Op. Hsg. Soc. Ltd.", Azad Nagar No. 2, Near Vikas Complex, Meenatai Thakare Chowk, L. B. S. Marg, Village - Panchpakhadi, Thane (West), Taluka & District - Thane, PIN Code – 400 601, State - Maharashtra, Country – India.
3	Type of Building	Residential used
4	No. of Floors	Basement + Ground + 11 Upper Floors
5	Whether stilt / podium / open parking provided	Basement Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2007 (As per Occupancy Certificate)
11	Present age of building	16 Years
12	Residual age of the building	44 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	10 th Floor is having 4 Flats
14	Methodology adopted	As per visual site inspection



www.vastukala.org

Thane : 101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) - 400 601, (M.S.), INDIA
E-mail : thane@vastukala.org, Tel. : 80978 82976 / 90216 25621

Our Pan India Presence at :

- Mumbai
- Thane
- Delhi NCR
- Aurangabad
- Nanded
- Nashik
- Pune
- Indore
- Ahmedabad
- Rajkot
- Raipur
- Jaipur

Regd. Office : B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA
TeleFax : +91 22 28371325/24
mumbai@vastukala.org



B. External Observation of the Building		
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Not found
5	Filling cracks on the external walls	Not found
6	Cracks on columns & beams	Not found
7	Vegetation	Not found
8	Leakages of water in the drainage pipes or water pipes	Not found
9	Dampness external in the wall due to leakages	Not found
10	Any other observation about the condition of external side of the building	The external condition of the building is in good condition. External painting work was in progress.
C Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Not found
2	Columns (Cracks & Leakages)	Not found
3	Ceiling (Cracks & Leakages)	Not found
4	Leakages inside the property	Not found
5	Painting inside the property	Good
6	Maintenance of staircase & cracks	Good

D Common Observation		
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal

E Conclusion	
<p>The captioned building is having Basement + Ground + 11 Upper Floors which are constructed in year 2007 as per Occupancy Certificate. Estimated future life under present circumstances is about 44 years subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 24.06.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in good condition & will stand future life subject to proper, preventive periodic maintenance & normal structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Director

Auth. Sign.

Manoj B. Chalikwar


Registered Valuer

Chartered Engineer (India)

Reg. No. CAT-I-F-1763

SBI Empanelment No.: SME/TCC/2021-22/86/3

Actual Site Photographs



Actual Site Photographs8



Think.Innovate.Create