

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "79.00000",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": 0.0395,
    "quotedAmount": "2950"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
```

```
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.082338473332555",
  "longitude": "73.00206974907582"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.00206974907582,
    19.082338473332555
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-09-06T03:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-09-06T03:30:00.000Z",
      "remark": ""
    }
  ]
}
```

```
    "dateTime": "2023-09-06T03:30:00.000Z",
    "remark": ""
  }
],
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Vashi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
```

```
"key": "buildingNo",
"value": "A Type",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "12 & 13",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Indu Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
```

```
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "14",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
```



```
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "A-1",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
```

```
"status": false,
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 703",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
```

```
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "CIDCO",
    "label": "City Industrial Development Corporation of Maharashtra"
  }
}
```

```
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Saravana CHSL",
  "west": "Radhika CHSL / Sai Vaibhav Building",
  "south": "Internal Road",
  "east": "Internal Road"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "54",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "1350",
  "depreciatedCostOfConstruction": "14650.00",
  "depreciatedBuildingRate": "1150"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "131600",
  "landRate": "52500",
  "igrImage": "cases/64f71faceb1f822256e4c882/igr_1694003811061_Image.png",
  "squareMeterGuideLineRate": "131600.00",
  "squareFeetGuideLineRate": "12226.00"
},
"igrFinalRate": {
  "rate": "9581.00",
  "squareMeterGuideLineRate": "103124.00",
  "squareFeetGuideLineRate": "9581.00",
  "depreciationPercentage": "64"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  }
}
```

```
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "19,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per CIDCO nomrs",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  }
},
"waterTank": {
  "value": "CIDCO",
  "label": "CIDCO"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Yes",
```

```
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1987",
  "fullDate": "1/1/1987"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
```

```
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_agreement",
  "label": "As per agreement"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "24",
"ageOfBuilding": "36",
"noOfBasement": "",
"noOfPodium": ""
```

```
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "609.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64f71faceb1f822256e4c882/
routeMap_1693998174222_Image.png",
    "routeLat": "19.082056",
    "routeLng": "73.002000",
    "stationName": "Vashi",
    "routeDistance": "2.7KM"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "0odh9v",
      "name": "0odh9v",
      "image": "cases/64f71faceb1f822256e4c882/
routeMap_1693998022858_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
```



```
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "8921850.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "8921850.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
```

```
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5834829.00",
  "selectedBuildUpValue": "609.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64f8533a63830d2aa3b4082c",
      "name": "externalimg_r_1693995834351_05306__20230906_121557PM__kkk
mmjlmkmmkkkkkImkkmmkmmkkmmkkkkmmkkkkommmmmmmkmmmmjlmkmmkmmkmmkmmkmmkmm
mkk__line4__line1_____hnbm_lmmmmmmmmmmmm_mmmmkmmmmmmmmmmmmmmmm
mmmmmmmmmm_mmmm_mmmm_mm_mmmkkm__org.jpg",
      "path": "cases/64f71faceb1f822256e4c882/externalimg_r_1693995834351_05306
__20230906_121557PM__kkkmjlmkmmkkkkkImkkmmkmmkkmmkkkkommmmmmmkmm
kmmjlmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmm
m_mmmmkmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmm
rg.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
```

```
"status": false,
  "_id": "64f8533a63830d2aa3b40824",
  "name": "externallmg_1693995834356_05307__20230906_121605PM__kkkmm
jlmkmmkkkklmkkmmkkmmkkkmmkkkkommmmmmmkmmkmmjlmkmmkmmkmmkmmkmmkmmkmmk
__line4__line1____hnbm_lmmmmmmmmmmmmmmmmmmkmmmmmmmmmmmmmmmmmmmmmm
mmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmm
"org.jpg",
  "path": "cases/64f71faceb1f822256e4c882/externallmg_1693995834356_05307__
_20230906_121605PM__kkkmmjlmkmmkkkklmkkmmkkmmkkkmmkkkkommmmmmmkmmkmm
mjlmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmk
__line4__line1____hnbm_lmmmmmmmmmmmmmmmmmmkmmmmmmmmmmmmmmmmmmmmmm
mmmmkmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmm
pg",
  "orientation": "portrait"
}
],
"externalPhotos": [
  {
    "status": false,
    "_id": "64f8533a63830d2aa3b4082d",
    "name": "externallmg_r_1693995834366_05309__20230906_121728PM__kkk
mmjlmkmmkkkklmkkmmkkmmkkkmmkkkkommmmmmmkmmkmmjlmkmmkmmkmmkmmkmmkmmkmm
mkk__line4__line1____hnbm_lmmmmmmmmmmmmmmmmmmkmmmmmmmmmmmmmmmmmmmmmm
mmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmm
"org.jpg",
    "path": "cases/64f71faceb1f822256e4c882/externallmg_r_1693995834366_05309
__20230906_121728PM__kkkmmjlmkmmkkkklmkkmmkkmmkkkmmkkkkommmmmmmkmmkmm
kmmjlmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmk
m__mmmmkmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmm
rg.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64f8533a63830d2aa3b4082a",
    "name": "externallmg_r_1693995834347_05305__20230906_121555PM__kkk
mmjlmkmmkkkklmkkmmkkmmkkkmmkkkkommmmmmmkmmkmmjlmkmmkmmkmmkmmkmmkmmkmm
mkk__line4__line1____hnbm_lmmmmmmmmmmmmmmmmmmkmmmmmmmmmmmmmmmmmmmmmm
mmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmm
"org.jpg",
    "path": "cases/64f71faceb1f822256e4c882/externallmg_r_1693995834347_05305
__20230906_121555PM__kkkmmjlmkmmkkkklmkkmmkkmmkkkmmkkkkommmmmmmkmmkmm
kmmjlmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmk
m__mmmmkmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmm
rg.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
```



```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "609.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
```

```
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"_id": "64f71faceb1f822256e4c882",
"ownerName": "Ms. Jyoti Kadam",
"ownerPhoneNo": "9224314313",
"appAddress": "flat no. A 1 Ground floor indu co. opertive H s Ltd plot no 12 sector
14 vashi ",
"remark": "Ravindra sir code sandeep sir \nsir Urgent ahe ",
"documents": [
  {
    "documentType": {
      "value": "60ae1254aa6d152c1801b326",
      "label": "Agreement For Sale"
    },
    "inputs": {
      "documentDate": "05/09/2023",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Amol Badgujar",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Ms. Jyoti Kadam"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "773570",
    "path": "cases/64f71faceb1f822256e4c882/
document_1693971672599_Sbi_Rscpc_Belapur_Jyoti_kadam.pdf",
    "fileName": "document_1693971672599_Sbi_Rscpc_Belapur_Jyoti_kadam.pdf"
  },
  {
    "documentType": {
      "value": "60af71e62ffdf65bcd65862c",
      "label": "NOC"
    },
    "inputs": {
      "documentDate": "18/08/2023",
      "nameOfApprovingAuthority": {
        "value": "CIDCO",
        "label": "CIDCO"
      },
      "to": {
        "value": "Seller",
```

```
    "label": "Seller"
  },
  "Seller": "Amol Madhukar Badgujar"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1694004305311_NOC_for_Transfer.pdf",
"path": "cases/64f71faceb1f822256e4c882/
document_1694004305311_NOC_for_Transfer.pdf",
"id": "341430",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Wed Sep 06 2023 18:15:05 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d6",
    "label": "Society No Due Certificate"
  },
  "inputs": {
    "documentDate": "21/06/2023",
    "nameOfApprovingAuthority": {
      "value": "SOCIETY",
      "label": "SOCIETY"
    }
  }
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1694004406783_No_Due_Cum_No_Objection.pdf",
"path": "cases/64f71faceb1f822256e4c882/
document_1694004406783_No_Due_Cum_No_Objection.pdf",
"id": "327255",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Wed Sep 06 2023 18:16:46 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003589",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "907928",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Sep 05 2023 18:01:40 GMT+0530 (India Standard Time)"
  }
],
"owners": [
```

```
{
  "name": "Ms. Jyoti Kadam",
  "phone": "9224314313",
  "ownershipShare": "",
  "email": "",
  "id": "610843"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "685392",
    "name": "Passage",
    "length": "3.00",
    "length1": "3",
    "length2": "00",
    "width": "4.00",
    "width1": "4",
    "width2": "00",
    "totalArea": "12.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "12.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Living Room",
    "length": "9.58",
    "length1": "9",
    "length2": "7",
    "width": "16.92",
    "width1": "16",
    "width2": "11",
    "totalArea": "162.12",
    "images": [],
    "extraAreas": [],
    "finalArea": "162.12"
  }
]
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "",
  "length1": "6",
  "length2": "7",
  "width": "",
  "width1": "3",
  "width2": "0",
  "totalArea": "19.75",
  "images": [],
  "finalArea": "19.75",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "",
  "length1": "5",
  "length2": "3",
  "width": "",
  "width1": "7",
  "width2": "7",
  "totalArea": "39.81",
  "images": [],
  "finalArea": "43.81",
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "64f8611963830d2aa3b42b1c",
      "name": "Toilet",
      "extraAreaType": "Add",
      "length": "1.00",
      "length1": "1",
```

```
    "length2": "00",
    "width": "4.00",
    "width1": "4",
    "width2": "00",
    "totalArea": "4.00"
  }
]
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "6.67",
  "length1": "6",
  "length2": "8",
  "width": "12.50",
  "width1": "12",
  "width2": "6",
  "totalArea": "83.33",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "64f861c363830d2aa3b42cb2",
      "name": "Kitchen",
      "extraAreaType": "Add",
      "length": "3.50",
      "length1": "3",
      "length2": "6",
      "width": "6.50",
      "width1": "6",
      "width2": "6",
      "totalArea": "22.75"
    }
  ],
  "finalArea": "106.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "9.25",
  "length1": "9",
  "length2": "3",
  "width": "13.67",
  "width1": "13",
  "width2": "8",
  "totalArea": "126.42",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "64f8620f63830d2aa3b42dd2",
      "name": "Bedroom",
      "extraAreaType": "Add",
      "length": "2.00",
      "length1": "2",
      "length2": "00",
      "width": "6.00",
      "width1": "6",
      "width2": "00",
      "totalArea": "12.00"
    }
  ],
  "finalArea": "138.42000000000002"
},
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1254aa6d152c1801b326",
      "label": "Agreement For Sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },
  "id": "388872",
```

```
"selectAreaTypeDocument": "Built_Up",
"totalAreaDocument": "609",
"squareMeterArea": "56.58",
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docBuiltupPercentage": "",
"docSaleablePercentage": "20",
"docFinalSaleable": "730.8",
"docFinalSaleableSquareMeter": "67.896"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "64f8726c63830d2aa3b46220",
  "property": "Residential Flat",
  "area": "420",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "8500000",
  "expectedRate": "20238.10",
  "builtUpExpectedRate": "16865.08",
  "image": "cases/64f71faceb1f822256e4c882/indicator_1694003686700_Image.png",
  "squareMeter": "39.02",
  "id": "735420"
},
{
  "printlnReport": true,
  "_id": "64f8726c63830d2aa3b46221",
  "property": "Residential Flat",
  "area": "600",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "9990000",
  "expectedRate": "16650.00",
  "builtUpExpectedRate": "0.00",
  "image": "cases/64f71faceb1f822256e4c882/indicator_1694003711560_Image.png",
  "squareMeter": "55.74",
  "id": "179498"
}
```



```
},
{
  "printlnReport": true,
  "_id": "64f8726c63830d2aa3b46222",
  "property": "Residential Flat",
  "area": "550",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "7200000",
  "expectedRate": "13090.91",
  "builtUpExpectedRate": "0.00",
  "image": "cases/64f71faceb1f822256e4c882/indicator_1694003733416_Image.png",
  "squareMeter": "51.10",
  "id": "835316"
},
{
  "printlnReport": true,
  "_id": "64f8726c63830d2aa3b46223",
  "property": "Residential Flat",
  "area": "575",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "8600000",
  "expectedRate": "14956.52",
  "builtUpExpectedRate": "0.00",
  "image": "cases/64f71faceb1f822256e4c882/indicator_1694003758555_Image.png",
  "squareMeter": "53.42",
  "id": "962720"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f8533a63830d2aa3b40824",
    "name": "externallmg_1693995834356_05307___20230906_121605PM___kkkmmjl  
mkmkkkklmkkmkkmmkkkmmkkkkommmmmmmkmmjmlkmmkmmkmmkmmkmmkmmkmmkmmk  
___line4___line1_____hnbm_lmmmmmmmmmm_mmmmmkmmmmmmmmmmmmmmmm  
mmmmmm_mmmm_mmmm_mm_mmmkkm___org.jpg",
    "path": "cases/64f71faceb1f822256e4c882/externallmg_1693995834356_05307___
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f8533a63830d2aa3b40829",
  "name": "externallmg_1693995834431_Screenshot_20230906_154615.jpg",
  "path": "cases/64f71faceb1f822256e4c882/
externallmg_1693995834431_Screenshot_20230906_154615.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f8533a63830d2aa3b4082a",
  "name": "externallmg_r_1693995834347_05305__20230906_121555PM__kkkm
mjlkmkkkklmkkmkkmmkkkmmkkkkommmmmmmkmmkmmjmlkmkmmkmmkmmkmmkmmkmm
kk__line4__line1_____hnbm_lmmmmmmmmmmmmmmmmmmkmmmmmmmmmmmmmmmmmm
mmmmmmmm_mmmm_mmmm_mm_mmmkkm__org.jpg",
  "path": "cases/64f71faceb1f822256e4c882/externallmg_r_1693995834347_05305_
__20230906_121555PM__kkkmmjmlkmkkkklmkkmkkmmkkkmmkkkkommmmmmmkmmk
mmjmlkmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmk
__line4__line1_____hnbm_lmmmmmmmmmmmmmmmmmmkmmmmmmmmmmmmmmmmmm
_mmmmmkmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmm
g.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f8533a63830d2aa3b4082b",
  "name": "externallmg_r_1693995834343_05304__20230906_121553PM__kkkm
mjlkmkkkklmkkmkkmmkkkmmkkkkommmmmmmkmmkmmjmlkmkmmkmmkmmkmmkmmkmmkmm
kk__line4__line1_____hnbm_lmmmmmmmmmmmmmmmmmmkmmmmmmmmmmmmmmmmmm
mmmmmmmm_mmmm_mmmm_mm_mmmkkm__org.jpg",
  "path": "cases/64f71faceb1f822256e4c882/externallmg_r_1693995834343_05304_
__20230906_121553PM__kkkmmjmlkmkkkklmkkmkkmmkkkmmkkkkommmmmmmkmmk
mmjmlkmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmk
__line4__line1_____hnbm_lmmmmmmmmmmmmmmmmmmkmmmmmmmmmmmmmmmmmm
_mmmmmkmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmm
g.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f8533a63830d2aa3b4082c",
  "name": "externallmg_r_1693995834351_05306__20230906_121557PM__kkkm
```

```
mjlmkmmkkklmkkmkkmmkkkmmkkkkkommmmmmmkmmkmmjlmkmmkmmkmmkmmkmmkmmkmm
kk__line4__line1_____hnbm_lm____mmmmmmmmmmmmmmmmmmkmmmmmmmmmmmmmmmmmm
mmmmmmmm_mmmm_mmmm_mm_mmmkkm__org.jpg",
    "path": "cases/64f71faceb1f822256e4c882/externalimg_r_1693995834351_05306_
__20230906_121557PM__kkkmmjlmkmmkkklmkkmkkmmkkkmmkkkkkommmmmmmkmmk
mmjlmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmm
__line4__line1_____hnbm_lm____mmmmmmmmmmmmmmmmmmkmmmmmmmmmmmmmmmmmm
_mmmmkmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmm
g.jpg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f8533a63830d2aa3b4082d",
    "name": "externalimg_r_1693995834366_05309__20230906_121728PM__kkkm
mjlmkmmkkklmkkmkkmmkkkmmkkkkkommmmmmmkmmkmmjlmkmmkmmkmmkmmkmmkmmkmmkmm
kk__line4__line1_____hnbm_lm____mmmmmmmmmmmmmmmmmmkmmmmmmmmmmmmmmmmmm
mmmmmmmm_mmmm_mmmm_mm_mmmkkm__org.jpg",
    "path": "cases/64f71faceb1f822256e4c882/externalimg_r_1693995834366_05309_
__20230906_121728PM__kkkmmjlmkmmkkklmkkmkkmmkkkmmkkkkkommmmmmmkmmk
mmjlmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmm
__line4__line1_____hnbm_lm____mmmmmmmmmmmmmmmmmmkmmmmmmmmmmmmmmmmmm
_mmmmkmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmm
g.jpg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f8533a63830d2aa3b4082e",
    "name": "externalimg_r_1693995834370_05310__20230906_121730PM__kkkm
mjlmkmmkkklmkkmkkmmkkkmmkkkkkommmmmmmkmmkmmjlmkmmkmmkmmkmmkmmkmmkmmkmm
kk__line4__line1_____hnbm_lm____mmmmmmmmmmmmmmmmmmkmmmmmmmmmmmmmmmmmm
mmmmmmmm_mmmm_mmmm_mm_mmmkkm__org.jpg",
    "path": "cases/64f71faceb1f822256e4c882/externalimg_r_1693995834370_05310_
__20230906_121730PM__kkkmmjlmkmmkkklmkkmkkmmkkkmmkkkkkommmmmmmkmmk
mmjlmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmm
__line4__line1_____hnbm_lm____mmmmmmmmmmmmmmmmmmkmmmmmmmmmmmmmmmmmm
_mmmmkmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmm
g.jpg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f8533a63830d2aa3b40830",
    "name": "externalimg_r_1693995834392_05312__20230906_121752PM__kkkm
mjlmkmmkkklmkkmkkmmkkkmmkkkkkommmmmmmkmmkmmjlmkmmkmmkmmkmmkmmkmmkmmkmm
```

```
kk_line4_line1_____hnbm_lmmmmmmmmmm_mmmmkmmmmmmmmmmmm
mmmmmmmm_mmmm_mmmm_mm_mmmkkm___org.jpg",
  "path": "cases/64f71faceb1f822256e4c882/externalimg_r_1693995834392_05312_
__20230906_121752PM___kkkmmjlmkmmkkkklmkkmkmmkkkmmkkkkmmkkmmmmmmmmmmkmmk
mmjlmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmm
_line4_line1_____hnbm_lmmmmmmmmmmmm
_mmmmkmmmmmmmmmmmmmmmmmmmmmmmmmmmm_mmmm_mmmm_mm_mmmkkm___or
g.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f8533a63830d2aa3b40831",
  "name": "externalimg_r_1693995834395_05313__20230906_122150PM___kkkm
mjlmkmmkkkklmkkmkmmkkkmmkkkmmkkmmmmmmmmkmmkmmjlmkmmkmmkmmkmmkmmkmmkmm
kk_line4_line1_____hnbm_lmmmmmmmmmmmm
mmmmmmmm_mmmm_mmmm_mm_mmmkkm___org.jpg",
  "path": "cases/64f71faceb1f822256e4c882/externalimg_r_1693995834395_05313_
__20230906_122150PM___kkkmmjlmkmmkkkklmkkmkmmkkkmmkkkkmmkkmmmmmmmmmmkmmk
mmjlmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmm
_line4_line1_____hnbm_lmmmmmmmmmmmm
_mmmmkmmmmmmmmmmmmmmmmmmmmmmmmmmmm_mmmm_mmmm_mm_mmmkkm___or
g.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f8533a63830d2aa3b40832",
  "name": "externalimg_r_1693995834398_05314__20230906_122154PM___kkkm
mjlmkmmkkkklmkkmkmmkkkmmkkkmmkkkmmmmmmmmmmkmmkmmjlmkmmkmmkmmkmmkmmkmmkmm
kk_line4_line1_____hnbm_lmmmmmmmmmmmm
mmmmmmmm_mmmm_mmmm_mm_mmmkkm___org.jpg",
  "path": "cases/64f71faceb1f822256e4c882/externalimg_r_1693995834398_05314_
__20230906_122154PM___kkkmmjlmkmmkkkklmkkmkmmkkkmmkkkkmmkkmmmmmmmmmmkmmk
mmjlmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmmkmm
_line4_line1_____hnbm_lmmmmmmmmmmmm
_mmmmkmmmmmmmmmmmmmmmmmmmmmmmmmmmm_mmmm_mmmm_mm_mmmkkm___or
g.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f8533a63830d2aa3b40833",
  "name": "externalimg_r_1693995834402_05315__20230906_122155PM___kkkm
mjlmkmmkkkklmkkmkmmkkkmmkkkmmkkkmmmmmmmmmmkmmkmmjlmkmmkmmkmmkmmkmmkmmkmm
kk_line4_line1_____hnbm_lmmmmmmmmmmmm
mmmmmmmm_mmmm_mmmm_mm_mmmkkm___or
```



```

"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9867318101",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Passage + Toilet",
"carpetTotal": "482.18",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "578.62",
"finalCarpetArea": "482.18",
"finalSalableArea": "694.34",
"salablePercentage": "20",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "20",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 609.00",
"buildingServicesRate": "2500",
"flatRate": "16000",
"landOtherRate": "13500",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"

```

Name	Length	Width	Total
Composition :			
Passage	3'00"	4'00"	12.00
Living Room	9'7"	16'11"	162.12
Passage	6'7"	3'0"	19.75
Toilet	5'3"	7'7"	39.81
Kitchen	6'8"	12'6"	83.33
Bedroom	9'3"	13'8"	126.42

Other
Composition :
