PROFORMA INVOICE

Invoice No. Dated Vastukala Consultants (I) Pvt Ltd B1-001, U/B FLOOR, PG-2381/23-24 8-Sep-23 BOOMERANG, CHANDIVALI FARM ROAD, **Delivery Note** Mode/Terms of Payment ANDHERI-EAST 400072 GSTIN/UIN: 27AADCV4303R1ZX Reference No. & Date. Other References State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org Buyer's Order No. Dated Buyer (Bill to) JANSEVA SAHAKARI BANK-VASAI WEST Dispatch Doc No. Delivery Note Date JAI KHODIYAR OPP GURUSWARA AMBADI ROAD 3614 /2302455 VASAI WEST PALGHAR -Dispatched through Destination GSTIN/UIN : 27AAAAJ1528R2ZA State Name : Maharashtra, Code: 27 Terms of Delivery SI **Particulars** HSN/SAC GST Amount No. Rate 997224 1 STRUCTURAL REPORT FEE 18 % 1,500.00 (Technical Inspection and Certification Services) CGST 135.00 SGST 135.00 Total ₹ 1.770.00 Amount Chargeable (in words) E. & O.E Indian Rupee One Thousand Seven Hundred Seventy Only HSN/SAC Taxable Central Tax State Tax Total Value Rate Rate Amount Amount Tax Amount 997224 1,500.00 9% 135.00 135.00 270.00 Total 1,500.00 135.00 135,00 270.00 Tax Amount (in words) : Indian Rupee Two Hundred Seventy Only Company's Bank Details Bank Name ICICI BANK LTD 123105000319 A/c No. Branch & IFS Code: MIG Colony, Bandra (E.), Mumbai & ICIC0001231 数规国 Mr. Atul Bachchulal Jaiswal - Residential Flat No. 102, 1st Floor, Wing - G, "Shri Laxman Co-Op. Hsg. Soc. Ltd. ", 100 Feet Road, Village - Dewanman, Vasai (West), Taluka - Vasai, District - Palghar, PIN - 401 202, State – Maharashtra, Country – India. Company's PAN : AADCV4303R : vastukala@icici Declaration NOTE - AS PER MSME RULES INVOICE NEED TO BE for Vastukala Consultants (II) Pvt Ltd Gitanjali CLEARED WITHIN 45 DAYS OR INTEREST CHARGES Kulaye APPLICABLE AS PER THE RULE MSME Registration No. - 27222201137 **Authorised Signatory**

This is a Computer Generated Invoice





CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: JSB / Vasai (West) Branch / Mr. Atul Bachchulal Jaiswal (003614/2302455)

Page 1 of 3

Vastu/Mumbai/09/2023/003614/2302455 08/16-99-PRNI Date: 08.09.2023

Structural Stability Report

Structural Observation Report of Residential Flat No. 102, 1st Floor, Wing - G, "Shri Laxman Co-Op. Hsg. Soc. Ltd.", 100 Feet Road, Village – Dewanman, Vasai (West), Taluka – Vasai, District – Palghar, PIN – 401 202, State – Maharashtra, Country – India.

Name of Owner: Mr. Atul Bachchulal Jaiswal.

This is to certify that on visual inspection, it appears that the structure of the "Shri Laxman Co-Op. Hsg. Soc. Ltd." is in normal condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 30 years.

General Information:

A.		Introduction
1	Name of Building	"Shri Laxman Co-Op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 102, 1st Floor, Wing - G, "Shri Laxman Co-Op. Hsg. Soc. Ltd.", 100 Feet Road, Village – Dewanman, Vasai (West), Taluka – Vasai, District – Palghar, PIN – 401 202, State – Maharashtra, Country – India.
3	Type of Building	Residential used
4	No. of Floors	Ground + 2 Upper Floors
5	Whether stilt / podium / open parking provided	Open Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1993 (As per site information)
11	Present age of building	30 years
12	Residual age of the building	30 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	4 Flats on 1st Floor
14	Methodology adopted	As per visual site inspection







TeleFax : +91 22 28371325/24

mumbai@vastukala.org

B.	External Observation of the Building		
1	Plaster	Normal Condition	
2	Chajjas	Normal Condition	
3	Plumbing	Normal Condition	
4	Cracks on the external walls	Not found	
5	Filling cracks on the external walls	Not found	
6	Cracks on columns & beams	Not found	
7	Vegetation	Not found	
8	Leakages of water in the drainage pipes	Not found	
	or water pipes		
9	Dampness external in the wall due to	Not found	
	leakages		
10	Any other observation about the condition	The external condition of the building is in normal condition	
	of external side of the building		
С	Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Normal Condition	
2	Columns (Cracks & Leakages)	Normal Condition	
3	Ceiling (Cracks & Leakages)	Normal Condition	
4	Leakages inside the property	Not Found	
5	Painting inside the property	Normal	
6	Maintenance of staircase & cracks	Normal	

D	Common Observation	
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws
	- Laws No. 77 of the Model Bye Laws (Co-	under the Act the society shall conduct a Structural Audit of
	Operative Societies Act / Rules)	the building of the society as follows
2	Remark	1. No Structural Audit Report is furnished for the
		perusal.

E Conclusion

The captioned building is having Ground + 2 Upper Floors which are constructed in year 1993 as per site information. Estimated future life under present circumstances is about 30 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 04.09.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in good condition & will stand future life subject to proper, preventive periodic maintenance & good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar B. Chalikwar

Digitally signed by Sharadkumar B. Chalikwar DN: cn=Sharadkumar B. Chalikwar, o=Yastukala Consultants (I) Pvt. Ltd., ou=CMD, email=cmd @vastukala.org, cDate: 2023.09.08 16:17:04 +05'30'

Auth. Sign.

Director

Sharadkumar B. Chalikwar

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09





Actual site photographs















