#### PROFORMA INVOICE

Invoice No. Dated Vastukala Consultants (I) Pvt Ltd PG-2433/23-24 B1-001, U/B FLOOR, 12-Sep-23 BOOMERANG, CHANDIVALI FARM ROAD, **Delivery Note** Mode/Terms of Payment ANDHERI-EAST 400072 AGAINST REPORT GSTIN/UIN: 27AADCV4303R1ZX Reference No. & Date. Other References State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org Buyer's Order No. Dated Buyer (Bill to) UNION BANK OF INDIA-UMFB BRANCH Dispatch Doc No. Delivery Note Date Shree Rasraj Heights, Rokadia Lane, 003630 / 2302513 borivali West, Mumbai -400092 Destination Dispatched through GSTIN/UIN : 27AAACU0564G1ZH State Name : Maharashtra, Code: 27 Terms of Delivery Particulars HSN/SAC GST Amount SI Rate No. 1 STRUCTURAL REPORT FEE 997224 18 % 3,000.00 (Technical Inspection and Certification Services) **CGST** 270.00 **SGST** 270.00 Total 3,540.00 E. & O.E Amount Chargeable (in words) Indian Rupee Three Thousand Five Hundred Forty Only HSN/SAC Taxable Central Tax State Tax Total Value Rate Rate Tax Amount Amount Amount 997224 3,000.00 270.00 270.00 540.00 9% 9% Total 3,000.00 270.00 270.00 540.00 Tax Amount (in words): Indian Rupee Five Hundred Forty Only Company's Bank Details Bank Name : UNION BANK OF INDIA A/c No. 635301010050194 Branch & IFS Code: Bandra East & UBIN0563536 Remarks: Mrs. Manisha Nimish Mehta - Residential Flat No. 105, 1st Floor, Building No. D/25, Wing - B, "Yogi Krishna Co-Op. Hsg. Soc. Ltd., Yogi Nagar, Eksar Road, Borivali (West), Mumbai - 400 091, State -Maharashtra, Country - India Company's PAN : AADCV4303R Declaration UPI Virtual ID : Vastukala@icici NOTE - AS PER MSME RULES INVOICE NEED TO for Vastukala Consultants (I) Pvt Ltd BE CLEARED WITHIN 45 DAYS OR INTEREST Asmita Rathod

This is a Computer Generated Invoice

CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137





Authorised Signatory

CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: UBI/ UMFB Branch / Mrs. Manisha Nimish Mehta (3630/2302513)

Page 1 of 4

Vastu/Mumbai/09/2023/3630/2302513 12/18-157-PRSH Date: 12.09.2023

### Structural Stability Report

Structural Observation Report of Residential Flat No. 105, 1st Floor, Building No. D/25, Wing - B, "Yogi Krishna Co-Op. Hsg. Soc. Ltd., Yogi Nagar, Eksar Road, Borivali (West), Mumbai – 400 091, State - Maharashtra, Country – India.

### Name of Owner: Mrs. Manisha Nimish Mehta

This is to certify that on visual inspection, it appears that the structure of the "Yogi Krishna Co-Op. Hsg. Soc. Ltd." is in normal condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 18 years.

#### **General Information:**

Α.	1	Introduction
1	Name of Building	"Yogi Krishna Co-Op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 105, 1st Floor, Building No. D/25, Wing
		- B, "Yogi Krishna Co-Op. Hsg. Soc. Ltd., Yogi Nagar,
	//	Eksar Road, Borivali (West), Mumbai - 400 091, State -
	.0	Maharashtra, Country – India.
3	Type of Building	Residential used
4	No. of Floors	Ground + 4th Upper Floors
5	Whether stilt / podium / open parking	Open Car Parking Space
	provided	
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1981 (As per Previous Valuation Report)
11	Present age of building	42 years
12	Residual age of the building	18 years Subject to proper, preventive periodic
		maintenance & structural repairs.
13	No. of flats (Per Floor)	3 Flats on 1st Floor
14	Methodology adopted	As per visual site inspection



Regd. Office: B1-001, U/B Floor, Boomerang,



Ahmedabad 9 Jaipur

🖓 Delhi NCR 💡 Nashik

Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA TeleFax: +91 22 28371325/24

TeleFax : +91 22 28371325/24 mumbai@vastukala.org

В.	External O	bservation of the Building
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Found
5	Filling cracks on the external walls	Found at some places
6	Cracks on columns & beams	Not found
7	Vegetation	Not found
8	Leakages of water in the drainage pipes	Not found
	or water pipes	
9	Dampness external in the wall due to	Found
	leakages	
10	Any other observation about the condition	The external condition of the building is in normal condition
	of external side of the building	
С	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Normal Condition
2	Columns (Cracks & Leakages)	Found at some places
3	Ceiling (Cracks & Leakages)	Found at some places
4	Leakages inside the property	Found at some places
5	Painting inside the property	Normal (At some places paint is pulled out)
6	Maintenance of staircase & cracks	Normal

D	Common Observation	
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws
	- Laws No. 77 of the Model Bye Laws (Co-	under the Act the society shall conduct a Structural Audit of
	Operative Societies Act / Rules)	the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal.

### Conclusion

The captioned building is having Ground + 4th Upper Floors which are constructed in year 1982 as per Previous Valuation Report. Estimated future life under present circumstances is about 19 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 11.09.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar Digitally signed by Sharadkumar B. B. Chalikwar

Director

DN: cn=Sharadkumar B. Chalikwar. a=Vastukala Consultants (I) Pvt. Ltd., ou=CMD, email=cmd@vastukala.org, Date: 2023.09.12 17:12:50 +05'30'

Auth. Sign.

Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09





# **Actual site photographs**

















## **Actual site photographs**













eate

