#### PROFORMA INVOICE

Invoice No. Dated Vastukala Consultants (I) Pvt Ltd B1-001, U/B FLOOR, PG-2399/23-24 8-Sep-23 BOOMERANG, CHANDIVALI FARM ROAD, Delivery Note Mode/Terms of Payment ANDHERI-EAST 400072 GSTIN/UIN: 27AADCV4303R1ZX Reference No. & Date. Other References State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org Buyer's Order No. Dated Buyer (Bill to) STATE BANK OF INDIA - RACPC CHINCHPOKALI Dispatch Doc No. Delivery Note Date RACPC, Voltas House, 1st Floor, 3634 /2302463 Dr. Ambedkar Marg, Chinchpokali (East), Dispatched through Destination Mumbai - 400 033 GSTIN/UIN : 27AAACS8577K2ZO State Name : Maharashtra, Code: 27 Terms of Delivery SI **Particulars** HSN/SAC GST Amount No. Rate 1 997224 18 % STRUCTURAL REPORT FEE 2,500.00 (Technical Inspection and Certification Services) CGST 225.00 **SGST** 225.00 Total ₹ 2,950.00 Amount Chargeable (in words) E. & O.E Indian Rupee Two Thousand Nine Hundred Fifty Only HSN/SAC Taxable Central Tax State Tax Total Value Rate Amount Rate **Amount** Tax Amount 997224 2,500.00 225.00 225.00 450.00 225.00 Total 2,500.00 225.00 450.00 Tax Amount (in words) : Indian Rupee Four Hundred Fifty Only Company's Bank Details Bank Name State Bank of India 32632562114 Branch & IFS Code: MIDC Andheri (E) & SBIN0007074 Remarks: Mrs. Aruna Mohan Kumar Naik - Residential Flat No. 301, 3rd Floor, Wing - B, "Vasant Nagri Kaveri Co-Op. Hsq. Soc. Ltd., Sector - 9, Vasant Township, Village -Achole, Vasai (East), Palghar - 401 209, State -Maharashtra, Country - India Company's PAN : AADCV4303R vastukala@icici UPI Virtual ID Declaration NOTE - AS PER MSME RULES INVOICE NEED TO BE for Vastukala Consultants (I) Pvt Ltd CLEARED WITHIN 45 DAYS OR INTEREST CHARGES Gitanjali Kulaye APPLICABLE AS PER THE RULE.

This is a Computer Generated Invoice

MSME Registration No. - 27222201137





Authorised Signatory

CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: SBI/ RACPC - Chinchpokli (East) / Mrs. Aruna Mohan Kumar Naik (3634/2302463)

Page 1 of 4

Vastu/Mumbai/09/2023/3634/2302463 08/24-107-PRSH Date: 08.09.2023

### Structural Stability Report

Structural Observation Report of Residential Flat No. 301, 3rd Floor, Wing - B, "Vasant Nagri Kaveri Co-Op. Hsg. Soc. Ltd., Sector - 9, Vasant Township, Village - Achole, Vasai (East), Palghar - 401 209, State - Maharashtra, Country - India.

Name of Owner: Mrs. Aruna Mohan Kumar Naik.

This is to certify that on visual inspection, it appears that the structure of the "Vasant Nagri Kaveri Co-Op. Hsg. Soc. Ltd." is in normal condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 35 years.

#### **General Information:**

Α.		Introduction
1	Name of Building	"Vasant Nagri Kaveri Co-Op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 301, 3rd Floor, Wing - B, "Vasant Nagri
	//	Kaveri Co-Op. Hsg. Soc. Ltd., Sector - 9, Vasant
	10	Township, Village – Achole, Vasai (East), Palghar – 401
		209, State - Maharashtra, Country - India.
3	Type of Building	Residential used
4	No. of Floors	Ground + 3 <sup>rd</sup> Upper Floors
5	Whether stilt / podium / open parking	Open Car Parking Space
	provided	L
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1998 (As per Part Occupancy Certificate)
11	Present age of building	25 years
12	Residual age of the building	35 years Subject to proper, preventive periodic
		maintenance & structural repairs.
13	No. of flats (Per Floor)	6 Flats on 3 <sup>rd</sup> Floor
14	Methodology adopted	As per visual site inspection







B.	External O	bservation of the Building
1	Plaster	Good Condition
2	Chajjas	Good Condition
3	Plumbing	Good Condition
4	Cracks on the external walls	Found
5	Filling cracks on the external walls	Not found
6	Cracks on columns & beams	Not found
7	Vegetation	Found
8	Leakages of water in the drainage pipes	Not found
	or water pipes	·
9	Dampness external in the wall due to	Found
	leakages	
10	Any other observation about the condition	The external condition of the building is in normal condition
	of external side of the building	//
С	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Normal Condition
2	Columns (Cracks & Leakages)	Normal Condition
3	Ceiling (Cracks & Leakages)	Normal Condition
4	Leakages inside the property	Found at some places
5	Painting inside the property	Normal
6	Maintenance of staircase & cracks	Normal

D	Common Observation	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of
	Operative Societies Act / Rules)	the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal.

### Conclusion

The captioned building is having Ground + 3rd Upper Floors which are constructed in year 1998 as per Occupancy Certificate. Estimated future life under present circumstances is about 35 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 21.07.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

## For VASTUKALA CONSULTANTS (I) PVT. LTD.

B. Chalikwar

Sharadkumar Digitany ang...
Chalikwar DN: cn=Sharadkumar B. Chalikwar, DN: cn=Sharadkumar B. Chalikwar, D=Vastukala Consultants (I) Pvr. Ltd., CMD. email=cmdevastukala.org. ou=CMD, email=cmd@vastukala.org, c Date: 2023.09.08 18:04:16 +05'30'

Auth. Sign.

Sharadkumar B. Chalikwar


Director

Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09





## **Actual site photographs**























# **Actual site photographs**





Think.Innovate.Create

