

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7e7"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b9423119d",
    "firstName": "Akshay Kumar",
    "email": "0_default_akshay.kumar10@sbi.co.in_and_sbi.17879@sbi.co.in",
    "mobileNo": "0_DEFAULT_022-28329367",
    "workMobileNo": "0_DEFAULT_91-7053284426"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
  }
}
```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7e7",
  "branchCode": "000048",
  "type": "BRANCH",
  "name": "MIDC Andheri (East) Branch",
  "email": "sbi.17879@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Plot No. B-1, MIDC Industrial Area, Central Road, Andheri (East),
Mumbai, State - Maharashtra, Country - India. ",
  "ledgerName": "STATE BANK OF INDIA- MIDC ANDHERI",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
```

```
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "64d09914dc9f3034f3008833",
"role": "SITEENGINEER+MAKAR",
"firstName": "Meetal",
"email": "meetalirasal@gmail.com",
"lastName": "Rasal",
"mobileNo": "7397882283",
"designation": "Junior Architect",
"shortName": "MR",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.549009443764113",
  "longitude": "73.09413968558034"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": false,
"schedule": [],
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
```

```
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": " Dadara Haveli",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Classic Ecohomes",
  "label": false
},
"selectArea": {
  "status": false,
```

```
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
}
```



```
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "110",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
```

```
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
```

```
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
},
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```



```
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "6500138ba8e9b70221dfbb7b",
"ownerName": "M/s. Cruise Appliances Pvt. Ltd. ",
"ownerPhoneNo": "7045959271",
"fullAddress": "Residential Flat No. 110, Basement Floor, Classic Ecohomes, Dadara
Haveli, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1694503777594_cruise_appliance_flat_no_110_1.pdf",
    "path": "cases/6500138ba8e9b70221dfbb7b/
document_1694503777594_cruise_appliance_flat_no_110_1.pdf",
    "id": "442580",
    "uploadedBy": "62691c48afd7d55eddecfda3",
    "createdAt": "Tue Sep 12 2023 12:59:44 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae12a0aa6d152c1801b483",
      "label": "site Details"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1694851238532_site_details_and_sketch.pdf",
    "path": "cases/6500138ba8e9b70221dfbb7b/
document_1694851238532_site_details_and_sketch.pdf",
    "id": "931643",
    "uploadedBy": "64d09914dc9f3034f3008833",
    "createdAt": "Sat Sep 16 2023 13:30:38 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003711",
"createdBy": "62691c48afd7d55eddecfda3",
"caseHistory": [
```

```
{
  "id": "336603",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Tue Sep 12 2023 13:00:19 GMT+0530 (India Standard Time)"
}
],
"owners": [
  {
    "name": "M/s. Cruise Applaiques Pvt. Ltd. ",
    "phone": "7045959271",
    "ownershipShare": "",
    "email": "",
    "id": "994886"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffa4a8e9b70221e9bc7c",
    "name":
"externallmg_1695023012696_WhatsApp_Image_20230918_at_10903_PM.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023012696_WhatsApp_Image_20230918_at_10903_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffa4a8e9b70221e9bc7d",
    "name":
"externallmg_1695023012697_WhatsApp_Image_20230918_at_10904_PM_1.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023012697_WhatsApp_Image_20230918_at_10904_PM_1.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffa4a8e9b70221e9bc7e",
    "name":
"externallmg_1695023012699_WhatsApp_Image_20230918_at_10904_PM_2.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023012699_WhatsApp_Image_20230918_at_10904_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffa4a8e9b70221e9bc7f",
    "name":
"externallmg_1695023012702_WhatsApp_Image_20230918_at_10904_PM_3.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023012702_WhatsApp_Image_20230918_at_10904_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffa4a8e9b70221e9bc80",
    "name":
"externallmg_1695023012704_WhatsApp_Image_20230918_at_10904_PM.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023012704_WhatsApp_Image_20230918_at_10904_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffa4a8e9b70221e9bc81",
    "name":
"externallmg_1695023012707_WhatsApp_Image_20230918_at_10905_PM_1.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023012707_WhatsApp_Image_20230918_at_10905_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffa4a8e9b70221e9bc82",
    "name":
"externallmg_1695023012710_WhatsApp_Image_20230918_at_10905_PM_2.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023012710_WhatsApp_Image_20230918_at_10905_PM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffa4a8e9b70221e9bc83",
    "name":
"externallmg_1695023012713_WhatsApp_Image_20230918_at_10905_PM.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023012713_WhatsApp_Image_20230918_at_10905_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffa4a8e9b70221e9bc84",
    "name":
"externallmg_1695023012715_WhatsApp_Image_20230918_at_10906_PM_1.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023012715_WhatsApp_Image_20230918_at_10906_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffa4a8e9b70221e9bc85",
    "name":
"externallmg_1695023012718_WhatsApp_Image_20230918_at_10906_PM_2.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023012718_WhatsApp_Image_20230918_at_10906_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffa4a8e9b70221e9bc86",
    "name":
"externallmg_1695023012720_WhatsApp_Image_20230918_at_10906_PM.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023012720_WhatsApp_Image_20230918_at_10906_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffa4a8e9b70221e9bc87",
```

```
    "name":
"externallmg_1695023012723_WhatsApp_Image_20230918_at_10907_PM_1.jpeg",
  "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023012723_WhatsApp_Image_20230918_at_10907_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507ffa4a8e9b70221e9bc88",
  "name":
"externallmg_1695023012725_WhatsApp_Image_20230918_at_10907_PM_2.jpeg",
  "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023012725_WhatsApp_Image_20230918_at_10907_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507ffa4a8e9b70221e9bc89",
  "name":
"externallmg_1695023012727_WhatsApp_Image_20230918_at_10907_PM.jpeg",
  "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023012727_WhatsApp_Image_20230918_at_10907_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507ffaca8e9b70221e9bcc6",
  "name":
"externallmg_1695023020593_WhatsApp_Image_20230918_at_10213_PM.jpeg",
  "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020593_WhatsApp_Image_20230918_at_10213_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507ffaca8e9b70221e9bcc7",
  "name":
"externallmg_1695023020598_WhatsApp_Image_20230918_at_10217_PM.jpeg",
  "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020598_WhatsApp_Image_20230918_at_10217_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507ffaca8e9b70221e9bcc8",
  "name":
"externallmg_1695023020603_WhatsApp_Image_20230918_at_10220_PM.jpeg",
  "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020603_WhatsApp_Image_20230918_at_10220_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507ffaca8e9b70221e9bcc9",
  "name":
"externallmg_1695023020609_WhatsApp_Image_20230918_at_10221_PM.jpeg",
  "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020609_WhatsApp_Image_20230918_at_10221_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507ffaca8e9b70221e9bccb",
  "name":
"externallmg_1695023020612_WhatsApp_Image_20230918_at_10222_PM.jpeg",
  "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020612_WhatsApp_Image_20230918_at_10222_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507ffaca8e9b70221e9bccb",
  "name":
"externallmg_1695023020614_WhatsApp_Image_20230918_at_10223_PM_1.jpeg",
  "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020614_WhatsApp_Image_20230918_at_10223_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6507ffaca8e9b70221e9bccb",
  "name":
"externallmg_1695023020619_WhatsApp_Image_20230918_at_10223_PM.jpeg",
```

```
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020619_WhatsApp_Image_20230918_at_10223_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffaca8e9b70221e9bccd",
    "name":
"externallmg_1695023020623_WhatsApp_Image_20230918_at_10453_PM.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020623_WhatsApp_Image_20230918_at_10453_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffaca8e9b70221e9bcce",
    "name":
"externallmg_1695023020625_WhatsApp_Image_20230918_at_10844_PM.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020625_WhatsApp_Image_20230918_at_10844_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffaca8e9b70221e9bccf",
    "name":
"externallmg_1695023020630_WhatsApp_Image_20230918_at_10857_PM.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020630_WhatsApp_Image_20230918_at_10857_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffaca8e9b70221e9bcd0",
    "name":
"externallmg_1695023020637_WhatsApp_Image_20230918_at_10859_PM.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020637_WhatsApp_Image_20230918_at_10859_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6507ffaca8e9b70221e9bcd1",
    "name":
"externallmg_1695023020639_WhatsApp_Image_20230918_at_10901_PM.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020639_WhatsApp_Image_20230918_at_10901_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffaca8e9b70221e9bcd2",
    "name":
"externallmg_1695023020642_WhatsApp_Image_20230918_at_10902_PM_1.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020642_WhatsApp_Image_20230918_at_10902_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffaca8e9b70221e9bcd3",
    "name":
"externallmg_1695023020645_WhatsApp_Image_20230918_at_10902_PM.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020645_WhatsApp_Image_20230918_at_10902_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffaca8e9b70221e9bcd4",
    "name":
"externallmg_1695023020647_WhatsApp_Image_20230918_at_10903_PM_1.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020647_WhatsApp_Image_20230918_at_10903_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6507ffaca8e9b70221e9bcd5",
    "name":
"externallmg_1695023020696_WhatsApp_Image_20230918_at_10903_PM_2.jpeg",
    "path": "cases/6500138ba8e9b70221dfbb7b/
externallmg_1695023020696_WhatsApp_Image_20230918_at_10903_PM_2.jpeg",
```



```

    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-12T07:30:19.163Z",
"updatedAt": "2023-09-18T07:43:40.775Z",
"__v": 0,
"invoiceId": "6500138da8e9b70221dfbb83",
"updatedBy": "64d09914dc9f3034f3008833",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "M/s. Cruise Appliaes Pvt. Ltd. ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7045959271"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			