

Structural Stability Report Prepared For: SBI / Jai Bhavani Road Branch / Mr. Sanjay Sudhakar Dixit (3740/2302523) Page 1 of 3

Vastu/Nashik/09/2023/3740/2302523 13/09-167-RPSH Date: 13.09.2023

## **Structural Stability Report**

Residential Flat No. 2, Ground Floor, **"Amruti Apartment"**, Survey No. 26/3/3/1, Plot No. 3+4, Near Madhav Lawns, Veena Society, K.J. Mahta Road, Sadhguru Nagar, Village – Deolali, Taluka & District – Nashik - 422 101, State – Maharashtra, Country – India belongs **Mr. Sanjay Sudhakar Dixit.** 

This is to certify that on visual inspection, it appears that the structure of "Amruti Apartment" is in normal condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 38 years.

#### General Information:

Α.		Introduction
1	Name of Building	"Amruti Apartment"
2	Property Address	Residential Flat No. 2, Ground Floor, <b>"Amruti Apartment",</b> Survey No. 26/3/3/1, Plot No. 3+4, Near Madhav Lawns, Veena Society, K.J. Mahta Road, Sadhguru Nagar, Village – Deolali, Taluka & District – Nashik - 422 101, State – Maharashtra, Country – India.
3	Type of Building	Flat No. 2
4	No. of Floors	Ground + 2 Upper Floors
5	Whether stilt / podium / open parking provided	Covered Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	6' thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction Think. In	2001 (As per Full Occupancy Certificate)
11	Present age of building	22 years
12	Residual age of the building	38 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of Flats	2 Flats On Ground Floor
14	Methodology adopted	As per visual site inspection





(

0

9

0

Nashik : 4, 1<sup>st</sup> Floor, Madhusha Elite, Vrundavan Nagar, Jatra-Nandur Naka Link Road, Adgaon, Nashik - 422 003, (M.S.) E-mail : nashik@vastukala.org, Tel. : +91 253 4068262 / 9890380564

(	Dur Pan	In	dia Prese	nc	e at :			
	Mumbai Thane Delhi NCR	9	Aurangabad Nanded Nashik	9	Pune Indore Ahmedabad	9	Rajkot Raipur Jaipur	

Regd. Office : B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

- 🖀 TeleFax : +91 22 28371325/24
- 🖂 mumbai@vastukala.org

Structural Stability Report Prepared For: SBI / Jai Bhavani Road Branch / Mr. Sanjay Sudhakar Dixit (3740/2302523) Page 2 of 3

В.	External Observation of the Building				
1	Plaster	Good			
2	Chajjas	Good			
3	Plumbing	Good			
4	Cracks on the external walls	Not Found			
5	Filling cracks on the external walls	Not Found			
6	Cracks on columns & beams	Not Found			
7	Vegetation	Not Found			
8	Leakages of water in the drainage pipes	Not Found			
	or water pipes				
9	Dampness external in the wall due to	Found			
	leakages				
10	Any other observation about the condition	The external condition of the structure is in normal condition			
	of external side of the building				
С	Internal Observation of the comm	on areas of the building and captioned premises			
1	Beams (Cracks & Leakages)	Not found			
2	Columns (Cracks & Leakages)	Not found			
3	Ceiling (Cracks & Leakages)	Not found			
4	Leakages inside the property	Not Found			
5	Painting inside the property	Normal			
6	Maintenance of staircase & cracks	Normal			

D	Common Observation			
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws		
	– Laws No. 77 of the Model Bye Laws (Co-	under the Act the society shall conduct a Structural Audit of		
	Operative Societies Act / Rules)	the building of the society as follows		
2	Remark	-		

#### E Conclusion

The captioned Flat is having Ground floor which are constructed in year 2001 (As per Full Occupancy Certificate). Estimated future life under present circumstances is about 38 years' subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 01.06.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

### For VASTUKALA CONSULTANTS (I) PVT. LTD.

### Director

Auth. Sign.

Sharadkumar B. Chalikwar Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09 Encl: Valuation report.



Think.Innovate.Create Vastukala Consultants (I) Pvt. Ltd. An ISO 9001:2015 Certified Company www.vastukala.org Structural Stability Report Prepared For: SBI / Jai Bhavani Road Branch / Mr. Sanjay Sudhakar Dixit (3740/2302523) Page 3 of 3

# Actual site Photographs









