PROFORMA INVOICE

Invoice No. Dated Vastukala Consultants (I) Pvt Ltd B1-001, U/B FLOOR, PG-2571/23-24 21-Sep-23 BOOMERANG, CHANDIVALI FARM ROAD, **Delivery Note** Mode/Terms of Payment ANDHERI-EAST 400072 **AGAINST REPORT** GSTIN/UIN: 27AADCV4303R1ZX Reference No. & Date. Other References State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org Buyer's Order No. Dated Buyer (Bill to) State Bank of India - SPI PBB Branch Dispatch Doc No. Delivery Note Date SPI PBB FORT BRANCH 003937 / 2302652 Mumbai Main Branch Building, Gate no 1 Dispatched through Destination Horniman Circle Mumbai samachar marg Fort GSTIN/UIN : 27AAACS8577K2ZO State Name : Maharashtra, Code: 27 Terms of Delivery SI HSN/SAC GST **Particulars** Amount No. Rate 1 18 % 997224 STRUCTURAL REPORT FEE 2,500.00 (Technical Inspection and Certification Services) **CGST** 225.00 **SGST** 225.00 Total 2.950.00 Amount Chargeable (in words) E. & O.E Indian Rupee Two Thousand Nine Hundred Fifty Only HSN/SAC Taxable Central Tax State Tax Total Value Amount Rate Amount Rate Tax Amount 997224 2,500.00 9% 225.00 9% 225.00 450.00 Total 2,500.00 225.00 225.00 450.00 Tax Amount (in words) : Indian Rupee Four Hundred Fifty Only Company's Bank Details Bank Name : State Bank of India A/c No. 32632562114 Branch & IFS Code: MIDC Andheri (E) & SBIN0007074 Remarks: Mr. Prasad Balwant Mhase, Mr. Balwant B. Mhase & Mrs. Nanda Balwant Mhase - Residential Flat No. 7374, 2nd Floor, Building No 192, Wing - B, "Chintan Anandmay Co-op. Hsg. Soc. Ltd.", Kannamwar Nagar No. 2, Village - Hanyali, Vikroli (East), Taluka - Kurla, District - Mumbai, PIN Code - 400 083, State -Maharashtra, India Company's PAN : AADCV4303R UPI Virtual ID : vastukala@icici Declaration NOTE - AS PER MSME RULES INVOICE NEED TO for Vastukala Consultants (I) Pvt Ltd BE CLEARED WITHIN 45 DAYS OR INTEREST

This is a Computer Generated Invoice

CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137



Asmita Rathod

Authorised Signatory



CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: SBI / SPL PBB Fort / Mr. Prasad Balwant Mhase (3937/2302652)

Page 1 of 3

Vastu/Mumbai/09/2023/3937/2302652 21/08-296-PRSH Date: 21.09.2023

Structural Stability Report

Structural Observation Report of Residential Flat No. 7374, 2nd Floor, Building No 192, Wing - B, "Chintan Anandmay Co-op. Hsg. Soc. Ltd.", Kannamwar Nagar No. 2, Village - Hariyali, Vikroli (East), Taluka - Kurla, District - Mumbai, PIN Code - 400 083, State - Maharashtra, India.

Name of Owner: Mr. Prasad Balwant Mhase, Mr. Balwant B. Mhase & Mrs. Nanda Balwant Mhase.

This is to certify that on visual inspection, it appears that the structure of the "Chintan Anandmay Co-op. Hsg. Soc. Ltd." is in average condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 17 years.

General Information:

A.		Introduction
1	Name of Building	"Chintan Anandmay Co-op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 7374, 2nd Floor, Building No 192, Wing - B, Chintan Anandmay Co-op. Hsg. Soc. Ltd., Kannamwar Nagar No. 2, Village - Hariyali , Vikroli (East), Taluka - Kurla, District - Mumbai, PIN Code - 400 083, State - Maharashtra, India
3	Type of Building	Residential used
4	No. of Floors	Ground + 4 Upper Floors
5	Whether stilt / podium / open parking provided	Open Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1980 (Approx.)
11	Present age of building	43 years
12	Residual age of the building	17 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	8 Flats on 2 nd Floor
14	Methodology adopted	As per visual site inspection







Regd. Office: B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

TeleFax: +91 22 28371325/24
mumbai@vastukala.org

B.	External O	bservation of the Building
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Found
5	Filling cracks on the external walls	Not found
6	Cracks on columns & beams	Found
7	Vegetation	Found
8	Leakages of water in the drainage pipes	Found
	or water pipes	
9	Dampness external in the wall due to	Found
	leakages	
10	Any other observation about the condition	The external condition of the building is in average
	of external side of the building	condition
С	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Normal Condition
2	Columns (Cracks & Leakages)	Normal Condition
3	Ceiling (Cracks & Leakages)	Normal Condition
4	Leakages inside the property	Not found .
5	Painting inside the property	Normal
6	Maintenance of staircase & cracks	Normal

D	Common Observation	
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws
	- Laws No. 77 of the Model Bye Laws (Co-	under the Act the society shall conduct a Structural Audit of
	Operative Societies Act / Rules)	the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal.

Ē Conclusion

The captioned building is having Ground + 4 Upper Floors which are constructed in year 1980 (Approx.) Estimated future life under present circumstances is about 17 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 23.08.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in average condition & will stand future life subject to proper, preventive periodic maintenance & good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar Chalikwar Chalikwar R. Chalikw

B. Chalikwar

o=Vastukala Consultants (I) Pvt. Ltd., ou=CMD, email=cmd@vastukala.org, c Date: 2023.09.21 16:19:04 +05'30'

Director

Auth. Sign.

Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09





Actual site photographs















