

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26511191f7b344b008a1d"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b8b",
    "email": "coorddesk.rasmecbhy@sbi.co.in",
    "firstName": "SHASHI RANJAN",
    "mobileNo": "",
    "workMobileNo": "9867369914",
    "lastName": "RANJAN"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2350000",
    "discussWithPerson": "SHASHI RANJAN",
    "expectedFees": 1175,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26511191f7b344b008a1d",
  "name": "RASMECCC BHAYANDAR",
  "branchCode": "",
  "mobileNo": "022-28149108",
  "alternateMobileNo": "",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RASMECCC Bhayandar Branch\nUnit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, \nOpp. Maxus Mall,
Bhayander (West), Thane – 401 101, \nState – Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "627219d6afd7d55eddedd283",
"role": "PICKUPPERSON",
"firstName": "Mangesh ",
"email": "mangeshpalande17@gmail.com",
"lastName": "Palande",
"mobileNo": "9833030550",
"shortName": "MP",
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "64c8cdd2a5c3051014f62c65",
"role": "SITEENGINEER",
"firstName": "Bhavesh",
"email": "freelancevaluer@gmail.com",
"lastName": "Shelar",
"mobileNo": "9272696074",
"designation": "",
"shortName": "BSS",
"workWithDocumentMaker": "",
"profilePhoto": "users/64c8cdd2a5c3051014f62c65/profilePhoto_1690881490040_3
25961526_225125063269350_5532229620043102208_n.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
```

```
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"checker": {
  "_id": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg",
  "firstName": "Shobha",
  "lastName": "Kuperkar",
  "shortName": "SH",
  "email": "shobha@vastukala.org",
  "designation": "",
  "mobileNo": "9004134140",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.453825892703758",
  "longitude": "72.82052236853885"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82052236853885,
    19.453825892703758
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-09-21T12:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-09-21T12:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-22",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
```

```
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Virar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Virar (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": true,
"name": "Taluka",
"key": "taluka",
"value": "Vasai",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Blue Skyline",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
```



```
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Blue Sky Line Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "97, 98",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "18, 2C",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
```

```
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "311",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
}
```

```
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Virar East",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
```

```
"value": "Cement_Plastering+_POP_Finish",
"label": "Cement Plastering + POP Finish"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Semi_Urban",
"label": "Semi Urban"
},
"townplanApprovedByList": {
"value": "CIDCO",
"label": "City Industrial Development Corporation of Maharashtra"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Internal Road",
"west": "Blue Skyline Tower",
"south": "Phoolpada Road",
"east": "Phoolpada Road"
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
"asPerActual": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"asPerDocument": {
"north": "",
```

```
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "Details not available",
"dateOfIssusApprovePlan": " Copy of Part Occupancy Certificate No. CIDCO /
VVSR / POC / BP-1382 / E / 568 Dated 22.06.2006\n",
"approvePlanVerified": "NO",
"empanelledOfApprovePlan": "NO"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "25.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "6062.5",
  "depreciatedBuildingRate": "1862.5"
},
"igrRate": {
  "propertyName": "Virar",
  "rate": "57800",
  "landRate": "15100",
  "igrImage": "cases/650c2b4e612315172eae8ade/igr_1695563254322_Image.png",
  "squareMeterGuideLineRate": "49130.00",
  "squareFeetGuideLineRate": "4564.00"
},
"igrFinalRate": {
  "depreciationPercentage": "83",
  "rate": "4027.00",
  "squareFeetGuideLineRate": "4027.00",
  "squareMeterGuideLineRate": "43345.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Seller_Occupied",
```

```
"label": "Seller Occupied"
},
"monthlyRent": "6000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per CIDCO norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  }
}
```

```
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2006",
  "fullDate": "1/1/2006"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
}
```

```
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "17",
"totalLifeBuilding": "60",
"estimatedAge": "43",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
```



```
"area": "435.00",
"measurementType": "Sq. Ft.",
"areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/650c2b4e612315172eae8ade/
routeMap_1695622936381_Image.png",
    "routeLat": "19.456035",
    "routeLng": "72.820275",
    "stationName": "Virar",
    "routeDistance": "950 Mt. Walkable"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "ymwhan",
      "name": "ymwhan",
      "image": "cases/650c2b4e612315172eae8ade/
routeMap_1695622793931_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
```

```
"totalKitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalSuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalInteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalElectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalExtraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalPotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalOthersRate": "0",
"finalTotal": "2637405.00",
"finalValue": "2637405.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Sep 25 2023 17:44:50 GMT+0530 (India Standard Time)",
  "number": "2302710",
  "dayCount": "15",
  "monthCount": "354",
  "generatedBy": "60f915d3f3dd69653a592199"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
```

```
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1751745.00",
  "selectedBuildUpValue": "435.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "650e871e0c1bfd1d9fddd203",
      "name": "externallmg_1695450909841_IMG20230922WA0215.jpg",
      "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909841_IMG20230922WA0215.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "650e871e0c1bfd1d9fddd204",
      "name": "externallmg_1695450909844_IMG20230922WA0216.jpg",
      "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909844_IMG20230922WA0216.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
}
],
"externalPhotos": [
  {
    "status": false,
    "_id": "650e871e0c1bfd1d9fddd200",
    "name": "externallmg_1695450909828_IMG20230922WA0212.jpg",
    "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909828_IMG20230922WA0212.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "650e871e0c1bfd1d9fddd206",
    "name": "Living Room",
    "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909852_IMG20230922WA0218.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e87450c1bfd1d9fddd263",
    "name": "Living Room",
    "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450949630_IMG20230922WA0228.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e87450c1bfd1d9fddd265",
    "name": "Living Room",
    "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450949637_IMG20230922WA0231.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "650e87450c1bfd1d9fddd266",
    "name": "Living Room",
    "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450949641_IMG20230922WA0232.jpg",
    "orientation": "portrait"
  }
]
```

```
},
{
  "status": false,
  "_id": "650e87450c1bfd1d9fddd268",
  "name": "Living Room",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450949652_IMG20230922WA0234.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "650e87450c1bfd1d9fddd26d",
  "name": "Living Room",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450949672_IMG20230922WA0241.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "650e87450c1bfd1d9fddd26c",
  "name": "Living Room",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450949669_IMG20230922WA0240.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "650e87450c1bfd1d9fddd270",
  "name": "Living Room",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450949680_IMG20230922WA0244.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "650e87610c1bfd1d9fddd31a",
  "name": "Living Room",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450977769_IMG20230922WA0248.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "650e87610c1bfd1d9fddd319",
  "name": "Living Room",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450977766_IMG20230922WA0247.jpg",
```

```
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": null,
    "max": null
  },
  "builtUpRateRange": {
    "min": "5941",
    "max": "7011"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```



```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "435.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "650c2b4e612315172eae8ade",
"ownerName": "Miss. Priyanka Sanjay Palav & Mr. Sanjay Vasudeo Palav",
"ownerPhoneNo": "9975857669",
"appAddress": "flat c /311 bldg type b blue skyline chs swastik skyline phoolpada Rd
virar east",
```

```
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "12/09/2023",
      "from": {
        "value": "The_Transferor",
        "label": "The Transferor"
      },
      "The_Transferor": "Mr. Pradeep Sampatrao Chavan",
      "to": {
        "value": "The_Transferee",
        "label": "The Transferee"
      },
      "The_Transferee": "Miss. Priyanka Sanjay Palav & Mr. Sanjay Vasudeo Palav"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "434644",
    "path": "cases/650c2b4e612315172eae8ade/
document_1695295930872_PRIYANKA_PALAV_VALUATION.pdf",
    "fileName": "document_1695295930872_PRIYANKA_PALAV_VALUATION.pdf"
  },
  {
    "documentType": {
      "value": "60ae1250aa6d152c1801b316",
      "label": "Part Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "22/06/2006",
      "nameOfApprovingAuthority": {
        "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
        "label": "City and Industrial Development Corp Of Maharashtra Ltd."
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "CIDCO / VVSR / POC / BP-1382 / E / 568"
    },
    "isHardCopy": false,
    "displayStatus": false,
  }
]
```

```
"id": "801453",
"path": "cases/650c2b4e612315172eae8ade/
document_1695296250984_oc__rera_.pdf",
"fileName": "document_1695296250984_oc__rera_.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "02/06/2004",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CIDCO / VVSR /AM / BP-1382 / E / 665"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/650c2b4e612315172eae8ade/document_1695563486348_document
_1695295930872_PRIYANKA_PALAV_VALUATION.pdf",
"fileName": "document_1695563486348_document_1695295930872_PRIYANKA_P
ALAV_VALUATION.pdf",
"id": "964501",
"uploadedBy": "62691c48afd7d55eddecfda3",
"createdAt": "Mon Sep 25 2023 10:47:54 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003951",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "184666",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Sep 21 2023 17:08:54 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Miss. Priyanka Sanjay Palav & Mr. Sanjay Vasudeo Palav",
```

```
"phone": "9975857669",
"ownershipShare": "",
"email": "",
"id": "467961"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "152844",
"name": "Living Room",
"length": "8.92",
"length1": "8",
"length2": "11",
"width": "15.83",
"width1": "15",
"width2": "10",
"totalArea": "141.18",
"images": [],
"extraAreas": [],
"finalArea": "141.18"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Kitchen",
"length": "8.33",
"length1": "8",
"length2": "4",
"width": "10.58",
"width1": "10",
"width2": "7",
"totalArea": "88.19",
"images": [],
"extraAreas": [],
"finalArea": "88.19"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "3",
"name": "Bathroom",
"length": "",
"length1": "4",
"length2": "9",
"width": "",
"width1": "4",
"width2": "2",
"totalArea": "19.79",
"images": [],
"finalArea": "19.79",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "2.83",
  "width1": "2",
  "width2": "10",
  "totalArea": "10.86",
  "images": [],
  "extraAreas": [],
  "finalArea": "10.86"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Cupboard",
      "value": "Cupboard"
    }
  },
  {
    "toBeAdded": {
      "label": "Cupboard",
      "value": "Cupboard"
    },
    "name": {
      "label": "Carpet",
      "value": "Carpet"
    }
  }
]
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "0",
"length1": "3",
"length2": "9",
"length": "3.75",
"width1": "7",
"width2": "3",
"width": "7.25",
"totalArea": "27.19",
"percentageBeforeTotal": "27.19",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "27.19"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "4",
  "length2": "2",
  "length": "4.17",
  "width1": "1",
  "width2": "10",
  "width": "1.83",
  "totalArea": "7.64",
  "percentageBeforeTotal": "7.64",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "7.64"
},
{
```

```
"toBeAdded": {
  "label": "Carpet",
  "value": "Carpet"
},
"name": {
  "label": "Passage",
  "value": "Passage"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "2",
"length1": "8",
"length2": "2",
"length": "8.17",
"width1": "4",
"width2": "1",
"width": "4.08",
"totalArea": "33.35",
"percentageBeforeTotal": "33.35",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "33.35"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Built_Up",
  "squareMeterArea": "40.41",
  "totalAreaDocument": "435",
  "docBultupPercentage": "",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
```



```
"docFinalSaleableSquareMeter": "0.00",
"id": "859932"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65103f630c1bfd1d9fdf450b",
  "property": "Phoolpada Road, Virar East",
  "area": "485",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "3400000",
  "expectedRate": "7010.31",
  "builtUpExpectedRate": "0.00",
  "image": "cases/650c2b4e612315172eae8ade/
indicator_1695562963391_Image.png",
  "squareMeter": "45.06",
  "id": "181160"
},
{
  "printlnReport": true,
  "_id": "65103f630c1bfd1d9fdf450c",
  "property": "Rushi Vihar Complex, Virar East",
  "area": "485",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "3100000",
  "expectedRate": "6391.75",
  "builtUpExpectedRate": "0.00",
  "image": "cases/650c2b4e612315172eae8ade/
indicator_1695563033060_Image.png",
  "squareMeter": "45.06",
  "id": "475321"
},
{
  "printlnReport": true,
```

```
  "_id": "65103f630c1bfd1d9fdf450d",
  "property": "Gokuldham CHSL Virar East",
  "area": "530",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "Ground",
  "source": "Index_no.2",
  "expectedPrice": "3300000",
  "expectedRate": "6226.42",
  "builtUpExpectedRate": "0.00",
  "image": "cases/650c2b4e612315172eae8ade/
indicator_1695563139819_Image.png",
  "squareMeter": "49.24",
  "id": "163611"
},
{
  "printlnReport": true,
  "_id": "65103f630c1bfd1d9fdf450e",
  "property": "Dwarka Nagari Virar East",
  "area": "505",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "1st Floor",
  "source": "Index_no.2",
  "expectedPrice": "3000000",
  "expectedRate": "5940.59",
  "builtUpExpectedRate": "0.00",
  "image": "cases/650c2b4e612315172eae8ade/
indicator_1695563321887_Image.png",
  "squareMeter": "46.92",
  "id": "198310"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e871e0c1bfd1d9fddd1fc",
    "name": "externalImg_1695450909810_IMG20230922WA0208.jpg",
    "path": "cases/650c2b4e612315172eae8ade/
externalImg_1695450909810_IMG20230922WA0208.jpg",
    "orientation": "portrait"
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650e871e0c1bfd1d9fddd1fd",
      "name": "externallmg_1695450909814_IMG20230922WA0209.jpg",
      "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909814_IMG20230922WA0209.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650e871e0c1bfd1d9fddd1fe",
      "name": "externallmg_1695450909818_IMG20230922WA0210.jpg",
      "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909818_IMG20230922WA0210.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650e871e0c1bfd1d9fddd1ff",
      "name": "externallmg_1695450909821_IMG20230922WA0211.jpg",
      "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909821_IMG20230922WA0211.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650e871e0c1bfd1d9fddd200",
      "name": "externallmg_1695450909828_IMG20230922WA0212.jpg",
      "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909828_IMG20230922WA0212.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650e871e0c1bfd1d9fddd201",
      "name": "externallmg_1695450909832_IMG20230922WA0213.jpg",
      "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909832_IMG20230922WA0213.jpg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e871e0c1bfd1d9fddd202",
  "name": "externallmg_1695450909836_IMG20230922WA0214.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909836_IMG20230922WA0214.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e871e0c1bfd1d9fddd203",
  "name": "externallmg_1695450909841_IMG20230922WA0215.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909841_IMG20230922WA0215.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e871e0c1bfd1d9fddd204",
  "name": "externallmg_1695450909844_IMG20230922WA0216.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909844_IMG20230922WA0216.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e871e0c1bfd1d9fddd205",
  "name": "externallmg_1695450909848_IMG20230922WA0217.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909848_IMG20230922WA0217.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e871e0c1bfd1d9fddd206",
  "name": "externallmg_1695450909852_IMG20230922WA0218.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909852_IMG20230922WA0218.jpg",
  "orientation": "portrait"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "650e871e0c1bfd1d9fddd207",
"name": "externallmg_1695450909855_IMG20230922WA0219.jpg",
"path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909855_IMG20230922WA0219.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "650e871e0c1bfd1d9fddd208",
"name": "externallmg_1695450909862_IMG20230922WA0220.jpg",
"path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909862_IMG20230922WA0220.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "650e871e0c1bfd1d9fddd209",
"name": "externallmg_1695450909865_IMG20230922WA0221.jpg",
"path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450909865_IMG20230922WA0221.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "650e871e0c1bfd1d9fddd20a",
"name": "externallmg_r_1695450909761_IMG_20230923_012452.jpg",
"path": "cases/650c2b4e612315172eae8ade/
externallmg_r_1695450909761_IMG_20230923_012452.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "650e871e0c1bfd1d9fddd20b",
"name": "externallmg_r_1695450909789_IMG_20230923_012456.jpg",
"path": "cases/650c2b4e612315172eae8ade/
externallmg_r_1695450909789_IMG_20230923_012456.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "650e87450c1bfd1d9fddd25e",
  "name": "externalimg_1695450949602_IMG20230922WA0223.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externalimg_1695450949602_IMG20230922WA0223.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e87450c1bfd1d9fddd25f",
  "name": "externalimg_1695450949608_IMG20230922WA0224.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externalimg_1695450949608_IMG20230922WA0224.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e87450c1bfd1d9fddd260",
  "name": "externalimg_1695450949611_IMG20230922WA0225.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externalimg_1695450949611_IMG20230922WA0225.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e87450c1bfd1d9fddd261",
  "name": "externalimg_1695450949618_IMG20230922WA0226.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externalimg_1695450949618_IMG20230922WA0226.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e87450c1bfd1d9fddd262",
  "name": "externalimg_1695450949624_IMG20230922WA0227.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externalimg_1695450949624_IMG20230922WA0227.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "650e87450c1bfd1d9fddd263",
    "name": "externallmg_1695450949630_IMG20230922WA0228.jpg",
    "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450949630_IMG20230922WA0228.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e87450c1bfd1d9fddd264",
    "name": "externallmg_1695450949633_IMG20230922WA0230.jpg",
    "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450949633_IMG20230922WA0230.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e87450c1bfd1d9fddd265",
    "name": "externallmg_1695450949637_IMG20230922WA0231.jpg",
    "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450949637_IMG20230922WA0231.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e87450c1bfd1d9fddd266",
    "name": "externallmg_1695450949641_IMG20230922WA0232.jpg",
    "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450949641_IMG20230922WA0232.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e87450c1bfd1d9fddd267",
    "name": "externallmg_1695450949644_IMG20230922WA0233.jpg",
    "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450949644_IMG20230922WA0233.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e87450c1bfd1d9fddd268",
```

```
    "name": "externalImg_1695450949652_IMG20230922WA0234.jpg",
    "path": "cases/650c2b4e612315172eae8ade/
externalImg_1695450949652_IMG20230922WA0234.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e87450c1bfd1d9fddd269",
    "name": "externalImg_1695450949656_IMG20230922WA0235.jpg",
    "path": "cases/650c2b4e612315172eae8ade/
externalImg_1695450949656_IMG20230922WA0235.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e87450c1bfd1d9fddd26a",
    "name": "externalImg_1695450949662_IMG20230922WA0238.jpg",
    "path": "cases/650c2b4e612315172eae8ade/
externalImg_1695450949662_IMG20230922WA0238.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e87450c1bfd1d9fddd26b",
    "name": "externalImg_1695450949667_IMG20230922WA0239.jpg",
    "path": "cases/650c2b4e612315172eae8ade/
externalImg_1695450949667_IMG20230922WA0239.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e87450c1bfd1d9fddd26c",
    "name": "externalImg_1695450949669_IMG20230922WA0240.jpg",
    "path": "cases/650c2b4e612315172eae8ade/
externalImg_1695450949669_IMG20230922WA0240.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e87450c1bfd1d9fddd26d",
    "name": "externalImg_1695450949672_IMG20230922WA0241.jpg",
```



```
    "path": "cases/650c2b4e612315172eae8ade/  
externallmg_1695450949672_IMG20230922WA0241.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "650e87450c1bfd1d9fddd26e",  
    "name": "externallmg_1695450949675_IMG20230922WA0242.jpg",  
    "path": "cases/650c2b4e612315172eae8ade/  
externallmg_1695450949675_IMG20230922WA0242.jpg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "650e87450c1bfd1d9fddd26f",  
    "name": "externallmg_1695450949678_IMG20230922WA0243.jpg",  
    "path": "cases/650c2b4e612315172eae8ade/  
externallmg_1695450949678_IMG20230922WA0243.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "650e87450c1bfd1d9fddd270",  
    "name": "externallmg_1695450949680_IMG20230922WA0244.jpg",  
    "path": "cases/650c2b4e612315172eae8ade/  
externallmg_1695450949680_IMG20230922WA0244.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "650e87450c1bfd1d9fddd271",  
    "name": "externallmg_1695450949682_IMG20230922WA0245.jpg",  
    "path": "cases/650c2b4e612315172eae8ade/  
externallmg_1695450949682_IMG20230922WA0245.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "650e87610c1bfd1d9fddd318",  
    "name": "externallmg_1695450977762_IMG20230922WA0246.jpg",  
    "path": "cases/650c2b4e612315172eae8ade/  
externallmg_1695450977762_IMG20230922WA0246.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e87610c1bfd1d9fddd319",
  "name": "externallmg_1695450977766_IMG20230922WA0247.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450977766_IMG20230922WA0247.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e87610c1bfd1d9fddd31a",
  "name": "externallmg_1695450977769_IMG20230922WA0248.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450977769_IMG20230922WA0248.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e87610c1bfd1d9fddd31b",
  "name": "externallmg_1695450977774_IMG20230922WA0249.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450977774_IMG20230922WA0249.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e87610c1bfd1d9fddd31c",
  "name": "externallmg_1695450977776_IMG20230922WA0250.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450977776_IMG20230922WA0250.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e87610c1bfd1d9fddd31d",
  "name": "externallmg_1695450977781_IMG20230922WA0251.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externallmg_1695450977781_IMG20230922WA0251.jpg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650e87610c1bfd1d9fddd31e",
      "name": "externalImg_1695450977785_IMG20230922WA0252.jpg",
      "path": "cases/650c2b4e612315172eae8ade/
externalImg_1695450977785_IMG20230922WA0252.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650e87610c1bfd1d9fddd31f",
      "name": "externalImg_1695450977787_Screenshot_20230923012240563_cnwpsm
office_eng.png",
      "path": "cases/650c2b4e612315172eae8ade/externalImg_1695450977787_Screens
hot_20230923012240563_cnwpsmoffice_eng.png",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650e87610c1bfd1d9fddd320",
      "name": "externalImg_1695450977794_Screenshot_20230923012243500_cnwpsm
office_eng.png",
      "path": "cases/650c2b4e612315172eae8ade/externalImg_1695450977794_Screens
hot_20230923012243500_cnwpsmoffice_eng.png",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650e87610c1bfd1d9fddd321",
      "name": "externalImg_1695450977799_Screenshot_20230923012301419_cnwpsm
office_eng.png",
      "path": "cases/650c2b4e612315172eae8ade/externalImg_1695450977799_Screens
hot_20230923012301419_cnwpsmoffice_eng.png",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "650e87610c1bfd1d9fddd322",
      "name": "externalImg_1695450977802_IMG20230922WA0222.jpg",
      "path": "cases/650c2b4e612315172eae8ade/
externalImg_1695450977802_IMG20230922WA0222.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e87610c1bfd1d9fddd323",
  "name": "externalImg_1695450977805_IMG20230922WA0229.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externalImg_1695450977805_IMG20230922WA0229.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e87610c1bfd1d9fddd324",
  "name": "externalImg_1695450977807_IMG20230922WA0236.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externalImg_1695450977807_IMG20230922WA0236.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e87610c1bfd1d9fddd325",
  "name": "externalImg_1695450977808_IMG20230922WA0237.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externalImg_1695450977808_IMG20230922WA0237.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e87610c1bfd1d9fddd326",
  "name": "externalImg_1695450977826_IMG20230922WA0253.jpg",
  "path": "cases/650c2b4e612315172eae8ade/
externalImg_1695450977826_IMG20230922WA0253.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation.xlsx",
    "filename": "1695563750793_Calculation.xlsx",
    "path": "cases/650c2b4e612315172eae8ade/
processingDocuments/1695563750793_Calculation.xlsx",
```

```
"size": "1309494",
"createdAt": "Sun Sep 24 2023 19:25:54 GMT+0530 (India Standard Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
},
{
"originalname": "document_1695296250984_oc__rera_.pdf",
"filename": "1695563751382_document_1695296250984_oc__rera_.pdf",
"path": "cases/650c2b4e612315172eae8ade/
processingDocuments/1695563751382_document_1695296250984_oc__rera_.pdf",
"size": "6682408",
"createdAt": "Sun Sep 24 2023 19:25:54 GMT+0530 (India Standard Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
}
],
"remarks": [],
"createdAt": "2023-09-21T11:38:54.320Z",
"updatedAt": "2023-09-25T12:16:56.674Z",
"__v": 0,
"invoiceId": "650c2b4f612315172eae8af9",
"fullAddress": "Residential Flat No. 311, 3rd Floor, Wing - C, Blue Skyline, Blue Sky
Line Co-op. Hsg. Soc. Ltd., Village - Virar, Virar East, Taluka - Vasai, District - Palghar,
Vlrrar (East), State - Maharashtra, India",
"updatedAt": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "Miss. Priyanka Sanjay Palav ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9975857669",
"buildingServicesRate": "2500.00",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 435.00",
"flatRate": "6700.00",
"landOtherRate": "4200",
"briefDescOfProperty": "Living Room + Kitchen + Bathroom + WC",
"carpetTotal": "260.02",
"otherCarpetTotal": "40.99",
"builtupPercentage": "10",
```

```

"extendOfSiteRemark": "",
"finalBuiltupArea": "361.02",
"finalCarpetArea": "328.20",
"finalSalableArea": "397.12",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in sq. Ft. = 301.00\nCupboard Area in sq. Ft.
= 27.00\nTotal Carpet Area in sq. Ft. = 328.00",
"toBeAdded": "",
"finalSaleablePercentage": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "68.18",
"otherCompositionSaleableTotal": "0.00",
"shopDetails": {
  "typeOfShops": {
    "label": "",
    "value": ""
  },
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Mon Sep 25 2023 17:37:18 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-09-22"
}

```

Name	Length	Width	Total
Composition :			

Living Room	8'11"	15'10"	141.18
Kitchen	8'4"	10'7"	88.19
Bathroom	4'9"	4'2"	19.79
WC	3'10"	2'10"	10.86
Other Composition :			
Cupboard	3'9"	7'3"	27.19
Passage	4'2"	1'10"	7.64
Passage	8'2"	4'1"	33.35