

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b2655b191f7b344b008aa0"
    },
    "type": "CREDITOFFICER",
    "_id": "65080841a8e9b70221e9ce15",
    "firstName": "Dikshant",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "7972931571",
    "email": "sbi.116931@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "26713600",
    "discussWithPerson": "Dikshant",
    "expectedFees": 13356.800000000001,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b2655b191f7b344b008aa0",
  "name": "HOUSING FINANCE BORIVALI (WEST)",
  "branchCode": "",
  "mobileNo": "022-28914194",
  "alternateMobileNo": "",
  "email": "sbi.11693@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Victory Park, 1st Floor, Om Shanti Chowk, \nChandravarkar Road,
Borivali (West), Mumbai - 400 092."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627219d6afd7d55eddedd283",
```

```
"role": "PICKUPPERSON",
"firstName": "Mangesh ",
"email": "mangeshpalande17@gmail.com",
"lastName": "Palande",
"mobileNo": "9833030550",
"shortName": "MP",
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc575ece84bf289ba9e82d",
"role": "SITEENGINEER",
"firstName": "Deepak ",
"email": "daksh7831@gmail.com",
"lastName": "Jain ",
"mobileNo": "9022815908",
"designation": "",
"shortName": "DJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER + RATE VERFIER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      },
      {
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      }
    }
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.204047393178517",
  "longitude": "72.83505277735642"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83505277735642,
    19.204047393178517
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": true,
"schedule": [
  {
    "dateTime": "2023-09-21T12:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-09-21T12:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-09-21T12:30:00.000Z",
    "remark": ""
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-09-22",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kandivali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "51",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
}
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Siddha - Seabrook",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Shankarpada",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Dahanukarwadi, Linking Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```



```
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "47",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "8",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "817",
  "label": true
},
"blockNo": {
```

```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "5102",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 067",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali (West)\t",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Under Construction Building",
    "west": "New Link Road",
    "south": "Slum Area",
    "east": "Shivshankar SRA Building"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
```

```
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Approved Building Plan were not provided and not
verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Kandivali",
  "rate": "143500",
  "landRate": "67730",
  "igrImage": "cases/650c2dce612315172eae915d/igr_1695462569527_Image.png",
  "squareMeterGuideLineRate": "172200.00",
  "squareFeetGuideLineRate": "15998.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "143500",
  "squareMeterGuideLineRate": "172200.00",
  "squareFeetGuideLineRate": "15998.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
```

```
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"monthlyRent": "73000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "carParking": "Yes",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
```

```
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2023",
  "fullDate": "1/1/2023"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "Building_Under_Construction",
```

```
"label": "Building Under Construction"
},
"appearanceOfTheBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "7",
"noOfAmenityFloors": "1",
"noOfFloors": "57",
"flatFloorNo": "",
"noOfLifts": "6",
"noOfDwellingUnitsInBuilding": "6"
},
```



```
"finalPlinthArea": {
  "area": "1108.80",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/650c2dce612315172eae915d/
routeMap_1695460766770_Image.png",
    "routeLat": "19.203777",
    "routeLng": "72.834519",
    "stationName": "Kandivali",
    "routeDistance": "2.4KM"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "qihgv",
      "name": "qihgv",
      "image": "cases/650c2dce612315172eae915d/
routeMap_1695460679415_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
```

```
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "29232000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "29232000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
```

```
"status": true
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "57",
  "percentage": "34.02985074626865",
  "isHideFloor": false,
  "status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "57",
  "percentage": "5.96",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "57",
  "percentage": "5.96",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "57",
  "percentage": "2.98",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "57",
  "percentage": "2.98",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "57",
  "percentage": "2.13",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "57",
"percentage": "2.13",
"isHideFloor": false,
"status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "57",
  "percentage": "8.51",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "57",
  "percentage": "1.28",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "57",
  "percentage": "1.28",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "57",
  "percentage": "4.25",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "81.49",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "17738582.00",
  "selectedBuildUpValue": "1108.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "650e5fe30c1bfd1d9fdd4fb2",
      "name": "externallmg_1695440867615_IMG_20230922_143216.jpg",
      "path": "cases/650c2dce612315172eae915d/
externallmg_1695440867615_IMG_20230922_143216.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "650e60270c1bfd1d9fdd50f9",
      "name": "externallmg_1695440935080_IMG_20230922_143205.jpg",
      "path": "cases/650c2dce612315172eae915d/
externallmg_1695440935080_IMG_20230922_143205.jpg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "650e5fe30c1bfd1d9fdd4fb3",
```

```
    "name": "externallmg_1695440867626_IMG_20230922_143217.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440867626_IMG_20230922_143217.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e60010c1bfd1d9fdd500b",
    "name": "externallmg_1695440897159_IMG_20230922_143154.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897159_IMG_20230922_143154.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e60010c1bfd1d9fdd500a",
    "name": "externallmg_1695440897151_IMG_20230922_143137.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897151_IMG_20230922_143137.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "650e5fe30c1bfd1d9fdd4fb5",
    "name": "Living Room",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440867645_IMG_20230922_142400.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e5fe30c1bfd1d9fdd4fb6",
    "name": "Living Room",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440867651_IMG_20230922_142408.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e5fe30c1bfd1d9fdd4fb7",
    "name": "Living Room",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440867654_IMG_20230922_142412.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e60010c1bfd1d9fdd4ff9",
    "name": "Living Room",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897079_IMG_20230922_142427.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e60010c1bfd1d9fdd4ffc",
    "name": "Living Room",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897101_IMG_20230922_142442.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e60010c1bfd1d9fdd4ffe",
    "name": "Living Room",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897109_IMG_20230922_142507.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e60010c1bfd1d9fdd4ffd",
    "name": "Living Room",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897106_IMG_20230922_142502.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e60010c1bfd1d9fdd5006",
    "name": "Living Room",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897134_IMG_20230922_142718.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e60010c1bfd1d9fdd5005",
    "name": "Living Room",
```

```
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897130_IMG_20230922_142714.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "650e60010c1bfd1d9fdd5002",
    "name": "Living Room",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897121_IMG_20230922_142710.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "25181",
    "max": "30655"
  },
  "builtUpRateRange": {
    "min": "22893",
    "max": "27868"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1008.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
```

```
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "650c2dce612315172eae915d",
"ownerName": "Mr. Jitesh Bhagwandas Makwana, Mr. Bhagwandas Jethalal Makwana
& Mrs. Bijal Jitesh Makwana",
"ownerPhoneNo": "9112005624",
"appAddress": "flat no 5102 siddha subric bldg Shankar pada dahanukar wadi linking
Rd kandivali w",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "08/09/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Brizeal Realtors & Developers LLP",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Jitersh Bhagwandas Makwana, Bhagwandas Jethalal Makwana
& Mrs. Bijal Jitesh Makwana"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "path": "cases/650c2dce612315172eae915d/
document_1695462685262_document_1695296691491_Dikshant_Sir_HFB.pdf",
    "fileName":
"document_1695462685262_document_1695296691491_Dikshant_Sir_HFB.pdf",
    "id": "232879",
    "uploadedBy": "60f91b6f344e052188ffd1fc",
    "createdAt": "Sat Sep 23 2023 15:55:49 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    }
  }
]
```

```
},
"inputs": {
  "documentDate": "16/03/2017",
  "nameOfApprovingAuthority": {
    "value": "Slum_Rehabilitation_Authority_(SRA)",
    "label": "Slum Rehabilitation Authority (SRA)"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "SRA / ENG / 3879 / RS / ML & PL / AP"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1695464818154_Commencement_Certificate.pdf",
"path": "cases/650c2dce612315172eae915d/
document_1695464818154_Commencement_Certificate.pdf",
"id": "481607",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Sat Sep 23 2023 15:56:58 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2021",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "P518020008859"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1695464893544_P51800008859.pdf",
  "path": "cases/650c2dce612315172eae915d/
document_1695464893544_P51800008859.pdf",
  "id": "601814",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Sat Sep 23 2023 15:58:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
```

```
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "30/08/2023",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "SRA / ENG / 3879 / RS / ML & PL / AP"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1695472713905_13plan_copy.pdf",
  "path": "cases/650c2dce612315172eae915d/
document_1695472713905_13plan_copy.pdf",
  "id": "567816",
  "uploadedBy": "60f915d3f3dd69653a592199",
  "createdAt": "Sat Sep 23 2023 18:08:34 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003954",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "691873",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Sep 21 2023 17:19:34 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Jitesh Bhagwandas Makwana, Mr. Bhagwandas Jethalal Makwana &
Mrs. Bijal Jitesh Makwana",
    "phone": "9112005624",
    "ownershipShare": "",
    "email": "",
    "id": "312271"
  }
],
"proposePurchasers": [],
```

```
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "112937",
    "name": "Dining",
    "length": "12.42",
    "length1": "12",
    "length2": "5",
    "width": "5.25",
    "width1": "5",
    "width2": "3",
    "totalArea": "65.19",
    "images": [],
    "extraAreas": [],
    "finalArea": "65.19"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Living Room",
    "length": "25.58",
    "length1": "25",
    "length2": "7",
    "width": "8.92",
    "width1": "8",
    "width2": "11",
    "totalArea": "228.12",
    "images": [],
    "extraAreas": [],
    "finalArea": "228.12"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "2",
    "name": "Toilet",
    "length": "4.33",
```

```
"length1": "4",
"length2": "4",
"width": "8.00",
"width1": "8",
"width2": "00",
"totalArea": "34.67",
"images": [],
"extraAreas": [],
"finalArea": "34.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "10.17",
  "length1": "10",
  "length2": "2",
  "width": "11.67",
  "width1": "11",
  "width2": "8",
  "totalArea": "118.61",
  "images": [],
  "extraAreas": [],
  "finalArea": "118.61"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "8.50",
  "width1": "8",
  "width2": "6",
  "totalArea": "37.54",
  "images": [],
  "extraAreas": [],
  "finalArea": "37.54"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "10.83",
  "length1": "10",
  "length2": "10",
  "width": "11.00",
  "width1": "11",
  "width2": "00",
  "totalArea": "119.17",
  "images": [],
  "extraAreas": [],
  "finalArea": "119.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "32.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "",
  "length1": "8",
  "length2": "0",
```



```
"width": "",
"width1": "4",
"width2": "0",
"totalArea": "32.00",
"images": [],
"finalArea": "32.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "9.58",
  "length1": "9",
  "length2": "7",
  "width": "12.67",
  "width1": "12",
  "width2": "8",
  "totalArea": "121.39",
  "images": [],
  "extraAreas": [],
  "finalArea": "121.39"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Kitchen",
  "length": "",
  "length1": "8",
  "length2": "11",
  "width": "",
  "width1": "12",
  "width2": "5",
  "totalArea": "110.71",
  "images": [],
  "finalArea": "114.41",
  "extraAreas": []
}
],
"otherComposition": [
```

```
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "9",
  "length2": "00",
  "length": "9.00",
  "width1": "4",
  "width2": "00",
  "width": "4.00",
  "totalArea": "36.00",
  "percentageBeforeTotal": "36.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "36"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "93.65",
    "totalAreaDocument": "1008",
    "docBuiltpPercentage": "10",
    "docFinalBUILTUp": "1108.80",
    "docFinalBUILTUpSquareMeter": "103.01",
    "docSaleablePercentage": ""
  }
]
```

```
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "663627"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "650eb5a20c1bfd1d9fde5e98",
  "property": "Siddha Seabrook, Kandivli West",
  "area": "1008",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "magic_bricks",
  "expectedPrice": "29500000",
  "expectedRate": "29265.87",
  "builtUpExpectedRate": "26605.34",
  "image": "cases/650c2dce612315172eae915d/
indicator_1695461794416_Image.png",
  "squareMeter": "93.65",
  "id": "565755"
},
{
  "printlnReport": true,
  "_id": "650eb5a20c1bfd1d9fde5e99",
  "property": "Siddha Seabrook, Kandivli West",
  "area": "1006",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "31",
  "source": "https://www.99acres.com/",
  "expectedPrice": "30000000",
  "expectedRate": "29821.07",
  "builtUpExpectedRate": "27110.07",
  "image": "cases/650c2dce612315172eae915d/
indicator_1695461860313_Image.png",
  "squareMeter": "93.46",
  "id": "818903"
},
{
```

```
"printlnReport": true,
  "_id": "650eb5a20c1bfd1d9fde5e9a",
  "property": "Siddha Seabrook, Kandivli West",
  "area": "1008",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "magic_bricks",
  "expectedPrice": "30900000",
  "expectedRate": "30654.76",
  "builtUpExpectedRate": "27867.97",
  "image": "cases/650c2dce612315172eae915d/
indicator_1695461911861_Image.png",
  "squareMeter": "93.65",
  "id": "693743"
},
{
  "printlnReport": true,
  "_id": "650eb5a20c1bfd1d9fde5e9b",
  "property": "Siddha Seabrook, Kandivli West",
  "area": "1008",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "55",
  "source": "Index_no.2",
  "expectedPrice": "25382752",
  "expectedRate": "25181.30",
  "builtUpExpectedRate": "22892.09",
  "image": "cases/650c2dce612315172eae915d/
indicator_1695462482514_Image.png",
  "squareMeter": "93.65",
  "id": "435218"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e5fe30c1bfd1d9fdd4fb2",
    "name": "externalImg_1695440867615_IMG_20230922_143216.jpg",
    "path": "cases/650c2dce612315172eae915d/
externalImg_1695440867615_IMG_20230922_143216.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e5fe30c1bfd1d9fdd4fb3",
  "name": "externallmg_1695440867626_IMG_20230922_143217.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440867626_IMG_20230922_143217.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e5fe30c1bfd1d9fdd4fb4",
  "name": "externallmg_1695440867641_IMG_20230922_214142__01.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440867641_IMG_20230922_214142__01.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e5fe30c1bfd1d9fdd4fb5",
  "name": "externallmg_1695440867645_IMG_20230922_142400.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440867645_IMG_20230922_142400.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e5fe30c1bfd1d9fdd4fb6",
  "name": "externallmg_1695440867651_IMG_20230922_142408.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440867651_IMG_20230922_142408.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e5fe30c1bfd1d9fdd4fb7",
  "name": "externallmg_1695440867654_IMG_20230922_142412.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440867654_IMG_20230922_142412.jpg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e5fe30c1bfd1d9fdd4fb8",
    "name": "externallmg_1695440867660_IMG_20230922_142417.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440867660_IMG_20230922_142417.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e5fe30c1bfd1d9fdd4fb9",
    "name": "externallmg_1695440867669_IMG_20230922_142417__01.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440867669_IMG_20230922_142417__01.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e5fe30c1bfd1d9fdd4fba",
    "name": "externallmg_1695440867678_IMG_20230922_142420.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440867678_IMG_20230922_142420.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e5fe30c1bfd1d9fdd4fbb",
    "name": "externallmg_1695440867685_IMG_20230922_142424.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440867685_IMG_20230922_142424.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e60010c1bfd1d9fdd4ff9",
    "name": "externallmg_1695440897079_IMG_20230922_142427.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897079_IMG_20230922_142427.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e60010c1bfd1d9fdd4ffa",
  "name": "externallmg_1695440897087_IMG_20230922_142431.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897087_IMG_20230922_142431.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e60010c1bfd1d9fdd4ffb",
  "name": "externallmg_1695440897095_IMG_20230922_142432.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897095_IMG_20230922_142432.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e60010c1bfd1d9fdd4ffc",
  "name": "externallmg_1695440897101_IMG_20230922_142442.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897101_IMG_20230922_142442.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e60010c1bfd1d9fdd4ffd",
  "name": "externallmg_1695440897106_IMG_20230922_142502.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897106_IMG_20230922_142502.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e60010c1bfd1d9fdd4ffe",
  "name": "externallmg_1695440897109_IMG_20230922_142507.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897109_IMG_20230922_142507.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e60010c1bfd1d9fdd4fff",
    "name": "externallmg_1695440897112_IMG_20230922_142508.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897112_IMG_20230922_142508.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e60010c1bfd1d9fdd5000",
    "name": "externallmg_1695440897115_IMG_20230922_142510.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897115_IMG_20230922_142510.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e60010c1bfd1d9fdd5001",
    "name": "externallmg_1695440897118_IMG_20230922_142551.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897118_IMG_20230922_142551.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e60010c1bfd1d9fdd5002",
    "name": "externallmg_1695440897121_IMG_20230922_142710.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897121_IMG_20230922_142710.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e60010c1bfd1d9fdd5003",
    "name": "externallmg_1695440897124_IMG_20230922_142711.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897124_IMG_20230922_142711.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "650e60010c1bfd1d9fdd5004",
  "name": "externallmg_1695440897127_IMG_20230922_142713.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897127_IMG_20230922_142713.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e60010c1bfd1d9fdd5005",
  "name": "externallmg_1695440897130_IMG_20230922_142714.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897130_IMG_20230922_142714.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e60010c1bfd1d9fdd5006",
  "name": "externallmg_1695440897134_IMG_20230922_142718.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897134_IMG_20230922_142718.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e60010c1bfd1d9fdd5007",
  "name": "externallmg_1695440897137_IMG_20230922_142738.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897137_IMG_20230922_142738.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650e60010c1bfd1d9fdd5008",
  "name": "externallmg_1695440897140_IMG_20230922_142741.jpg",
  "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897140_IMG_20230922_142741.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "650e60010c1bfd1d9fdd5009",
    "name": "externallmg_1695440897144_IMG_20230922_143136.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897144_IMG_20230922_143136.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e60010c1bfd1d9fdd500a",
    "name": "externallmg_1695440897151_IMG_20230922_143137.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897151_IMG_20230922_143137.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e60010c1bfd1d9fdd500b",
    "name": "externallmg_1695440897159_IMG_20230922_143154.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897159_IMG_20230922_143154.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e60010c1bfd1d9fdd500c",
    "name": "externallmg_1695440897164_IMG_20230922_143156.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440897164_IMG_20230922_143156.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e60270c1bfd1d9fdd50f7",
    "name": "externallmg_1695440935051_IMG_20230922_143156.jpg",
    "path": "cases/650c2dce612315172eae915d/
externallmg_1695440935051_IMG_20230922_143156.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e60270c1bfd1d9fdd50f8",
```

```
    "name": "externalImg_1695440935060_IMG_20230922_143157.jpg",
    "path": "cases/650c2dce612315172eae915d/
externalImg_1695440935060_IMG_20230922_143157.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650e60270c1bfd1d9fdd50f9",
    "name": "externalImg_1695440935080_IMG_20230922_143205.jpg",
    "path": "cases/650c2dce612315172eae915d/
externalImg_1695440935080_IMG_20230922_143205.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (1).xlsx",
    "filename": "1695462866224_Calculation_1.xlsx",
    "path": "cases/650c2dce612315172eae915d/
processingDocuments/1695462866224_Calculation_1.xlsx",
    "size": "2036701",
    "createdAt": "Sat Sep 23 2023 15:24:41 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "Site Details.pdf",
    "filename": "1695465418785_Site_Details.pdf",
    "path": "cases/650c2dce612315172eae915d/
processingDocuments/1695465418785_Site_Details.pdf",
    "size": "101381",
    "createdAt": "Sat Sep 23 2023 16:06:59 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  }
],
"remarks": [],
"createdAt": "2023-09-21T11:49:34.796Z",
"updatedAt": "2023-09-23T12:38:53.927Z",
"__v": 0,
"invoiceId": "650c2dcf612315172eae9176",
"fullAddress": "Residential Flat No. 5102, 51st Floor, Siddha - Seabrook,
Shankarpada, Dahanukarwadi, Linking Road, Village - Kandivali, Kandivali (West)\t,
Taluka - Borivali, District - Mumbai Suburban, PIN - 400 067, State - Maharashtra,
India",
"updatedAt": "60f915d3f3dd69653a592199",
```

```
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "Mr. Dharmil Vora",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Employee of Developer",
"siteVisitContactNo": "9112005624",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Dining + 3 Toilet +
Passage",
"carpetTotal": "903.1",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "36.00",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "36.00",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1033.01",
"finalCarpetArea": "939.10",
"finalSalableArea": "1033.01",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1008.00",
"buildingServicesRate": "3000",
"flatRate": "29000.00",
"landOtherRate": "26000",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
```

```

    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"shopDetails": {
  "typeOfShops": {
    "label": "",
    "value": ""
  },
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Sat Sep 23 2023 16:35:50 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-09-22"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Dining	12'5"	5'3"	65.19
Living Room	25'7"	8'11"	228.12
Toilet	4'4"	8'00"	34.67
Bedroom	10'2"	11'8"	118.61
Passage	4'5"	8'6"	37.54
Bedroom	10'10"	11'00"	119.17
Toilet	4'00"	8'00"	32.00
Toilet	8'0"	4'0"	32.00
Bedroom	9'7"	12'8"	121.39
Kitchen	8'11"	12'5"	110.71
Other Composition :			
Balcony Area	9'00"	4'00"	36.00